

May 15, 2026

Sheryl Bilbrey, Program Manager **BY ENERGY SAFETY E-FILING**
Environmental Science Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_ESD_SCE_GCA_20260326_0845)

Dear Ms Bilbrey,

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_ESD_SCE_GCA_20260326_0845** which SCE received on **April 15, 2026 (Notice)**, based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **March 26, 2026**. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the Notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//

Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_ESD_SCE_GCA_20260326_0845	1	At coordinates 34.150924, -118.746338 and Vegetation Management ID 1WLRn0000019PD7OAM-2025_4.

Summary of Findings:

Energy Safety’s Notice states that SCE failed to implement its 2025 WMP initiative 8.2.3.3.1 Expanded Clearing (VM-7), which requires compliance with Public Resource Code section 4293, by not maintaining a four-foot clearance distance around the primary conductors near pole ID 4848157E, at coordinates 34.150924, -118.746338 and Vegetation Management ID 1WLRn0000019PD7OAM-2025_4.

Energy Safety states that it “considers this non-performance to be in the **Moderate risk category**.”¹

Response:

On April 15, 2026, OEIS issued a Notice of Non-Performance related to this palm. In response, SCE promptly dispatched an inspector on the same day to reassess the condition of the palm. Based on the findings, follow-up mitigation was completed on April 16, 2026, to address the identified concerns (see image below).

SCE maintains that all actions taken reflect a good-faith effort to balance public safety, system reliability, and applicable regulatory requirements, and that the condition was addressed promptly upon notification.

For additional context, this palm was last inspected on August 5, 2025, as part of a routine inspection cycle. Mitigation work was completed on November 19, 2025, which included a crown reduction to achieve clearance in accordance with applicable vegetation management standards.

¹ Notice, p. 1.

