

August 3, 2026

Patrick Doherty, Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_PAD_SCE_SIS_20260617_1224)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_PAD_SCE_SIS_20260617_1224** which SCE received on **July 2, 2026 (Notice)**, based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **June 17, 2026**. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//
Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_PAD_SCE_SIS_20260617_1224	1	4433322E

Summary of Findings:

Energy Safety's Notice states that on June 17, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Corona, California. Energy Safety found the following deficiencies:

Deficiency 1. Energy Safety observed that in implementing 2025 WMP initiative 8.1.3.1 – Distribution High Fire Risk-Informed (HFRI) Inspection and Remediations (IN-1.1), SCE failed to complete replacement of damaged primary avian protection covers on Structure ID 4433322E, Grid Hardening ID 414433095-4433322E at coordinates 33.827317849068, -117.576067920235.

Energy Safety states that it "considers this non-performance to be in the Minor risk category."¹

Response:

SCE confirms that the avian protection cover on structure 4433322E was remediated on October 20, 2025. During a subsequent inspection in response to this Notice, SCE's Field Operations team identified that the previously installed avian protection cover had become dislodged likely due to environmental exposure or other external factors. On July 27, 2026, SCE personnel remediated the avian cover on structure 4433322E. Please see the photos below showing the most recently completed avian protection cover remediation.

¹ Notice, p. 1.



