

**December 10, 2025**

Patrick Doherty, Compliance Program Manager  
Compliance Assurance Division  
Office of Energy Infrastructure Safety  
California Natural Resources Agency  
715 P Street 20<sup>th</sup> Floor  
Sacramento, CA 95814

**BY ENERGY SAFETY E-FILING**

**SUBJECT:** Southern California Edison Company's Response to Notice of Non-Performance NON\_CAD\_SCE\_AXS\_20250904\_1406

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance NON\_CAD\_SCE\_AXS\_20250904\_1406, which SCE received on November 10, 2025 (Notice), based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on September 4, 2025. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the Notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or [Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com).

Sincerely,

//s//  
Shinjini C Menon  
Senior Vice President of System Planning & Engineering  
Southern California Edison

## SCE Response

### **Finding:**

| <b>Notice</b>                 | <b>#</b> | <b>Structures</b> |
|-------------------------------|----------|-------------------|
| NON_CAD_SCE_AXS_20250904_1406 | 1        | 1232599E          |

### **Summary of Findings:**

Energy Safety's Notice states that in implementing 2025 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1) SCE failed to complete the corrective action of tightening a down guy wire on Pole ID 1232599E, Grid Hardening ID 412153145-1232599E at coordinates 33.796000, -118.357955.

Energy Safety states that it "considers this non-performance to be in the **Minor risk category.**"<sup>1</sup>

### **Response:**

The notification for structure ID 1232599E called for the tightening of the down-guy wire. Upon additional review and field verification conducted on November 19, 2025 in response to this Notice, SCE personnel further tightened the guy wire to the maximum extent feasible while maintaining the structural stability of the pole. Field personnel also noted a slight lean toward the guyed side. Out of an abundance of caution, SCE is assessing whether any additional maintenance of the pole is warranted; however, the pole remains stable and has been assessed by SCE personnel to be safe. Please see

---

<sup>1</sup> Notice, p. 1.

below for photos showing the adjustment of the guy wire following the field verification conducted on November 19, 2025.

Photo 1




Photo 2



Photo 3




Photo 4



Photo 5

