

**December 29, 2025**

Patrick Doherty, Compliance Program Manager  
Compliance Assurance Division  
Office of Energy Infrastructure Safety  
California Natural Resources Agency  
715 P Street 20<sup>th</sup> Floor  
Sacramento, CA 95814

**BY ENERGY SAFETY E-FILING**

**SUBJECT:** Southern California Edison Company's Response to Notice of Non-Performance NON\_CAD\_SCE\_AXS\_20250904\_1343

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – NON\_CAD\_SCE\_AXS\_20250904\_1343 , which SCE received on December 01, 2025 (Notice), based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on September 4, 2025. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the Notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or [Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com).

Sincerely,

//s//  
Shinjini C Menon  
Senior Vice President of System Planning & Engineering  
Southern California Edison

## SCE Response

### **Finding:**

| <b>Notice</b>                 | <b>#</b> | <b>Structures</b> |
|-------------------------------|----------|-------------------|
| NON_CAD_SCE_AXS_20250904_1343 | 1        | 1232593E          |

### **Summary of Findings:**

Energy Safety's Notice states that in implementing 2025 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1), SCE failed to complete the remediation of tightening a guy wire on Pole ID 1232593E, Grid Hardening ID 412152966-1232593E at coordinates 33.796231, -118.360156. Energy Safety states that it "considers this non-performance to be in the **Minor risk category.**"<sup>1</sup>

### **Response:**

SCE disagrees with this Notice of Non-Performance for failure to complete the tightening of the guy wire on structure ID 1235296E. SCE completed remediation of the loose guy wire on February 5, 2025. SCE completed a follow-up inspection on December 26, 2025, in response to this Notice and confirmed that the subject guy wire is properly secured and compliant with SCE's construction standards. Please find photo

---

<sup>1</sup> Notice, p. 1.

evidence below from SCE's December 26, 2025 inspection, documenting the guy wire in its secured condition.<sup>2</sup>



---

<sup>2</sup> Please note that guy wires do not always require maximum tension. Appropriate tension levels may vary based on location, environmental factors, and structural design requirements.