

March 3, 2026

Patrick Doherty, Compliance Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_PAD_SCE_SIS_20260112_1222)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_PAD_SCE_SIS_20260112_1222** which SCE received on **February 12, 2026 (Notice)**, based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **January 12, 2026**. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the Notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//

Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_PAD_SCE_SIS_20260112_1222	1	1157204E

Summary of Findings:

Energy Safety’s Notice states that in implementing its 2025 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1), SCE failed to complete replacement of a capacitor’s avian guard on Pole ID 1157204E, Grid Hardening ID 414164307-1157204E at coordinates 33.7351225874564, - 118.3269464985.

Energy Safety states that it “considers this non-performance to be in the **Minor Risk category**.”¹

Response:

SCE confirms that the avian guard on structure ID 1157204E was remediated on July 4, 2025. During a subsequent inspection in response to this Notice, SCE’s Field Operations team identified that the previously installed avian guard had become dislodged likely due to environmental exposure or other external factors. On February 22, 2026, SCE personnel remediated the avian guard on structure

¹ Notice, p. 1.

1157204E once again. Please find the photo evidence below of the most recently completed avian guard remediation.

