



February 24, 2022

NOV_SCE_ATJ_ 20211207-01

TRANSMITTED VIA ELECTRONIC MAIL

February 24, 2022

Erik Takayesu

NOV_SCE_ATJ_ 20211207-01

Vice President Asset Strategy and Planning

Southern California Edison

2244 Walnut Grove

Rosemead, CA 91770

NOTICE OF VIOLATION

Dear Mr. Takayesu,

Pursuant to Government Code § 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has completed a compliance assessment of Southern California Edison (SCE) and determined the existence of one or more violations. In accordance with Government Code § 15475.2 and the California Code of Regulations, Title 14, Division 17 § 29302(b)(2), noncompliance with an approved wildfire mitigation plan (WMP) or any law, regulation, or guideline within Energy Safety’s authority is considered a violation.

Anthony Trujillo, Energy Safety staff, conducted a walking inspection in Riverside County on December 7, 2021, and discovered the following violation(s):

1. Violation 1: Per SCE’s 2021-Q1 quarterly data report (QDR), covered conductor was installed on pole 4467330E. This structure was reported in covered conductor initiative (2021 WMP initiative number 7.3.3.3.1) with a status of “complete.” However, upon inspection, SCE did not install covered conductor at this pole. Covered conductor work starts at next pole. Energy Safety considers this data accuracy violation to be in the Minor risk category.
2. Violation 2: At poles numbered 1289686E, 1789149E, and 4475177E the pole ID did not match the ID provided by SCE in its QDR spatial data. Energy Safety considers this data accuracy violation to be in the Minor risk category.
3. Violation 3: Per SCE’s Distribution Design Standards (DDS), section DDS-10, page 10-82, “for the 336 (30/7) ACSR covered conductor, vibration dampers shall be installed on every



February 24, 2022

NOV_SCE_ATJ_20211207-01

span in both light loading and heavy loading areas.” SCE’s Distribution Overhead Construction Standards (DOH), section CC 190, page 1 of 11, indicates vibration dampers are required when installing covered conductor. Poles numbered 4556899E, 4554785E, 4554799E, 4554798E, 4554796E, 4554794E, 4545339E, 4554790E, 4554788E, 4554787E, 1026956E, 1407366E, 1789149E, and 4475177E had covered conductor installed but failed to install vibration dampers. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category.

4. Violation 4: Per SCE's protocols for Distribution Overhead Construction (DOH), PO 300 page 9 of 9, when an anchor location is abandoned, the rod and plate shall be removed if in a hazardous or potentially dangerous location. Otherwise, cut the rods off at least 12 inches below the ground line and abandon the remaining anchor. Screw anchor rods may be either unscrewed or cut off. Under no conditions should the rod be bent over or left exposed. Energy Safety identified pole numbered 4554787E in violation of this protocol with an abandoned guy anchor left above the ground line. Energy Safety considers this violation to be in the Minor risk category.
5. Violation 5: Per SCE DOH, “Dead-ends shall be covered with a Dead End Clamp in covered conductor systems. Covering dead-ends will ensure that stripped portions of the covered conductor at the dead-end will be protected from contact that could lead to phase-to-phase or phase-to-ground faults.”¹ Pole numbered 1789149E had a dead-end clamp that was loosely attached to a conductor. Energy Safety considers this a violation for failure of adhering to protocol to be in the Minor risk category.
6. Violation 6: Per SCE’s Distribution Overhead Construction Standards (DOH, Section CC 150.4, covered conductor construction should use covered conductor jumpers at dead-end construction. Pole numbered 1789149E had covering that was detaching and frayed from its jumper wire. Energy Safety considers this a violation for failure of adhering to protocol to be in the Minor risk category.

In accordance with the Energy Safety Compliance Process, outlined in Table 1 below are the correction timelines for identified violations relative to their risk category. Within 30 days from the issuance date of this notice of violation (NOV), March 28, 2022, advise Energy Safety of corrective actions taken or planned by SCE to remedy the above identified violation(s) and prevent recurrence. This response shall be filed in the Energy Safety e-Filing system under the [2021-NOV docket](#) and the associated file name(s) must begin with the NOV identification number provided above.

¹ SCE DOH CC 150.2



February 24, 2022

NOV_SCE_ATJ_ 20211207-01

Table 1 Energy Safety Violation Correction Timeline by Risk Category

Risk Category	Violation and defect correction timeline
Severe	<ul style="list-style-type: none"> • Immediate resolution
Moderate	<ul style="list-style-type: none"> • 2 months (in HFTD Tier 3) • 6 months (in HFTD Tier 2) • 6 months (if relevant to worker safety; not in HFTD Tier 3)
Minor	<ul style="list-style-type: none"> • 12 months or resolution scheduled in WMP update

Pursuant to Government Code § 15475.4(b), this NOV is served electronically, and SCE may request a hearing to take public comment or present additional information. Per statute, the deadline to request a hearing is within 30 days from the issuance date of this NOV – March 28, 2022. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Pursuant to Public Utilities Code § 8389(g), following receipt of SCE’s response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission (CPUC) for its consideration of potential enforcement action, as the CPUC deems appropriate.

Sincerely,

Koko Tomassian
Compliance Program Manager
Compliance Assurance Division
Office of Energy Infrastructure Safety

Cc:

- Gary Chen, SCE
- Elizabeth Leano, SCE
- Diana Gallegos, SCE
- Melissa Semcer, Energy Safety
- Edward Chavez, Energy Safety
- Anthony Trujillo, Energy Safety

Energy Safety Inspection Report



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Table of Contents

I.	BACKGROUND	1
II.	RESULTS.....	2
	Table 1. Risk Category and Correction Timelines.....	3
	Table 2. WMP Initiative Inspections.....	4
III.	DISCUSSION	6
IV.	CONCLUSION	7
V.	APPENDICES	A-1

Report Name: ATJ_SCE_20211207-01

Date(s): December 7, 2021

Inspector: Anthony Trujillo

Utility: Southern California Edison

Attention: Erik Takayesu, Vice President Assets Strategy and Planning

I. BACKGROUND

While wildfires are a natural part of California's ecosystem, the “fire season” in California and throughout the West is beginning and finishing earlier and later each year. Climate change and drought are believed to be a major contributor to this unsettling pattern. Utility-ignited wildfires are also a significant contributor to the wildfire risk in the Golden State, as this ignition cause category represents a disproportionate amount of the largest and most destructive fires in state history. Consequently, the Office of Energy Infrastructure Safety (Energy Safety) was established per the California Energy Infrastructure Safety Act (Government Code Sections 15470 – 15476) with the primary purpose of ensuring electrical corporations are reducing wildfire risk and complying with energy infrastructure safety measures. One such method for Energy Safety meeting its objective is to conduct detailed visual inspections of electrical infrastructure.

Inspections are carried out by Energy Safety's Compliance Division on a regular basis to verify the work performed by utilities, as reported in approved wildfire mitigation plans (WMPs) or subsequent filings and assess general conditions of electrical infrastructure that may adversely impact an electrical corporation's wildfire risk. Accordingly, Energy Safety inspections are distinguished into two lines of effort. Inspections related to an electrical corporation's execution of its WMP initiatives is referred to as “WMP Initiative Inspections,” findings of which are detailed in Table 2. Issues discovered during these inspections are categorized as violations and are accompanied by a notice of violation (NOV). In addition to assessing compliance with WMP initiatives, Energy Safety inspectors also visually assess the electrical infrastructure and surrounding vegetation to determine whether conditions are present which increase an electrical corporation's ignition and wildfire risk. These inspections are referred to as “General Wildfire Safety Inspections” and findings are detailed in Table 3 below. Issues discovered during these inspections are categorized as defects and are accompanied by a notice of defect (NOD).

This report details the findings of a recent Energy Safety inspection.

Section 15475.1. of the Government Code states that:

(a) The office may determine that a regulated entity is not in compliance with any matter under the authority of the office. If necessary, the office may undertake an investigation into whether the



regulated entity is noncompliant with its duties and responsibilities or has otherwise committed violations of any laws, regulations, or guidelines within the authority of the office.

(b) The office's primary objective is to ensure that regulated entities are reducing wildfire risk and complying with energy infrastructure safety measures as required by law.

On December 7, 2021, I performed a walking inspection of Southern California Edison (SCE) covered conductor installations, 2021 WMP initiative number 7.3.3.3.1, in the cities of Beaumont and Calimesa. I was accompanied by Energy Safety supervisor Edward Chavez. Detailed findings from this field inspection are laid out in Section II below.

II. RESULTS

In accordance with Energy Safety's Wildfire Mitigation Plan Compliance Process, violations and defects discovered by Energy Safety must be corrected in a timely manner. The timeline for corrective action is dependent on the risk category, location, and potential impact to worker safety of the violation or defect discovered. Risk categories range from severe to minor, and locational risks are determined with tier levels in the California Public Utility Commission's High Fire Threat District (HFTD) map. Table 1 below outlines violation and defect risk categories and their associated correction timelines. The correction timelines identified below apply to the results of both WMP initiative inspections as well as general wildfire safety inspections.



Table 1. Risk Category and Correction Timelines

Risk Category	Violation and defect correction timeline
Severe	<ul style="list-style-type: none">• Immediate resolution
Moderate	<ul style="list-style-type: none">• 2 months (in HFTD Tier 3)• 6 months (in HFTD Tier 2)• 6 months (if relevant to worker safety; not in HFTD Tier 3)
Minor	<ul style="list-style-type: none">• 12 months or resolution scheduled in WMP update

Table 2. WMP Initiative Inspections

Item	Structure ID	HFTD	Initiative Number	Violation Type	Severity	Violation Description
1	1289686E	Tier 2	7.3.3.3.1	Data Accuracy	Minor	Wrong pole ID provided. Provided pole ID is 1289686E. Actual pole ID is 4941451E
2	4467330E	Tier 2	7.3.3.3.1	Data Accuracy	Minor	Pole submitted to Energy Safety as covered conductor work completed. Covered conductor not installed at this pole. Covered conductor starts at next pole
3	4556899E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
4	4554799E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
5	4554798E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
6	4554796E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
7	4554794E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
8	4545339E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
9	4554790E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
10	4554788E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
11	4554787E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
12	4554787E	Tier 2	7.3.3.3.1	Completeness	Minor	Failure to remove guy anchor
13	4554785E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span

Item	Structure ID	HFTD	Initiative Number	Violation Type	Severity	Violation Description
14	1026956E	Non-HFTD	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
15	1407366E	Non-HFTD	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
16	1789149E	Tier 2	7.3.3.3.1	Data Accuracy	Minor	Wrong Pole ID reported. Provided pole ID is 1789149E. Actual pole ID is 4775181E
17	1789149E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
18	1789149E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Covered conductor covering is frayed
19	1789149E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Loose dead-end clamp
20	4475177E	Non-HFTD	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
21	4475177E	Non-HFTD	7.3.3.3.1	Data Accuracy	Minor	Wrong Pole ID reported. Provided pole ID is 4475177E. Actual pole ID is 4775177E

III. DISCUSSION

In its 2021-Q1 and 2021-Q2 quarterly data report (QDR) submission on May 1, 2021, and August 1, 2021, respectively, SCE provided initiative data indicating that covered conductor installation projects (WMP initiative number 7.3.3.3.1) in Calimesa and Beaumont were completed. This QDR submission represented the reporting periods of January through March (Q1) and April through June (Q2) of 2021. Based on this information received from SCE, Energy Safety planned an inspection of select structures in these areas to assess the accuracy of SCE data, the completeness of SCE's work, and whether SCE followed its protocols for covered conductor installation. Upon arriving to the inspection location, Energy Safety observed that covered conductor was not installed where SCE's QDR indicated covered conductor work had a status of "Complete." This structure is noted in Table 2 above.

Per SCE's Distribution Design Standards (DDS) and Distribution Overhead Construction (DOH), when installing covered conductor, vibration dampers must also be installed.¹ Energy Safety staff found that no vibration dampers were installed at multiple structures where covered conductor was installed. The structures missing vibration dampers where covered conductor was installed are identified in Table 2 above. On November 19, 2021, SCE submitted a memo to Energy Safety titled, "Interim Deviation from Standards on Vibration Damper for Covered Conductor"² (hereafter, "Memo"). This Memo was dated August 18, 2021, and indicates that due to supply chain issues, SCE will suspend the installation of vibration dampers until December 31, 2021. In accordance with SCE's Q2 QDR submission, the covered conductor installations inspected by Energy Safety were completed prior to the issuance of the Memo. Also, SCE informed Energy Safety of this supply chain issue only after inspections commenced. Consequently, Energy Safety finds that SCE is still in violation of its protocols requiring the installation of vibration dampers as part of covered conductor installations.

During inspections, Energy Safety found three structures where the structure ID provided by SCE did not match the structure ID observed in the field. Structures where Energy Safety observed this data accuracy issue are noted in Table 2 above.

Energy Safety discovered a dead-end clamp that was loosely attached to the covered conductor. Per SCE DOH, "Dead-ends shall be covered with a dead-end clamp in covered conductor systems. Covering dead-ends will ensure that stripped portions of the covered conductor at the dead-end will be protected from contact that could lead to phase-to-phase or phase-to-ground faults."³ The structure where this violation was observed is noted in Table 2 above.

¹ DOH CC section 190, DDS section DDS-10, page 10-82

² Interim Deviation from Standards on Vibration Damper for Covered Conductor, See Appendix B

³ SCE DOH CC 150.2

Energy Safety found a structure where the covering on a jumper cable was frayed. Per SCE's DOH, "When making connections, jumpers shall be covered conductor of equal or greater ampacity."⁴This may compromise the insulation's ability to prevent foreign objects from contacting the energized conductor. The structure where the frayed covering was observed is noted in Table 2 above.

Per SCE's protocols for Distribution Overhead Construction (DOH), PO 300 page 9 of 9, "When an anchor location is abandoned, the rod and plate shall be removed if in a hazardous or potentially dangerous location."⁵ Otherwise, cut the rods off at least 12 inches below the ground line and abandon the remaining anchor. Screw anchor rods may be either unscrewed or cut off. Under no conditions should the rod be bent over or left exposed. Structures where this protocol was not followed are noted in Table 2 above.

IV. CONCLUSION

Pursuant to its objectives and statutory obligations, Energy Safety has completed the above referenced inspection and discovered violations and/or defects by Southern California Edison. Southern California Edison's required response to these non-compliances and options for hearing are detailed in the associated notice of violation and/or defect, respectively.

⁴ SCE DOH CC 150.4.

⁵ SCE DOH PP 300, page 9 of 9.

V. APPENDICES

APPENDIX A: Photo Log

Structure ID: 1289686E

General Photo

	
<p>Item1Gimg1: Overall Pole</p>	<p>Item1Gimg2: Pole ID</p>

Structure ID: 1289687E

General Photo



Item2GImg1: Overall pole



Item2GImg2: Pole ID

Structure ID: 4467330E

General Photo



Item3GImg1: Overall pole



Item3GImg2: Pole ID

Initiative Activity #1 Photo



Item3IA1img1: Bare conductor when data indicates that there should be covered conductor

Structure ID: 4556899E

General Photo



Item4Gimg1: Overall pole



Item4Gimg2: Pole ID

Initiative Activity #1 Photo



Item4IA1img1: No vibration dampers

Structure ID: 4554799E

General Photo




Item5Gimg1: Overall pole



Item5Gimg2: Pole ID

Initiative Activity #1 Photo

	
<p>Item5IA1mg1: No vibration dampers</p>	

Structure ID: 4554798E

General Photo



Item6GImg1: Overall pole



Item6GImg2: Pole ID

Initiative Activity #1 Photo



Item6IA1Img1: No vibration dampers

Structure ID: 4554796E

General Photo



Item7GImg1: Overall pole



Item7GImg2: Pole ID

Initiative Activity #1 Photo



Item7IA1Img1: No vibration dampers

Structure ID: 4554794E

General Photo



Item8GImg1: Overall pole



Item8GImg2: Pole ID

Initiative Activity #1 Photo



Item8IA1img1: No vibration dampers

Structure ID: 4545339E

General Photo



Item9GImg1: Overall pole



Item9GImg2: Pole ID

Initiative Activity #1 Photo



Item9IA1Img1: No vibration dampers

Structure ID: 4554790E

General Photo



Item10GImg1: Overall pole



Item10GImg2: Pole ID

Initiative Activity #1 Photo



Item10IA1mg1: No vibration dampers

Structure ID: 4554788E

General Photo



Item11Gimg1: Overall pole



Item11Gimg2: Pole ID

Initiative Activity #1 Photo



Item11IA1mg1: No vibration dampers

Structure ID: 4554787E

General Photo



Item12GImg1: Overall pole



Item12GImg2: Pole ID

Initiative Activity #1 Photo



Item12IA1Img1: No vibration dampers

Initiative Activity #2 Photo



Item12IA3Img1: Abandoned guy anchor

Structure ID: 4554785E

General Photo



Item13G1mg1: Overall pole



Item13G1mg2: Pole ID

Initiative Activity #1 Photo



Item13IA1mg1: No vibration dampers

Structure ID: 1026956E

General Photo




Item14GImg1: Overall pole



Item14GImg2: Pole ID

Initiative Activity #1 Photo



Item14IA1mg1: No vibration dampers

Structure ID: 1407366E

General Photo



Item15GImg1: Overall pole



Item15GImg2: Pole ID

Initiative Activity #1 Photo



Item15IA1Img1: No vibration dampers

Structure ID: 1789149E

General Photo



Item16G1mg1: Overall pole




Item16G1mg2: Pole ID

Initiative Activity #2 Photo



Item16IA2img1: No vibration dampers

Initiative Activity #3 Photo



Item16IA3Img1: Covering falling off covered jumper cable

Initiative Activity #4 Photo



Item16IA4Img1: Loose dead-end clamp

Structure ID: 4475177E

General Photo



Item17G1mg1: Overall pole



Item17G1mg2: Pole ID

Initiative Activity #1 Photo



Item17IA1mg1: No vibration dampers

Interim Deviation from Standards on Vibration Damper for Covered Conductor



8/18/2021

Ref. No. HL-1921

Interim Deviation from Standards on Vibration Damper for Covered Conductor

*****This Bulletin Supersedes HL-0821*****

Purpose

This Hotline Bulletin provides SCE, Contract Construction, and Quality Control Personnel guidance on the requirement for installation of vibration dampers due to the temporary shortage of vibration dampers. This deviation allows installation of covered conductor without dampers.

This deviation only applies if the work location does not have the required dampers to complete the installation and will be in effect until December 31, 2021; dampers are still required to be installed for the work locations that have inventory on hand.

Background

Installing vibration dampers on the covered conductor mitigates Aeolian vibration by protecting the covered conductor from abrasion and fatigue damage. The vibration damper standard was put into effect in October 2020 and is required for all covered conductors in light loading areas (elevation below 3,000 feet). Recently, SCE has been experiencing an acute shortage of Stockbridge Dampers (refer to Figure 1) for 336 ACSR Covered Conductor due to the high demand and supplier constraints. Additionally, the spiral vibration dampers (refer to Figure 2) for 1/0 ACSR, #2 Copper, and 2/0 Copper may be running low on stock.



Figure 1: Stockbridge Damper



Figure 2: Spiral Damper

Discussion

Apart from supply shortages, a review of the orders placed for vibration dampers indicates inconsistent ordering practices at various store locations. For example, the analysis shows that some locations are ordering up to ten times more vibration dampers than needed based on the circuit miles of covered conductors to be installed. On the other hand, the analysis shows that some locations with high covered conductor orders are not ordering enough dampers. To ensure consistent delivery of vibration dampers, the following guidance is developed by Supply Chain and Asset & Engineering Strategy team, and it will be applied towards the field requests.¹

As more inventories become available, Supply Chain will distribute vibration dampers based on the guidance developed and the covered conductor assigned on-site at the designated location.

- 10214215 Spiral Dampers: 1 damper required per phase per span
 - 30 dampers should be allocated per 5,280 feet of covered conductor²

- 10214216 (Spiral), 10214493, 10214494, 10214495, 10214496, 10214497, 10214498, 10214499 Stockbridge Dampers: 2 dampers required per phase per span
 - 60 dampers allocated per 5,280 feet of covered conductor²

Action

Deviation from Distribution Overhead Construction Standards CC 190 when dampers are not available is acceptable for the duration of the damper shortage³, which is projected to last until December 31, 2021. SCE field crews and contractor personnel shall record any spans/locations on the Job Information Sheet (JIS) and [Damper Shortage Report](#), which can be filled out online or in the form attached at the end of this bulletin (refer to Appendix A). The Damper Shortage Report is intended to capture pertinent information where vibration dampers were not installed due to the shortage. The Shortage Reports shall be sent to Niousha Tavakoli biweekly for damper retrofit determination⁴. Then, they will be compiled and sent to the Quality Organization to ensure that no QC corrective actions are given on these work orders. Once the material shortage has been resolved, another bulletin will be published to revoke the deviation process.

¹ This is distinguished from the standard installation requirement, and it is only for inventory purposes.

² Damper allocation assumptions are based on a system average of 180 feet span and should be utilized as guidance, not a one size fits all.

³ The interim deviation from the standard only applies to construction, and planners need to plan the projects in accordance with the standard as required.

⁴ The go back will only target the high vibration susceptibility areas.

Standards Affected

DOH CC 190

Contact Information

If you have any questions related to this bulletin, please contact:

- Niousha Tavakoli: 949-910-8819
 - Niousha.Tavakoli@sce.com

