



**TRANSMITTED VIA ELECTRONIC MAIL**

March 23, 2022

Erik Takayesu

NOV\_SCE\_ATJ\_ 20211201-01

Vice President Asset Strategy and Planning

Southern California Edison

2244 Walnut Grove

Rosemead, CA 91770

## **NOTICE OF VIOLATION**

Dear Mr. Takayesu,

Pursuant to Government Code § 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has completed a compliance assessment of Southern California Edison (SCE) and determined the existence of one or more violations. In accordance with Government Code § 15475.2 and the California Code of Regulations, Title 14, Division 17 § 29302(b)(2), noncompliance with an approved wildfire mitigation plan (WMP) or any law, regulation, or guideline within Energy Safety’s authority is considered a violation.

Anthony Trujillo, Energy Safety staff, conducted a walking inspection in Los Angeles County on December 1, 2021, and discovered the following violation(s):

1. Violation 1: Per SCE’s Distribution Design Standards (DDS), section DDS-10, page 10-82, “for the 336 (30/7) ACSR covered conductor, vibration dampers shall be installed on every span in both light loading and heavy loading areas.” Also, SCE’s Distribution Overhead Construction Standards (DOH), section CC 190, page 1 of 11, indicates that vibration dampers are required when installing covered conductor. Poles numbered 1121374E, 1219492E, 1219493E, 2093435E, 4622656E, 1309679E, 2058723E, 4191310E, 447040E, 2139296E, 4278547E, 4278546E, 4278545E, 676783E, 4373743E, 4373744E, and 4373745E had covered conductor installed but failed to install vibration dampers. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category.
2. Violation 2: Per SCE’s DOH, section CC 180, sheet 1 of 1, when transitioning from covered conductor to bare wire, “if conductor is exposed, install bolted wedge connector



March 21, 2022

NOV\_SCE\_ATJ\_ 20211201-01

cover.” Per SCE’s DDS, Section 10, 5.7.C.1.f, “Covered conductor systems shall be an all-covered system. This means that wildlife covers shall be installed on dead-ends, terminations, connectors, equipment bushings, and any partially covered exposed conductor.” Poles numbered 4147040E and 4487750E did not have bolted wedge connector covers installed when transitioning from bare to covered conductor or at a double dead end. Energy Safety considers this a violation for failure of adhering to protocol and in the Minor risk category.

3. Violation 3: Per SCE’s DOH, when transitioning from covered conductor to bare wire, “if conductor is exposed, install bolted wedge connector cover.” Per SCE’s DDS, Section 10, 5.7.C.1.f, “Covered conductor systems shall be an all-covered system. This means that wildlife covers shall be installed on dead-ends, terminations, connectors, equipment bushings, and any partially covered exposed conductor.” Pole number 676783E had a bolted wedge connector cover that was loosely attached to a conductor. Energy Safety considers this a violation for failure of adhering to protocol and in the Minor risk category.

In accordance with the Energy Safety Compliance Process, outlined in Table 1 below are the correction timelines for identified violations relative to their risk category. Within 30 days from the issuance date of this notice of violation (NOV), April 22, 2021, advise Energy Safety of corrective actions taken or planned by SCE to remedy the above identified violation(s) and prevent recurrence. This response shall be filed in the Energy Safety e-Filing system under the [2021-NOV docket](#)<sup>1</sup> and the associated file name(s) must begin with the NOV identification number provided above.

*Table 1 Energy Safety Violation Correction Timeline by Risk Category*

<b>Risk Category</b>	<b>Violation and defect correction timeline</b>
Severe	<ul style="list-style-type: none"> <li>• Immediate resolution</li> </ul>
Moderate	<ul style="list-style-type: none"> <li>• 2 months (in HFTD Tier 3)</li> <li>• 6 months (in HFTD Tier 2)</li> <li>• 6 months (if relevant to worker safety; not in HFTD Tier 3)</li> </ul>
Minor	<ul style="list-style-type: none"> <li>• 12 months or resolution scheduled in WMP update</li> </ul>

Pursuant to Government Code § 15475.4(b), this NOV is served electronically, and SCE may request a hearing to take public comment or present additional information. Per statute, the deadline to request a hearing is within 30 days from the issuance date of this NOV – April 22,

<sup>1</sup> <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2021-NOV>



March 21, 2022

NOV\_SCE\_ATJ\_20211201-01

2021. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Pursuant to Public Utilities Code § 8389(g), following receipt of SCE's response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission (CPUC) for its consideration of potential enforcement action, as the CPUC deems appropriate.

Sincerely,

A handwritten signature in black ink, appearing to read "Koko Tomassian".

Koko Tomassian  
Compliance Program Manager  
Compliance Assurance Division  
Office of Energy Infrastructure Safety

Cc:

Gary Chen, SCE  
Elizabeth Leano, SCE  
Diana Gallegos, SCE  
Johnny Parker, SCE  
Jonathan Chacon, SCE  
Melissa Semcer, Energy Safety  
Edward Chavez, Energy Safety  
Anthony Trujillo, Energy Safety

# Energy Safety Inspection Report



OFFICE OF ENERGY  
INFRASTRUCTURE  
SAFETY

# Table of Contents

I.	BACKGROUND .....	2
II.	RESULTS.....	3
	<b>Table 1.</b> Risk Category and Correction Timelines .....	3
	<b>Table 2.</b> WMP Initiative Inspections.....	4
III.	DISCUSSION .....	6
IV.	CONCLUSION.....	7
V.	APPENDICES.....	A-1

Report Name: ATJ\_SCE\_20211201-01

Date(s): December 1, 2021

Inspector: Anthony Trujillo

Utility: Southern California Edison

Attention: Erik Takayesu, Vice President Asset Strategy and Planning

## I. BACKGROUND

While wildfires are a natural part of California's ecosystem, the “fire season” in California and throughout the West is beginning and finishing earlier and later each year. Climate change and drought are believed to be a major contributor to this unsettling pattern. Utility-ignited wildfires are also a significant contributor to the wildfire risk in the Golden State, as this ignition cause category represents a disproportionate amount of the largest and most destructive fires in state history. Consequently, the Office of Energy Infrastructure Safety (Energy Safety) was established per the California Energy Infrastructure Safety Act (Government Code Sections 15470 – 15476) with the primary purpose of ensuring electrical corporations are reducing wildfire risk and complying with energy infrastructure safety measures. One such method for Energy Safety meeting its objective is to conduct detailed visual inspections of electrical infrastructure.

Inspections are carried out by Energy Safety's Compliance Division on a regular basis to verify the work performed by utilities, as reported in approved wildfire mitigation plans (WMPs) or subsequent filings and assess general conditions of electrical infrastructure that may adversely impact an electrical corporation's wildfire risk. Accordingly, Energy Safety inspections are distinguished into two lines of effort. Inspections related to an electrical corporation's execution of its WMP initiatives is referred to as “WMP Initiative Inspections,” findings of which are detailed in Table 2. Issues discovered during these inspections are categorized as violations and are accompanied by a notice of violation (NOV). In addition to assessing compliance with WMP initiatives, Energy Safety inspectors also visually assess the electrical infrastructure and surrounding vegetation to determine whether conditions are present which increase an electrical corporation's ignition and wildfire risk. These inspections are referred to as “General Wildfire Safety Inspections” and findings are detailed in Table 3 below. Issues discovered during these inspections are categorized as defects and are accompanied by a notice of defect (NOD).

This report details the findings of a recent Energy Safety inspection.

### ***Section 15475.1. of the Government Code states that:***

*(a) The office may determine that a regulated entity is not in compliance with any matter under the authority of the office. If necessary, the office may undertake an investigation into whether the*



*regulated entity is noncompliant with its duties and responsibilities or has otherwise committed violations of any laws, regulations, or guidelines within the authority of the office.*

*(b) The office’s primary objective is to ensure that regulated entities are reducing wildfire risk and complying with energy infrastructure safety measures as required by law.*

On December 1, 2021, I performed a walking inspection of Southern California Edison (SCE) covered conductor installations, 2021 WMP initiative number 7.3.3.3.1, in the cities of Acton and Lincoln Crest, California. Detailed findings from this field inspection are laid out in Section II below.

## II. RESULTS

In accordance with Energy Safety’s Wildfire Mitigation Plan Compliance Process, violations and defects discovered by Energy Safety must be corrected in a timely manner. The timeline for corrective action is dependent on the risk category, location, and potential impact to worker safety of the violation or defect discovered. Risk categories range from severe to minor, and locational risks are determined with tier levels in the California Public Utility Commission’s High Fire Threat District (HFTD) map. Table 1 below outlines violation and defect risk categories and their associated correction timelines. The correction timelines identified below apply to the results of both WMP initiative inspections as well as general wildfire safety inspections.

**Table 1. Risk Category and Correction Timelines**

<b>Risk Category</b>	<b>Violation and defect correction timeline</b>
Severe	<ul style="list-style-type: none"> <li>• Immediate resolution</li> </ul>
Moderate	<ul style="list-style-type: none"> <li>• 2 months (in HFTD Tier 3)</li> <li>• 6 months (in HFTD Tier 2)</li> <li>• 6 months (if relevant to worker safety; not in HFTD Tier 3)</li> </ul>
Minor	<ul style="list-style-type: none"> <li>• 12 months or resolution scheduled in WMP update</li> </ul>

**Table 2. WMP Initiative Inspections**

Item	Structure ID	HFTD	Initiative Number	Violation Type	Severity	Violation Description
1	1121374E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
2	1219492E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
3	1219493E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
4	2093435E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
5	4622656E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
6	1309679E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
7	2058723E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
8	4191310E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
9	4147040E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
10	4147040E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install bolted wedge connector cover
11	2139296E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
12	4278547E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
13	4278546E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
14	4278545E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span



Item	Structure ID	HFTD	Initiative Number	Violation Type	Severity	Violation Description
15	4487750E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install bolted wedge connector cover
16	676783E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
17	676783E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Loose bolted wedge cover connector
18	4373743E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
19	4373744E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span
20	4373745E	Tier 3	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install vibration dampers on a span

### III. DISCUSSION

In its 2021-Q1 and 2021-Q2 quarterly data report (QDR) submission on May 1, 2021, and August 1, 2021, respectively, SCE provided initiative data indicating that covered conductor installation projects (2021 WMP initiative number 7.3.3.3.1) in Acton and Lincoln Crest were completed. These QDR submissions represented the reporting periods of January through March (Q1) and April through June (Q2) of 2021. Based on this information received from SCE, Energy Safety planned an inspection of select structures in these areas to assess the accuracy of SCE data, the completeness of SCE's work, and whether SCE followed its protocols for covered conductor installation.

Per SCE's Distribution Design Standards (DDS) and Distribution Overhead Construction Standards (DOH), when installing covered conductor, vibration dampers must also be installed.<sup>1</sup> Energy Safety staff found that vibration dampers were not installed at multiple structures where covered conductor installation was completed. The structures missing vibration dampers where covered conductor was installed are identified in Table 2 above. On November 19, 2021, SCE submitted a memo to Energy Safety titled, "Interim Deviation from Standards on Vibration Damper for Covered Conductor" (hereafter, "Memo"). This Memo was dated August 18, 2021, and indicates that due to supply chain issues, SCE will suspend the installation of vibration dampers until December 31, 2021. In accordance with SCE's Q2 QDR submission, the covered conductor installations inspected by Energy Safety were completed prior to the issuance of the Memo. Also, SCE informed Energy Safety of this supply chain issue only after inspections commenced. Consequently, Energy Safety finds that SCE is still in violation of its protocols requiring the installation of vibration dampers as part of covered conductor installations.

Per SCE's DOH, Section CC 150, page 3 of 5, in circumstances of 4-wire covered conductor double dead-end construction, if conductor is exposed, bolted wedge connector covers must be installed. Also, DDS, Section 10, 5.7.C.1.f. states, "Covered conductor systems shall be an all-covered system." Per SCE's DOH, Section CC 150.4, page 5 of 5, "All overhead equipment shall utilize appropriate wildlife covers. This means that wildlife covers shall be installed on dead-ends, terminations, connectors, equipment bushings, and any partially covered exposed conductor." Energy Safety observed structure numbered 4487750E that did not have bolted wedge connector cover installed when transitioning from bare to covered conductor. Similarly, structure numbered 4147040E did not have bolted wedge connector cover installed at a double dead end transition point. Energy Safety also observed that structure numbered 676783E had a loose bolted wedge connector cover. These structures are noted in Table 2 above.

---

<sup>1</sup> DOH CC section 190, DDS section DDS-10, page 10-82

## **IV. CONCLUSION**

Pursuant to its objectives and statutory obligations, Energy Safety has completed the above referenced inspection and discovered violations and/or defects by Southern California Edison. Southern California Edison's required response to these non-compliances and options for hearing are detailed in the associated notice of violation and/or defect, respectively.

# V. APPENDICES

## APPENDIX A: Photo Log

**Structure ID:** 1121374E

General Photo

	
<p><b>Item1GImg1:</b> Overall pole</p>	<p><b>Item1GImg2:</b> Pole ID</p>

**Structure ID: 1219492E**

General Photo



**Item2GImg1:** Overall pole



**Item2GImg2:** Pole ID



Initiative Activity #1 Photo




**Item2IA1Img1:** No vibration dampers

Structure ID: 1219493E

General Photo

 A photograph of a tall wooden utility pole standing in an open field with a fence and trees in the background under a clear blue sky.	 A close-up photograph of the wooden pole showing a yellow identification tag with the number '1219493E' attached to it.
<p><b>Item3GImg1:</b> Overall pole</p>	<p><b>Item3GImg2:</b> Pole ID</p>

Initiative Activity #1 Photo

 A photograph showing the top of the utility pole with cross-arms and power lines against a clear blue sky. No vibration dampers are visible on the cross-arms.
<p><b>Item3IA1Img1:</b> No vibration dampers</p>

**Structure ID:** 2093435E

General Photo



**Item4GImg1:** Overall pole

Initiative Activity #1 Photo



**Item4IA1img1:** Vibration dampers not installed

**Structure ID:** 4622656E

General Photo



**Item5GIimg1:** Overall pole

Initiative Activity #1 Photo



**Item5IA1img1:** No vibration dampers



**Structure ID: 1309679E**

**General Photo**



**Item6GImg1: Overall pole**



**Item6GImg2: Pole ID**

**Initiative Activity #1 Photo**



**Item6IA1Img1: No vibration dampers**

**Structure ID: 2058723E**

General Photo



**Item7GImg1:** Overall pole

Initiative Activity #1 Photo



**Item7IA1Img1:** No vibration dampers

**Structure ID: 4191310E**

**General Photo**



**Item8GImg1:** Overall pole



**Item8GImg2:** Pole ID (confirmed with binoculars)

**Initiative Activity #1 Photo**



**Item8IA1Img1:** No vibration dampers

Structure ID: 4147040E

General Photo



Item9GImg1: Overall pole



Item9GImg2: Pole ID

Initiative Activity #1 Photo



Item9IA1Img1: No vibration dampers

Initiative Activity #2 Photo



**Item9IA2img1:** No bolted wedge connector cover at double dead end

**Structure ID: 2139296E**

General Photo



**Item10GImg1: Overall pole**



**Item10GImg2: Pole ID**



Initiative Activity #1 Photo



**Item10IA1img1: No vibration dampers**

Structure ID: 4278547E

General Photo


	
<p><b>Item11GImg1:</b> Overall pole</p>	<p><b>Item11GImg2:</b> Pole ID</p>

Initiative Activity #1 Photo


<p><b>Item11IA1img1:</b> No vibration dampers</p>

Structure ID: 4278546E

General Photo




Item12GImg1: Overall pole



Item12GImg2: Pole ID

Initiative Activity #1 Photo



Item12IA1img1: No vibration dampers



Structure ID: 4278545E

General Photo



Item13GImg1: Overall pole



Item13GImg2: Pole ID

Initiative Activity #1 Photo



Item13IA1Img1: No vibration dampers

**Structure ID: 4487750E**

General Photo



**Item15GImg1:** Overall pole



**Item15GImg2:** Pole ID

Initiative Activity #2 Photo



**Item15IA2Img2:** Bare to dead end with no bolted wedge connector covers

**Structure ID: 676783E**

**General Photo**



**Item16GImg1: Overall pole**



**Item16GImg2: Pole ID**

**Initiative Activity #1 Photo**




**Item16IA1Img1: No vibration dampers**

Initiative Activity #2 Photo



**Item16IA2Img1:** Loose center phase bolted wedge connector



**Item16IA2Img2:** Overall loose center phase bolted wedge connector

**Structure ID: 4373743E**

**General Photo**



**Item17GImg1: Overall pole**



**Item17GImg2: Pole ID**


**Initiative Activity #1 Photo**



**Item17IA1img1: No vibration dampers**


Structure ID: 4373744E

General Photo



Item18GImg1: Overall pole



Initiative Activity #1 Photo



Item18IA1img1: No vibration dampers

Structure ID: 4373745E

General Photo

	
<p>Item19GImg1: Overall pole</p>	<p>Item19GImg2: Pole ID</p>

Initiative Activity #1 Photo


<p>Item19IA1Img1: No vibration dampers</p>

[Interim Deviation from Standards on Vibration Damper for Covered Conductor](#)



8/18/2021

Ref. No. HL-1921

---

**Interim Deviation from Standards on Vibration Damper for Covered Conductor**

**\*\*\*This Bulletin Supersedes HL-0821\*\*\***

**Purpose**

This Hotline Bulletin provides SCE, Contract Construction, and Quality Control Personnel guidance on the requirement for installation of vibration dampers due to the temporary shortage of vibration dampers. This deviation allows installation of covered conductor without dampers.

This deviation only applies if the work location does not have the required dampers to complete the installation and will be in effect until December 31, 2021; dampers are still required to be installed for the work locations that have inventory on hand.

**Background**

Installing vibration dampers on the covered conductor mitigates Aeolian vibration by protecting the covered conductor from abrasion and fatigue damage. The vibration damper standard was put into effect in October 2020 and is required for all covered conductors in light loading areas (elevation below 3,000 feet). Recently, SCE has been experiencing an acute shortage of Stockbridge Dampers (refer to Figure 1) for 336 ACSR Covered Conductor due to the high demand and supplier constraints. Additionally, the spiral vibration dampers (refer to Figure 2) for 1/0 ACSR, #2 Copper, and 2/0 Copper may be running low on stock.



Figure 1: Stockbridge Damper



Figure 2: Spiral Damper



**Discussion**

Apart from supply shortages, a review of the orders placed for vibration dampers indicates inconsistent ordering practices at various store locations. For example, the analysis shows that some locations are ordering up to ten times more vibration dampers than needed based on the circuit miles of covered conductors to be installed. On the other hand, the analysis shows that some locations with high covered conductor orders are not ordering enough dampers. To ensure consistent delivery of vibration dampers, the following guidance is developed by Supply Chain and Asset & Engineering Strategy team, and it will be applied towards the field requests.<sup>1</sup>

As more inventories become available, Supply Chain will distribute vibration dampers based on the guidance developed and the covered conductor assigned on-site at the designated location.

- 10214215 Spiral Dampers: 1 damper required per phase per span
  - 30 dampers should be allocated per 5,280 feet of covered conductor<sup>2</sup>
  
- 10214216 (Spiral), 10214493, 10214494, 10214495, 10214496, 10214497, 10214498, 10214499 Stockbridge Dampers: 2 dampers required per phase per span
  - 60 dampers allocated per 5,280 feet of covered conductor<sup>2</sup>

**Action**

Deviation from Distribution Overhead Construction Standards CC 190 when dampers are not available is acceptable for the duration of the damper shortage<sup>3</sup>, which is projected to last until December 31, 2021. SCE field crews and contractor personnel shall record any spans/locations on the Job Information Sheet (JIS) and [Damper Shortage Report](#), which can be filled out online or in the form attached at the end of this bulletin (refer to Appendix A). The Damper Shortage Report is intended to capture pertinent information where vibration dampers were not installed due to the shortage. The Shortage Reports shall be sent to Niousha Tavakoli biweekly for damper retrofit determination<sup>4</sup>. Then, they will be compiled and sent to the Quality Organization to ensure that no QC corrective actions are given on these work orders. Once the material shortage has been resolved, another bulletin will be published to revoke the deviation process.

---

<sup>1</sup> This is distinguished from the standard installation requirement, and it is only for inventory purposes.

<sup>2</sup> Damper allocation assumptions are based on a system average of 180 feet span and should be utilized as guidance, not a one size fits all.

<sup>3</sup> The interim deviation from the standard only applies to construction, and planners need to plan the projects in accordance with the standard as required.

<sup>4</sup> The go back will only target the high vibration susceptibility areas.

**Standards Affected**

DOH CC 190

**Contact Information**

If you have any questions related to this bulletin, please contact:

- Niousha Tavakoli: 949-910-8819
  - [Niousha.Tavakoli@sce.com](mailto:Niousha.Tavakoli@sce.com)

