



**TRANSMITTED VIA ELECTRONIC MAIL**

July 22, 2022

Erik Takayesu  
Vice President Asset Strategy and Planning  
Southern California Edison  
2244 Walnut Grove  
Rosemead, CA 91770

NOV\_SCE ATJ\_20220420-01

## **NOTICE OF VIOLATION**

Mr. Takayesu,

Pursuant to Government Code § 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has completed a compliance assessment of Southern California Edison (SCE) and determined the existence of one or more violations. In accordance with Government Code § 15475.2 and the California Code of Regulations, Title 14, Division 17 § 29302(b)(2), noncompliance with an approved wildfire mitigation plan (WMP) or any law, regulation, or guideline within Energy Safety’s authority is considered a violation.

Anthony Trujillo, Energy Safety staff, conducted a walking inspection in and around the city of Oak Hills, California, on April 20, 2022, and discovered the following violation(s):

1. Violation 1: Per SCE’s Distribution Overhead Construction Standards (DOH), Section CC 150.4, All overhead equipment shall utilize appropriate wildlife covers.” Pole number 4346696E had a fuse cover that fell off and was found approximately 50 feet from the pole. Energy Safety considers this a violation for failure of adhering to protocol and in the Minor risk category.
2. Violation 2: Per SCE’s DOH, Table DC 535-1: Wildlife Protection Material, SCE requires that anti-rotation clips be used with Dead-End Clamp Covers.<sup>1</sup> Pole numbered 4071366E did not have an anti-rotational clip installed in a dead-end cover. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category.
3. Violation 3: Per SCE’s DOH, Section CO 100, page 3 of 4, “When dead-ending, the tail of the conductor shall be oriented in the direction that the conductor is intended to be routed. Efforts should be made to ensure that the tail and/or connector does not make contact with the dead-end rails/legs.” Poles numbered 4071366E and 4135843E had

---

<sup>1</sup> SCE DOH, Table DC 535-01, SAP 10214048



July 22, 2022

NOV\_ SCE ATJ\_20220420-01

jumpers not connected in the direction that the conductor was routed. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category.

In accordance with the Energy Safety Compliance Process, outlined in Table 1 below are the correction timelines for identified violations relative to their risk category. Within 30 days from the issuance date of this notice of violation (NOV), August 22, 2022, advise Energy Safety of corrective actions taken or planned by SCE to remedy the above identified violation(s) and prevent recurrence. This response shall be filed in the Energy Safety e-Filing system under the [2022-NOV docket](#)<sup>2</sup> and the associated file name(s) must begin with the NOV identification number provided above.

*Table 1 Energy Safety Violation Correction Timeline by Risk Category*

<b>Risk Category</b>	<b>Violation and defect correction timeline</b>
Severe	<ul style="list-style-type: none"> <li>• Immediate resolution</li> </ul>
Moderate	<ul style="list-style-type: none"> <li>• 2 months (in HFTD Tier 3)</li> <li>• 6 months (in HFTD Tier 2)</li> <li>• 6 months (if relevant to worker safety; not in HFTD Tier 3)</li> </ul>
Minor	<ul style="list-style-type: none"> <li>• 12 months or resolution scheduled in WMP update</li> </ul>

Pursuant to Government Code § 15475.4(b), this NOV is served electronically, and SCE may request a hearing to take public comment or present additional information. Per statute, the deadline to request a hearing is within 30 days from the issuance date of this NOV – August 22, 2022. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Pursuant to Public Utilities Code § 8389(g), following receipt of SCE’s response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission (CPUC) for its consideration of potential enforcement action, as the CPUC deems appropriate.

Sincerely,

<sup>2</sup> <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2021-NOV>



July 22, 2022

NOV\_ SCE ATJ\_20220420-01

Koko Tomassian  
Compliance Program Manager  
Compliance Assurance Division  
Office of Energy Infrastructure Safety

Cc:  
Gary Chen, SCE  
Elizabeth Leano, SCE  
Diana Gallegos, SCE  
Johnny Parker, SCE  
Jonathan Chacon, SCE  
Melissa Semcer, Energy Safety  
Edward Chavez, Energy Safety  
Anthony Trujillo, Energy Safety

# Energy Safety Inspection Report



OFFICE OF ENERGY  
INFRASTRUCTURE  
SAFETY



## Table of Contents

I.	BACKGROUND .....	1
II.	RESULTS.....	2
	<b>Table 1.</b> Risk Category and Correction Timelines .....	3
	<b>Table 2.</b> WMP Initiative Inspections .....	4
III.	DISCUSSION .....	5
IV.	CONCLUSION .....	6
V.	APPENDICES .....	A-1





Report Name: SCE\_ATJ\_ 20220420-01  
Date(s): April 20, 2022  
Inspector: Anthony Trujillo  
Utility: Southern California Edison  
Attention: Erik Takayesu, Vice President Asset Strategy and Planning

## I. BACKGROUND

While wildfires are a natural part of California’s ecosystem, the “fire season” in California and throughout the West is beginning and finishing earlier and later each year. Climate change and drought are believed to be a major contributor to this unsettling pattern. Utility-ignited wildfires are also a significant contributor to the wildfire risk in the Golden State, as this ignition cause category represents a disproportionate amount of the largest and most destructive fires in state history. Consequently, the Office of Energy Infrastructure Safety (Energy Safety) was established per the California Energy Infrastructure Safety Act (Government Code Sections 15470 – 15476) with the primary purpose of ensuring electrical corporations are reducing wildfire risk and complying with energy infrastructure safety measures. One such method for Energy Safety meeting its objective is to conduct detailed visual inspections of electrical infrastructure.

Inspections are carried out by Energy Safety’s Compliance Division on a regular basis to verify the work performed by utilities, as reported in approved wildfire mitigation plans (WMPs) or subsequent filings and assess general conditions of electrical infrastructure that may adversely impact an electrical corporation’s wildfire risk. Accordingly, Energy Safety inspections are distinguished into two lines of effort. Inspections related to an electrical corporation’s execution of its WMP initiatives is referred to as “WMP Initiative Inspections,” findings of which are detailed in Table 2. Issues discovered during these inspections are categorized as violations and are accompanied by a notice of violation (NOV). In addition to assessing compliance with WMP initiatives, Energy Safety inspectors also visually assess the electrical infrastructure and surrounding vegetation to determine whether conditions are present which increase an electrical corporation’s ignition and wildfire risk. These



inspections are referred to as “General Wildfire Safety Inspections.” Issues discovered during these inspections are categorized as defects and are accompanied by a notice of defect (NOD).

This report details the findings of a recent Energy Safety inspection.

***Section 15475.1. of the Government Code states that:***

*(a) The office may determine that a regulated entity is not in compliance with any matter under the authority of the office. If necessary, the office may undertake an investigation into whether the regulated entity is noncompliant with its duties and responsibilities or has otherwise committed violations of any laws, regulations, or guidelines within the authority of the office.*

*(b) The office’s primary objective is to ensure that regulated entities are reducing wildfire risk and complying with energy infrastructure safety measures as required by law.*

On April 20, 2022, I performed a walking inspection of Southern California Edison (SCE) covered conductor installations, 2021 WMP initiative number 7.3.3.3.1, in and around the city of Oak Hills, California. Detailed findings from this field inspection are laid out in Section II below.

## **II. RESULTS**

In accordance with Energy Safety’s Wildfire Mitigation Plan Compliance Process, violations and defects discovered by Energy Safety must be corrected in a timely manner. The timeline for corrective action is dependent on the risk category, location, and potential impact to worker safety of the violation or defect discovered. Risk categories range from severe to minor, and locational risks are determined with tier levels in the California Public Utility Commission’s High Fire Threat District (HFTD) map. Table 1 below outlines violation and defect risk categories and their associated correction timelines. The correction timelines identified below apply to the results of both WMP initiative inspections as well as general wildfire safety inspections.



**Table 1. Risk Category and Correction Timelines**

<b>Risk Category</b>	<b>Violation and defect correction timeline</b>
Severe	<ul style="list-style-type: none"><li>• Immediate resolution</li></ul>
Moderate	<ul style="list-style-type: none"><li>• 2 months (in HFTD Tier 3)</li><li>• 6 months (in HFTD Tier 2)</li><li>• 6 months (if relevant to worker safety and not in HFTD Tiers 2 or 3)</li></ul>
Minor	<ul style="list-style-type: none"><li>• 12 months or resolution scheduled in WMP update</li></ul>





**Table 2. WMP Initiative Inspections**

Item	Structure ID	HFTD	Initiative Number	Violation Type	Severity	Violation Description
1	4346696E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Fuse cover fell off
2	4071366E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to install anti-rotational clip on a dead-end cover
3	4071366E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to connect jumper tail to tail
4	4135843E	Tier 2	7.3.3.3.1	Adherence to Protocol	Minor	Failure to connect jumper in direction conductor is intended to be routed (connected side by side, not tail to tail)



## III. DISCUSSION

In its 2021, Q1-Q4 quarterly data reports (QDR) submissions, SCE provided initiative data indicating that a covered conductor installation project (WMP initiative number 7.3.3.3.1) in and near the city of Oak Hills, California was completed. This QDR submission represented the reporting periods of January through December (i.e., Q1-Q4) of 2021. Based on this information received from SCE, Energy Safety planned an inspection of select structures in this area to assess the accuracy of SCE data, the completeness of SCE's work, and whether SCE followed its protocols for covered conductor installation.

Per SCE's DOH, Section CC 150.4, page 5 of 5, "All overhead equipment shall utilize appropriate wildlife covers." Also, DDS, Section 10, 5.7.C.1.f., "Covered conductor systems shall be an all-covered system. This means that wildlife covers shall be installed on dead-ends, terminations, connectors, equipment bushings, and any partially covered exposed conductor." Energy Safety staff found one instance where a wildlife fuse cover was missing and found about 50 feet from the structure. The structure where this violation was observed is noted in Table 2 above.

Per SCE's DOH, Table DC 535-1: Wildlife Protection Material, SCE requires that anti-rotation clips be used with Dead-End Clamp Covers.<sup>1</sup> Energy Safety discovered a dead-end cover that was missing an anti-rotational device. The structure where this violation was observed is noted in Table 2 above.

Per SCE's DOH, Section CO 100, page 3 of 4, "When dead-ending, the tail of the conductor shall be oriented in the direction that the conductor is intended to be routed. Efforts should be made to ensure that the tail and/or connector does not make contact with the dead-end rails/legs." Energy Safety discovered two instances where dead-end jumpers (i.e., conductor) were not oriented in the direction that the conductor was routed. The structures where this violation was observed is noted in Table 2 above.

---

<sup>1</sup> SCE DOH, Table DC 535-01, SAP 10214048

## **IV. CONCLUSION**

Pursuant to its objectives and statutory obligations, Energy Safety has completed the above referenced inspection and discovered violations and/or defects by Southern California Edison. Southern California Edison's required response to these non-compliances and options for hearing are detailed in the associated notice of violation and/or defect, respectively.

# V. APPENDICES

## APPENDIX A: Photo Log

Structure ID: 4346696E

General Photo



Item4Gimg1: Overall pole




Item4Gimg2: Pole ID



Initiative Activity #1 Photo



**Item4IA1Img1:** Missing fuse cover



**Item4IA1Img2:** Missing fuse cover



**Item4IA1Img3:** Fuse cover found on floor



**Item4IA1Img4:** Fuse cover location relative to pole

Structure ID: 4071366E

General Photo




Item7Gimg1: Overall pole




Item7Gimg2: Pole ID



Initiative Activity #2 Photo



**Item71A2Img2:** No anti rotation clip installed, jumped underneath cover



**Item71A2Img3:** Northwest dead-end cover with no anti-rotational clip installed



**Item71A2Img4:** Other, Northwest dead-end cover with anti-rotational clip installed



Jumper is not oriented in the direction that the conductor is intended to be routed

Structure ID: 4135843E

General Photo



Item8GImg1: Overall pole



Item8GImg2: Pole ID

Initiative Activity #1 Photo



Item8IA1Img1: Jumper is not oriented in the direction that the conductor is intended to be routed