

June 9, 2025

Patrick Doherty, Compliance Program Manager
Compliance Assurance Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Violation
- NOV_CAD_SCE_CAC12_20250203_1607

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Violation – NOV_CAD_SCE_CAC12_20250203_1607 received on May 13, 2025 (Notice), based on Energy Safety field inspections conducted in SCE's service area on January 31, 2025. SCE appreciates the Office of Energy Infrastructure Safety's (Energy Safety) efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the above notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//

Shinjini C Menon
Senior Vice President of System Planning & Engineering
Southern California Edison

SCE Response

While SCE is not requesting a written hearing for the finding addressed in this response, SCE reserves the right to identify these facts and further explain its position in subsequent procedural stages and/or proceedings.¹ Although Energy Safety has the right to refer certain issues to the CPUC for an enforcement action, the finding in this Notice does not support such referral.²

Finding: Completeness

Notice	Violation	Structures
NOV_CAD_SCE_CAC12_20250203_1607	1	1898072E

Summary of Findings:

Energy Safety’s Notice states that in implementing 2024 WMP initiative 8.1.3.1 - Distribution Detailed Inspections Remediations (IN-1.1), SCE failed to complete remediation of the loose transformer hanger bolt on Pole ID 1898072E, Grid Hardening ID 414080465-1898072E, at coordinates 35.142054, -118.512856.

Energy Safety considers this data accuracy violation “to be in the Minor risk category.”³

Response:

SCE acknowledges the findings from Energy Safety's inspection on January 31, 2025, which identified a loose transformer bolt on structure 1898072E. Although SAP, SCE's system of record, indicates that notification #414080465 was completed on September 27, 2024, an inspection by SCE's Field Operations team conducted on June 2, 2025 in

¹ Government Code Section 15475.4 anticipates a “hearing” process, which traditionally implies an in-person hearing affording parties the right to present evidence and examine witnesses.

² In the Notice, Energy Safety states that pursuant to Public Utilities Code section 8389(g), following receipt of SCE's response to this Notice and resolution of any disputes, this matter may be referred to the California Public Utilities Commission (CPUC) for its consideration of a potential enforcement action, as the CPUC deems appropriate. Notice, p. 2. The Notice discussed herein does not meet the requirement for Energy Safety referral for enforcement action to the CPUC based on the statutory requirements that Energy Safety referral be based on substantial compliance with WMPs. Energy Safety cites Public Utilities Code Section 8389(g) in support of a potential enforcement action. However, Section 8389(g) only provides for a possible enforcement action where “an electrical corporation is not in compliance with its approved wildfire mitigation plan.” Public Utilities Code Section 8386.1 further specifies that penalties shall be assessed for failure to substantially comply with a WMP.

³ Notice, p. 1.

response to this Notice found that there was a loose transformer bolt. Loose bolts can be a result of fluctuations in the weather or pole vibrations.

On June 4, 2025, SCE personnel tightened the loose bolt on structure 1898072E to ensure the transformer bracket is now flush with the pole. Please find the photo evidence below of the secured transformer.

Jun 05, 2025 07:33 AM

Network: Jun 4, 2025 at 1:05:26 PM PDT

Local: Jun 4, 2025 at 1:05:26 PM PDT

N 35° 8' 31.247", W 118° 30' 46.234"

21508 Country Club Dr

Tehachapi CA 93561

United States

Remark: 1898072e



35.142141,-118.5126656 1898072e