SOUTHERN CALIFORNIA EDISON®
An EDISON INTERNATIONAL® Company

Brandon Tolentino
VP of Wildfire and Business Resiliency
Brandon.Tolentino@sce.com

August 17, 2026

Patrick Doherty, Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_PAD_SCE_YLO_20260617_0938)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_PAD_SCE_YLO_20260617_0938** which SCE received on **July 16, 2026 (Notice),** based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **June 17,2026.** SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//
Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_PAD_SCE_YLO_20260617_0938	1	4818186E

Summary of Findings:

Energy Safety's Notice states that on June 17, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Corona, California. Energy Safety found the following deficiencies:

Deficiency 1. Energy Safety observed that in implementing 2025 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1), SCE failed to complete remediation related to a tap cover on Structure ID 4818186E, Grid Hardening ID 414446525-4818186E at coordinates 33.9459558727957, -117.62203775654.
.

Energy Safety states that it "considers this non-performance to be in the Minor risk category."[1]

Response:

The Notice states that the "tap cover was unsecured and bare wire was exposed." SCE confirms that the tap cover on structure 4818186E was installed and in place with no bare wire exposed on November 24, 2025. During a subsequent inspection in response to this Notice, SCE's Field Operations team identified that the previously installed tap cover had become dislodged likely due to environmental exposure or other external factors. On July 30, 2026, SCE field personnel remediated the tap cover on structure 4818186E once again. Please see the photos below showing the recently completed avian protection cover remediation.

[1] Notice, p. 1.

