



April 27, 2026

Brandon Tolentino
Vice President, Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF DATA INACCURACY

Mr. Tolentino:

Pursuant to Government Code Section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues SCE a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy may lead to a Notice of Non-Performance (NON) if the inaccuracy causes SCE to miss a WMP target or prevents Energy Safety from ensuring that SCE performed the targets and statements made in SCE's 2025 WMP.

On January 28, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the City of Pine Mountain Club, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Pole ID 2038652E, at coordinates 34.8508489998326, -119.159022000629, the inspector observed that a single pole replacement was reported under two unique Grid Hardening IDs: 414077620-2038652E and 414580192-2038652E, and therefore the work reported as completed Grid Hardening ID 414580192-2038652E is duplicative.

The data inaccuracy identified in this notice could make it appear as though SCE reached the target set in WMP initiative 8.1.3.1 – Distribution Detailed Inspections and Remediation when it has not. If SCE does not address this data inaccuracy and includes the inaccurate data in its reporting regarding WMP initiative Distribution Detailed Inspections and Remediation, SCE may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on SCE's WMP Performance.

Within 30 days from the issuance date of this NODI, SCE should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:

Peter Van Mieghem, SCE

Peter.Vanmieghem@sce.com

Elizabeth Leano, SCE

Elizabeth.Leano@sce.com

Cynthia Childs, SCE

Cynthia.Childs@sce.com

Raghu Rayalu, SCE

Raghu.Rayalu@sce.com

Erick G Sanchez, SCE

Erick.G.Sanchez@sce.com

Sally Jeun, SCE

Sally.Jeun@sce.com

Keyshawn Ford, Energy Safety

Keyshawn.Ford@energysafety.ca.gov

Yana Loginova, Energy Safety

Yana.Loginova@energysafety.ca.gov

Samuel Isaiah, Energy Safety

Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety

Shannon.Greene@energysafety.ca.gov

AssetPerformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/Lists/DocketLog.aspx?docketnumber=2025%20NODI>



INSPECTION REPORT

Electrical Corporation:	Southern California Edison Company
Report Number:	PAD_SCE_KSF_20260128_1206
Date of Inspection:	January 28, 2026
City and/or County of Inspection:	Pine Mountain Club, Kern County
Inspector:	Keyshawn Ford
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 3 (Q3)
Inspection Selection:	Energy Safety viewed the contents of the Q3 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.3.1 – Distribution Detailed Inspections and Remediation
Inspection Purpose:	Assess the accuracy of Southern California Edison Company’s QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	2038652E	414580192-2038652E	34.8508489998326, -119.159022000629	Tier 3	8.1.3.1 - Distribution Detailed Inspections and Remediation	Duplicate work was reported at the location.

Observations

On Pole ID 2038652E, Grid Hardening ID 414580192-2038652E at 2445 Innsbruck Ct, Pine Mountain Club, CA, 93222, USA, 34.8508489998326, -119.159022000629, the inspector observed that two separate grid hardening points were reported for the completed pole replacement work. The inspector's observation is documented in Data Inaccuracy 1 photographs GImg1 and GImg2, which are attached to this report as Exhibit A.

Energy Safety concludes that there is inaccurate data because of these facts:

1. The description of work details pole replacement at this location; however, that pole replacement was counted twice under two separate Grid Hardening IDs.
2. The "Long Text" for Grid Hardening ID 414580192-2038652E, provided via "ES-SCE-2025 Q3 Problem Statement Remediations" states "Per the multiple notification process, this is a duplicate notification. Setting REJC status. Pole will be or is already replaced on notification 414077620."
3. The "Long Text" for Grid Hardening ID 414077620-2038652E, provided via "ES-SCE-2025 Q3 Problem Statement Remediations" states "Per multiple notification process, pole is in process to be changed out on this notification, notification required start and end dates have been adjusted to match earlier due notification 414580192."



This observation warrants a notice of data inaccuracy. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.

Exhibits

Exhibit A: Photo Log

Structure ID: 2038652E

Data Inaccuracy 1

 A photograph of a tall, brown utility pole standing in a wooded area. The pole has several cross-arms and wires. The background shows green trees and a clear blue sky.	 A close-up photograph of a yellow identification tag attached to the brown utility pole. The tag is oriented vertically and contains the alphanumeric string 'E2038652E' in black text.
<p>G1mg1: Overall Structure</p>	<p>G1mg2: Structure ID</p>