



October 20, 2026

Dan Marsh
Director, Rates and Regulatory Affairs
Liberty Utilities
701 National Avenue
Tahoe Vista, CA 96148

NOTICE OF DATA INACCURACY

Mr. Marsh:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Liberty Utilities (LU) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues LU a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy may lead to a Notice of Non-Performance (NON) if the inaccuracy causes LU to miss a WMP target or prevents Energy Safety from ensuring that LU performed the targets and statements made in LU 2025 WMP.

On June 2, 2026, Energy Safety conducted an inspection of Liberty Utilities' WMP initiatives in the vicinity of the city of South Lake Tahoe, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Structure ID 300113, Grid Hardening ID ce741644-91bd-486d-bb46-0105de3d452e at coordinates 38.9393273496841, -119.955749799512, the inspector observed that LU failed to adhere to data accuracy.

The data inaccuracy identified in this notice could make it appear as though LU reached the target set in its WMP initiative related to tree attachment removals when it has not. If LU does not address this data inaccuracy and includes the inaccurate data in its reporting regarding its WMP initiative related to tree attachment removals, LU may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on LU's WMP Performance.

Within 30 days from the issuance date of this NODI, LU should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

/s/ Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:

Peter Stoltman, Liberty Utilities
Peter.Stoltman@libertyutilities.com
Jordan Parrillo, Liberty Utilities
Jordan.Parrillo@libertyutilities.com
Babak Kaviani, Energy Safety
Babak.Kaviani@energysafety.ca.gov
Samuel Isaiah, Energy Safety
Samuel.Isaiah@energysafety.ca.gov
Shannon Greene, Energy Safety
Shannon.Greene@energysafety.ca.gov
Cecilia Yaniz, Energy Safety
Cecilia.Yaniz@energysafety.ca.gov
AssetPerformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI>



State of California – A Natural Resources Agency

OFFICE OF ENERGY INFRASTRUCTURE SAFETY

715 P Street, 15th Floor | Sacramento, CA 95814

916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor

Forest Kaser, Director

INSPECTION REPORT

Electrical Corporation:	Liberty Utilities
Report Number:	PAD_LU_CYA_20260602_1500
Date of Inspection:	June 2, 2026
City and/or County of Inspection:	South Lake Tahoe, El Dorado County
Inspector:	Cecilia Yaniz
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 3 (Q3)
Inspection Selection:	Energy Safety viewed the contents of the Q3 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.12 - Tree attachment removals
Inspection Purpose:	Assess the accuracy of Liberty Utilities' QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	300113	ce741644-91bd-486d-bb46-0105de3d452e	38.9393273496841, -119.955749799512	Tier 2	8.1.2.12 - Tree attachment removals	Inaccurate data provided on tree attachment removals

Observations

On Structure ID 300113, Grid Hardening ID ce741644-91bd-486d-bb46-0105de3d452e at 1311 Heather Lake Rd, South Lake Tahoe, CA, 96150, USA, 38.9393273496841, -119.955749799512, the inspector observed that no prior tree attachment existed at the reported location. The inspector's observation is documented in Data Inaccuracy 1 photographs, which are attached to this report as Exhibit A.

Energy Safety concludes that there are inaccurate data because of these facts:

1. LU reported in the 2025 Q3 QDR that work on WMP initiative 8.1.2.12 – Tree attachment removals was completed at this location.
2. Based on review of Google Maps imagery from September 2024, the inspector observed that there was no existing tree attachment at this location to remove, given that the location in question provides service to homes that did not previously utilize a tree attachment.

This observation indicates that the data regarding tree attachment removals were not accurate. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.

Exhibits

Exhibit A: Photo Log

Structure ID: 300113

Data Inaccuracy 1

 A photograph showing a wooden utility pole in a residential area. In the background, there is a light green house with a white roof and a chimney. The area is surrounded by tall pine trees and a wooden fence.	 A close-up photograph of a wooden utility pole. A silver metal tag with the number '300113' is attached to the pole. A yellow reflective safety band is visible near the bottom of the pole.
General Image 1: Overall Structure	General Image 2: Structure ID
 A photograph showing a wooden utility pole with a service conductor. The pole is surrounded by tall pine trees. In the background, there is a small white building and a wooden fence.	 A photograph showing a white pickup truck parked on a paved area. A portable toilet is visible in the foreground. The background features tall pine trees and a wooden building.
Asset Image 1: Overview of service conductor - view 1	Asset Image 2: Overview of service conductor - view 2



Asset Image 3: Overview of service conductor - view 3