



April 15, 2026

Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF NON-PERFORMANCE

Mr. Brandon Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) conducted inspections of work completed by Southern California Edison Company (SCE) in accordance with its 2025 Wildfire Mitigation Plan (WMP). During the inspections, Energy Safety determined the existence of non-performance requiring correction. Energy Safety therefore issues SCE a Notice of Non-Performance (NON).

On March 26, 2026, Energy Safety conducted an inspection of SCE's WMP initiatives in the vicinity of the city of Agoura Hills, California in High Fire Threat District (HFTD) Tier 3 and State Responsibility Area (SRA). The inspection report is enclosed herewith. Energy Safety found the following deficiency:

Deficiency 1. Energy Safety observed that SCE failed to implement its 2025 WMP initiative 8.2.3.3.1 Expanded Clearing (VM-7), which requires compliance with Public Resource Code section 4293, by not maintaining a four-foot clearance distance around the primary conductors near pole ID 4382726E and coordinates 34.15106162767872, -118.7405848910039. Energy Safety considers this non-performance to be in the Moderate risk category. SCE must complete a corrective action for this non-performance by two months from the date of this notice.¹

Within 30 days from the issuance date of this NON, SCE must provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified deficiency.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NON Docket² and the associated file name(s) must begin with the NON identification number.

¹ Gov. Code section 15475.2(a)(2)

² <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NON>

Prior to its response, SCE may request an informal conference with Energy Safety for the purpose of disputing any issues raised in this NON no later than 10 business days before the response deadline.³ Requests for informal conference with Energy Safety must be e-mailed to environmentalscience@energysafety.ca.gov, with a copy sent to me and Elizabeth McAlpine, Elizabeth.McAlpine@energysafety.ca.gov.

Sincerely,



Sheryl Bilbrey
Program Manager | Environmental Science Division
Office of Energy Infrastructure Safety
Sheryl.Bilbrey@energysafety.ca.gov

Cc:

Cynthia Childs, Southern California Edison
Cynthia.childs@sce.com

Elizabeth Leano, Southern California Edison
Elizabeth.Leano@sce.com

Erick G Sanchez, Southern California Edison
Erick.g.sanchez@sce.com

Sally Jeun, Southern California Edison
Sally.jeun@sce.com

Raghu Rayalu, Southern California Edison
Raghu.Rayalu@sce.com

³ Energy Safety Performance Guidelines, p. 4



INSPECTION REPORT

Overview

The Office of Energy Infrastructure Safety (Energy Safety) conducts field inspections to verify the work performed by an electrical corporation as reported in an approved Wildfire Mitigation Plan (WMP), and to assess general conditions of electrical infrastructure that may adversely impact an electrical corporation’s wildfire risk. A Notice of Non-Performance (NON) is issued for any instances of non-performance identified during an inspection of its WMP initiatives.

Energy Safety has designated this finding of a deficiency as a “Moderate” risk. SCE must correct the deficiency pursuant to the timeline provided in Table 1.⁴

Table 1. Risk Category and Correction Timelines

Risk Category	Deficiency correction timeline
Severe	<ul style="list-style-type: none">• Immediate resolution
Moderate	<ul style="list-style-type: none">• 2 months (in High Fire Threat District (HFTD) Tier 3)• 6 months (in HFTD Tier 2)• 6 months (if relevant to worker safety; not in HFTD Tiers 2 or 3)
Minor	<ul style="list-style-type: none">• 12 months

⁴ Energy Safety Performance Guidelines, p. 4



Inspection Summary

Energy Safety found a “Moderate” deficiency near pole ID 4382726E in HFTD Tier 3. SCE failed to maintain vegetation at least four feet from the primary conductors.⁵

The inspection location and WMP initiative summary are included in Table 2.

Table 2: Inspection Location and Initiative Summary

Electrical Corporation:	SCE
Report Number:	NON_ESD_SCE_GCA_20260326_0756
Inspector:	Gary Candelas
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 4 (Q4) 2025
Inspection Selection:	Energy Safety inspected the locations based on SCE’s Q4 QDR.
Relevant WMP Initiative(s):	8.2.3.3.1 Expanded Clearing
Date of inspection:	March 26, 2026
City and/or County of Inspection:	Agoura Hills, California

⁵ SCE “2023-2025 Base WMP,” published November 14, 2024. p. 412-413
(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=57620&shareable=true> accessed March 30, 2026).

Inspection Findings

Deficiency 1

Relevant Requirement:

SCE's WMP states the following regarding initiative number 8.2.3.3.1 Expanded Clearing: "At a minimum, SCE's Routine Line Clearing work within [High Fire Risk Area] HFRA maintains at least the required four feet clearance for Distribution lines and the required 10 feet clearance for Transmission lines for a full annual inspection cycle."⁶

Findings:

Energy Safety considers this deficiency as "Moderate" because SCE failed to maintain the required minimum clearance distance between vegetation and its conductors, consistent with the requirement of Public Resources Code section 4293. A pine tree was growing within four feet of the conductors, and the continued encroachment presents a wildfire risk.

On March 26, 2026, Energy Safety conducted an inspection of SCE's WMP initiatives in the vicinity of Agoura Hills, California. During the inspection, Energy Safety identified a pine tree growing within the four-foot minimum clearance distance near pole ID 4382726E and near coordinates 34.15106162767872, -118.7405848910039 along Fairview Place. The pine tree is located within SCE's defined HFRA, in HFTD Tier 3, and in SRA. SCE's Q4 QDR data indicated it completed tree work in the area on November 10, 2025. The inspector measured the distance between the primary conductors and the closest branches of the pine tree using a Nikon Forestry Pro II Laser range finder. The measured distance was 3.2 feet, which is less than required four-foot clearance. The pine tree is located at approximately 0.1 span south of pole ID 4382726E. The inspector's observations are documented in Exhibit A photographs, which are attached to this report. Photo 1 depicts pole ID 4382726E. Photo 2 shows of the pine tree relative to the pole. Photo 3 depicts the pine tree in relation to the driveway. Photos 4, 5, and 6 depict the pine tree encroaching within the four-foot minimum clearance distance.

⁶ Southern California Edison Company, [2023-2025 Base Wildfire Mitigation Plan](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=57620&shareable=true), published November 14, 2024, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=57620&shareable=true> accessed on April 9, 2026). Pages 412-413.

Exhibits

Exhibit A: Photo Log

Structure ID: 4382726E

Deficiency 1

	
<p>Photo 1: Photo of pole ID 4382726E.</p>	<p>Photo 2: Overview photo showing the orientation of the pole, conductors, and the pine tree.</p>



Photo 3: Close-up photo of the pine tree encroaching within the four-foot minimum clearance distance from the primary conductor. Photo taken approximately 27 feet south of the tree.



Photo 4: Additional photo of the pine tree in relation to the pole.



Photo 5: Additional photo of the pine tree within the four-foot minimum clearance distance from the primary conductor. Photo taken from under the primary conductors.