



July 2, 2026

Brandon Tolentino  
Vice President, Wildfire and Business Resiliency  
Southern California Edison Company  
2244 Walnut Grove Ave  
Rosemead, CA 91770

## **NOTICE OF NON-PERFORMANCE**

Mr. Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of non-performance requiring correction. Energy Safety therefore issues SCE a Notice of Non-Performance (NON), identifying non-performance with its approved WMP.

On June 17, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Corona, California. The inspection report is enclosed herewith. Energy Safety found the following deficiencies:

Deficiency 1. Energy Safety observed that in implementing 2025 WMP initiative 8.1.3.1 – Distribution High Fire Risk-Informed (HFRI) Inspection and Remediations (IN-1.1), SCE failed to complete replacement of missing covers on Structure ID 1904215E, Grid Hardening ID 414433083-1904215E at coordinates 33.8277250445338, -117.575228522755. Energy Safety considers this non-performance to be in the Minor risk category. SCE must complete a corrective action for this deficiency by 12 months from the date of this notice.<sup>1</sup>

Within 30 days from the issuance date of this NON, the electrical corporation must provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified deficiency or deficiencies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NON Docket,<sup>2</sup> and the associated file name(s) must begin with the NON identification number.

Prior to its response, the electrical corporation may request an informal conference with Energy Safety for the purpose of disputing any issues raised in this NON no later than 10 business days before the response

---

<sup>1</sup> Gov. Code section 15475.2(a)(2)

<sup>2</sup> <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NON>

deadline.<sup>3</sup> Requests for informal conference with Energy Safety must be e-mailed to [AssetPerformance@energysafety.ca.gov](mailto:AssetPerformance@energysafety.ca.gov), with a copy sent to all Energy Safety staff identified in the NON.

Sincerely,

/s/ Patrick Doherty

Patrick Doherty  
Program Manager | Performance Assessment Division  
Office of Energy Infrastructure Safety  
[Patrick.Doherty@energysafety.ca.gov](mailto:Patrick.Doherty@energysafety.ca.gov)

Cc:

Peter Van Mieghem, SCE  
[Peter.Vanmieghem@sce.com](mailto:Peter.Vanmieghem@sce.com)

Elizabeth Leano, SCE  
[Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com)

Cynthia Childs, SCE  
[Cynthia.Childs@sce.com](mailto:Cynthia.Childs@sce.com)

Raghu Rayalu, SCE  
[Raghu.Rayalu@sce.com](mailto:Raghu.Rayalu@sce.com)

Erick G Sanchez, SCE  
[Erick.G.Sanchez@sce.com](mailto:Erick.G.Sanchez@sce.com)

Sally Jeun, SCE  
[Sally.Jeun@sce.com](mailto:Sally.Jeun@sce.com)

Yana Loginova, Energy Safety  
[Yana.Loginova@energysafety.ca.gov](mailto:Yana.Loginova@energysafety.ca.gov)

Samuel Isaiah, Energy Safety  
[Samuel.Isaiah@energysafety.ca.gov](mailto:Samuel.Isaiah@energysafety.ca.gov)

Shannon Greene, Energy Safety  
[Shannon.Greene@energysafety.ca.gov](mailto:Shannon.Greene@energysafety.ca.gov)  
[AssetPerformance@energysafety.ca.gov](mailto:AssetPerformance@energysafety.ca.gov)

---

<sup>3</sup> Energy Safety Performance Guidelines, p. 4



# INSPECTION REPORT

## Overview

The Office of Energy Infrastructure Safety (Energy Safety) conducts inspections to verify the work performed by an electrical corporation pursuant to an approved Wildfire Mitigation Plan (WMP) or subsequent filing, and to assess general conditions of electrical infrastructure that may adversely affect an electrical corporation's wildfire risk.

A Notice of Non-Performance (NON) is issued for any deficiencies discovered during an inspection related to an electrical corporation's performance of its WMP.

Deficiencies must be corrected in a timely manner. Energy Safety may prescribe a timeframe for resolution of a deficiency.<sup>4</sup> If Energy Safety assigns a risk category to a deficiency, an electrical corporation must correct the deficiency as required per the timelines provided in Table 1.<sup>5</sup>

**Table 1. Risk Category and Correction Timelines**

| Risk Category | Deficiency correction timeline                                                                                                                                                                                          |
|---------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Severe        | <ul style="list-style-type: none"><li>• Immediate resolution</li></ul>                                                                                                                                                  |
| Moderate      | <ul style="list-style-type: none"><li>• 2 months (in High Fire Threat District (HFTD) Tier 3)</li><li>• 6 months (in HFTD Tier 2)</li><li>• 6 months (if relevant to worker safety; not in HFTD Tiers 2 or 3)</li></ul> |
| Minor         | <ul style="list-style-type: none"><li>• 12 months or resolution scheduled in WMP update</li></ul>                                                                                                                       |

---

<sup>4</sup> Gov. Code section 15475.2(a)(2)

<sup>5</sup> Energy Safety Performance Guidelines, p. 4

# Inspection Summary

Table 2 provides a summary of the selection of the WMP inspection location and initiative. Table 3 provides a summary of the deficiency or deficiencies found during the inspection. Details regarding the inspection that identified the deficiency or deficiencies are provided in the Inspections Details section below.

Table 2. Inspection Location and Initiative Summary

|                                         |                                                                                                                                                                          |
|-----------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Electrical Corporation:                 | Southern California Edison Company                                                                                                                                       |
| Report Number:                          | PAD_SCE_SIS_20260617_1231                                                                                                                                                |
| Inspector:                              | Samuel Isaiah                                                                                                                                                            |
| WMP Year Inspected:                     | 2025                                                                                                                                                                     |
| Quarterly Data Report (QDR) Referenced: | Quarter 4 (Q4)                                                                                                                                                           |
| Inspection Selection:                   | Energy Safety viewed the contents of the Q4 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report. |
| Relevant WMP Initiative(s):             | 8.1.3.1 - Distribution Detailed Inspections and Remediations (IN-1.1)                                                                                                    |
| Date of Inspection:                     | June 17, 2026                                                                                                                                                            |
| City and/or County of Inspection:       | Corona, Riverside County                                                                                                                                                 |
| Inspection Purpose:                     | Assess the accuracy of Southern California Edison Company’s QDR data, completeness of its work, and performance of WMP requirements.                                     |

Table 3. WMP Inspection Deficiency

| Deficiency # | Structure ID | Grid Hardening ID  | Lat/Long                            | HFTD   | Initiative Number                                                     | Severity | Deficiency Description                                       |
|--------------|--------------|--------------------|-------------------------------------|--------|-----------------------------------------------------------------------|----------|--------------------------------------------------------------|
| Deficiency 1 | 1904215E     | 414433083-1904215E | 33.8277250445338, -117.575228522755 | Tier 2 | 8.1.3.1 - Distribution Detailed Inspections and Remediations (IN-1.1) | Minor    | Failure to complete replacing missing avian protection cover |


# Inspection Details

## Relevant Requirement:

Southern California Edison Company's WMP states the following regarding initiative number 8.1.3.1 Distribution Detailed Inspections and Remediations (IN-1.1):

1. "The frequency of [High Fire Risk-Informed inspections] varies by the location-specific risk... within SCE's [High Fire Risk Area] and emergent conditions. Issues identified by inspectors during the detailed inspections are prioritized for remediation to be completed within [General Order 95] compliance timelines. Remediations can be repairs to or replacements of existing assets depending on asset condition. For example, SCE repairs ground molding with that is found to be broken/damaged with an exposed ground wire at the public level. Also, SCE replaces wood guy guards if found to be missing, damaged or outdated."<sup>6</sup>
2. The following is a workflow diagram from SCE's WMP showing the conditions under which SCE will execute remediations under initiative number 8.1.3.1:<sup>7</sup>

**Figure 8-1a - Distribution Detailed Inspections and Remediations Workflow**



<sup>6</sup> Southern California Edison Company, "2023-25 Wildfire Mitigation Plan," October 26, 2023, p. 284. [Online]. Available: <https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=55866&shareable=true>

<sup>7</sup> Southern California Edison Company, "2023-25 Wildfire Mitigation Plan," October 26, 2023, p. 285. [Online]. Available: <https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=55866&shareable=true>

**Findings:**

In the 2025 Q4 Quarterly Data Report Submission, Southern California Edison Company reported that work to replace missing covers under its Distribution Remediation WMP initiative was completed at Structure ID 1904215E, Grid Hardening ID 414433083-1904215E at 3230 Manning Ave. Corona, CA, 92882, 33.8277250445338, -117.575228522755. At this location, the inspector observed that the primary tab cover was dislodged and the bare conductor was exposed. The inspector's observation is documented in Deficiency 1 photographs, which are attachments to this report. Photo numbers Asset Image 1 and Asset Image 2 depict that primary conductor tab cover is dislodged.

Energy Safety concludes that there is a deficiency because of these facts:

1. Southern California Edison Company's 2025 WMP initiative number 8.1.3.1 Distribution Detailed Inspections and Remediations work identified that the replacement of missing covers was complete at this location.
2. The tab cover was dislodged, and the bare conductor was exposed.

# Exhibits

Exhibit A: Photo Log

Structure ID: 1904215E

Deficiency 1

|                                                                                                                                                                                                                                                                                                                      |                                                                                                                                                                                                                                                                                                                                      |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  A photograph showing a tall wooden utility pole with multiple crossarms and insulators. The pole is situated in a field with dry grass and a chain-link fence in the foreground. Trees are visible on the left side of the frame. |  A close-up photograph of the utility pole showing a yellow identification tag with the number '1904215E' and a yellow band with the number '8366'. Below the band, the text 'HIGH VOLTAGE' and 'Southern California Edison' is partially visible. |
| <b>General Image 1:</b> Overall Structure                                                                                                                                                                                                                                                                            | <b>General Image 2:</b> Structure ID                                                                                                                                                                                                                                                                                                 |
|  A close-up photograph of a utility pole crossarm showing a dislocated tab cover and a bare conductor exposed.                                                                                                                    |  A close-up photograph of a utility pole crossarm showing a dislocated tab cover and a bare conductor exposed.                                                                                                                                   |
| <b>Asset Image 1:</b> Tab cover dislocated; bare conductor exposed                                                                                                                                                                                                                                                   | <b>Asset Image 2:</b> Tab cover dislocated; bare conductor exposed                                                                                                                                                                                                                                                                   |