



August 22, 2025

Shinjini Menon  
Vice President, Asset Management and Wildfire Safety  
Southern California Edison Company  
2244 Walnut Grove  
Rosemead, CA 91770

## NOTICE OF VIOLATION

Ms. Menon:

Pursuant to Public Utilities Code section 326 and Government Code section 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2024 Wildfire Mitigation Plan (WMP) and determined the existence of a violation. Energy Safety therefore issues SCE a Notice of Violation (NOV), identifying noncompliance with an approved WMP or any law, regulation, or guideline within the authority of the Office.<sup>1</sup>

On July 8, 2025, Energy Safety conducted an inspection of SCE's WMP initiatives in the vicinity of the city of Temecula, California. The inspection report is enclosed herewith. Energy Safety found the following violation:

Violation 1. Energy Safety observed that in implementing 2024 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1), SCE failed to complete the remediation of avian protection on Pole ID 2343288E, Grid Hardening ID 413885136-2343288E at coordinates 33.477405, -117.297697. Energy Safety considers this completeness violation to be in the Minor risk category.

---

<sup>1</sup> Cal. Code Regs., tit. 14, section 29302(b)(2)

## Response Options

Energy Safety may prescribe a timeframe for resolution of a violation associated with the assigned risk category.<sup>2</sup> Within 30 days from the issuance date of this NOV, the electrical corporation must provide a response advising Energy Safety of corrective actions taken or planned to remedy the above identified violation(s) and prevent recurrence. Alternatively, the electrical corporation must advise Energy Safety that it will not correct the violation, including the reasoning or justification for inaction and all supporting documentation.<sup>3</sup>

This response shall be filed in the Energy Safety e-Filing system under the 2024 NOV Docket<sup>4</sup> and the associated file name(s) must begin with the NOV identification number provided above.

Pursuant to Government Code section 15475.4, if the electrical corporation intends to request a hearing “to take public comment or present additional information,” it must also do so within the 30-day timeframe. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Prior to its response or request for hearing, the electrical corporation may also request an informal conference with Energy Safety’s Compliance Assurance Division for the purpose of disputing any issues raised in this NOV no later than five (5) business days before the response deadline.<sup>5</sup> Requests for informal conference with Energy Safety must be e-mailed to [compliance@energysafety.ca.gov](mailto:compliance@energysafety.ca.gov), with a copy sent to all Energy Safety Compliance Assurance Division staff identified in the NOV.

Pursuant to Public Utilities Code section 8389(g), following receipt of the electrical corporation’s response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission for its consideration of potential enforcement action, as it deems appropriate.

Sincerely,

*Patrick Doherty*

Patrick Doherty  
Program Manager | Compliance Assurance Division  
Office of Energy Infrastructure Safety  
[Patrick.Doherty@energysafety.ca.gov](mailto:Patrick.Doherty@energysafety.ca.gov)

Cc:

Raymond Fugere, SCE  
[Raymond.Fugere@sce.com](mailto:Raymond.Fugere@sce.com)

---

<sup>2</sup> Energy Safety Compliance Guidelines, pp. 3

<sup>3</sup> Energy Safety Compliance Guidelines, pp. 4-5

<sup>4</sup> <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2024%20NOV>

<sup>5</sup> Energy Safety Compliance Guidelines, p. 4

Gary Chen, SCE

[Gary.Chen@sce.com](mailto:Gary.Chen@sce.com)

Sunny Chu, SCE

[Sunny.Chu@sce.com](mailto:Sunny.Chu@sce.com)

Elizabeth Leano, SCE

[Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com)

Johnny Parker, SCE

[Johnny.Parker@sce.com](mailto:Johnny.Parker@sce.com)

Cynthia Childs, SCE

[Cynthia.Childs@sce.com](mailto:Cynthia.Childs@sce.com)

Raghu Rayalu, SCE

[Raghu.Rayalu@sce.com](mailto:Raghu.Rayalu@sce.com)

Yana Loginova, Energy Safety

[Yana.Loginova@energysafety.ca.gov](mailto:Yana.Loginova@energysafety.ca.gov)

Samuel Isaiah, Energy Safety

[Samuel.Isaiah@energysafety.ca.gov](mailto:Samuel.Isaiah@energysafety.ca.gov)

Shannon Greene, Energy Safety

[Shannon.Greene@energysafety.ca.gov](mailto:Shannon.Greene@energysafety.ca.gov)

[Compliance@energysafety.ca.gov](mailto:Compliance@energysafety.ca.gov)



# INSPECTION REPORT

## Overview

### Inspection Categories

The Office of Energy Infrastructure Safety (Energy Safety) conducts inspections to verify the work performed by an electrical corporation as reported in an approved Wildfire Mitigation Plan (WMP) or subsequent filing, and to assess general conditions of electrical infrastructure that may adversely impact an electrical corporation’s wildfire risk.

A Notice of Violation (NOV) is issued for any instances of noncompliance discovered during an inspection related to an electrical corporation’s execution of its WMP initiatives.

### Correction Timelines

Violations must be corrected in a timely manner. Energy Safety may prescribe a timeframe for resolution of a violation. If Energy Safety assigns a risk category to a violation, an electrical corporation must correct the violation as required per the timelines provided in Table 1.<sup>6</sup>

**Table 1. Risk Category and Correction Timelines**

Risk Category	Violation and defect correction timeline
Severe	<ul style="list-style-type: none"><li>• Immediate resolution</li></ul>
Moderate	<ul style="list-style-type: none"><li>• 2 months (in High Fire Threat District (HFTD) Tier 3)</li><li>• 6 months (in HFTD Tier 2)</li><li>• 6 months (if relevant to worker safety; not in HFTD Tiers 2 or 3)</li></ul>
Minor	<ul style="list-style-type: none"><li>• 12 months or resolution scheduled in WMP update</li></ul>

---

<sup>6</sup> Energy Safety Compliance Guidelines, p. 3



# Inspection Summary

Table 2 provides a summary of the selection of the WMP inspection location and initiative. Table 3 provides a summary of the violation(s) found during the inspection. Details regarding the inspection that identified the violation(s) are provided in the Inspections Details Section below.

***Table 2: Inspection Location and Initiative Summary***

Electrical Corporation:	Southern California Edison Company
Report Number:	CAD_SCE_SIS_20250708_1316
Inspector:	Samuel Isaiah
WMP Year Inspected:	2024
Quarterly Data Report (QDR) Referenced:	Quarter 4 (Q4)
Inspection Selection:	Energy Safety viewed the contents of the Q4 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.3.1 - Distribution Detailed Inspections and Remediations (IN-1.1)
Date of inspection:	July 8, 2025
City and/or County of Inspection:	Temecula, Riverside County
Inspection Purpose:	Assess the accuracy of Southern California Edison Company's QDR data, completeness of its work, compliance with WMP requirements, and compliance with its protocols.

**Table 3: WMP Inspection Violation(s)**

Violation #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Violation Type	Severity	Violation Description
Violation 1	2343288E	413885136-2343288E	33.477405, -117.297697	Tier 3	Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations	Completeness	Minor	Failure to complete the avian protection remediation


# Inspection Details

## Relevant Requirement:

Southern California Edison Company's WMP states the following regarding initiative number 8.1.3.1 Distribution Detailed Inspections and Remediations (IN-1.1):

1. "The frequency of [High Fire Risk-Informed inspections] varies by the location-specific risk... within SCE's [High Fire Risk Area] and emergent conditions. Issues identified by inspectors during the detailed inspections are prioritized for remediation to be completed within [General Order 95] compliance timelines. Remediations can be repairs to or replacements of existing assets depending on asset condition. For example, SCE repairs ground molding with that is found to be broken/damaged with an exposed ground wire at the public level. Also, SCE replaces wood guy guards if found to be missing, damaged or outdated."<sup>7</sup>
2. The following is a workflow diagram from SCE's WMP showing the conditions under which SCE will execute remediations under initiative number 8.1.3.1:<sup>8</sup>

**Figure 8-1a - Distribution Detailed Inspections and Remediations Workflow**



<sup>7</sup> Southern California Edison Company, "2023-25 Wildfire Mitigation Plan," October 26, 2023, p. 284. [Online]. Available: <https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=55866&shareable=true>

<sup>8</sup> Southern California Edison Company, "2023-25 Wildfire Mitigation Plan," October 26, 2023, p. 285. [Online]. Available: <https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=55866&shareable=true>

**Finding:****Violation1**

On Pole ID 2343288E, Grid Hardening ID 413885136-2343288E at 45231 Vía Los Ventos, Temecula, CA, 92590, 33.477405, -117.297697, the inspector observed that the avian protection replacement work was not completed. The inspector's observation is documented in Violation 1 photographs, which are attachments to this report. Photo numbers IA1Img1, IA1Img2 and IA1Img3 depict that both transformer's bushings were unhinged, and the external connecting terminals were exposed. Per information provided by SCE to the Compliance Inbox on April 3, 2025, at 12:15 pm, the unsecured transformer bushings were repaired.

Energy Safety concludes that there is a violation because of these facts:

1. Southern California Edison Company's 2024 WMP 8.1.3.1 Distribution Detailed Inspections and Remediations work identified that the unsecured transformer's bushings were repaired at this location.
2. The transformer bushings were unhinged, and the external connecting terminals were exposed to wildlife.





# Exhibits

Exhibit A: Photo Log

Structure ID: 2343288E

Violation 1

 A photograph showing a tall utility pole with cross-arms and wires, situated in a wooded area. A blue dumpster is visible in the foreground on a dirt path.	 A close-up photograph of a utility pole wrapped in grey plastic. A yellow vertical label with black text reads '2343288E'. A small white circular marker is visible below the label.
<p><b>G1mg1:</b> Overall Structure</p>	<p><b>G1mg2:</b> Structure ID</p>



**IA1Img1:** Transformer bushings unhinged



**IA1Img2:** Transformer bushings unhinged



**IA1Img3:** Transformer bushings unhinged