

August 22, 2022

Koko Tomassian, Compliance Program Manager      **BY ENERGY SAFETY E-FILING**  
Compliance Assurance Division  
Office of Energy Infrastructure Safety  
California Natural Resources Agency  
715 P Street 20<sup>th</sup> Floor  
Sacramento, CA 95814

**SUBJECT:**      Southern California Edison Company's Response to Notice of Violation  
                         - SCE ATJ 20220411-01 (Written Hearing Requested; Extension for  
                         Response Granted)

Dear Koko Tomassian:

Southern California Edison Company (SCE) appreciates the opportunity to review Notice of Violation - SCE ATJ 20220411-01 received on July 22, 2022 based on Energy Safety field inspections conducted in SCE's service area in April 2022. SCE appreciates the Office of Energy Infrastructure Safety's (Energy Safety) efforts to identify, communicate and work together to resolve potential wildfire risks.

Consistent with Government Code § 15475.4 & California Code of Regulations, Title 14, Division 17 (Emergency Regulation) § 29104, SCE requests written hearing. SCE requested a 30-day extension for providing a response to findings #2 and #3 in Notice of Violation - SCE ATJ 20220411-01. Energy Safety granted this extension on August 17, 2022. SCE will file a response by September 16, 2022.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or [Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com). SCE is looking forward to address finding where appropriate and work to support clarification of the inspection process as Energy Safety expands the geographic scope of its inspection program in 2022.

Sincerely,

//s//

Shinjini C Menon  
VP Asset Management & Wildfire Safety  
Southern California Edison

## SCE Basis for Written Hearing Request

### Finding: Missing Anti-rotational Clip

Notice	Finding #	Structures
NOV SCE ATJ 20220411-01	2	683849E

**Summary of Finding:** “Pole numbered 683849E did not have an anti-rotational clip installed on dead-end cover. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category.”

**Basis for Written Hearing Request:** SCE does not agree with the condition as identified by Energy Safety. Evidence shows that the anti-rotational clip was installed as intended. No violation should have been found. Please see photo reflecting the anti-rotational clip installed at the structure.



**Finding: Vibration Damper Within 6" of Insulator**

Notice	Finding #	Structures
NOV SCE ATJ 20220411-01	3	683848E

**Summary of Finding:** "Pole number 683848E had a vibration damper installed but was found to be within six inches of an insulator. Energy Safety considers this violation for failure of adhering to protocol to be in the Minor risk category."

**Basis for Written Hearing Request:** SCE **does not** agree with the condition as identified by Energy Safety. Evidence shows that the vibration damper is at the 6" mark, as intended. No violation should have been found. Please see photo below reflecting the vibration damper at the 6" mark.

