Laura M. Fulton Senior Counsel 8330 Century Park Court, CP32F San Diego, CA 92123-1548 LFulton@SDGE.com



May 10, 2024

VIA ELECTRONIC FILING Dockets 2022-NOV and 2022-QDR

Patrick Doherty Program Manager, Compliance Assurance Division Office of Energy Infrastructure Safety 715 P Street, 20th Floor Sacramento, CA 95814

RE: San Diego Gas & Electric Company's Revised Q4 2022 QDR Geodatabase Files Regarding its Response to Notice of Violations NOV_SDGE_CAC12_20230427_0742 and NOV_SDGE_CAC12_20230426_0847

Dear Program Manager Doherty:

As stated in San Diego Gas & Electric Company's (SDG&E) response to the finding(s) identified in the "Notice of Violation SDGE_CAC12_20230427_0742" and "Notice of Violation SDGE_CAC12_20230426_0847" (together "Notices of Violation or NOVs"), issued by the Office of Energy Infrastructure Safety's (Energy Safety) regarding SDG&E's compliance with its 2022 Wildfire Mitigation Plan (WMP), SDG&E hereby provides this notice of SDG&E's submittal of its revised Q4 2022 quarterly data reports (QDR) geodatabase files.¹

Specifically, the NOVs describe that on April 26, 2023 and April, 27, 2023, Energy Safety conducted inspections of SDG&E's WMP initiatives in the vicinity of the city of Alpine, California and found the following violations related to SDG&E's 2022 WMP Initiative 7.3.3.3 – Covered Conductor Installation:

Violation 1 – Energy Safety observed that in implementing 2022 WMP initiative 7.3.3.3 - Covered Conductor Installation, SDG&E failed to install covered conductor on pole ID P574883 at coordinates 32.8093471616653, -116.65015668652. Energy Safety considers this violation for failure to complete initiative to be in the Minor risk category.

¹ Notice of Violations SDGE_CAC12_20230427_0742 and SDGE_CAC12_20230426_0847 were issued by Energy Safety on April 3, 2024 and April 4, 2024, respectively. SDG&E submitted its response to both NOVs on May 3, 2024 to Energy Safety docket #2022-NOV.

Violation 2 – Energy Safety observed that in implementing 2022 WMP initiative 7.3.3.3 – Covered Conductor, SDG&E failed to install covered conductor on pole ID JP33462 at coordinates 32.7647823656679, -116.679371731863. Energy Safety considers this violation for failure to complete an initiative to be in the Minor risk category.

In SDG&E's response to the NOVs, SDG&E provided additional information to reflect that these two violations observed by Energy Safety are the result of a data error in SDG&E's fourth quarter QDR spatial data. While the data demonstrated that SDG&E installed covered conductor in the area, SDG&E had not implemented covered conductor in the site of Energy Safety's April 26, 2023 and April 27, 2023 inspections. SDG&E apologizes for the confusion resulting from the data error. It has corrected the data issue in subsequent reporting and hereby resubmits revised Q4 2022 spatial data without the incorrect line data as shown in the table in Attachment A.

Respectfully submitted,

/s/ Laura M. Fulton

Attorney for San Diego Gas and Electric Company

Attachment A – Incorrect Line Data Removed from 2022 Q4 QDR

GhID	GhLogID	WMPInitiative Activity	GhStatus	CircuitName	Feeder ID	CircuitID	GLOBALIDGUID	SHAPE_Length
Primary- 0445-L- CC- 2022-19	WMP.455 -0445-L- CC-2022	Covered conductor installation	Complete	0445-L-CC- 2022	73	{ADF596C A-05CE- 4DCA- 947E- 652D27A32 73D}	{B7A2AE67-7362- 4CF6-BB34- DEEB60823220}	371.580384
Primary- 0448-J- CC- 2022-21	WMP.455 -0448-J- CC-2022	Covered conductor installation	Complete	0448-J-CC- 2022	73	{C3286D0E -6715- 4A3B- BBAD- 97D06DEB 0F25}	{C4173CC0-65A8- 46C1-9C9C- D85D8FCD5A29}	412.952461
Primary- 0448- 02-CC- 2022-24	WMP.455 -0448-02- CC-2022	Covered conductor installation	Complete	0448-O2-CC- 2022	73	{F8AFAF11 -90E5- 48E4-A504- 41B8F838D B19}	{4CC9061E-B28B- 44AC-A818- DDBDD008FF98}	354.234116
Primary- 0448- K2-CC- 2022-26	WMP.455 -0448-K2- CC-2022	Covered conductor installation	Complete	0448-K2-CC- 2022	73	{F3BA82A F-5E25- 4183-8638- 58768ED1E 47C}	{F3BA82AF-5E25- 4183-8638- 58768ED1E47C}	98.551635
Primary- 0157-A- CC- 2022-27	WMP.455 -0157-A- CC-2022	Covered conductor installation	Complete	0157-A-CC- 2022	73	{8100F6EA -6A1D- 4219-AF3F- A77D1CB3 9207}	{8100F6EA-6A1D- 4219-AF3F- A77D1CB39207}	105.426031

Office of Energy Infrastructure Safety

2

May 10, 2024

GhID	GhLogID	WMPInitiative Activity	GhStatus	CircuitName	Feeder ID	CircuitID	GLOBALIDGUID	SHAPE_Length
Primary- 0448-J- CC- 2023-22	WMP.455 -0448-J- CC-2023	Covered conductor installation	In progress	0448-J-CC- 2023	73	{7EB8C374 -FE0D- 4C43- BA6F- 415CCA79 EAD3}	{7EB8C374-FE0D- 4C43-BA6F- 415CCA79EAD3}	388.658199
Primary- 0448- 02-CC- 2023-23	WMP.455 -0448-02- CC-2023	Covered conductor installation	In progress	0448-O2-CC- 2023	73	{12ED2D8 D-9203- 4CFD- A1B4- 87632FAFA 94D}	{7EB8C374-FE0D- 4C43-BA6F- 415CCA79EAD3}	200.264007
Primary- 0448- K2-CC- 2023-25	WMP.455 -0448-K2- CC-2023	Covered conductor installation	In progress	0448-K2-CC- 2023	73	{4CC9061E -B28B- 44AC- A818- DDBDD008 FF98}	{4CC9061E-B28B- 44AC-A818- DDBDD008FF98}	349.302267
Primary- 0157-A- CC- 2023-28	WMP.455 -0157-A- CC-2023	Covered conductor installation	In progress	0157-A-CC- 2023	73	{9606AFF0 -4BBF- 48CD- A37C- DC21E5D5 1C3D}	{9606AFF0-4BBF- 48CD-A37C- DC21E5D51C3D}	240.096005