December 24, 2024

Allen Berreth
Vice President of Transmission & Distribution Operations
PacifiCorp
1700 NE Multnomah, Suite 2000
Portland, OR 97232

NOTICE OF VIOLATION

Mr. Berreth:

Pursuant to Public Utilities Code section 326 and Government Code section 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by PacifiCorp (PC) in accordance with its 2024 Wildfire Mitigation Plan (WMP) and determined the existence of a violation. Energy Safety therefore issues PC a Notice of Violation (NOV), identifying noncompliance with an approved WMP or any law, regulation, or guideline within the authority of the Office.¹

On September 5, 2024, Energy Safety conducted an inspection of PC's WMP initiatives in the vicinity of the city of Seiad Valley, California. The inspection report is enclosed herewith. Energy Safety found the following violation(s):

Violation 1. Energy Safety observed that in implementing 2024 WMP initiative 8.1.2.1 - Line Rebuild Program - Covered Conductor Installation, PC failed to provide accurate data in reporting that covered conductor was installed on Pole ID 06246012.0121101, Grid Hardening ID 8236604a, at coordinates 41.8407836260049, -123.191359417292.

¹ Cal. Code Regs., tit. 14, section 29302(b)(2)

Response Options

Energy Safety may prescribe a timeframe for resolution of a violation associated with the assigned risk category. Within 30 days from the issuance date of this NOV, the electrical corporation must provide a response advising Energy Safety of corrective actions taken or planned to remedy the above identified violation(s) and prevent recurrence. Alternatively, the electrical corporation must advise Energy Safety that it will not correct the violation, including the reasoning or justification for inaction and all supporting documentation.³

This response shall be filed in the Energy Safety e-Filing system under the 2024 NOV Docket⁴ and the associated file name(s) must begin with the NOV identification number provided above.

Pursuant to Government Code section 15475.4, if the electrical corporation intends to request a hearing "to take public comment or present additional information," it must also do so within the 30-day timeframe. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Prior to its response or request for hearing, the electrical corporation may also request an informal conference with Energy Safety's Compliance Assurance Division for the purpose of disputing any issues raised in this NOV no later than five (5) business days before the response deadline. Requests for informal conference with Energy Safety must be e-mailed to compliance@energysafety.ca.gov, with a copy sent to all Energy Safety Compliance Assurance Division staff identified in the NOV.

Pursuant to Public Utilities Code section 8389(g), following receipt of the electrical corporation's response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission for its consideration of potential enforcement action, as it deems appropriate.

Sincerely,

Patrick Doherty

Program Manager | Compliance Assurance Division

Office of Energy Infrastructure Safety

Patrick Doherty

Patrick.Doherty@energysafety.ca.gov

Cc:

californiadockets@pacificorp.com

² Energy Safety Compliance Guidelines, p. 3

³ Energy Safety Compliance Guidelines, pp. 4-5

⁴ https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2024%20NOV

⁵ Energy Safety Compliance Guidelines, p. 4

Megan Buckner, PacifiCorp

Megan.buckner@pacificorp.com

Pooja Kishore, PacifiCorp

pooja.kishore@pacificorp.com

Tim Clark, PacifiCorp

tim.clark@pacificorp.com

Johnathan Moulton, PacifiCorp

Jonathan.moulton@pacificorp.com

Bruce Dao, PacifiCorp

Bruce.Dao@pacificorp.com

Melissa Swenson, PacifiCorp

Melissa.Swenson@pacificorp.com

Yana Loginova, Energy Safety

Yana.Loginova@energysafety.ca.gov

Compliance@energysafety.ca.gov

INSPECTION REPORT

Overview

Inspection Categories

The Office of Energy Infrastructure Safety (Energy Safety) conducts inspections to verify the work performed by an electrical corporation as reported in an approved Wildfire Mitigation Plan (WMP) or subsequent filing, and to assess general conditions of electrical infrastructure that may adversely impact an electrical corporation's wildfire risk.

A Notice of Violation (NOV) is issued for any instances of noncompliance discovered during an inspection related to an electrical corporation's execution of its WMP initiatives.

Correction Timelines

Violations must be corrected in a timely manner. Energy Safety may prescribe a timeframe for resolution of a violation. If Energy Safety assigns a risk category to a violation, an electrical corporation must correct the violation as required per the timelines provided in Table 1.⁶

Table 1. Risk Category and Correction Timelines

Risk Category	Violation and defect correction timeline				
Severe	Immediate resolution				
Moderate	 2 months (in High Fire Threat District (HFTD) Tier 3) 6 months (in HFTD Tier 2) 6 months (if relevant to worker safety; not in HFTD Tiers 2 or 3) 				
Minor	12 months or resolution scheduled in WMP update				

⁶ Energy Safety Compliance Guidelines, p. 3

Inspection Summary

Table 2 provides a summary of the selection of the WMP inspection location and initiative. Table 3 provides a summary of the violation found during the inspection. Details regarding the inspection that identified the violation are provided in the Inspections Details Section below.

Table 2: Inspection Location and Initiative Summary

Electrical Corporation:	PacifiCorp				
Report Number:	CAD_PC_CAC17_20240905_1356				
Inspector:	CAC17				
WMP Year Inspected:	2024				
Quarterly Data Report (QDR) Referenced:	Quarter 1 (Q1)				
Inspection Selection:	Energy Safety viewed the contents of the Q1 QDR and performed an analysis that resulted in the selection of				
	the WMP initiatives and locations referenced in this report.				
Relevant WMP Initiative:	8.1.2.1 Line Rebuild Program - Covered Conductor Installation				
Date of inspection:	September 5, 2024				
City and County of Inspection:	Seiad Valley, Siskiyou County				
Inspection Purpose:	Assess the accuracy of PacifiCorp's QDR data, completeness of its work, compliance with WMP requirements,				
	and compliance with its protocols.				

Table 3: WMP Inspection Violation

Violation #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Violation Type	Severity	Violation Description
Violation 1	06246012.0121101	8236604a	41.8407836260049, -123.191359417292	Tier 2	8.1.2.1 Line Rebuild Program - Covered Conductor Installation	Data Accuracy	N/A	Inaccurate data provided on covered conductor installation.

Inspection Details

Violation 1:

Relevant Requirement:

PC's WMP states the following regarding initiative number 8.1.2.1 Line Rebuild Program - Covered Conductor Installation:

1. "Reconductor with covered conductor: Specialized overhead covered conductors can be constructed with additional shielding and enhanced insulating properties to aid in wildfire mitigation." ⁷

Version 3.1 of Energy Safety's Data Guidelines states the following with respect to data submitted by an electrical corporation when reporting on its 2024 WMP initiatives:

2 "Electrical corporations must ensure location accuracy in their [geographic information system] data submissions..."8

Finding:

On pole ID 06246012.0121101, Grid Hardening ID 8236604a at 308 Old Seiad Creek Road, Seiad Valley, Siskiyou County, CA 96086, USA, 41.8407836260049, -123.191359417292, the inspector observed that covered conductor was present north of the subject pole but not south. The inspector's observation is documented in Violation 1 photographs, which are attachments to this report. Photo numbers Item1IA1Img2 and Item1IA1Img3 depict that no covered conductor was installed south of the location as indicated by PacifiCorp in its QDR submission.

Energy Safety concludes that:

- 1. PacifiCorp's 2024 WMP Covered Conductor Installation (8.1.2.1) was identified as complete at this location to the south of pole 06246012.0121101.
- 2. Covered conductor was not installed to the south of pole 06246012.0121101 as reported.

⁷ PacifiCorp, "2023-25 Final Wildfire Mitigation Plan," February 22, 2024, p. 141. [Online.] Available: https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=55773&shareable=true

⁸ Office of Energy Infrastructure Safety, "Data Guidelines, Version 3.1," February 17, 2023, p. 10. [Online.] Available: https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=53475&shareable=true

Exhibits

Exhibit A: Photo Log

Structure ID: 06246012.0121101

Violation 1





Item1IA1Img3: Covered conductor was present to the north of the structure (Left), but no covered conductor was present to the south (Right)