State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 15th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Forest Kaser, Director

October 29, 2026

Paul Marconi
President, Treasurer & Secretary
Bear Valley Electric Service, Inc
42020 Garstin Dr.
Big Bear Lake, CA 92315

NOTICE OF DATA INACCURACY

Mr. Marconi:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Bear Valley Electric Service, Inc. (BVES) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of inaccurate data. Energy Safety therefore issues BVES a Notice of Data Inaccuracy (NODI). Failure to remedy these data inaccuracies may lead to Notices of Non-Performance (NONs) if the inaccuracies cause BVES to miss a WMP target or prevent Energy Safety from ensuring that BVES performed the targets and statements made in BVES's 2025 WMP.

On August 26, 2026, Energy Safety conducted inspections of BVES's 2025 Q3 WMP initiatives in the vicinity of the city of Big Bear Lake, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

1. 8.1.2.1 Covered Conductor: BVES reported covered conductor installation was completed; however, no covered conductor was observed at the locations identified below.

See Table 1, WMP Inspection Data Inaccuracies, for more information.

The data inaccuracies identified in this notice could make it appear as though Bear Valley Electric Service, Inc., reached the target set for its WMP initiatives 8.1.2.1 – Covered Conductor when it has not. If BVES does not address these data inaccuracies and includes the inaccurate data in its reporting regarding WMP initiative 8.1.2.1 – Covered Conductor, Energy Safety may find that BVES failed to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on BVES's WMP performance.

Within 30 days from the issuance date of this NODI, BVES should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,[1] and the associated file name(s) must begin with the NODI identification number (i.e., PAD_BVES_AXS_20260826_1129). The response shall specify which of the Record ID numbers in this NODI it is responding to.

Sincerely,

/s/ Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:
Tom Tzu-Tong Chou, BVES
Tom.Chou@bvesinc.com
Jarred Hennen, BVES
Jared.Hennen@bvesinc.com
Alexander Scott, Energy Safety
Alexander.Scott@energysafety.ca.gov
Yana Loginova, Energy Safety
Yana.Loginova@energysafety.ca.gov
Samuel Isaiah, Energy Safety
Samuel.Isaiah@energysafety.ca.gov
Shannon Greene, Energy Safety
Shannon.Greene@energysafety.ca.gov
AssetPerformance@energysafety.ca.gov

[1] https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI

Table 1: WMP Inspection Data Inaccuracies

Data Inaccuracy Number	Record ID	Actual Structure ID	IOU Provided Structure ID	Grid Hardening ID	QDR Referenced	Lat/Long	WMP Initiative Number	Data Inaccuracy Description
1	PAD_BVES_AXS_20260826_1129	16620BV	16620BV	CC_2025_97	2025 Q3	34.241674, -116.929101	8.1.2.1 Covered Conductor Installation	Failure to provide accurate data on covered conductor installation
2	PAD_BVES_AXS_20260826_1103	No Structure Present	15860BV	CC_2025_6	2025 Q3	34.249864, -116.928001	8.1.2.1 Covered Conductor Installation	Failure to provide accurate data on covered conductor installation

Exhibits

Exhibit A: Photo Log

Data Inaccuracy 1

Structure ID: 16620BV



Data Inaccuracy Img1-1: No covered conductor at this location



Data Inaccuracy Img1-2: Structure ID



Data Inaccuracy Img1-3: No covered conductor at this location.

Data Inaccuracy 2

Structure ID: No Structure ID



Data Inaccuracy Img2-1: Equipment was not present at the reported location.



Data Inaccuracy Img2-2: Equipment was not present at the reported location.



Data Inaccuracy Img2-3: Equipment was not present at the reported location.