State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 15th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Forest Kaser, Director

October 15, 2026

Brandon Tolentino
Vice President, Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF DATA INACCURACY

Mr. Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted inspections of work completed by Southern California Edison Company (SCE) in accordance with its 2026 Wildfire Mitigation Plan (WMP) and determined the existence of inaccurate data. Energy Safety therefore issues SCE a Notice of Data Inaccuracy (NODI).

On July 8, 2026, Energy Safety conducted an inspection of Southern California Edison Company's 2026 Q1 WMP initiatives in the vicinity of the city of Canyon Country, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

1. Long Span Initiative: SCE reported line spacer installation as completed; however, no line spacers were observed at the locations identified below.

See Table 1, WMP Inspection Data Inaccuracies, for more information.

The data inaccuracies identified in this notice could make it appear as though SCE reached the target set in WMP initiatives 8.2.5.1 - Long Span Initiative (LSI), when it has not. If SCE does not address these data inaccuracies and includes the inaccurate data in its reporting regarding WMP initiative 8.2.5.1 – Long Span Initiative (LSI), Energy Safety may find that SCE failed to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2026 Annual Performance Report on SCE's WMP Performance.

Within 30 days from the issuance date of this NODI, SCE should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies. This response shall be filed in the Energy Safety e-Filing system under the 2026 NODI Docket,[1] and the associated file name(s) must begin with the NODI identification number and specify which Record ID number it is responding to.

[1] https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026%20NODI

Sincerely,

Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:
Peter Van Mieghem, SCE
Peter.Vanmieghem@sce.com
Elizabeth Leano, SCE
Elizabeth.Leano@sce.com
Edward Trinh, SCE
Edward.trinh@sce.com
Raghu Rayalu, SCE
Raghu.Rayalu@sce.com
Erick G Sanchez, SCE
Erick.G.Sanchez@sce.com
Sally Jeun, SCE
Sally.Jeun@sce.com
Yana Loginova, Energy Safety
Yana.Loginova@energysafety.ca.gov
Samuel Isaiah, Energy Safety
Samuel.Isaiah@energysafety.ca.gov
Shannon Greene, Energy Safety
Shannon.Greene@energysafety.ca.gov
AssetPerformance@energysafety.ca.gov

Table 1. WMP Inspection Data Inaccuracies

Data Inaccuracy #	Record ID	Actual Structure ID	IOU Provided Structure ID	Grid Hardening ID	QDR Referenced	Lat/Long	WMP Initiative Number	Data Inaccuracy Description
1	PAD_SCE_YLO_20260708_0808	1988304E	1988304E	411831430-1988304E	2026 Q1	34.4105083513192, -118.420669239272	8.2.5.1	Failure to provide accurate data on long span initiative
2	PAD_SCE_YLO_20260708_0819	1988304E	1988304E	411831431-1988304E	2026 Q1	34.4105083513192, -118.420669239272	8.2.5.1	Failure to provide accurate data on long span initiative


Exhibits

Exhibit A: Photo Log

Data Inaccuracy 1

Structure ID: 1988304E

	
DI1-GImg1: Overall Structure	**DI1-GImg2**: Structure ID




DI1-IA1Img1: View showing no line spacers installed

Data Inaccuracy 2

Structure ID: 1988304E

	
DI2-GImg1: Overall Structure	**DI2-GImg2**: Structure ID



DI2-IA1Img1: View showing no line spacers installed