State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 15th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Forest Kaser, Director

October 29, 2026

Brandon Tolentino
Vice President, Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF DATA INACCURACY

Mr. Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2026 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues SCE a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy may lead to a Notice of Non-Performance (NON) if the inaccuracy causes SCE to miss a WMP target or prevents Energy Safety from ensuring that SCE performed the targets and statements made in SCE's 2026 WMP.

On August 24, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Redlands, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Structure ID 1589101E, Grid Hardening ID 413553741-1589101E at coordinates 34.0264110854407, -117.18703623228, the inspector observed that inaccurate data were provided on the long span initiative.

The data inaccuracy identified in this notice could make it appear as though SCE reached the target set in WMP initiative 8.2.5.1 - Long Span Initiative (LSI), when it has not. If SCE does not address this data inaccuracy and includes the inaccurate data in its reporting regarding WMP initiative 8.2.5.1 - Long Span Initiative (LSI), SCE may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2026 Annual Performance Report on SCE's WMP performance.

Within 30 days from the issuance date of this NODI, SCE should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy.

This response shall be filed in the Energy Safety e-Filing system under the 2026 NODI Docket,[1] and the associated file name(s) must begin with the NODI identification number.

Sincerely,

/s/ Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:
Peter Van Mieghem, SCE
Peter.Vanmieghem@sce.com
Elizabeth Leano, SCE
Elizabeth.Leano@sce.com
Cynthia Childs, SCE
Cynthia.Childs@sce.com
Raghu Rayalu, SCE
Raghu.Rayalu@sce.com
Erick G Sanchez, SCE
Erick.G.Sanchez@sce.com
Sally Jeun, SCE
Sally.Jeun@sce.com
Yana Loginova, Energy Safety
Yana.Loginova@energysafety.ca.gov
Samuel Isaiah, Energy Safety
Samuel.Isaiah@energysafety.ca.gov
Shannon Greene, Energy Safety
Shannon.Greene@energysafety.ca.gov
AssetPerformance@energysafety.ca.gov

[1] https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026%20NODI

State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 15th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Forest Kaser, Director

INSPECTION REPORT

Electrical Corporation:	Southern California Edison Company
Report Number:	PAD_SCE_YLO_20260824_1007
Date of Inspection:	August 24, 2026
City and/or County of Inspection:	San Bernardino County
Inspector:	Yana Loginova
WMP Year Inspected:	2026
Quarterly Data Report (QDR) Referenced:	Quarter 1 (Q1)
Inspection Selection:	Energy Safety viewed the contents of the Q1 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.2.5.1 - Long Span Initiative (LSI)
Inspection Purpose:	Assess the accuracy of Southern California Edison Company's QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	1589101E	413553741-1589101E	34.026411085440 7, -117.18703623228	Tier 3	8.2.5.1 - Long Span Initiative (LSI)	Inaccurate data was provided on long span initiative

Observations

Findings:

On Structure ID 1589101E, Grid Hardening ID 413553741-1589101E at 1294 W Sunset Dr, Redlands, CA 92373, USA, 34.0264110854407, -117.18703623228, the inspector observed that no work related to the long span initiative was performed at the location. The inspector's observation is documented in Data Inaccuracy 1 photographs, which are attached to this report as Exhibit A.

Energy Safety concludes that there is inaccurate data because of these facts:

1. Southern California Edison Company's 8.2.5.1 - Long Span Initiative (LSI) work was identified as complete at this location.
2. No electrical lines were observed at the locations.

This observation indicates that the data regarding long span initiative was not accurate. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.

Exhibits

Exhibit A: Photo Log

Structure ID: 1589101E

Data Inaccuracy 1

	
General Image 1: Overall Structure	**Asset Image 1**: View showing that there are no electrical lines present at the location, despite work on the Long Span Initiative being reported as complete at this location.