SOUTHERN CALIFORNIA EDISON®
An EDISON INTERNATIONAL® Company

Brandon Tolentino
VP of Wildfire and Business Resiliency
Brandon.Tolentino@sce.com

September 3, 2026

Patrick Doherty, Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_PAD_SCE_SIS_20260707_0915)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_PAD_SCE_SIS_20260707_0915** which SCE received on **August 6, 2026 (Notice),** based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **July 7, 2026.** SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//
Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_PAD_SCE_SIS_20260707_0915	1	625650E

Summary of Findings:

Energy Safety's Notice states that on July 7, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Canyon Country, California. The inspection report is enclosed herewith. Energy Safety found the following deficiencies:
Deficiency 1. Energy Safety observed that in implementing 2026 WMP initiative 8.3.1 – Distribution High Fire Risk-Informed (HFRI) Inspection – Ground and Aerial (IN-1.1), SCE failed to replace a missing primary avian protection cover on Structure ID 625650E, Grid Hardening ID 414841474-625650E at coordinates 34.4138635296778, -118.465373369502.
Energy Safety states that it "considers this non-performance to be in the Minor risk category."[1]

Response:

The Notice states that the "middle capacitor bushing cover was missing." SCE confirms that all bushing covers on structure 625650E were installed and in place on January 8, 2026, resulting in the closure of notification #414841474. During a subsequent inspection in response to this Notice, SCE's Field Operations team identified that the previously installed middle capacitor bushing cover had become dislodged likely due to environmental exposure or other external factors. SCE will iniatiate a notification to replace the missing middle capacitor bushing cover and will remediate the issue within the applicable 12-month correction timeline.

[1] Notice, p. 1.