SOUTHERN CALIFORNIA EDISON®
An EDISON INTERNATIONAL® Company

Brandon Tolentino
VP of Wildfire and Business Resiliency
Brandon.Tolentino@sce.com

October 8, 2026

Patrick Doherty, Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_PAD_SCE_YLO_20260826_1436)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_PAD_SCE_YLO_20260826_1436** which SCE received on **September 9, 2026 (Notice),** based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **August 26, 2026.** SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//
Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_PAD_SCE_YLO_20260826_1436	1	517907E

Summary of Findings:

Energy Safety's Notice states that on August 26, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Chino Hills, California. The inspection report is enclosed herewith. Energy Safety found the following deficiencies:

Deficiency 1. Energy Safety observed that in implementing 2026 WMP initiative 8.3.1 Distribution High Fire Risk-Informed (HFRI) Inspections - Ground and Aerial (IN-1.1), SCE failed to complete the remediation of buried anchor in a customer's backyard garden on Structure ID 517907E, Grid Hardening ID 413658337-517907E at coordinates 33.9570795865286, -117.767951189578.

Energy Safety states that it "considers this non-performance to be in the Minor risk category."[1]

Response:

The Notice cites a "failure to complete the remediation of a buried anchor." SCE confirms that the buried anchor remediation on structure 517907E was completed on January 5, 2026.

During an inspection conducted in response to this Notice, SCE's Field Operations team observed that the anchor was buried again. The inspection also identified customer activity in the vicinity of the anchor, including landscaping and work associated with a retaining wall. Although SCE was unable to determine when or how the anchor became buried, available information indicates that ground disturbing activities have occurred in the immediate area since the completion of SCE's original remediation work in January 2026.

Following the inspection in response to this Notice, SCE's Field Operations team met with the customer and agreed on the relocation of the anchor. Completion of the relocation is currently estimated to be completed by the end of October 2026.

[1] Notice, p. 1.