SOUTHERN CALIFORNIA EDISON®
An EDISON INTERNATIONAL® Company

Brandon Tolentino
VP of Wildfire and Business Resiliency
Brandon.Tolentino@sce.com

October 30, 2026

Michael Robertson, Supervisory Env. Scientist
Environmental Science Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (**NON_ESD_SCE_RGA_20260916_1150**)

Dear Mr. Robertson:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_ESD_SCE_RGA_20260916_1150** which SCE received on **September 30, 2026 (Notice),** based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **September 9, 2026.** SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//
Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_ESD_SCE_RGA_20260916_1150	1	1735724E

Summary of Findings:

Energy Safety's Notice states that on September 9, 2026, Energy Safety conducted an inspection of SCE's WMP initiatives in the vicinity of the city of Bishop, California in the State Responsibility Area (SRA). The inspection report is enclosed herewith. Energy Safety found the following deficiency:

Deficiency 1. Energy Safety observed that SCE failed to implement its 2026 WMP Compliance Structure Brushing 9.4.1.1 initiative, which requires compliance with Public Resource Code (PRC) 4292, by not maintaining the required radial firebreak distance of ten feet around the base of pole ID 1735724E at coordinates 37.36115887496976, -118.44448605736704. Energy Safety states that it "considers this non-performance to be in the Moderate risk category

Response:

According to SCE's records, structure 1735724E was brushed on 6/17/26 and indicated as "partial brushing" due to inaccessibility from a private property fenced area. On October 1, 2026, SCE's Structure Brushing contractor was dispatched and performed the necessary brushing. The crew was able to access previously inaccessible areas.

Below are photographs from the initial brushing performed on 6/17/26 and the subsequent visit on 10/1/26.



Initial brushing performed on 6/17/26



Brushing performed on 10/1/26



Brushing performed on 10/1/26



Brushing performed on 10/1/26



Brushing performed on 10/1/26



Brushing performed on 10/1/26