



September 30, 2026

Carrie Laird
VP of Wildfire Mitigation and Emergency Operations
PacifiCorp
825 NE Multnomah, Suite 1700
Portland, OR 97232

NOTICE OF DATA INACCURACY

Ms. Laird:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by PacifiCorp (PC) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of inaccurate data. Energy Safety therefore issues PC a Notice of Data Inaccuracy (NODI).

From May 19, 2026, to May 21, 2026, Energy Safety inspected 2025 Q4 WMP initiatives in the vicinity of Etna and Yreka. Energy Safety found the following data inaccuracies: Data Inaccuracies 1-10: 8.1.2.8 Installation of system automation equipment, the inspector observed that PC failed to adhere to data accuracy. No system automation was observed by the inspector at the submitted locations. See Table 1: WMP Inspection Data Inaccuracies and associated photos.

The data inaccuracies identified in this notice could make it appear as though PacifiCorp reached the target set for its WMP initiatives when it has not. Therefore, PacifiCorp may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on PacifiCorp's WMP Performance.

If PacifiCorp chooses to respond to this NODI, response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

/s/ Patrick Doherty
Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI>

Cc:

californiadockets@pacificorp.com

Robert Meredith, PacifiCorp

Robert.Meredith@pacificorp.com

Chelsey Roth, PacifiCorp

Chelsey.Roth@pacificorp.com

Mitchell Harbick, PacifiCorp

Mitchell.Harbick@pacificorp.com

Lakshmi Nair, PacifiCorp

Lakshmi.Nair@pacificorp.com

Melissa Swenson, PacifiCorp

Melissa.Swenson@pacificorp.com

John Garrett, PacifiCorp

john.garrett@pacificorp.com

David Kowalek, PacifiCorp

David.Kowalek@pacificorp.com

Ivan Garcia

Ivan.Garcia@energysafety.ca.gov

Babak Kaviani

Babak.Kaviani@energysafety.ca.gov

Samuel Isaiah

Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety

Shannon.Greene@energysafety.ca.gov

AssetPerformance@energysafety.ca.gov

Table 1: WMP Inspection Data Inaccuracies

Data Inaccuracy #	Record ID	Actual Structure ID	IOU Provided Structure ID	Grid Hardening ID	QDR Referenced	Lat/Long	Initiative Number	Data Inaccuracy Description
1	PAD_PC_CYA_20260519_1312	06242009.0106101	06242009.0106101	7425466	2025 Q4	41.500039881359655, -122.86415653840032	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
2	PAD_PC_CYA_20260519_1337	06242009.0110401	06242009.0110401	7425466	2025 Q4	41.50487623805265, -122.857270640835	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
3	PAD_PC_RMA_20260519_1416	06242009.0111902	06242009.0111902	7425031	2025 Q4	41.511444464309065, -122.8555101376506	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
4	PAD_PC_RMA_20260521_0919	06245007.0229641	06245007.0229641	7221400	2025 Q4	41.73780588401379, -122.63275048783626	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
5	PAD_PC_CYA_20260521_0920	06245007.0228545	06245007.0228545	7221400	2025 Q4	41.7362267167895, -122.635394624455	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
6	PAD_PC_IAG_20260521_1202	06245007.0227545	06245007.0227545	7221400	2025 Q4	41.73667123557792, -122.6370776888446	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.

Data Inaccuracy #	Record ID	Actual Structure ID	IOU Provided Structure ID	Grid Hardening ID	QDR Referenced	Lat/Long	Initiative Number	Data Inaccuracy Description
7	PAD_PC_IAG_20260521_1528	06245007.0 218707	06245007.021 8707	7221402	2025 Q4	41.7392205044699, -122.65340108900726	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
8	PAD_PC_IAG_20260521_1552	06245007.0 222206	06245007.022 2206	7221400	2025 Q4	41.73228332138991, -122.6463764780706	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
9	PAD_PC_IAG_20260521_1604	06245007.0 226441	06245007.022 6441	7221400	2025 Q4	41.7344680627637, -122.63966014470972	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.
10	PAD_PC_IAG_20260521_1614	06245007.0 226542	06245007.022 6542	7221400	2025 Q4	41.73574264218975, -122.63846628209087	8.1.2.8 Installation of system automation equipment	Inaccurate data provided on system automation installation.

Exhibits

Exhibit A: Photo Log

Data Inaccuracy 1

Structure ID: 06242009.0106101

	
Data Inaccuracy Img1-1: No system automation installed	Data Inaccuracy Img1-2: Structure ID - 06242009.0106101

Data Inaccuracy 2

Structure ID: 06242009.0110401



Data Inaccuracy Img2-1: No system automation installed



Data Inaccuracy Img2-2: Structure ID - 06242009.0110401

Data Inaccuracy 3

Structure ID: 062420090054101

	
Data Inaccuracy Img3-1: No system automation installed	Data Inaccuracy Img3-2: Structure ID - 062420090054101

Data Inaccuracy 4

Structure ID: 06245007.0229641

	
Data Inaccuracy Img4-1: No system automation installed	Data Inaccuracy Img4-2: Structure ID - 06245007.0229641

Data Inaccuracy 5

Structure ID: 06245007.0228545

	
Data Inaccuracy Img5-1: No system automation installed	Data Inaccuracy Img5-2: Structure ID - 06245007.0228545

Data Inaccuracy 6

Structure ID: 06245007.0227545



Data Inaccuracy Img6-1: No system automation installed



Data Inaccuracy Img6-2: Structure ID - 06245007.0227545

Data Inaccuracy 7

Structure ID: 06245007.0218707

	
Data Inaccuracy Img7-1: No system automation installed	Data Inaccuracy Img7-2: Structure ID - 06245007.0218707

Data Inaccuracy 8

Structure ID: 06245007.0222206

	
Data Inaccuracy Img8-1: No system automation installed	Data Inaccuracy Img8-2: Structure ID - 06245007.0222206

Data Inaccuracy 9

Structure ID: 06245007.0226441

	
Data Inaccuracy Img9-1: No system automation installed	Data Inaccuracy Img9-2: Structure ID - 06245007.0226441

Data Inaccuracy 10

Structure ID: 06245007.0226542



Data Inaccuracy Img10-1: No system automation installed



Data Inaccuracy Img10-2: Structure ID - 06245007.0226542