825 NE Multnomah St
Portland, OR 97232

October 23, 2026

VIA ELECTRONIC FILING

Docket # 2026 NON

Elizabeth McAlpine
Supervisory Environmental Scientist
Environmental Science Division
Office of Energy Infrastructure Safety
715 P Street, 15th Floor
Sacramento, CA 95814
Elizabeth.McAlpine@energysafety.ca.gov

RE: PacifiCorp's Response to Notice of Non-Performance
NON_ESD_PC_RGA_20260922_1304

Dear Elizabeth McAlpine:

PacifiCorp provides the following response to the finding identified in Notice of Non-Performance NON_ESD_PC_RGA_20260922_1304 (NON), issued by the Office of Energy Infrastructure Safety (Energy Safety) on September 24, 2026. On September 22, 2026, Energy Safety conducted an inspection of PacifiCorp's WMP initiatives in the vicinity of Cedarville, California.

Energy Safety found the following deficiency:

Deficiency 1. Energy Safety observed that PacifiCorp failed to implement its 2026 WMP initiative Routine Clearance 9.2.1.3, which requires compliance with General Order (GO) 95, by not maintaining a four-foot clearance distance around the primary conductors near pole ID 06142015.0030901 at coordinates 41.540509, -120.23388. The Douglas fir tree shows burn marks indicating the possibility of prior contact with, or arcing from, the conductor. Energy Safety considers this non-performance to be in the Moderate risk category. PacifiCorp must complete a corrective action for this non-performance by six months from the date of this notice.

PacifiCorp Response:

In response to the Notice of Non-Performance, PacifiCorp conducted a field review of the reported condition. On September 25, 2026, a vegetation crew pruned the entire span near pole ID 06142015.0030901 to 12-foot specification clearance.

Picture 1: View of the pruned span near pole ID 06142015.0030901 at coordinates 41.540509, -120.23388. Photograph taken September 25, 2026.



Picture 2: View of the pruned span near pole ID 06142015.0030901 at coordinates 41.540509, -120.23388. Photograph taken September 25, 2026.



Picture 3: View of the pruned span near pole ID 06142015.0030901 at coordinates 41.540509, 120.23388. Photograph taken September 25, 2026.



PacifiCorp appreciates the opportunity to provide this response to Energy Safety's NON_ESD_PC_RGA_20260922_1304.

Please refer any questions to Chelsey Roth, Regulatory Projects Manager at 503-813-6895 or via email at Chelsey.Roth@pacificorp.com and californiadockets@pacificorp.com.

Sincerely,

Melissa Swenson
Director, Wildfire Mitigation Program Delivery

cc: sheryl.bilbrey@energysafety.ca.gov
Elizabeth.McAlpine@energysafety.ca.gov
ricardo.garcia@energysafety.ca.gov
Max.Zazzeron@energysafety.ca.gov
environmentalscience@energysafety.ca.gov