CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION

INVESTIGATION REPORT

Date: August 25, 2026
Case No.: C250710002

Violations:

Adalberto Estrella

Government Code § 4216.2(b): Excavating without first notifying the regional notification center.

Bravo Farms Restaurant Inc.

Government Code § 4216.2(b): Excavating without first notifying the regional notification center.

Cal. Code Regs., title 19, § 4151(c): Bravo Farms Restaurant Inc did not cooperate with the investigation.

Executive Summary:

On February 20, 2025, Kinder Morgan reported that its Fresno line rider, Adam Rix, observed Adalberto Estrella using a handheld posthole digger to repair a Bravo Farms billboard near Kinder Morgan's LS-15 pipeline, located near 36220 South Golden State Boulevard in Traver, California. According to Kinder Morgan, the work involved digging postholes approximately 29 inches deep and approximately six feet from Kinder Morgan's pipeline. Kinder Morgan reported that the work was stopped because no valid one-call ticket was in place before excavation began.

During the investigation, Adalberto Estrella told the Board's investigator that Jonathan Van Ryn, associated with Bravo Farms Restaurant Inc., hired him to repair the billboard after it had fallen over. Estrella stated that he used a 4-inch by 4-inch wooden post, concrete, and screws to hold the billboard back up. Estrella also stated that he reported to Jonathan Van Ryn on the progress of the repair. Estrella stated that he did not contact the regional notification center before he began digging because he did not know a ticket was required.

USA North ticket records show that a ticket for Adalberto Estrella was created on February 20, 2025, at 9:01 a.m., after Kinder Morgan reported stopping the work at approximately 8:30 a.m. The legal start date and time for that ticket was February 20, 2025, at 5:01 p.m. The ticket records do not show that Adalberto Estrella or Bravo Farms Restaurant Inc. contacted the regional notification center before excavation began.

The investigation also identified Bravo Farms Restaurant Inc. as the entity for the billboard. The billboard displayed Bravo Farms branding, and California Secretary of State records identified Jonathan Van Ryn as Chief Executive Officer, Secretary, and Chief Financial Officer of Bravo Farms Restaurant Inc. as of April 10, 2025. Bravo Farms Restaurant Inc. did not provide information to the Board during the investigation, despite a telephone call with a Bravo Farms supervisor and a written information request that was delivered to the business address.

Based on the facts gathered, the report finds that Adalberto Estrella excavated without first notifying the appropriate regional notification center. The report also finds that Bravo Farms Restaurant Inc., which hired Adalberto Estrella to repair its billboard, and did not notify the regional notification center before the excavation began. The report further finds that Bravo Farms Restaurant Inc. failed to respond to the Board's information request and did not provide information needed to complete the investigation.

Reporting Party Information:
Kinder Morgan
1550 Solano Way
Concord, California 94520

Date of Incident:
February 20, 2025

Location of the Incident:
36220 South Golden State Boulevard
Traver, California, 93673

Operator:
Kinder Morgan
Regional Notification Center Member Code KMESTK
PO Box 837
Rocklin, California 95677

Excavator:
Adalberto Estella
2327 North Vicki Court
Visalia, California 93291

Subsurface Installation Type Damaged:
No damage

Notification of the Incident
On March 12, 2025, Kinder Morgan submitted a complaint notification (number C241990006) to the Underground Safety Board Case Management System. The notification stated, “ON 2/20/2025 AT 830 AM THE FRESNO LINE RIDER ENCOUNTERED A THIRD-PARTY DIGGING POSTHOLES WITHOUT A VALID ONE CALL TICKET. THIS WORK WAS BEING PERFORMED USING A HANDHELD POST HOLE DIGGER AND WAS APPROXIMATELY 6' FROM LS-15 KM'S PIPELINE. THE LINE RIDER IMMEDIATELY STOPPED THE WORK AND INFORMED THE THIRD PARTY THAT HE MUST HAVE A VALID ONE CALL TICKET BEFORE ANY EXCAVATION COULD CONTINUE. THE LINE RIDER LOCATED THE PIPE, WHICH IS 4' 3' DEEP IN THIS LOCATION. THE POSTHOLES WERE APPROXIMATELY 29' DEEP BUT DID NOT IMPACT HE PIPELINE THAT WAS 6' AWAY, RUNNING PARALLEL.” (Exh. 1.)

Identity of the Excavator
Government Code section 4216(h) defines an excavator as any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with its own employees or equipment, performs any excavation.

The billboard displayed the name “Bravo Farms” in black lettering. (Exh. 2.) During an interview on March 27, 2025, Estrella stated that Jonathan Van Ryn, Chief Executive Officer of Bravo Farms Restaurant Inc., asked him to repair the billboard after it had fallen over. Estrella stated that he used a 4-inch by 4-inch wooden post, concrete, and screws to hold the billboard back up. (Exh. 3.)

Estrella stated he reported to Jonathan Van Ryn on the progress of the repair. During the telephone interview with Estrella, the investigator asked how much Estrella was paid to perform the repair, Estrella refused to disclose the amount. Immediately afterward, Estrella stated that he had not been paid for the day and had not yet received any payment. Furthermore, Estrella stated that he did not have a contractor’s state license. (Exh. 3.)

Estrella stated he had known Jonathan Van Ryn for years and was hired by Jonathan Van Ryn to repair the billboard. Estrella stated to the investigator that he communicated to Jonathan Van Ryn regarding the progress of the repair. (Exh. 3.)

On April 10, 2025, the investigator called Bravo Farms Restaurant Inc. and spoke with a supervisor named Daniel. The investigator informed Daniel that the Board was investigating the repair of the Bravo Farms billboard and asked for Jonathan Van Ryn’s contact information. Daniel declined to provide Jonathan Van Ryn’s contact information but stated that he could deliver a message to him. The investigator provided his telephone number and requested a return call as soon as possible. (Exh. 4.)

No return call was received from Jonathan Van Ryn or any other representative of Bravo Farms Restaurant Inc. (Exh. 4.)

California Secretary of State records identified Jonathan Van Ryn as Chief Executive Officer, Secretary, and Chief Financial Officer of Bravo Farms Restaurant Inc. as of April 10, 2025. (Exh. 5.)

Estrella performed the excavation, and Bravo Farms Restaurant Inc., through Jonathan Van Ryn, hired Estrella to repair the billboard that involved excavation. (Exhs. 2, 3, 5.)

Excavation and Location of the Sign

Government Code section 4216(g) defines "excavation" to be the use of tools or equipment to move or displace earth, rock, or other material in the ground.

During the March 27, 2025, interview, Estrella stated that Kinder Morgan stopped to talk to him when they caught him digging with a posthole digger. Estrella stated work stopped that day and he contacted the regional notification center after talking to Kinder Morgan on February 20, 2025, and later completed the billboard repair on February 27, 2025, while Kinder Morgan was onsite. (Exh. 3.)

Kinder Morgan reported that the billboard was located near 36220 South Golden State Boulevard, approximately one mile south of Traver, California, on the east shoulder of the northbound lanes of Highway 99. (Exh. 2.)

The investigator asked Estrella whether he had received permission from the property owner to work on the billboard. Estrella stated that he did not install the billboard and that it was already there, like other signs installed along the highway. (Exh. 3.)

Kinder Morgan provided its Liquids O&M Form to the investigator. The form included three photographs taken by Kinder Morgan employee Adam Rix. The form stated that the work was performed with a handheld posthole digger approximately six feet from Kinder Morgan's pipeline, that the line rider stopped the work, and that the postholes were approximately 29 inches deep and did not impact the pipeline. (Exh. 2.)



Photo 1 provided by Kinder Morgan as an attachment to the O&M Form depicting the location of the billboard installation near the LS 50 Pipeline. (Exh. 2.)



Photo 2 provided by Kinder Morgan as an attachment to the O&M Form depicting the location of the billboard installation near the LS 50 Pipeline. (Exh. 2.)



Photo 3 provided by Kinder Morgan as an attachment to the O&M Form depicting the location of the billboard installation near the LS 50 Pipeline. (Exh. 2.)

The Excavators Did Not Contact the Regional Notification Center Before Repairing the Sign

Government Code section 4216.2(b) provides that, except in an emergency, an excavator planning to conduct an excavation shall notify the appropriate regional notification center of the excavator's intent to excavate at least two working days before beginning that excavation. The date of the notification does not count as part of the two-working-day notice.

On February 20, 2025, Kinder Morgan reported that its line rider observed Estrella digging postholes near Kinder Morgan's LS-15 pipeline at approximately 8:30 a.m. The work was being performed with a handheld posthole digger and was approximately six feet from the pipeline. Kinder Morgan reported that the line rider stopped the work and informed Estrella that a valid one-call ticket was required before excavation could continue. (Exhs. 1, 2.)

During his interview, Estrella stated that Jonathan Van Ryn asked him to repair the Bravo Farms billboard after it had fallen over. Estrella stated that the repair required him to use a 4-inch by 4-inch wooden post, concrete, and screws to hold the billboard back up. Estrella also stated that he reported to Jonathan Van Ryn on the progress of the repair. Estrella stated that he did not contact the regional notification center before beginning the work because he did not know a ticket was required. (Exh. 3.)

Estrella performed the excavation after Jonathan Van Ryn hired him to repair the Bravo Farms billboard, and Estrella reported back to Jonathan Van Ryn about the progress of the work. California Secretary of State records identified Jonathan Van Ryn as the Chief Executive Officer, Secretary, and Chief Financial Officer of Bravo Farms Restaurant Inc. as of April 10, 2025. (Exhs. 2, 3, 5.)

The investigator requested ticket records from USA North for the location and date of the work. USA North provided ticket 2025022000713-000 for Estrella. That ticket was created on February 20, 2025, at 9:01 a.m. The ticket listed the address as CA-99, Kingsburg, California 93631, with a nearby cross street of Merritt Drive. The work type was listed as road work. The ticket's legal start date and time was February 24, 2025, at 5:01 p.m., and the ticket expired on March 20, 2025, at 11:59 p.m. (Exh. 7.)

Kinder Morgan reported that the excavation was observed and stopped at approximately 8:30 a.m. on February 20, 2025. Because ticket 2025022000713-000 was created at 9:01 a.m., the ticket was created after the excavation had already begun. The legal start time for the ticket was also after the excavation had already begun. (Exhs. 1, 7.)

USA North also provided ticket 2025022000624-000. That ticket was created on February 20, 2025, at 8:41 a.m. USA North created cancelled ticket 2025022000624-001because the caller changed in start time on February 20, 2025, at 9:06 a.m. The ticket records provided by USA North show the Adalberto Estrella as the excavator and have excavator remarks of "At a Point approximately 1.67 Mi SE of Merritt Dr on NE Side of CA-99 (GPS: 36.43201, -119.47439), To Include 15' Radius" for ticket 2025022000713-000 and ticket 2025022000624-000. (Exh. 7.)

The investigator also reviewed ticket 2025030300441-000, which USA North provided in response to the investigator's ticket search request for 36220 South Golden State Boulevard. That ticket identified Tulare County Traffic Control as the excavator and listed the work activity as "Signs – Street/Highway/Pole Structures/Ect." The ticket did not identify Estrella, Bravo Farms Restaurant Inc., or Jonathan Van Ryn as the excavator or caller for the February 20, 2025, billboard repair. (Exh. 6.)

The ticket records reviewed during the investigation do not show that Estrella, Bravo Farms Restaurant Inc., or Jonathan Van Ryn notified the regional notification center before excavation began on February 20, 2025. (Exhs. 6, 7.)

Estrella performed excavation before notifying the regional notification center. Bravo Farms Restaurant Inc., through Jonathan Van Ryn, arranged for or authorized the repair work that required excavation, and no regional notification center ticket was obtained before that excavation began. (Exhs. 1, 2, 3, 5, 6, 7.)

Bravo Farms Restaurant Inc. Did Not Respond to the Information Requests

California Code of Regulations, title 19, section 4151(c) provides that an excavator who obstructs an investigation by taking actions that were known or reasonably should have been known to prevent, hinder, or impede an investigation is subject to sanctions under the Act and the Board's regulations.

Bravo Farms Restaurant Inc. did not provide information to the Board during the investigation. As a result, the investigator relied on information obtained from Kinder Morgan, Estrella, USA North, and publicly available business records.

On April 10, 2025, the investigator called Bravo Farms Restaurant Inc.'s main office and spoke with a supervisor named Daniel. The investigator requested to speak with Jonathan Van Ryn or obtain his contact information to learn more about the billboard repair. Daniel declined to provide that information but stated that he could deliver a message to Jonathan Van Ryn. The investigator provided his telephone number and requested that Jonathan Van Ryn return the call as soon as possible. (Exh. 4.)

During the call, the investigator informed Daniel that the Board was investigating the excavation that occurred for the billboard and required a response. The investigator also informed Daniel that if no response or return call was received, an information request letter would be sent to Bravo Farms Restaurant Inc. (Exh. 4.)

On April 16, 2025, the investigator mailed Information Request IR-2025-103 to Bravo Farms Restaurant Inc. The response was due by May 1, 2025. USPS tracking showed that the letter was delivered to an individual at the address on April 19, 2025, at 3:02 p.m. Bravo Farms Restaurant Inc. did not respond to the information request. (Exh. 8.)

On May 5, 2025, the investigator mailed a second information request, IR-2025-2-061, to Bravo Farms Restaurant Inc. The second information request was not delivered due to "No Authorized Receipt Available." (Exh. 9.)

Bravo Farms Restaurant Inc. did not provide information to the Board during the investigation. Bravo Farms Restaurant Inc.'s failure to respond hindered the investigation because the investigator was unable to obtain information from Bravo Farms Restaurant Inc. regarding the billboard, the scope of work, whether Bravo Farms Restaurant Inc. had any ticket information, and whether Bravo Farms Restaurant Inc. had additional information relevant to the excavation. (Exhs. 4, 8, 9.)

Findings:

1. Kinder Morgan operates and maintains the LS-15 pipeline near the billboard location.
2. On February 20, 2025, at approximately 8:30 a.m., Kinder Morgan observed Estrella using a posthole digger 6 feet from Kinder Morgan's LS-15 pipeline.
3. The posthole work was excavation because it involved digging into the ground repair and support a billboard.
4. Estrella stated that Jonathan Van Ryn asked him to repair the Bravo Farms billboard after it had fallen over.

5. Estrella stated that he reported to Jonathan Van Ryn on the progress of the repair. (Exh. 3.)
6. California Secretary of State records identified Jonathan Van Ryn as Chief Executive Officer, Secretary, and Chief Financial Officer of Bravo Farms Restaurant Inc. as of April 10, 2025.
7. Estrella did not notify the regional notification center before beginning excavation.
8. Ticket 2025022000713-000 for Estrella was created on February 20, 2025, at 9:01 a.m., after Kinder Morgan stopped the excavation.
9. The legal start date and time for ticket 2025022000713-000 was February 24, 2025, at 5:01 p.m., after the excavation had already begun.
10. No ticket records were located by the regional notification center for Bravo Farms Restaurant Inc. or Jonathan Van Ryn to notify the regional notification center at least two working days before the excavation began.
11. Adalberto Estrella refused to answer the Board investigator's question as to how much he was paid for the work during an interview
12. Bravo Farms Restaurant Inc. did not provide information to the Board during the investigation, despite a telephone contact and a delivered written information request.
13. Bravo Farms Restaurant Inc.'s nonresponse hindered the investigation by preventing the investigator from obtaining information directly from Bravo Farms Restaurant Inc. about the billboard, the repair work, the relationship with Estrella, and any ticket-related information.

Investigator	Supervisor
Adrian Anaya	Anona Bonner
Signature	Signature
/s/Adrian Anaya	/s/*Anona Bonner*

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 03/12/2025	Jason Brothers, Damage Prevention, Kinder Morgan
2.	Board's Information Request to Kinder Morgan Kinder Morgan's response to the Board's Information Request	Emailed on 03/21/2025 Received on 03/24/2025	Jason Brothers, Damage Prevention, Kinder Morgan
3.	Summary of Telephone Interview with Adalberto Estrella	Called on 03/27/2025	
4.	Summary of Telephone Conversation with Bravo Farm Restaurant Inc.'s Supervisor	Called on 04/10/2025	
5.	California Secretary of State Information for Bravo Farms Restaurant Inc.	Downloaded on 04/10/2025	https://www.sos.ca.gov/
6.	Ticket search request to Underground Service Alert of Northern California Ticket search results provided by the Underground Service Alert of Northern California	Submitted on 03/13/2025 Received on 03/15/2025	Nick White, Member Services Manager, Underground Service Alert of Northern California
7.	Additional ticket search request to the Underground Service Alert of Northern California	Emailed on 05/30/2025	Nick White, Member Services Manager, Underground Service Alert of Northern California

	Ticket search results provided by the Underground Service Alert of Northern California	Received on 06/02/2025	
8.	Information Request mailed to Bravo Farm Restaurant Inc. with the United States Postal Service tracking history	Mailed on 04/16/2025	
9.	2nd Information Request mailed to Bravo Farm Restaurant Inc. with the United States Postal Service tracking history	Mailed on 05/05/2025	

Exhibit 1

Notification Information Report

Information for Notification Number:- C250710002

Date Logged to CRM:- **3/12/2025 11:00 AM**

Complaint/Incident Information	
Incident/Complaint Description	ON 2/20/2025 AT 830 AM THE FRESNO LINE RIDER ENCOUNTERED A THIRD-PARTY DIGGING POSTHOLES WITHOUT A VALID ONE CALL TICKET. THIS WORK WAS BEING PERFORMED USING A HANDHELD POST HOLE DIGGER AND WAS APPROXIMATELY 6' FROM LS-15 KM'S PIPELINE. THE LINE RIDER IMMEDIATELY STOPPED THE WORK AND INFORMED THE THIRD PARTY THAT HE MUST HAVE A VALID ONE CALL TICKET BEFORE ANY EXCAVATION COULD CONTINUE. THE LINE RIDER LOCATED THE PIPE, WHICH IS 4' 3' DEEP IN THIS LOCATION. THE POSTHOLES WERE APPROXIMATELY 29' DEEP BUT DID NOT IMPACT THE PIPELINE THAT WAS 6' AWAY, RUNNING PARALLEL.
Incident Date	2/20/2025 7:30 AM
Incident State	CA
Incident County	Tulare
Incident Place	Traver
Incident St from Address	36220
Incident St to Address	36220
Incident Street	S. Golden Sate Blvd
Incident Cross1	
Incident Location	
Type of Complaint	Excavating without 811 ticket
Other Complaint Detail	NONE
Notification Number	C250710002
Notification Created	3/12/2025 10:59 AM
Notification Type	complaint
Damage Injury	Undefined
Damage Death	Undefined
Damage Fire Evacuation	Undefined
Damage Facility Type	
Damage Equipment	

Reporter Information	
Reporter First Name	Jason
Reporter Middle Name	
Reporter Last Name	Brothers
Reporter Company	Kinder Morgan Inc.
Reporter Email	brothersj@kindermorgan.com
Reporter Phone	5593331799
Reporter Address	6050 #B Pacific St.
Reporter Address 2	
Reporter City	Rocklin
Reporter State	CA
Reporter Zip	95677

Other Party Information	
First Name	Adalberto
Middle Name	
Last Name	Estrella
Company	Bravo Farms
Address	2327 N. Vicki Ct.
City	Visalia
State	CA
Zip Code	93291
Email	
Phone	5598700052

Ticket Entry	
Ticket Number	
Ticket Type	
Revision	
Created	
Account	
Channel	
Work Date	
Response Required	
Response Due	
Expires	
One Year	
Priority	
Priority Number	
Category	
Lookup	
State	
County	
Place	
Work area zip code	
St to address	
St from address	
Street	
Cross 1	
Cross 2	
How delineated	
Excav st walk	
Work Type	
Boring	
Explosives	
Vacuum	
Permit	
Work Order	
Done For	
Remarks Type	
Company Name	
Address1	
Address2	
City	

State	
Zip Code	
Phone	
Phone ext	
Caller	
Caller Language	
Cell	
Email	
Contact Name	
Contact Phone	
Contact Phone Ext	
Contact Cell	
Contact Email	
Location	
Comments	
Map URL	MAP URL of Notification Number C250710002

Ticket GPS Coordinates

Caller GPS Coordinates		
Name	Latitude	Longitude

Best Fit Rectangle GPS Coordinates		
Name	Latitude	Longitude

Ticket Member List

Member Code

Exhibit 2

From:	Brothers, Jason
To:	Anaya, Adrian@EnergySafety
Subject:	RE: Request for information for notification number C250710002 regarding excavation activities near a high-pressure petroleum pipeline near 36220 South Golden State Boulevard, Traver, CA
Date:	Monday, March 24, 2025 12:33:21
Attachments:	image002.png image001.png LS-15 MP 74.59 L_OM200-37.docx

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Please see attached.

Jason Brothers
Kinder Morgan Inc.
6050 Pacific St. #B
Rocklin, CA. 95677
916-303-9090 office
559-333-1799 cell

From: Anaya, Adrian@EnergySafety <Adrian.Anaya@energysafety.ca.gov>
Sent: Friday, March 21, 2025 2:47 PM
To: Brothers, Jason <BrothersJ@kindermorgan.com>
Subject: Request for information for notification number C250710002 regarding excavation activities near a high-pressure petroleum pipeline near 36220 South Golden State Boulevard, Traver, CA

You don't often get email from adrian.anaya@energysafety.ca.gov. Learn why this is important
[This email message was received from the Internet and came from outside of Kinder Morgan.]

WARNING: EXTERNAL EMAIL: PROCEED WITH CAUTION.

Do not respond, click on links or open attachments unless you recognize the sender or know the content is safe.

Hello,

I attached the Information Request. Please contact me if you have any questions.

Thank you,
Adrian Anaya
Investigator
Office of Energy Infrastructure Safety
Mobile: (279) 245-1133
EnergySafety.ca.gov



State of California – A Natural Resources Agency
Gavin Newsom, Governor

OFFICE OF ENERGY INFRASTRUCTURE SAFETY
UNDERGROUND SAFETY BOARD
715 P Street, 20th Floor | Sacramento, CA 95814
916.902.6000 | *www.energysafety.ca.gov*

MEMBERS
Amparo Munoz, Chair
Bill Johns, Vice Chair
Randy Charland
Marshall Johnson
Dave Sorem
Carl Voss

EXECUTIVE OFFICER
Tony Marino

TRANSMITTED VIA ELECTRONIC MAIL

Request Date: March 21, 2025

Response Due: April 7, 2025

To: Kinder Morgan
Jason Brothers, Damage Prevention/Right of Way Specialist
6050 Pacific Street #B, Rocklin, California 95677
brothersj@kindermorgan.com

Investigator: Adrian Anaya

Send your response to the investigator at this email address:

Adrian.Anaya@energysafety.ca.gov

Information Request Number: Underground Safety-IR-2025-087

Subject: Request for information for notification number C250710002 regarding excavation activities near a high-pressure petroleum pipeline near 36220 South Golden State Boulevard, Traver, California 93673 on February 20, 2025.

REQUESTS

1. Provide the incident report and any other documentation relating to the excavation near a high-pressure petroleum pipeline, including, but not limited to, photographs,

interview notes, communications via email, phone, or other digital or related correspondence.

2. Provide all documents that relate to any communication between Regional Notification Center and Kinder Morgan. This includes copies of any emergency tickets obtained, verification of no tickets, and any other tickets pertaining to the investigation.

3. Provide photograph of locate and marks that was done at the site.

INSTRUCTIONS

a. Provide all information in your possession, custody, or control, or the possession, custody, and/or control of your affiliates or agents, that is responsive to these requests by the due date identified above.
b. Identify the personnel (employees, consultants, agents, etc.) who provided information responsive to each of the information requests by stating the full name, business address, and title of each person.
c. If you do not know the exact answer to any of the requests above, please so indicate and provide your best estimate.
d. Provide data in its original format (i.e., PDF, Excel, GIS shapefile, etc.), unless otherwise specified in the request.

1. GENERAL INFORMATION:

Date Incident Discovered:	**2/20/2025**
Approximate Discovery Time:	**830am**
Date work performed, if known:	**2/20/2025**
How Discovered:	**Line Rider Patrolling ROW**
Incident Description:	**Fresno Line Rider encountered a third-party digging postholes without a valid One Call ticket.**

2. KM PIPELINE INFORMATION:

Date of Previous Aerial Patrol:	**2/19/24**
Visible During Aerial Patrol (Y/N):	☐ **Yes** ☒ **No**
Line Section/Pipeline Name:	**15**
ROW Section:	**22**
Easement Type (Fee/Permit/Other)	☐ **Fee** ☒ **Permit** ☐ **Other**
If Other, explain:	
High Consequence Area (Y/N):	☒ **Yes** ☐ **No**
Pipeline Depth(s):	**4'3" Per electronic readings**
Station #:	**3938+35**
PLMP#:	**74.59**

3. PROPERTY OWNER INFORMATION:

Property Owner:	**Union Pacific Railroad**
Incident Street Address:	**36220 S. Golden State Blvd**
County:	**Tulare**
City:	**Traver**
State:	**CA**
Nearest Cross Road:	**6th St.**
Latitude:	**36.431933,**
Longitude:	**-119.474207**

4. CONTRACTOR INFORMATION:

Contractor/Utility:	**Bravo Farm**
Contractor Owner/Manager:	**Adalberto Estrella**
Contractor Address:	**2327 N Vicki CT, Visalia CA. 93291**
Contractor Phone#:	**559-870-0052**
One Call Ticket Number:	**No valid USA**
Equipment Involved:	**Hand tools**

5. OTHER INCIDENT / INVESTIGATION INFORMATION:

Load Stress Calculation Required? (Y/N)	☐ **Yes** ☒ No
Load Stress Calculation (if applicable):	N/A
Did Encroachment Cross Line (Y/N):	☐ **Yes** ☒ **No**
Incident ID:	**3389536**
State Reporting Required. (Y/N):	☒ **Yes** ☐ **No**
State Reporting Documentation (if applicable):	LS-15 MP 74.59.pdf
Photographs:	

Highlighting indicates revisions made as of the date on this form.

	 
Findings:	**This work was being performed using a handheld post hole digger and was approximately 6' from LS-15, an Out of Service KM pipeline. The line rider immediately stopped the work and informed the third party that he must have a valid One Call ticket before any excavation could continue. The line rider located the pipe, which is 4' 3" deep in this location. The postholes were approximately 29" deep but did not impact the OOS pipeline that was 6' away, running parallel.**
Corrective Actions:	**Notified the excavator of the importance of having a valid One-Call ticket and following USA North's One-Call Laws and Kinder Morgan's (KM) construction guidelines and Damage Prevention Procedures and the importance of having a KM Representative on-site for all work within 10' of KM.**
L-O&M 200-32:	LS-15 MP 74.59 200-32 Traver encroa
L-O&M 200-71:	LS-15 MP 74.59 200-71 Excavation Site
L-O&M 200-72/Aerial Patrol (if applicable):	**N/A**
L-O&M 200-02/200-04 (if applicable):	**N/A**
Dirt Report:	DIRT-18718.pdf

KINDER MORGAN

LIQUIDS O&M FORM

No.: L_OM200-37
Title: Unauthorized Right-of-Way Encroachment Package
Revised: 09-28-2023

Warning Letter:	Warning Letter LS-15 MP 74.59.pdf
Submitter Name:	**Jason Brothers**
Approver Name:	**Mike LaPeaux**

Highlighting indicates revisions made as of the date on this form.

200-32 Public Awareness/Liaison Record

Stakeholder Information

Event/Company: Bravo Farms Contact Name: ADALBERTO ESTRELLA Title: Foreman Email: ADALBERTO96ESTR@GMAIL.COM	Address: 2327 N VICKIE CT City: Visalia State: CA Zip: 93291 County: Tulare	Phone Number: Cell Phone Number: 559-870-0052 Fax Number: Alt. Phone Number: Meeting Date: 2025-02-27

Details

Stakeholder Type: Excavtors/Contractors Contact Type: Face-to-Face Meeting Contact Made?	PA Website information Request? Materials Provided? PA Toolkit Reason for Meeting: Response to encroachment.

Kinder Morgan Information

KM Rep: Adam Rix Date of Submission: 2025-02-27	KM Entity: LS 15 Operating Region: PNR

Signature


Project Photos

KINDER MORGAN

200-71 Excavation Site Inspection

Which Company is using this form? PRODUCTS One Call

Ticket Number 2025022000713

GPS: 36.43201, -119.47439

Begin Work Date/Time	Excavation within 50ft of Pipeline	Have marks been placed?	Copy of the sketch supplied to the excavator?
Feb 27, 2025, 8:00:00 AM	YES	Feb 20, 2025, 11:05:00 AM	YES

Location of Encroachment: Worksite is 1 mile south of Traver Ca on the east shoulder of northbound lanes of Highway 99.

Scope of work is replacing post on highway (small) billboard sign, approximately 6 feet west of line section 15.Excavator will be using hand tools for excavation.

Excavator agrees no excavation with in 10 ft of KM LS 15, unless KM representative is present. Also a 48 hour notice is required be fore work can be completed that requires a KM representative.

Excavator Representative	Excavator Company	Excavator Phone Number	Excavator Signature

KINDER MORGAN

200-71 Excavation Site Inspection

ADALBERTO ESTRELLA	Bravo farms	559-870-0052	

Excavator agrees no excavation with 10 feet of KM line section 15 unless cam representative is on site

Notice to Excavator

Excavation equipment and blasting can damage pipelines/facilities resulting in the release of product which may cause serious injuries and/or death and severe damage to the environment.

No excavation is allowed within _____ feet of any Kinder Morgan (KM) pipeline/facility unless a KM representative is onsite or has given explicit exception. All excavation within _____ inches of a KM pipeline/facility must be done either using hand tools or, with approval, a hydrovac, unless state requirements are more stringent and require a larger tolerance zone.

To avoid damaging pipelines/facilities:


- Look for evidence of a pipeline including such things as caution signs, aerial patrol markers, casing vents and above ground piping. When excavating, you may encounter warning tape. If you encounter warning tape while excavating, cease excavation and contact the Kinder Morgan representative immediately.
- Never assume the location of pipelines because:
  - Pipelines can change directions abruptly between above ground physical evidence.
  - Pipeline depths can vary substantially in short distances.
  - More than one pipeline may be present.
- Call Kinder Morgan and 811 to have all pipelines/facilities approximately located, and to have a representative provide on-site assistance before ANY excavation activity begins (both are FREE services).
- **Excavator/Contractor has been made aware of Kinder Morgan Policies and Procedures.**

No excavation is allowed with (feet) without KM Represenative: 10

All excavation within (inches) of KM pipeline must be done using hand tools: 24

Excavator Meeting Date/Time: Feb 27, 2025, 8:00:00 AM

Kinder Morgan Representative	Kinder Morgan Phone Number	Kinder Morgan Signature
Adam Rix	559-818-3864	



Project Photos

Damage Information Reporting Tool (DIRT) - Field Form

Rev: 5/10/18
'*' indicates a Required Field

Part A - Who is Submitting This Information

Who is providing the information?

- ☐ Excavator
- ☐ Natural Gas
- ☐ Electric
- ☐ Locator
- ☐ Equipment Manufacturer
- ☐ Railroad
- ☐ Private Water
- ☑ Liquid Pipeline
- ☐ Public Works
- ☐ Unknown/Other
- ☐ Road Builders
- ☐ Federal/State Regulator
- ☐ Engineer/Design
- ☐ Telecommunications

Impact Supervisor/Manager: _____

Part B - Date and Location of Event

***Date of Event:** 2/20/2025 (MM/DD/YYYY)

***Country:** US ***State:** CA ***County:** Tulare **City:** Traver

Street address: 36220 S Golden State Blvd **Nearest Intersection:** 6th St

Latitude/Longitude: **Lat:** 36.431933 **Lon:** -119.474207

***Right of Way where event occurred**

Public:
- ☐ City Street
- ☐ State Highway
- ☐ County Road
- ☐ Interstate Highway
- ☐ Public-Other

Private:
- ☐ Private Business
- ☐ Private Land Owner
- ☐ Federal Land
- ☐ Private Easement
- ☐ Dedicated Public Utility Easement
- ☐ Pipeline
- ☐ Power/Transmission Line
- ☑ Railroad
- ☐ Data not collected
- ☐ Unkown/Other

Part C - Affected Facility Information

***What type of facility operation was affected?**

- ☐ Cable Television
- ☐ Electric
- ☐ Natural Gas
- ☑ Liquid Pipeline
- ☐ Sewer
- ☐ Steam
- ☐ Telecommunications
- ☐ Water
- ☐ Unknown/Other

***What type of facility was affected?**

- ☐ Distribution
- ☐ Gathering
- ☐ Service/Drop
- ☑ Transmission
- ☐ Unknown/Other

Was the facility part of a joint trench?
- ☐ Unknown
- ☐ Yes
- ☑ No

Did this event involve a Cross Bore?
- ☐ Yes
- ☑ No

Was the facility owner a member of One-Call Center?
- ☐ Unknown
- ☑ Yes
- ☐ No

If No, is facility owner exempt from One Call Center membership?
- ☐ Yes
- ☐ No

Measured Depth From Grade?
- ☐ Embedded in concrete/asphalt pavement
- ☐ <18in / 46cm
- ☐ 18in - 36in / 46 - 91cm
- ☑ >36in / 91cm

Measured depth from grade: _____ in/cm

Part D - Excavation Information

***Type of excavator**

- ☐ Contractor
- ☐ County
- ☐ Developer
- ☐ Farmer
- ☐ Municipality
- ☐ Railroad
- ☐ State
- ☐ Utility
- ☑ Occupant
- ☐ Unknown/Other

***Type of Excavation Equipment**

- ☐ Auger
- ☐ Backhoe/Trackhoe
- ☐ Boring
- ☐ Drilling
- ☐ Directional Drilling
- ☐ Explosives
- ☐ Farm Equipment
- ☐ Grader/Scraper
- ☑ Hand Tools
- ☐ Bulldozer
- ☐ Probing Device
- ☐ Trencher
- ☐ Vacuum Equipment
- ☐ Milling Equipment
- ☐ Unkown/Other

***Type of Work Performed**

- ☐ Agriculture
- ☐ Cable Television
- ☐ Curb/Sidewalk
- ☐ Bldg. Construction
- ☐ Bldg. Demolition
- ☐ Drainage
- ☐ Driveway
- ☐ Electric
- ☐ Engineering/Survey
- ☑ Fencing
- ☐ Grading
- ☐ Irrigation
- ☐ Landscaping
- ☐ Liquid Pipeline
- ☐ Milling
- ☐ Natural Gas
- ☐ Pole
- ☐ Public Transit Auth.
- ☐ Railroad Maint.
- ☐ Road Work
- ☐ Sewer (San/Storm)
- ☐ Site Development
- ☐ Steam
- ☐ Storm Drain/Culvert
- ☐ Street Light
- ☐ Telecommunication
- ☐ Traffic Signal
- ☐ Traffic Sign
- ☐ Water
- ☐ Waterway Improv.
- ☐ Unknown/Other

Part E - Notification

***Was the One-Call Center notified prior to excavation?** ☐ Yes ☑ No **Ticket # ?** _____ **Call Center:** _____

If yes, type of Locator
- ☐ Facility Owner
- ☐ Contract Locator
- ☐ Unknown/Other

If No, is excavation activity and/or excavator exempt from notification?
- ☐ Yes
- ☐ No
- ☐ Unknown/Other

Was work area white-lined?
- ☐ Yes
- ☑ No
- ☐ Unknown/Other

Part F - Intentionally left blank

Rev: 5/10/18

'*' indicates a Required Field

Part G - Excavator Downtime

Did Excavator incur down time?

☐ Yes ☑ No

If yes, how much time?

☐ < 1hr ☐ 1 - < 2hrs ☐ 2 - < 3hrs ☐ 3+ hrs Exact Value: _____ ☐ Unknown

Estimated cost of down time?

☑ $0 ☐ $1 - 1000 ☐ $1,001 to 5,000 ☐ $5001 to 25,000 ☐ $25,001 to 50,000

☐ >$50,000 Exact Value: _____ ☐ Unknown

Part H - Description of Damage

***Did the damage cause an interruption in service?**

☐ Yes ☑ No ☐ Unknown/Other

If yes, duration of Interruption

☐ < 1 hr ☐ 1 - < 6hrs ☐ 6 - <12hrs ☐ 12 - <24hrs ☐ 24 - < 48hrs

☐ 48+ hrs Exact Value: _____ ☐ Unknown

Approximately how many customers were affected?

☐ Unknown ☑ 0 ☐ 1 ☐ 2 to 10 ☐ 11 to 50 ☐ 51+ Exact Value: _____

Estimated cost of damage/repair/restoration

☑ $0 ☐ $1 - 1,000 ☐ $1,001 to 5,000 ☐ $5,001 to 25,000

☐ $25,001 to 50,000 ☐ > $50,000 Exact Value: _____ ☐ Unknown

*Part I - Description of the Root Cause *Please Choose one

Notification Issue

☑ No notification made to the One Call Center/ 811

☐ Excavator dug outside area described on ticket

☐ Excavator dug prior to valid start date/time

☐ Excavator dug after valid ticket expired

☐ Excavator provided incorrect notification information

Excavation Issue

☐ Excavator dug prior to verifying marks by test-hole (pothole)

☐ Excavator failed to maintain clearance after verifying marks

☐ Excavator failed to protect/shore support facilities

☐ Improper backfilling practices

☐ Marks faded or not maintained

☐ Improper excavation practice not listed above

Locating Issue

Facility not marked due to:

☐ Abandoned facility

☐ Incorrect facility records/maps

☐ Locator error

☐ No response from operator/contract locator

☐ Tracer wire issue

☐ Unlocatable Facility

Facility marked inaccurately due to

☐ Abandoned facility

☐ Incorrect facility records/maps

☐ Locator error

☐ Tracer wire issue

Miscellaneouse Root Causes

☐ Deteriorated facility ☐ One Call Center Error ☐ Previous damage

☐ Root Cause not listed (comment required)

Part J - Additional Comments

Installing fence posts without a valid One-call.

Rev: 5/10/18

'*' indicates a Required Field

Part K - Supplemental Questions

Was there damage to a pipeline facility?

☐ Yes ☑ No

Did excavator notify pipe operator of damage directly?

☐ Unknown ☐ Yes ☑ No

Date One Call Center was notified: _____

Did excavator wait 48 hours prior to excavating?

☐ Unknown ☐ Yes ☑ No

Did the pipeline operator provide a positive response to first notification?

☐ Unknown ☐ Yes ☑ No

(If Yes) Date of positive response: _____ **Time:** _____

Did Excavator make a second call to the One Call Center?

☐ Unknown ☐ Yes ☑ No

Reason for second call?

☐ No positive response to first call ☐ All clear appears questionable ☐ Positive response is unclear or incorrect

Other: _____

Second notice ticket number? _____

The date of second notice? _____

Did the pipeline operator provide a positive response to the second notification? **Positive Response Date?** **Response Time?**

☐ Unknown ☐ Yes ☑ No _____ _____

Organization that performed the locate?

☐ Pipeline Operator ☐ Utility Owner ☐ Contract Locator ☐ Data Not Collected ☐ Unknown / Other

Explanation of Other locator? _____

Name of locator? _____

Method used to locate?

☐ Conductive ☐ Inductive ☐ Other N/A

Describe Other Method: _____

Was Paint a type of marking used?

☐ Unknown ☐ Yes ☐ No

Were Flags a type of marking used?

☐ Unknown ☐ Yes ☐ No

Were Laths a type of marking used?

☐ Unknown ☐ Yes ☐ No

Was Other type of marking used?

☐ Unknown ☐ Yes ☐ No

Description of other type of marking used: _____

Were Special Instructions a part of the locate ticket?

☐ Unknown ☐ Yes ☐ No

Were maps used during marking?

☐ Unknown ☐ Yes ☐ No

Did the locator meet with the excavator at the time of the marking?

☐ Unknown ☐ Yes ☑ No

Were company representatives on site at the time of the excavation?

☐ Unknown ☐ Yes ☑ No

Did the operator follow their Damage Prevention/Locating Procedures?

☐ Unknown ☐ Yes ☑ No

Were Whiskers a type of marking used?

☐ Unknown ☐ Yes ☑ No

Rev: 5/10/18

'*' indicates a Required Field

Part K - Supplemental Questions Continued...

Was the RRC called to report the damage?

☐ Yes ☑ No

Did the excavator notify the pipeline operator of damage through the notification center?

☐ Unknown ☐ Yes ☐ No

The One Call center that was notified? _____

The Dig Up ticket number from the One Call Notification Center? _____

What product was being transported?

☐ Natural or Other Gases ☐ Hazardous Liquid ☐ Unknown

Pipeline is?

☐ Active ☑ Idle ☐ New Pipe (no product) ☐ Abandoned

Pipeline Material?

☐ Bare Steel ☑ Coated Steel ☐ Cast Iron ☐ Polyethylene Plastic

☐ Poly Vinyl Chloride Plastic (PVC) ☐ Other

Damage occurred to?

☐ Body of Pipe ☐ Coating ☐ Housing ☐ Other Protective Device

Was there a release of product (Blowing gas, hissing noise, bubbles or fluid leak)?

☐ Unknown ☐ Yes ☐ No

Diameter of Damaged Pipe? 8 (inches)

Damaged pipeline depth at point of contact? _____ (feet) _____ (inches)

Year the Pipeline as installed? 1961

Did excavator notify emergency services 911?

☐ Unknown ☐ Yes ☑ No

Number of people injured

☐ Unknown ☑ 0 ☐ 1 ☐ 2 to 9 ☐ 10 to 19 ☐ 20 to 49 ☐ 50 to 99

☐ 100 or more Exact Value: _____

Type of injuries, if any? _____

Number of fatalities

☐ Unknown ☑ 0 ☐ 1 ☐ 2 to 9 ☐ 10 to 19 ☐ 20 to 49 ☐ 50 to 99

☐ 100 or more Exact Value: _____

Was the type of pipeline damaged interstate, intrastate, unknown?

☐ interstate ☐ Intrastate ☐ Unknown

Did ignition or fire occur?

☐ Yes ☑ No

If Yes, Additional information regarding the ignition/fire. _____

Were people evacuated?

☐ Yes ☑ No

If Yes, How many people were evacuated? _____

Comment regarding evacuation? _____

Was media coverage an additional type of public impact?

☐ Yes ☑ No

If Yes, Additional information regarding media coverage. _____

Were blocked streets or traffic an additional type of impact?

☐ Yes ☑ No

If Yes, Additional information regarding rerouting of traffic or blocked streets. _____

Was an explosion and additional type of public impact?

☐ Yes ☑ No

If Yes, Additional information regarding an explosion. _____

Was there another type of public impact?

☐ Yes ☑ No

If Yes, Additional information regarding different type of impact. _____

Did incident meet the Pipeline Safety Telephonic or written criteria in Title 16 TX?

☐ Unknown ☐ Yes ☑ No

RRC Incident Number? _____

Part K - Supplemental Questions Continued...

Encroaching Company- Name? Bravo Farms
Encroaching Company- Address 1? 2327 N. Vicki Ct
Encroaching Company- Address 2?
Encroaching Company- City? Visaila
Encroaching Company- State? CA
Encroaching Company- Zipcode? 93291
Encroaching Company- Phone? (559) 870-0052
Encroaching Company- Contact? Adalberto Estrella
Encroaching Company- Contact Title?
Encroaching Company- Contact Phone? (559) 870-0052
Encroaching Company- Contact Fax?
Encroaching Company- Contact Email?

Type of Event?
☐ Underground Damage ☑ Underground Near Miss ☐ Above Grade ☐ Aerial ☐ Natural Cause ☐ Submarine

Date Damage Was Discovered? 2/20/2025 **Time?** 08:30 am

KM Location Description? LS-15 M.P. 74.59

Were Pipeline facility marks visible in the area of excavation at the time of damage?
☐ Unknown ☐ Yes ☐ No

Were Pipeline facilities marked accurately?
☐ Unknown ☑ Yes ☐ No

Reason for Pipeline(s) not marked accurately?
☐ Pipeline was not marked ☐ Portion of pipeline was not marked ☐ Pipeline was not marked accurately
☐ Improper type of marking ☐ Other

Explanation for other reason:

Distance of inaccurate marks from pipeline? _____ **feet** _____ **inches**

[Part Z] Kinder Morgan Specific Information

Company Entity? KINDER MORGAN PRODUCTS PIPELINES
Region? PAC NORTH
Division? FRESNO TERMINAL
Damage Prevention Supervisor? JASON BROTHERS
Damage Prevention Coordinator? MIKE LAPEAUX
IMPACT #? 3389536
Event PODS Pipeline #?
Event PODS Pipeline Name?
Incident Description?

Incident Description:On 2/20/2025, at approximately 8:30 a.m. the Fresno line rider encountered a third-party digging post holes without a valid One Call ticket. This work was being performed using a handheld post hole digger and was approximately 6' from LS-15, an Out of Service KM pipeline. (PLMP 74.59 Traver, CA) The line rider immediately stopped the work and informed the third party that he must have a valid One Call ticket before any excavation could continue. The line rider located the pipe, which is 4' 3" deep in this location. The post holes were approximately 29" deep but did not impact the OOS pipeline that was 6' away, running parallel.

Rev: 5/10/18

'*' indicates a Required Field

Part Z - Kinder Morgan Specific Information Continued...

☐ Same as Enroaching Company

Work Done For - Company? Bravo Farms

Work Done For - Company Address 1? 2327 N. Vicki Ct

Work Done For - Company Address 2?

Work Done For - Company City? Visaila

Work Done For - Company State? CA

Work Done For - Company Zipcode? 93291

Work Done For - Company Phone? (559) 870-0052

Work Done For - Company Contact? Adalberto Estrella

Work Done For - Company Contact Title?

Work Done For - Company Contact Phone? (559) 870-0052

Work Done For - Company Contact Fax?

Work Done For - Company Contact Email?

Type of Encroachment Event?

KM or KM's Contractor Hit the KM Line (1st or 2nd Party)

☐ Non-Pipeline ☐ Pipeline <200 PSI ☐ Pipeline >200 PSI

Someone Other than an Excavator Working for KM Hit the KM Asset (3rd Party)

☐ Non-Pipeline ☐ Pipeline <200 PSI ☐ Pipeline >200 PSI

During a KM Excavation or Activity, A 3rd Party Asset Was Hit

☐ Non-Pipeline ☐ Pipeline

Near Miss

☐ 1st or 2nd Party ☑ 3rd Party

☐ Non-Excavation Asset Hit (any contact or damage to KM asset and not involving excavation)

☐ Historical Damage (Prior Pipeline Damage Discovered Via ILi or Other Means)

Active One Call?

☐ Yes ☑ No

Ticket Number?

Has the person called in locate before?

☐ Yes ☑ No

How many in the last 2 yrs, through current date?

Has the excavator received PA information in the past?

☐ Yes ☑ No

What PA information?

☐ Event / Facility Tour ☐ Special Mailing - Letter ☑ Mass Mailing - Brochure ☐ One Call Contact
☐ Training / Mock Drill ☐ PA Tool Kit ☐ Other

Were permanent markers used?

☐ Yes ☑ No

Upstream footage? 55

Downstream footage? 125

KM Warning signs used?

☐ Yes ☑ No

Part Z - Kinder Morgan Specific Information Continued...

Description of state One Call rules not followed?

Installing fence posts without a valid One-call.

Description of Action Taken?

Filed with Agency or Legal?

Description of KM O&M procedures not followed?

Description of Resolution?

KINDER MORGAN
SFPP, L.P.

March 5, 2025

Adalberto Estrella
2327 N. Vicki Ct.
Visalia, CA. 93291

Re: Notification of unsafe excavation practices occurring near Kinder Morgan Energy Partners High Priority Subsurface Installation.

Dear Mr. Adalberto:

This notification is to alert you of the unsafe excavation practices that occurred at 36220 S. Golden State Blvd. Traver, CA. 93673. An inspection of Kinder Morgan, Inc. (KMI) Right of Way on February 2, 2025 revealed your crew excavating 4 feet from KMI's high-pressure petroleum pipeline without a valid USA-North One-Call ticket.

As a utility owner, KMI is mandated to comply with all State and Federal regulations and will not waiver in the execution thereof. KMI works diligently to maintain a safe environment by establishing and enforcing a 10-foot protection zone around each of KMI's subsurface utilities. No excavation activities are allowed within the 10-foot protection zone without a KMI representative present. All excavation activities require a USA-North One-Call notification at least 48 hours prior to beginning work.

Any and all Third Party work within the KMI's protection zone will be communicated to KMI via an agreement documenting the scope of work, schedule of work, procedures to execute work in a safe manner, responsible parties involved and procedures to communicate any change to the agreement.

The unsafe excavation practices conducted by your crew was 4 feet from KMI's LS-15 (Bakersfield to Fresno) high pressure petroleum pipeline and will be recorded as a Near Miss. Additionally, this recorded Near Miss will be used in the future to demonstrate any unsafe patterns of excavation practices unacceptable to KMI and which pose a significant threat to public safety. Attached is a copy of KMI's public awareness brochure and a USA North California Excavation Manual. To ensure the safety of underground utilities and the public, it is imperative that you follow the USA North Excavation Manual for all future excavation activities.

If you have any questions regarding this letter, please contact me at (916) 303-9087 or Mr. Jason Brothers at (559) 333-1799.

Sincerely,

Michelle Johnson
Operations Manager - PNR Central Division

cc: Daniel Ortiz (KMI)
Jason Brothers (KMI)
Scott Lichtig, Deputy Attorney General, State of California

Exhibit 3

CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION
INTERVIEW REPORT

REPORT DATE: March 27, 2025

CASE NO: C250710002

DATE AND TIME OF INTERVIEW: March 27, 2025, 2:57 p.m.

LOCATION OF INTERVIEW: Phone

INTERVIEWER: Adrian Anaya (Investigator)

NAME, TITLE, AND COMPANY OF INTERVIEWEE:
Adalberto Estrella
2327 North Vicki Court
Visalia, California

Narrative:
On March 27, 2025, the Investigator attempted to contact Adalberto Estrella (Estrella) via telephone at the number provided by Kinder Morgan, (559) 870-0052. However, there was no answer, and a voicemail was delivered requesting a call back.

That same day, Estrella contacted the Investigator via telephone. The Investigator informed Estrella that a notification was received from Kinder Morgan regarding his company excavating around 36222 South Golden State Boulevard, Traver, California, on February 20, 2025, at approximately 08:30 am. Estrella confirmed he was stopped by Kinder Morgan that day and that they caught him digging. Estrella stated that Kinder Morgan saw his work truck parked on the side of the road and stopped to talk to him. Estrella stated work had stopped that day, and he made an account with 811 to get a ticket after talking to Kinder Morgan. Estrella stated that an on-site meeting was completed with Kinder Morgan, where they were monitoring him as he completed his work. Estrella confirmed the onsite meeting happened on February 27, 2025. Estrella stated it was a 30-minute job and confirmed no damage, injuries, or casualties occurred.

Estrella stated 811 was not called since he just showed up to repair the billboard that fell over. Estrella reported he didn't know 811 had to be contacted prior. Estrella stated he was digging about 2 feet using a posthole digger, and he added concrete to hold it back up. The Investigator asked Estella if his company owned the posthole digger, and he responded by stating, “owned by my company, I guess.” Estrella stated that no permit was pulled for the work. Estrella stated that Bravo Farms had hired him, and when the investigator asked Estrella if there was a contract for the work, he stated he didn't know since he was just told to go fix the post. The Investigator asked Estrella how he learned about the job opportunity, and Estrella stated he had known the

owners for years. Estrella stated the owner is Jonathan Van Ryn. Estrella was asked who he reported to at Bravo Farms for the project progression. Estrella stated that Jonathan was who he reported to. Estrella stated that Jonathan is a friend who asked him to fix his sign and that it was just a 4x4 wooden post and a couple of screws to hold up the sign. The investigator asked Estrella if he received permission from the property owner to work on the billboard. Estrella stated he never installed the sign there and that it was already there just how all along the highway there are signs installed. The Investigator asked Estrella what the total amount he was paid for the work, and Estrella stated he was not going to disclose that. Estrella further stated he didn't get paid for the day, nor has he been paid for it yet. The investigator asked Estrella if he had a Contractor State License number, and Estrella responded, stating he did not have a contractor’s license.

Exhibit 4

CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION
INTERVIEW REPORT

REPORT DATE: April 10, 2025

CASE NO: C250710002

DATE AND TIME OF INTERVIEW: April 10, 2025, 2:38 pm

LOCATION OF INTERVIEW: Phone

INTERVIEWER: Adrian Anaya (Investigator)

NAME, TITLE, AND COMPANY OF INTERVIEWEE:
Daniel, Supervisor
Bravo Farms Restaurant Inc.
1691 Retherford Street
Tulare, California 93274

Narrative:
On April 10, 2025, the Investigator contacted the Bravo Farms Restaurant Inc. via telephone. An employee (name unknown) answered the Investigator's telephone call, where she greeted and announced the business name, “Bravo Farms.” The Investigator asked to speak to a supervisor or to Jonathan Van Ryn. The employee directed the phone to a supervisor named Daniel. The Investigator advised Daniel about the Investigation regarding the billboard sign and asked to speak to Jonathan Van Ryn or provide his contact information to discuss the billboard located on Highway 99. Danel stated that he cannot give Jonathan Van Ryn’s contact information, but he can deliver a message to him. The Investigator provided Daniel with his phone number and to have Jonanthan Van Ryn give a call as soon as possible. The Investigator informed Daniel that if no call is received within the next two days, a request for information will be mailed out to Bravo Farms Restaurant Inc. The Investigator advised Daniel that this is an active investigation and a response is required. The investigator also stated to Daniel that if no phone call is received or a response to the mailed information request letters, a possible violation may be issued against Bravo Farms Restaurant Inc. for not complying. Daniel stated, “okay” and terminated the call.

Exhibit 5

BA20241036859

STATE OF CALIFORNIA
Office of the Secretary of State
STATEMENT OF INFORMATION
CORPORATION

California Secretary of State
1500 11th Street
Sacramento, California 95814
(916) 657-5448

For Office Use Only

-FILED-

File No.: BA20241036859

Date Filed: 5/29/2024

Entity Details

Corporation Name	BRAVO FARMS RESTAURANT INC.
Entity No.	3572918
Formed In	CALIFORNIA

Street Address of Principal Office of Corporation

Principal Address	1691 RETHERFORD ST TULARE, CA 93274

Mailing Address of Corporation

Mailing Address	1691 RETHERFORD ST TULARE, CA 93274
Attention	

Street Address of California Office of Corporation

Street Address of California Office	1691 RETHERFORD ST TULARE, CA 93274

Officers

Officer Name	Officer Address	Position(s)
JONATHAN VAN RYN	1691 RETHERFORD ST TULARE, CA 93274	Chief Executive Officer, Secretary
nikki Van Ryn	1691 Retherford St tulare, CA 93274	Chief Financial Officer

Additional Officers

Officer Name	Officer Address	Position	Stated Position
None Entered			

Directors

Director Name	Director Address
Jonathan Van Ryn	1691 Retherford St tulare, CA 93274

The number of vacancies on Board of Directors is: 0

Agent for Service of Process

Agent Name	JONATHAN VAN RYN
Agent Address	1691 RETHERFORD ST TULARE, CA 93274

Type of Business

Type of Business	RESTAURANT

Email Notifications

Opt-in Email Notifications	Yes, I opt-in to receive entity notifications via email.

Labor Judgment

B2774-7465 05/29/2024 10:53 AM Received by California Secretary of State

No Officer or Director of this Corporation has an outstanding final judgment issued by the Division of Labor Standards Enforcement or a court of law, for which no appeal therefrom is pending, for the violation of any wage order or provision of the Labor Code.

Electronic Signature

☒ By signing, I affirm that the information herein is true and correct and that I am authorized by California law to sign.

Jonathan vanryn	*05/29/2024*
Signature	Date

B2774-7466 05/29/2024 10:53 AM Received by California Secretary of State

BA20241036837

STATE OF CALIFORNIA
Office of the Secretary of State
STATEMENT OF INFORMATION
CORPORATION

California Secretary of State
1500 11th Street
Sacramento, California 95814
(916) 657-5448

For Office Use Only

-FILED-

File No.: BA20241036837

Date Filed: 5/29/2024

Entity Details

Corporation Name	BRAVO FARMS FOODS
Entity No.	4076265
Formed In	CALIFORNIA

Street Address of Principal Office of Corporation

Principal Address	1691 RETHERFORD ST TULARE, CA 93274

Mailing Address of Corporation

Mailing Address	1691 RETHERFORD ST TULARE, CA 93274
Attention	

Street Address of California Office of Corporation

Street Address of California Office	1691 RETHERFORD ST TULARE, CA 93274

Officers

Officer Name	Officer Address	Position(s)
JONATHAN VAN RYN	1691 RETHERFORD ST TULARE, CA 93274	Chief Executive Officer, Secretary
nikki Van Ryn	1691 Retherford St tulare, CA 93274	Chief Financial Officer

Additional Officers

Officer Name	Officer Address	Position	Stated Position
None Entered			

Directors

Director Name	Director Address
Jonathan Van Ryn	1691 Retherford St tulare, CA 93274

The number of vacancies on Board of Directors is: 0

Agent for Service of Process

Agent Name	JONATHAN VAN RYN
Agent Address	1691 RETHERFORD ST TULARE, CA 93274

Type of Business

Type of Business	RESTAURANT

Email Notifications

Opt-in Email Notifications	No, I do NOT want to receive entity notifications via email. I prefer notifications by USPS mail.

Labor Judgment

B2774-7397 05/29/2024 10:51 AM Received by California Secretary of State

No Officer or Director of this Corporation has an outstanding final judgment issued by the Division of Labor Standards Enforcement or a court of law, for which no appeal therefrom is pending, for the violation of any wage order or provision of the Labor Code.

Electronic Signature

☒ By signing, I affirm that the information herein is true and correct and that I am authorized by California law to sign.

jonathanvanryn	*05/29/2024*
Signature	Date

B2774-7398 05/29/2024 10:51 AM Received by California Secretary of State

Exhibit 6

Anaya, Adrian@EnergySafety


From: Nick White <nick.white@usan.org>
Sent: Thursday, May 15, 2025 9:20 AM
To: Anaya, Adrian@EnergySafety
Subject: FW: Dig Safe Board Result #16225528
Attachments: 2025030300441-000.PDF; 2025030300441-000_PositiveResponse_20250515_091235.pdf; DPP_20250515_0915AM.csv

Follow Up Flag: Follow up
Flag Status: Flagged

CAUTION: This email originated from outside of the organization. Do not click links

Hello Adrian,


Here is the search polygon I used:



I don’t show any tickets submitted by Adalberto Estrella specifically but I do have one submitted for 36220 S. Golden State Blvd which is attached. Also attached is a ticket report for all of the tickets populated by my search polygon. Let me know if you need copies of those tickets and I will get them for you.

Thank you.

Nick White
Member Services Manager
O: 925-222-6501
W: undergroundservicealert.org
4005 Port Chicago Hwy #100 Concord, CA 94520
Members University



This message contains confidential information and is intended only for the intended recipients. If you are not an intended recipient you should not disseminate, distribute or copy this e-mail. Please notify us immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore we do not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

From: Formsite <noreply@fs26.formsite.com>
Date: Tuesday, May 13, 2025 at 1:30 PM
To: Nick White <nick.white@usan.org>
Subject: Dig Safe Board Result #16225528

Complaint Number (if known)	C250710002
Full Name	Adrian Anaya
Phone Number	2792451133
Email	adrian.anaya@energysafety.ca.gov
What information are you requesting?	Ticket
Ticket number (if known)	Unknown

Revision number(s) range (example - All or 000-005)	ALL
Do you have more tickets?	No
Do you need copies, if so which ones?	• Ticket(s) • Electronic Positive Response(s)
Location Description	Ticket search for day of incident 02/20/2025 36220 South Golden State Blvd, Tulare, CA Work type: Billboard repair Reporter: Kinder Morgan Excavator: Adalberto Estrella
Address/Street	36220 S. Golden State Blvd
Cross Street	**Highway
City	Tulare
Do you know the Excavator Information?	Yes
Excavator's/Contractor's Name	Adalberto Estrella
Excavator's/Contractor's Phone Number	5598700052
Excavator's/Contractor's Email	adalberto96estr@gmail.com

This email was sent as a result of a form being completed.
Report unwanted email.



Ticket #: 2025030300441 Revision: 000

Ticket Status: Original
Transmission ID 5
Ticket Type: Normal
Response Required: Yes

Excavator Details

Contact: Matthew Robinson **Phone:** 559-739-9166 **Mobile:** 559-798-7371
Company: Tulare County Traffic Control **Email:** MRobinson@tularecounty.ca.gov
Excavator Type: Municipality (in-house crew) **Language:** Not Supplied
Address: 15600 Ave 256 Visalia California 93292 **Excavator ID:** 72808

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.447133 -119.485181
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #		**Rev.#**	
Submitted	03/03/2025 09:02	**Medium**	WEB
Work Begin Date	03/05/2025 17:01		
Legal Start Date	03/05/2025 17:01		
Ticket Expiration	03/31/2025 23:59		
Work Duration	1 day or less		
Address/Location	36220 S Golden State Blvd		
City/Town/Place	Traver		
County	Tulare County		
State	CA	**Zip Code**	93673
Nearby Cross Street	Merritt Dr		
Subdivision/Lot			
Delineated Method	White Paint and Stakes		
Work Type	Road Work		
Work Activity	Signs - Street/Highway/Pole Structures/Etc		
Excavation Method	Hand digging		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	No		
Project Owner	County of Tulare		
Permit			
Job #/Name	Speed zone project.		
Onsite Contact Name	Jimmy Ibarra		
Onsite Contact Phone	5597399166		

Ticket Action Reason:

Excavator Remarks:

2477 Feet south of Merritt on the west shoulder. At the end of the Hwy 99 offramp to Traver.

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.
- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 7

Seq. No.	Authority Name	Phone	Status
18241027	ATT Distribution - California	8882903111	Notification Sent
18241028	Chevron Environmental Management Company (CEMC) - Legacy	7145082677	Notification Sent
18241026	Cogent Communications - California	9132534623	Notification Sent
18241022	Kinder Morgan / SFPP California	5593651078	Notification Sent
18241023	Level 3 / Lumen California	9185470147	Notification Sent
18241024	Pacific Gas & Electric Fresno	5593859392	Notification Sent
18241025	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 1

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	3/3/2025 9:02:19 AM	Original	Normal	Robinson2010	Web

----------End of Revision History----------

----------End of Transmission----------

2025030300441-000 36220 S Golden State Blvd, Traver, CA 93673

Legal start date	Created on	Downloaded at
05 Mar 2025, 05:01 PM	03 Mar 2025, 09:02 AM	15 May 2025, 09:12 AM

7/7
RECEIVED

Created by
Robinson2010

Reference
Speed zone project.

UTILITY NAME	RESPONSE CODE	UTILITY NOTES	STATION CODE	RECEIVED
ATT Distribution - California	022	Response by UtiliQuest	ATTDNORCAL	04 Mar 2025, 09:09 AM
Chevron Environmental Management Company (CEMC) - Legacy	001	Clear - No Conflict	CHEMC1	03 Mar 2025, 09:47 AM
Cogent Communications - California	001	No notes provided	SPRINT	04 Mar 2025, 01:10 PM
Kinder Morgan / SFPP California	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	KMEFNO	04 Mar 2025, 01:14 PM
Level 3 / Lumen California	001	No notes provided	LEVCAL	04 Mar 2025, 06:34 AM
Pacific Gas & Electric Fresno	001	No notes provided	PGEFNO	04 Mar 2025, 09:28 AM
Southern California Gas Company	001	No notes provided	SCGVIS	04 Mar 2025, 11:28 AM

2025030300441-000 (New) - Revised on: 03 Mar 2025, 09:02 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	04 Mar 2025, 09:09 AM	022	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	03 Mar 2025, 09:47 AM	001	Clear - No Conflict	Clear - No Conflict

Downloaded at 15 May 2025, 09:12 AM

2025030300441-000 36220 S Golden State Blvd, Traver, CA 93673

CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	04 Mar 2025, 01:10 PM	001	No notes provided	No notes provided
SPRINT	Cogent Communications - California	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	04 Mar 2025, 01:14 PM	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities
KMEFNO	Kinder Morgan / SFPP California	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
LEVCAL	Level 3 / Lumen California	04 Mar 2025, 06:34 AM	001	No notes provided	No notes provided
LEVCAL	Level 3 / Lumen California	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	04 Mar 2025, 09:28 AM	001	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SCGVIS	Southern California Gas Company	04 Mar 2025, 11:28 AM	001	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	03 Mar 2025, 09:03 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

Downloaded at 15 May 2025, 09:12 AM

Ticket t	Ticket	Address	Type of wor	Start date	Caller Name	Working on	Authority N
Normal	2025030300602	6th Street, Traver, CA	Road Work	Mar 05 2025 05:01:0	Matthew Robins	County	Not Supplie
Normal	2025030300520	6 th sreet, Traver, CA	Road Work	Mar 05 2025 05:01:0	Matthew Robins	County	Not Supplie
Normal	2025030300441	36220 S Golden State Blvd, Trav	Road Work	Mar 05 2025 05:01:0	Matthew Robins	County	Not Supplie
Normal	2024072000046	36218 CA-99, Traver, CA 93673	Non-reside	Jul 25 2024 08:00:00	Ranjit Singh Nag	Other	Not Supplie
Normal	2024050802278	36005 CA-99, Traver, CA 93673	Non-reside	May 10 2024 05:01:0	Nicolas Azar	Other	Not Supplie

Is area pre-marked
Any
Any
Any
Any
Any

Exhibit 7

Anaya, Adrian@EnergySafety


From: Nick White <nick.white@usan.org>
Sent: Monday, June 2, 2025 12:25 PM
To: Anaya, Adrian@EnergySafety
Cc: Trevor Harris
Subject: Re: Dig Safe Board Result #16225528
Attachments: 2025022000624-000.PDF; 2025022000624-001.PDF; 2025022000624-001_PositiveResponse_20250602_122244.pdf; 2025022000713-000.PDF; 2025022000713-000_PositiveResponse_20250602_122311.pdf; 2025030400086-000.PDF; 2025030400086-001.PDF; 2025030400086-002.PDF; 2025030400086-002_PositiveResponse_20250602_122405.pdf

Follow Up Flag: Flag for follow up
Flag Status: Flagged

CAUTION: This email originated from outside of the organization. Do not click links

Hello Adrian,


Attached are the tickets I was able to locate based of of the following search polygon:



Let me know if you need anything else.

Thank you.

Nick White
Member Services Manager
O: 925-222-6501
W: undergroundservicealert.org
4005 Port Chicago Hwy #100 Concord, CA 94520
Members University



This message contains confidential information and is intended only for the intended recipients. If you are not an intended recipient you should not disseminate, distribute or copy this e-mail. Please notify us immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore we do not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

From: Anaya, Adrian@EnergySafety <Adrian.Anaya@energysafety.ca.gov>
Date: Friday, May 30, 2025 at 9:09 AM
To: Nick White <nick.white@usan.org>
Subject: RE: Dig Safe Board Result #16225528

Hi Nick,

Can I obtain the tickets for the area described below:

The worksite is 1 mile south of Traver, California, on the east shoulder of the northbound lanes of Highway 99.

Attached is a screenshot from Google Maps of the approximate location of the billboard for reference.

Let me know if there are any tickets for that area. I would like to receive copies of the tickets and the EPRs.


Thanks!
Adrian Anaya
Investigator
Office of Energy Infrastructure Safety
Mobile: (279) 245-1133

From: Nick White <nick.white@usan.org>
Sent: Thursday, May 15, 2025 9:20 AM
To: Anaya, Adrian@EnergySafety <Adrian.Anaya@energysafety.ca.gov>
Subject: FW: Dig Safe Board Result #16225528

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hello Adrian,


Here is the search polygon I used:



I don't show any tickets submitted by Adalberto Estrella specifically but I do have one submitted for 36220 S. Golden State Blvd which is attached. Also attached is a ticket report for all of the tickets populated by my search polygon. Let me know if you need copies of those tickets and I will get them for you.

Thank you.

Nick White
Member Services Manager
O: 925-222-6501
W: undergroundservicealert.org
4005 Port Chicago Hwy #100 Concord, CA 94520
Members University



This message contains confidential information and is intended only for the intended recipients. If you are not an intended recipient you should not disseminate, distribute or copy this e-mail. Please notify us immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore we do not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

From: Formsite <noreply@fs26.formsite.com>
Date: Tuesday, May 13, 2025 at 1:30 PM
To: Nick White <nick.white@usan.org>
Subject: Dig Safe Board Result #16225528

Complaint Number (if known)	C250710002
Full Name	Adrian Anaya
Phone Number	2792451133
Email	adrian.anaya@energysafety.ca.gov
What information are you requesting?	Ticket
Ticket number (if known)	Unknown
Revision number(s) range (example - All or 000-005)	ALL
Do you have more tickets?	No
Do you need copies, if so which ones?	• Ticket(s) • Electronic Positive Response(s)
Location Description	Ticket search for day of incident 02/20/2025 36220 South Golden State Blvd, Tulare, CA Work type: Billboard repair Reporter: Kinder Morgan Excavator: Adalberto Estrella

Address/Street	36220 S. Golden State Blvd
Cross Street	**Highway
City	Tulare
Do you know the Excavator Information?	Yes
Excavator's/Contractor's Name	Adalberto Estrella
Excavator's/Contractor's Phone Number	5598700052
Excavator's/Contractor's Email	adalberto96estr@gmail.com

This email was sent as a result of a form being completed.
Report unwanted email.



Ticket #: 2025022000624 Revision: 000

Ticket Status: Original
Transmission ID 1
Ticket Type: Short
Response Required: Yes

Excavator Details

Contact: Adalberto Estrella **Phone:** 559-870-0052 **Mobile:** 559-870-0052
Company: Adalberto Estrella **Email:** adalberto96estr@gmail.com
Excavator Type: Homeowner (or private individual/volunteer group) **Language:** Not Supplied
Address: 2327 N Vickie Ct Visalia California 93291 **Excavator ID:** 185468

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.432007 -119.474390
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #		**Rev.#**	
Submitted	02/20/2025 08:41	**Medium**	CSR
Work Begin Date	02/20/2025 12:41		
Legal Start Date	02/24/2025 17:01		
Ticket Expiration	03/20/2025 23:59		
Work Duration	1 day or less		
Address/Location	Golden State Hwy		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	Merritt Dr		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Road Work		
Work Activity	Signs - Street/Highway/Pole Structures/Etc		
Excavation Method	Hand digging		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	No		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	Bravo Farms		
Onsite Contact Name	Caller		
Onsite Contact Phone	5598700052		

Ticket Action Reason:

Excavator Remarks:

At a Point approximately 1.67 Mi SE of Merritt Dr on NE Side of CA-99 (GPS: 36.43201, -119.47439), To Include 15' Radius

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.

- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 7

Seq. No.	Authority Name	Phone	Status
17988048	ATT Distribution - California	8882903111	Notification Sent
17988049	Chevron Environmental Management Company (CEMC) - Legacy	7145082677	Notification Sent
17988047	Cogent Communications - California	9132534623	Notification Sent
17988043	Kinder Morgan / SFPP California	5593651078	Notification Sent
17988044	Level 3 / Lumen California	9185470147	Notification Sent
17988045	Pacific Gas & Electric Fresno	5593859392	Notification Sent
17988046	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 1

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	2/20/2025 8:41:36 AM	Original	Short	SJS.USAN811	Phone

----------End of Revision History----------

----------End of Transmission----------

Ticket #: 2025022000624 Revision: 001

Ticket Status: Cancelled
Transmission ID 3
Ticket Type: Short
Response Required: No

Excavator Details

Contact: Adalberto Estrella **Phone:** 559-870-0052 **Mobile:** 559-870-0052
Company: Adalberto Estrella **Email:** adalberto96estr@gmail.com
Excavator Type: Homeowner (or private individual/volunteer group) **Language:** Not Supplied
Address: 2327 N Vickie Ct Visalia California 93291 **Excavator ID:** 185468

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.432007 -119.474390
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #	2025022000624	**Rev.#**	000
Submitted	02/20/2025 09:06	**Medium**	CSR
Work Begin Date	02/20/2025 12:41		
Legal Start Date	02/24/2025 17:01		
Ticket Expiration	03/20/2025 23:59		
Work Duration	1 day or less		
Address/Location	Golden State Hwy		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	Merritt Dr		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Road Work		
Work Activity	Signs - Street/Highway/Pole Structures/Etc		
Excavation Method	Hand digging		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	No		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	Bravo Farms		
Onsite Contact Name	Caller		
Onsite Contact Phone	5598700052		

Ticket Action Reason:

CANCEL TICKET Ticket Cancelled Start Time Changed per Caller- 02/20/2025 09:06 AM

Excavator Remarks:

At a Point approximately 1.67 Mi SE of Merritt Dr on NE Side of CA-99 (GPS: 36.43201, -119.47439), To Include 15' Radius

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.
- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 7

Seq. No.	Authority Name	Phone	Status
17989706	ATT Distribution - California	8882903111	Notification Sent
17989707	Chevron Environmental Management Company (CEMC) - Legacy	7145082677	Notification Sent
17989705	Cogent Communications - California	9132534623	Notification Sent
17989701	Kinder Morgan / SFPP California	5593651078	Notification Sent
17989702	Level 3 / Lumen California	9185470147	Notification Sent
17989703	Pacific Gas & Electric Fresno	5593859392	Notification Sent
17989704	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 2

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	2/20/2025 8:41:36 AM	Original	Short	SJS.USAN811	Phone
001	2/20/2025 9:06:51 AM	Cancelled	Short	vvl.usan811	Phone

----------End of Revision History----------

----------End of Transmission----------

2025022000624-001 Golden State Hwy, Kingsburg, CA 93631

Legal start date	Created on	Downloaded at
24 Feb 2025, 05:01 PM	20 Feb 2025, 09:06 AM	02 Jun 2025, 12:22 PM

2/7
RECEIVED

Created by
vvl.usan811

Reference
Bravo Farms

UTILITY NAME	RESPONSE CODE	UTILITY NOTES	STATION CODE	RECEIVED
ATT Distribution - California	000	Utility is yet to provide a suitable response code for this revision.	ATTDNORCAL	20 Feb 2025, 09:07 AM
Chevron Environmental Management Company (CEMC) - Legacy	001	Clear - No Conflict	CHEMC1	20 Feb 2025, 09:07 AM
Cogent Communications - California	000	Utility is yet to provide a suitable response code for this revision.	SPRINT	20 Feb 2025, 09:07 AM
Kinder Morgan / SFPP California	000	Utility is yet to provide a suitable response code for this revision.	KMEFNO	20 Feb 2025, 09:07 AM
Level 3 / Lumen California	000	Utility is yet to provide a suitable response code for this revision.	LEVCAL	20 Feb 2025, 09:07 AM
Pacific Gas & Electric Fresno	001	No notes provided	PGEFNO	20 Feb 2025, 09:07 AM
Southern California Gas Company	000	Utility is yet to provide a suitable response code for this revision.	SCGVIS	20 Feb 2025, 09:07 AM

2025022000624-001 (Cancel) - Revised on: 20 Feb 2025, 09:06 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	20 Feb 2025, 09:07 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	20 Feb 2025, 09:07 AM	001	Clear - No Conflict	Clear - No Conflict
SPRINT	Cogent Communications - California	20 Feb 2025, 09:07 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

2025022000624-001 Golden State Hwy, Kingsburg, CA 93631

KMEFNO	Kinder Morgan / SFPP California	20 Feb 2025, 09:07 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
LEVCAL	Level 3 / Lumen California	20 Feb 2025, 09:07 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	20 Feb 2025, 09:07 AM	001	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	20 Feb 2025, 09:07 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

2025022000624-000 (New) - Revised on: 20 Feb 2025, 08:41 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	20 Feb 2025, 08:49 AM	001	Clear - No Conflict	Clear - No Conflict
CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
LEVCAL	Level 3 / Lumen California	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	20 Feb 2025, 09:06 AM	001	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SCGVIS	Southern California Gas Company	20 Feb 2025, 08:42 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

Downloaded at 02 Jun 2025, 12:22 PM

Ticket #: 2025022000713 Revision: 000

Ticket Status: Original
Transmission ID 2
Ticket Type: Normal
Response Required: Yes

Excavator Details

Contact: Adalberto Estrella **Phone:** 559-870-0052 **Mobile:** 559-870-0052
Company: Adalberto Estrella **Email:** adalberto96estr@gmail.com
Excavator Type: Homeowner (or private individual/volunteer group) **Language:** Not Supplied
Address: 2327 N Vickie Ct Visalia California 93291 **Excavator ID:** 185468

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.432011 -119.474403
GIS coordinate system: WGS84 (WKID 4326)

Ticket Action Reason:

Previous Ticket #		**Rev.#**	
Submitted	02/20/2025 09:01	**Medium**	CSR
Work Begin Date	02/24/2025 17:01		
Legal Start Date	02/24/2025 17:01		
Ticket Expiration	03/20/2025 23:59		
Work Duration	1 day or less		
Address/Location	Ca-99		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	Merritt Dr		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Road Work		
Work Activity	Signs - Street/Highway/Pole Structures/Etc		
Excavation Method	Hand digging		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	No		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	Bravo Farms		
Onsite Contact Name	Caller		
Onsite Contact Phone	5598700052		

Excavator Remarks:

At a Point approximately 1.67 Mi SE of Merritt Dr on NE Side of CA-99 (GPS: 36.43201, -119.47439), To Include 15' Radius

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.
- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 7

Seq. No.	Authority Name	Phone	Status
17989253	ATT Distribution - California	8882903111	Notification Sent
17989254	Chevron Environmental Management Company (CEMC) - Legacy	7145082677	Notification Sent
17989252	Cogent Communications - California	9132534623	Notification Sent
17989248	Kinder Morgan / SFPP California	5593651078	Notification Sent
17989249	Level 3 / Lumen California	9185470147	Notification Sent
17989250	Pacific Gas & Electric Fresno	5593859392	Notification Sent
17989251	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 1

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	2/20/2025 9:01:34 AM	Original	Normal	VVL.USAN811	Phone

----------End of Revision History----------

----------End of Transmission----------

2025022000713-000 Ca-99, Kingsburg, CA 93631

7/7
RECEIVED

Legal start date	Created on	Downloaded at
24 Feb 2025, 05:01 PM	20 Feb 2025, 09:01 AM	02 Jun 2025, 12:23 PM

Created by
VVL.USAN811

Reference
Bravo Farms

UTILITY NAME	RESPONSE CODE	UTILITY NOTES	STATION CODE	RECEIVED
ATT Distribution - California	010	Response by UtiliQuest	ATTDNORCAL	24 Feb 2025, 08:28 AM
Chevron Environmental Management Company (CEMC) - Legacy	001	Clear - No Conflict	CHEMC1	20 Feb 2025, 10:36 AM
Cogent Communications - California	010	No notes provided	SPRINT	20 Feb 2025, 01:50 PM
Kinder Morgan / SFPP California	010	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	KMEFNO	20 Feb 2025, 01:59 PM
Level 3 / Lumen California	001	No notes provided	LEVCAL	21 Feb 2025, 12:02 PM
Pacific Gas & Electric Fresno	001	No notes provided	PGEFNO	20 Feb 2025, 09:07 AM
Southern California Gas Company	001	No notes provided	SCGVIS	21 Feb 2025, 09:25 AM

2025022000713-000 (Copy) - Revised on: 20 Feb 2025, 09:01 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	24 Feb 2025, 08:28 AM	010	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	20 Feb 2025, 10:36 AM	001	Clear - No Conflict	Clear - No Conflict

Downloaded at 02 Jun 2025, 12:23 PM

CHEMC1	Chevron Environmental Management Company (CEMC) - Legacy	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	20 Feb 2025, 01:50 PM	010	No notes provided	No notes provided
SPRINT	Cogent Communications - California	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	20 Feb 2025, 01:59 PM	010	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities
KMEFNO	Kinder Morgan / SFPP California	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
LEVCAL	Level 3 / Lumen California	21 Feb 2025, 12:02 PM	001	No notes provided	No notes provided
LEVCAL	Level 3 / Lumen California	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	20 Feb 2025, 09:07 AM	001	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SCGVIS	Southern California Gas Company	21 Feb 2025, 09:25 AM	001	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	20 Feb 2025, 09:02 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

Downloaded at 02 Jun 2025, 12:23 PM

Ticket #: 2025030400086 Revision: 000

Ticket Status: Original
Transmission ID 2
Ticket Type: Ag/Flood Control
Response Required: Yes

Excavator Details

Contact: BLAKE JACOBI
Phone: 559-909-9244
Mobile: 559-909-9244
Company: Streamline Irrigation
Email: blake@streamlineag.com
Excavator Type: Agriculture
Language: Not Supplied
Address: 3630 AVE 384 KINGSBURG California 93631
Excavator ID: 43960

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.425021 -119.474605
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #		**Rev.#**	
Submitted	03/04/2025 06:55	**Medium**	WEB
Work Begin Date	03/06/2025 17:01		
Legal Start Date	03/06/2025 17:01		
Ticket Expiration	03/04/2026 23:59		
Work Duration	15-31 days		
Address/Location	30283 Rd 44		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	AVE 352		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Agricultural/Farming		
Work Activity	Irrigation Work		
Excavation Method	Backhoe/trackhoe/excavator/mini ex		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	Yes		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	DJ DAIRY - 12"		
Onsite Contact Name	Blake Jacobi		
Onsite Contact Phone	5599099244		

Ticket Action Reason:

Excavator Remarks:
CALL LOGAN 559-303-2225

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.
- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 5

Seq. No.	Authority Name	Phone	Status
18269602	ATT Distribution - California	8882903111	Notification Sent
18269601	Cogent Communications - California	9132534623	Notification Sent
18269598	Kinder Morgan / SFPP California	5593651078	Notification Sent
18269599	Pacific Gas & Electric Fresno	5593859392	Notification Sent
18269600	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 1

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	3/4/2025 6:55:52 AM	Original	Ag/Flood Control	BLAKEJACOBI	Web

----------End of Revision History----------

----------End of Transmission----------

Ticket #: 2025030400086 Revision: 001

Ticket Status: REMK
Transmission ID 1
Ticket Type: Ag/Flood Control
Response Required: Yes

Excavator Details

Contact: BLAKE JACOBI **Phone:** 559-909-9244 **Mobile:** 559-909-9244
Company: Streamline Irrigation **Email:** blake@streamlineag.com
Excavator Type: Agriculture **Language:** Not Supplied
Address: 3630 AVE 384 KINGSBURG California 93631 **Excavator ID:** 43960

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.425021 -119.474605
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #	2025030400086	**Rev.#**	000
Submitted	03/12/2025 06:40	**Medium**	WEB
Work Begin Date	03/14/2025 17:01		
Legal Start Date	03/14/2025 17:01		
Ticket Expiration	03/04/2026 23:59		
Work Duration	15-31 days		
Address/Location	30283 Rd 44		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	AVE 352		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Agricultural/Farming		
Work Activity	Irrigation Work		
Excavation Method	Backhoe/trackhoe/excavator/mini ex		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	Yes		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	DJ DAIRY - 12"		
Onsite Contact Name	Blake Jacobi		
Onsite Contact Phone	5599099244		

Ticket Action Reason:

REQUEST RE-MARKS AT&T & SPRINT NEED TO MARK NORTHERN PART OF PROJECT-03/12/2025 06:40 AM

Excavator Remarks:

CALL LOGAN 559-303-2225

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.
- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 5

Seq. No.	Authority Name	Phone	Status
18474036	ATT Distribution - California	8882903111	Notification Sent
18474035	Cogent Communications - California	9132534623	Notification Sent
18474032	Kinder Morgan / SFPP California	5593651078	Notification Sent
18474033	Pacific Gas & Electric Fresno	5593859392	Notification Sent
18474034	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 2

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	3/4/2025 6:55:52 AM	Original	Ag/Flood Control	BLAKEJACOBI	Web
001	3/12/2025 6:40:38 AM	REMK	Ag/Flood Control	BLAKEJACOBI	Web

----------End of Revision History----------

----------End of Transmission----------

Ticket #: 2025030400086 Revision: 002

Ticket Status: REMK
Transmission ID 3
Ticket Type: Ag/Flood Control
Response Required: Yes

Excavator Details

Contact: BLAKE JACOBI **Phone:** 559-909-9244 **Mobile:** 559-909-9244
Company: Streamline Irrigation **Email:** blake@streamlineag.com
Excavator Type: Agriculture **Language:** Not Supplied
Address: 3630 AVE 384 KINGSBURG California 93631 **Excavator ID:** 43960

Dig Site and Ticket Details



Open Map

Latitude/Longitude: 36.425021 -119.474605
GIS coordinate system: WGS84 (WKID 4326)

Previous Ticket #	2025030400086	**Rev.#**	001
Submitted	04/01/2025 11:28	**Medium**	WEB
Work Begin Date	04/03/2025 17:01		
Legal Start Date	04/03/2025 17:01		
Ticket Expiration	03/04/2026 23:59		
Work Duration	15-31 days		
Address/Location	30283 Rd 44		
City/Town/Place	Kingsburg		
County	Tulare County		
State	CA	**Zip Code**	93631
Nearby Cross Street	AVE 352		
Subdivision/Lot			
Delineated Method	White Paint		
Work Type	Agricultural/Farming		
Work Activity	Irrigation Work		
Excavation Method	Backhoe/trackhoe/excavator/mini ex		
Anticipated Depth	24 to 48 inches		
Boring	No	**Explosive**	No
Street/Sidewalk	No	**Pavement Only**	No
Vacuum Excavation	Yes		
Project Owner	Agricultural/Farm Operation		
Permit			
Job #/Name	DJ DAIRY - 12"		
Onsite Contact Name	Blake Jacobi		
Onsite Contact Phone	5599099244		

Ticket Action Reason:

REQUEST RE-MARKS WOULD LIKE TO FIELD MEET WITH ATT-
04/01/2025 11:28 AM

Excavator Remarks:

CALL LOGAN 559-303-2225

Additional Information

Log in to One Call Access and click Positive Response on the menu to view responses from member facility operators and confirm that all operators have responded before you begin digging. https://onecallca.undergroundservicealert.org/ngen.web/.

Be sure the work location is accessible to facility owners/operators and their contract locators.

- Review your ticket details and utility members notified. If you notice anything that is in error or incorrect, please login to your One Call Access account and amend or create a new ticket to include the correct and accurate information. It is your responsibility to provide clear and accurate information on every ticket
- Do not proceed with your work until the legal start date/response due date has passed and ALL facility owners/operators have responded.
- When working within 24" tolerance zone of any facility marking, you are required by state law to hand dig and expose and protect the facility.
- If you make contact with a line even scrapes, nicks, dents or other contact, you are required to report it to 811 and the facility operator immediately.
- If you would like free training regarding the 811 process and state excavation laws, please visit www.811pro.com.
- If you need assistance, please contact us visiting www.undergroundservicealert.org, or information@usanorth811.org.

Members Operator Notified

Total members impacted: 5

Seq. No.	Authority Name	Phone	Status
18976433	ATT Distribution - California	8882903111	Notification Sent
18976432	Cogent Communications - California	9132534623	Notification Sent
18976429	Kinder Morgan / SFPP California	5593651078	Notification Sent
18976430	Pacific Gas & Electric Fresno	5593859392	Notification Sent
18976431	Southern California Gas Company	5593689494	Notification Sent

----------End of Member List----------

Ticket Revision History

Total revision history showing: 3

REV	DATE/TIME	STATUS	TYPE	USER	MEDIUM
000	3/4/2025 6:55:52 AM	Original	Ag/Flood Control	BLAKEJACOBI	Web
001	3/12/2025 6:40:38 AM	REMK	Ag/Flood Control	BLAKEJACOBI	Web
002	4/1/2025 11:28:11 AM	REMK	Ag/Flood Control	BLAKEJACOBI	Web

----------End of Revision History----------

----------End of Transmission----------

2025030400086-002 30283 Rd 44, Kingsburg, CA 93631

Legal start date	Created on	Downloaded at
03 Apr 2025, 05:01 PM	01 Apr 2025, 11:28 AM	02 Jun 2025, 12:24 PM

5/5
RECEIVED

Created by
BLAKEJACOBI

Reference
DJ DAIRY - 12"

UTILITY NAME	RESPONSE CODE	UTILITY NOTES	STATION CODE	RECEIVED
ATT Distribution - California	010	Response by UtiliQuest	ATTDNORCAL	04 Apr 2025, 10:11 AM
Cogent Communications - California	001	No notes provided	SPRINT	02 Apr 2025, 03:29 PM
Kinder Morgan / SFPP California	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	KMEFNO	01 Apr 2025, 12:15 PM
Pacific Gas & Electric Fresno	004	No notes provided	PGEFNO	01 Apr 2025, 12:59 PM
Southern California Gas Company	003	No notes provided	SCGVIS	01 Apr 2025, 12:04 PM

2025030400086-002 (Remark) - Revised on: 01 Apr 2025, 11:28 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	04 Apr 2025, 10:11 AM	010	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	03 Apr 2025, 04:20 PM	050	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	01 Apr 2025, 11:28 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	02 Apr 2025, 03:29 PM	001	No notes provided	No notes provided
SPRINT	Cogent Communications - California	01 Apr 2025, 11:28 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	01 Apr 2025, 12:15 PM	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities

KMEFNO	Kinder Morgan / SFPP California	01 Apr 2025, 11:28 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	01 Apr 2025, 12:59 PM	004	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	01 Apr 2025, 11:28 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SCGVIS	Southern California Gas Company	01 Apr 2025, 12:04 PM	003	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	01 Apr 2025, 11:28 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

2025030400086-001 (Remark) - Revised on: 12 Mar 2025, 06:40 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	18 Mar 2025, 02:57 PM	010	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	14 Mar 2025, 04:11 PM	050	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	12 Mar 2025, 06:41 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	12 Mar 2025, 06:45 AM	001	No notes provided	No notes provided
SPRINT	Cogent Communications - California	12 Mar 2025, 06:41 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	12 Mar 2025, 08:26 AM	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities
KMEFNO	Kinder Morgan / SFPP California	12 Mar 2025, 06:41 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	13 Mar 2025, 08:30 AM	010	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	12 Mar 2025, 06:41 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

Downloaded at 02 Jun 2025, 12:24 PM

2025030400086-002 30283 Rd 44, Kingsburg, CA 93631

SCGVIS	Southern California Gas Company	12 Mar 2025, 09:11 AM	031	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	12 Mar 2025, 06:41 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

2025030400086-000 (New) - Revised on: 04 Mar 2025, 06:55 AM

STATION CODE	STATION NAME	RESPONSE DATE	RESPONSE CODE	RESPONSE DESCRIPTION	COMMENTS
ATTDNORCAL	ATT Distribution - California	06 Mar 2025, 07:19 AM	021	Response by UtiliQuest	Response by UtiliQuest
ATTDNORCAL	ATT Distribution - California	04 Mar 2025, 06:56 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SPRINT	Cogent Communications - California	04 Mar 2025, 06:58 AM	001	No notes provided	No notes provided
SPRINT	Cogent Communications - California	04 Mar 2025, 06:56 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
KMEFNO	Kinder Morgan / SFPP California	04 Mar 2025, 08:31 AM	001	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities	Kinder Morgan does NOT agree to allow vacuum excavation around our facilities
KMEFNO	Kinder Morgan / SFPP California	04 Mar 2025, 06:56 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
PGEFNO	Pacific Gas & Electric Fresno	05 Mar 2025, 09:35 AM	010	No notes provided	No notes provided
PGEFNO	Pacific Gas & Electric Fresno	04 Mar 2025, 06:56 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.
SCGVIS	Southern California Gas Company	10 Mar 2025, 02:33 PM	031	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	05 Mar 2025, 09:14 AM	051	No notes provided	No notes provided
SCGVIS	Southern California Gas Company	04 Mar 2025, 06:56 AM	000	Utility is yet to provide a suitable response code for this revision.	Utility is yet to provide a suitable response code for this revision.

Downloaded at 02 Jun 2025, 12:24 PM

Exhibit 8

State of California – A Natural Resources Agency

Gavin Newsom, Governor

OFFICE OF ENERGY INFRASTRUCTURE SAFETY
UNDERGROUND SAFETY BOARD
715 P Street, 20th Floor | Sacramento, CA 95814
916.902.6000 | *www.energysafety.ca.gov*

MEMBERS
Amparo Munoz, Chair
Bill Johns, Vice Chair
Randy Charland
Travis Clausen
Marshall Johnson
Dave Sorem

EXECUTIVE OFFICER
Brittny Branaman (Acting)

TRANSMITTED VIA CERTIFIED MAIL

Request Date: April 16, 2025

Response Due: May 1, 2025

To: Jonathan Van Ryn
Bravo Farms Restaurant Inc.
1691 Retherford Street
Tulare, California 93274

Investigator: Adrian Anaya

Send your response to the investigator at this email address:

Adrian.anaya@energysafety.ca.gov

Information Request Number: Underground Safety-IR-2025-103

Subject: Request for information regarding the digging at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025, for a billboard repair.

REQUESTS

1. Provide information on who performed the work for the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025. This includes company name, personal first and last name, phone number, address and email address.

2. Provide a summary of the scope of work being performed for the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025.

3. Provide the date when the billboard was originally installed at 36222 South Golden State Boulevard, Traver, California 93673. This includes company name of who

installed the billboard and contact information. If exact date is unknown, please provide an approximate date such as month and year.

4. Did Bravo Farms Restaurant Inc. receive permission from the property owner to install the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673?

5. Did Bravo Farms Restaurant Inc. contact the regional notification center (811) prior to the commencement of work on February 20, 2025, at or around 36222 South Golden State Boulevard, Traver, California 93673?

   If answered to the previous question is “No”:
   a. Provide a statement to why the regional notification center (811) was not called.

6. Is Bravo Farms Restaurant Inc. the owner of the billboard located at or around 36222 South Golden State Boulevard, Traver, California 93673?

7. Provide the first and last name of the employee at Bravo Farms Restaurant Inc. who directed and managed the work being performed at or around 36222 South Golden State Boulevard, Traver, California 93673 during February 20, 2025.

INSTRUCTIONS

a. Provide all information in your possession, custody, or control, or the possession, custody, and/or control of your affiliates or agents, that is responsive to these requests by the due date identified above.
b. Identify the personnel (employees, consultants, agents, etc.) who provided information responsive to each of the information requests by stating the full name, business address, and title of each person.
c. If you do not know the exact answer to any of the requests above, please so indicate and provide your best estimate.
d. Provide data in its original format (i.e., PDF, Excel, GIS shapefile, etc.), unless otherwise specified in the request.

USPS Tracking®

FAQs >

Remove ×

Tracking Number:

9589071052702374150517

Copy Add to Informed Delivery (https://informeddelivery.usps.com/)

Latest Update

Your item was delivered to an individual at the address at 3:02 pm on April 19, 2025 in TULARE, CA 93274.

Get More Out of USPS Tracking:

USPS Tracking Plus®

Delivered

Delivered, Left with Individual

TULARE, CA 93274
April 19, 2025, 3:02 pm

Arrived at USPS Regional Facility

BAKERSFIELD CA DISTRIBUTION CENTER
April 18, 2025, 10:04 am

In Transit to Next Facility

April 17, 2025

Arrived at USPS Regional Facility

SACRAMENTO CA DISTRIBUTION CENTER
April 16, 2025, 11:10 pm

Hide Tracking History

Feedback

What Do USPS Tracking Statuses Mean? (https://faq.usps.com/s/article/Where-is-my-package)

Text & Email Updates

USPS Tracking Plus®

Product Information

See Less

Track Another Package

Enter tracking or barcode numbers

Need More Help?

Contact USPS Tracking support for further assistance.

FAQs

Exhibit 9

State of California – A Natural Resources Agency

Gavin Newsom, Governor

OFFICE OF ENERGY INFRASTRUCTURE SAFETY
UNDERGROUND SAFETY BOARD
715 P Street, 20th Floor | Sacramento, CA 95814
916.902.6000 | *www.energysafety.ca.gov*

MEMBERS
Amparo Munoz, Chair
Bill Johns, Vice Chair
Randy Charland
Travis Clausen
Marshall Johnson
Dave Sorem

EXECUTIVE OFFICER
Brittny Branaman (Acting)

TRANSMITTED VIA CERTIFIED MAIL

2nd NOTICE: IMMEDIATE ACTION REQUIRED

Request Date: May 5, 2025

Response Due: May 12, 2025

Re: Lack of response to the information letter of April 16, 2025, which contained a response date of May 1, 2025.

To: Jonathan Van Ryn
Bravo Farms Restaurant Inc.
1691 Retherford Street
Tulare, California 93274

Investigator: Adrian Anaya

Send your response to the investigator at this email address:

Adrian.anaya@energysafety.ca.gov

Information Request Number: Underground Safety-IR-2025-2-061

Subject: Request for information regarding the digging at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025, for a billboard repair.

REQUESTS

1. Provide information on who performed the work for the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025. This includes company name, personal first and last name, phone number, address and email address.

2. Provide a summary of the scope of work being performed for the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673 on February 20, 2025.

3. Provide the date when the billboard was originally installed at 36222 South Golden State Boulevard, Traver, California 93673. This includes company name of who installed the billboard and contact information. If exact date is unknown, please provide an approximate date such as month and year.

4. Did Bravo Farms Restaurant Inc. receive permission from the property owner to install the billboard at or around 36222 South Golden State Boulevard, Traver, California 93673?

5. Did Bravo Farms Restaurant Inc. contact the regional notification center (811) prior to the commencement of work on February 20, 2025, at or around 36222 South Golden State Boulevard, Traver, California 93673?

   If answered to the previous question is “No”:
   a. Provide a statement to why the regional notification center (811) was not called.

6. Is Bravo Farms Restaurant Inc. the owner of the billboard located at or around 36222 South Golden State Boulevard, Traver, California 93673?

7. Provide the first and last name of the employee at Bravo Farms Restaurant Inc. who directed and managed the work being performed at or around 36222 South Golden State Boulevard, Traver, California 93673 during February 20, 2025.

INSTRUCTIONS

a. Provide all information in your possession, custody, or control, or the possession, custody, and/or control of your affiliates or agents, that is responsive to these requests by the due date identified above.
b. Identify the personnel (employees, consultants, agents, etc.) who provided information responsive to each of the information requests by stating the full name, business address, and title of each person.
c. If you do not know the exact answer to any of the requests above, please so indicate and provide your best estimate.
d. Provide data in its original format (i.e., PDF, Excel, GIS shapefile, etc.), unless otherwise specified in the request.

USPS Tracking®

FAQs >

Track Packages Anytime, Anywhere

Get the free Informed Delivery® feature to receive automated notifications on your packages

Learn More

(https://reg.usps.com/xsell?app=UspsTools&ref=ho nepageBanner&appURL=https%3A%2F%2Finformeddelivery.usps.com/box/pages/intro/start.action)

Remove ×

Tracking Number:

9589071052702374150548

Copy **Add to Informed Delivery (https://informeddelivery.usps.com/)**

Latest Update

Your item has been delivered to the original sender at 11:01 am on June 12, 2025 in SACRAMENTO, CA 95814.

Get More Out of USPS Tracking:

USPS Tracking Plus®

Delivered
Delivered, To Original Sender
SACRAMENTO, CA 95814
June 12, 2025, 11:01 am

Arrived at USPS Regional Facility
SACRAMENTO CA DISTRIBUTION CENTER
June 11, 2025, 3:55 am

In Transit to Next Facility
June 10, 2025

Arrived at USPS Facility
PASADENA, CA 91109
June 9, 2025, 8:54 am

Unclaimed/Being Returned to Sender
TULARE, CA 93274
June 6, 2025, 12:50 pm

Reminder to Schedule Redelivery of your item
May 13, 2025

Notice Left (No Authorized Recipient Available)
TULARE, CA 93274
May 8, 2025, 3:30 pm

Feedback

Arrived at USPS Regional Facility

BAKERSFIELD CA DISTRIBUTION CENTER
May 7, 2025, 11:18 am

Arrived at USPS Regional Facility

SACRAMENTO CA DISTRIBUTION CENTER
May 5, 2025, 11:30 pm

Hide Tracking History

What Do USPS Tracking Statuses Mean? (https://faq.usps.com/s/article/Where-is-my-package)

Text & Email Updates

USPS Tracking Plus®

Product Information

See Less

Track Another Package

Enter tracking or barcode numbers

Need More Help?

Contact USPS Tracking support for further assistance.

FAQs