
Field Service 6:31 AM Wed Jun 7
100%
All
Manage Constraints
My Prescription
VM Prescription Name
RX-00005830
Work Code Name
NW - No Work
Removal Reason
Grow In Risk
Removal Comment
Observation Testing
Delisting Reason
Observation check
Completed Removal Prescribed
False
Veg. Point ID
VP-07017520
Status
Inspected, No Work
Constrained
False
Observed Radial Dist. to Asset (ft)
13
Trim to Vertical Clearance (in ft)
Trim to Horizontal Clearance (in ft)
2 of 3
35.0
Sources: Esri, HERE, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community
Powered by Esri

Field Service 6:32 AM Wed Jun 7

All

Manage Constraints ...

My Prescription

VM Prescription Name

RX-00005830

Work Code Name

NW - No Work

Removal Reason

Removal Comment

Delisting Reason

Observation check

Completed Removal Prescribed

False

Veg. Point ID

VP-07017520

Status

Inspected, No Work

Constrained

False

Observed Radial Dist. to Asset (ft)

13

Trim to Vertical Clearance (in ft)

Trim to Horizontal Clearance (in ft)

1 of 2

Lincoln Rd

Sources: Esri, HERE, Garmin, FAO, NOAA, USGS, © OpenStreetMap contributors, and the GIS User Community

Powered by Esri