



May 14, 2026

Carrie Laird
VP of Wildfire Mitigation and Emergency Operations
PacifiCorp
1700 NE Multnomah, Suite 2000
Portland, OR 97232

NOTICE OF DATA INACCURACY

Ms. Laird:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by PacifiCorp (PC) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues PC a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy may lead to a Notice of Non-Performance (NON) if the inaccuracy causes PC to miss a WMP target or prevents Energy Safety from ensuring that PC performed the targets and statements made in PC's 2025 WMP.

On October 9, 2025, Energy Safety conducted an inspection of PacifiCorp's WMP initiatives in the vicinity of the city of Weed, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Grid Hardening ID 8077661 at coordinates 41.43052973495417, -122.38938973187061, the inspector observed that PC failed to adhere to data accuracy.

The data inaccuracy identified in this notice could make it appear as though PC reached the target set in its WMP initiative related to expulsion fuse replacements when it has not. If PC does not address this data inaccuracy and includes the inaccurate data in PC's reporting regarding its WMP initiative related to expulsion fuse replacements, PC may be found to fail to achieve the target for that WMP initiative. This failure may be raised in future NON or in Energy Safety's 2025 Annual Report on PC's WMP Performance.

Within 30 days from the issuance date of this NODI, PC should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:

californiadockets@pacificorp.com

Pooja Kishore, PacifiCorp

Pooja.Kishore@pacificorp.com

Lakshmi Nair, PacifiCorp

Lakshmi.Nair@pacificorp.com

Melissa Swenson, PacifiCorp

Melissa.Swenson@pacificorp.com

John Garrett, PacifiCorp

John.Garrett@pacificorp.com

David Kowalek, PacifiCorp

David.Kowalek@pacificorp.com

Ivan Garcia, Energy Safety

Ivan.Garcia@energysafety.ca.gov

Babak Kaviani, Energy Safety

Babak.Kaviani@energysafety.ca.gov

Samuel Isaiah, Energy Safety

Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety

Shannon.Greene@energysafety.ca.gov

assetperformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI>



State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 15th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Tony Marino, Ph.D., Acting Director

INSPECTION REPORT

Electrical Corporation:	PacifiCorp
Report Number:	PAD_PC_IAG_20251009_1231
Date of Inspection:	October 9, 2025
City and/or County of Inspection:	Weed, Siskiyou County
Inspector:	Ivan Garcia
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 2 (Q2)
Inspection Selection:	Energy Safety viewed the contents of the Q2 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.12 - Expulsion Fuse Replacements
Inspection Purpose:	Assess the accuracy of PacifiCorp's QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	No Structure ID	8077661	41.43052973495417, -122.38938973187061	Tier 2	8.1.2.12 - Expulsion Fuse Replacements	Inaccurate data provided on expulsion fuse replacements.

Observations

On Grid Hardening ID 8077661 at Mile 0.6 US Hwy 97 S, Weed, CA, 96094, USA, 41.43052973495417, -122.38938973187061, the inspector observed that no overhead structure was present, and no expulsion fuses were replaced. The inspector's observation is documented in Data Inaccuracy 1 photographs, which are attached to this report as Exhibit A.

Energy Safety concludes that there are inaccurate data because of these facts:

1. PC reported in the 2025 Q2 QDR that work on WMP initiative 8.1.2.12 Expulsion Fuse Replacements was completed at this location.
2. The inspector did not observe expulsion fuses replaced at this location.
3. The inspector did not observe an overhead structure at this location.

This observation warrants a notice of data inaccuracy. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.

Exhibits

Exhibit A: Photo Log

Structure ID: No Structure ID

Data Inaccuracy 1



G1mg1: Overall view of the area.



G1mg2: No overhead structure observed at this location.



G1mg3: Underground work observed at this location.