

**June 5, 2026**

Patrick Doherty, Program Manager  
Performance Assessment Division  
Office of Energy Infrastructure Safety  
California Natural Resources Agency  
715 P Street 20<sup>th</sup> Floor  
Sacramento, CA 95814

**BY ENERGY SAFETY E-FILING**

**SUBJECT:** Southern California Edison Company's Response to Notice of Non-Performance (NON\_PAD\_SCE\_CYA\_20260128\_1511)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON\_PAD\_SCE\_CYA\_20260128\_1511** which SCE received on **May 19, 2026 (Notice)**, based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **January 28, 2026**. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or [Elizabeth.Leano@sce.com](mailto:Elizabeth.Leano@sce.com).

Sincerely,

//s//  
Brandon Tolentino  
Vice President of Wildfire and Business Resiliency  
Southern California Edison

## SCE Response

### Finding:

Notice	#	Structures
NON_PAD_SCE_CYA_20260128_1511	1	4925994E

### Summary of Findings:

Energy Safety’s Notice states that in implementing 2025 WMP initiative 8.1.3.1 - Distribution High Fire Risk-Informed (HFRI) Inspections and Remediations (IN-1.1), SCE failed to complete the remediation of multiple avian guards with obstructions on Pole ID 4925994E, Grid Hardening ID 414606467-4925994E at coordinates 34.4078317001898, -118.420343456959.

Energy Safety states that it “considers this non-performance to be in the Minor risk category.”<sup>1</sup>

### Response:

SCE confirms the remediation to remove acorns from the avian protection on structure 4925994E was completed on September 20, 2025. Photo evidence documenting the completed remediation is included below.

During a subsequent routine aerial inspection conducted by SCE on February 18, 2026, new acorn accumulation from recurring animal activity was found inside the avian protection.

Based on SCE’s February 18, 2026 inspection findings, Notification #415150444 was created to address the newly identified obstruction, with an estimated completion date of August 18, 2026.

---

<sup>1</sup> Notice, p. 1.

Photo 1 and 2: Completed Remediation, Structure 49925994E – September 20,2025




Photo 3: Completed Remediation, Structure 49925994E – September 20,2025

Sep 20, 2025 02:50 PM



34.40804142467233,-118.4203557671705 4925994E