



Liberty  
933 Eloise Avenue  
South Lake Tahoe, CA 96150  
Tel: 800-782-2506  
Fax: 530-544-4811

January 21, 2026

***VIA OEIS E-FILING***

Patrick Doherty  
Program Manager, Compliance Assurance Division  
Office of Energy Infrastructure Safety  
715 P Street, 20<sup>th</sup> Floor  
Sacramento, CA 95814

Docket #2025 NON

**Subject:** Liberty's Response to Notice of Non-Performance –  
NON\_CAD\_LU\_RMA\_20250924\_1435

Dear Patrick Doherty:

Liberty Utilities (CalPeco Electric) LLC (“Liberty”) appreciates the opportunity to provide this response to the finding(s) identified in the “NON\_CAD\_LU\_RMA\_20250924\_1435” (Notice of Non-Performance or NON), issued by the Office of Energy Infrastructure Safety (“Energy Safety”) on December 22, 2025, regarding Energy Safety’s inspection of work completed by Liberty in accordance with its 2025 Wildfire Mitigation Plan (“WMP”). Liberty also appreciates Energy Safety’s continued efforts to identify, communicate, and resolve wildfire risks throughout California.

The enclosed response demonstrates that Liberty did perform the reported WMP work from Quarter 2 of 2025 and no further work is required by Liberty at this time related to the Energy Safety findings identified in the above identified notice.

If you have any questions or require any additional information, please contact me at:

Jordan Parrillo  
Manager of Regulatory Affairs  
Liberty Utilities (CalPeco Electric) LLC  
701 National Ave,  
Tahoe Vista, CA 96148  
Telephone: 530-721-7818  
[jordan.parrilo@libertyutilities.com](mailto:jordan.parrilo@libertyutilities.com)

### Liberty Response

**Energy Safety Finding:** Energy Safety observed that in implementing the 2025 WMP initiative 8.1.2.12 - Tree Attachment Removals, Liberty failed to complete removal of two tree attachments on Pole ID 297905, Grid Hardening IDs c05bae02-301c-44fc-ba3e-093e5480bed7, 9c288076-e205-4406-b60d-de7aee69d097, 6a9d8845-7b27-4f67-a3ea-91e8173fe10e, and 8257935d-f917-44d9-b477-c09203aeee88 at coordinates 38.91285874805942, -119.999759. Energy Safety considers this non-performance to be in the Minor risk category.

Notice	Deficiency #	Location
NON_CAD_LU_RMA_20250924_1435	Deficiency 1	Coordinates 38.91285874805942, -119.999759

### Summary of Energy Safety Findings<sup>1</sup>:

Specifically, the NON describes that on September 24, 2025, Energy Safety conducted an inspection of Liberty's WMP initiatives in the vicinity of the city of South Lake Tahoe, California, and found the following deficiency:

Deficiency 1. On Pole ID 297905, Grid Hardening IDs c05bae02-301c-44fc-ba3e-093e5480bed7, 9c288076-e205-4406-b60d-de7aee69d097, 6a9d8845-7b27-4f67-a3ea-91e8173fe10e, and 8257935d-f917-44d9-b477-c09203aeee88 at Lake Tahoe Preschool, 2111 South Avenue, South Lake Tahoe, CA, 96150, USA, 38.91285874805942, -119.999759, the inspector observed that only two out of four tree attachments were transferred to the pole referenced in the QDR data. The remaining two tree attachments were observed on trees within 15 feet of the new pole and were not removed.

### Liberty Response:

Liberty completed the four tree attachment removals reported with Grid Hardening IDs c05bae02-301c-44fc-ba3e-093e5480bed7, 9c288076-e205-4406-b60d-de7aee69d097, 6a9d8845-7b27-4f67-a3ea-91e8173fe10e, and 8257935d-f917-44d9-b477-c09203aeee88. Liberty transferred all four tree attachments to Pole ID 297905. The Energy Safety pictures referenced in Energy Safety NON\_CAD\_LU\_RMA\_20250924\_1435 (Photo numbers IA1Img1, IA1Img2, IA1Img3, and IA1Img4) show telecommunications lines and not Liberty service wire.

---

<sup>1</sup> Energy Safety NON\_CAD\_LU\_RMA\_20250924\_1435