



February 3, 2025

Brandon Tolentino
Vice President, Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF DATA INACCURACY

Mr. Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues SCE a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy prior to the submission of SCE's 2025 Annual Implementation Report may lead to a Notice of Non-Performance (NON) if the inaccuracy causes SCE to miss a WMP target or prevents Energy Safety from ensuring that SCE performed the targets and statements made in SCE's 2025 WMP.

On October 7, 2025, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Three Rivers, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Pole ID 4226445E, Grid Hardening ID TD2056799-4226445E, at coordinates 36.4757551583404, -118.849816523769, the inspector observed that covered conductor was not installed at the stated location.

The data inaccuracy identified in this notice could make it appear as though SCE reached the target set in its WMP initiative related to covered conductor when it has not. If SCE does not address this data inaccuracy and includes the inaccurate data in its reporting regarding its WMP initiative related to covered conductor, SCE may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Report on SCE's WMP Performance.

Within 30 days from the issuance date of this NODI, SCE should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,



Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:

Gary Chen, SCE

Gary.Chen@sce.com

Elizabeth Leano, SCE

Elizabeth.Leano@sce.com

Cynthia Childs, SCE

Cynthia.Childs@sce.com

Raghu Rayalu, SCE

Raghu.Rayalu@sce.com

Erick G Sanchez, SCE

Erick.G.Sanchez@sce.com

Sally Jeun, SCE

Salley.Jeun@sec.com

Lovepreet Kaur, Energy Safety

Lovepreet.Kaur@energysafety.ca.gov

Yana Loginova, Energy Safety

Yana.Loginova@energysafety.ca.gov

Samuel Isaiah, Energy Safety

Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety

Shannon.Greene@energysafety.ca.gov

Assetperformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI>



State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 20th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Caroline Thomas Jacobs, Director

INSPECTION REPORT

Electrical Corporation:	Southern California Edison Company
Report Number:	PAD_SCE_LOK_20251007_1206
Date of Inspection:	October 7, 2025
City and/or County of Inspection:	Three Rivers, Tulare County
Inspector:	Lovepreet Kaur
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 1 (Q1)
Inspection Selection:	Energy Safety viewed the contents of the Q1 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.1.1 - Covered Conductor
Inspection Purpose:	Assess the accuracy of Southern California Edison Company's QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	4226445E	TD2056799-4226445E	36.4757551583404, - 118.849816523769	Tier 2	8.1.2.1.1 Covered Conductor	Covered conductor is not installed at stated location.

Observations

On Pole ID 4226445E, Grid Hardening ID TD2056799-4226445E at 45471 Sierra Dr, Three Rivers, CA 93271, USA, 36.4757551583404, -118.849816523769, the inspector observed that covered conductor was not installed. The inspector's observations are documented in Data Inaccuracy 1 photographs IA1Img1, IA1Img2, and IA1Img3 which are attached to this report as Exhibit A.

Energy Safety concludes that there is inaccurate data because of these facts:

1. Southern California Edison Company reported in the Q1 QDR that WMP initiative 8.1.2.1.1 - Covered Conductor installation was completed at the inspection location.
2. Covered conductor was not installed; bare conductor was observed.

This observation warrants a notice of data inaccuracy. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.


Exhibits

Exhibit A: Photo Log

Structure ID: 4226445E

Data Inaccuracy 1

 A photograph showing a tall, weathered wooden utility pole with multiple cross-arms and wires. The pole is situated in an open area with a chain-link fence in the foreground and a portable toilet to the left. The background features green trees and a clear blue sky.	 A close-up photograph of a cylindrical metal structure, likely a tower or antenna, covered in a dark, textured mesh. A yellow identification tag is attached to the structure, displaying the text '4226445E' and 'P S 0655'. A chain-link fence is visible in the foreground.
IA1Img1: Overall Structure	IA1Img2: Structure ID



IA1Img3: Closer look at bare wire