



March 5, 2026

***VIA ELECTRONIC FILING***

Docket # 2025 NODI

Patrick Doherty  
Program Manager  
Compliance Assurance Division  
Office of Energy Infrastructure Safety  
715 P Street, 20th Floor  
Sacramento, CA 95814  
[Patrick.Doherty@energysafety.ca.gov](mailto:Patrick.Doherty@energysafety.ca.gov)

**RE: PacifiCorp's Response to Notice of Data Inaccuracy - PAD\_PC\_IAG\_20251008\_1313**

Dear Patrick Doherty:

PacifiCorp provides the following response to the finding identified in the "Notice of Data Inaccuracy, "NODI\_PAD\_PC\_IAG\_20251008\_1313" (NODI) issued by the Office of Energy Infrastructure Safety (Energy Safety) on February 3, 2026. On October 8, 2025, Energy Safety conducted an inspection of PacifiCorp's WMP initiatives in the vicinity of the city of Klamath River, California.

Energy Safety found the following Data Inaccuracy:

**Data Inaccuracy 1:** On Pole ID 06246009.135501, Grid Hardening ID 7011447i at coordinates 41.83497875126414, -122.84000841347425, the inspector observed that PC failed to adhere to data accuracy.


The data inaccuracy identified in this notice could make it appear as though PC reached the target set in its WMP initiative related to covered conductor installation when it has not. If PC does not address this data inaccuracy and includes the inaccurate data in PC's reporting regarding its WMP initiative related to covered conductor installation, PC may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Report on PC's WMP Performance.

**PacifiCorp Response:**

In response to the notice of non-performance, the company conducted a field inspection on February 4, 2026. No corrective actions were required, as the pole was found to have covered conductor installed in all directions, with no bare wire present.

Pole ID 06246009.135501, Grid Hardening ID 7011447i at 21438-21606 Klamath River Rd, Klamath River, CA, 96050, USA, 41.83497875126414, -122.84000841347425

Pole has covered conductor installed in all directions. No bare wire present.



**Picture 1: Near Pole ID 06246009.135501, Grid Hardening ID 7011447i at coordinates 41.83497875126414, -122.84000841347425. Picture taken February 4, 2026.**

PacifiCorp appreciates the opportunity to provide this response to Energy Safety's NODI\_PAD\_PC\_IAG\_20251008\_1313.

Please refer any questions to Pooja Kishore, Regulatory Affairs Manager at 503-813-7314 or via email at [pooja.kishore@pacificorp.com](mailto:pooja.kishore@pacificorp.com) and [californiadockets@pacificorp.com](mailto:californiadockets@pacificorp.com).

Sincerely,

*Carrie Laird*

Carrie Laird  
Vice President, Wildfire Mitigation and Emergency Operations

cc: [assetperformance@energysafety.ca.gov](mailto:assetperformance@energysafety.ca.gov)  
[Shannon.Greene@energysafety.ca.gov](mailto:Shannon.Greene@energysafety.ca.gov)  
[Yana.Loginova@energysafety.ca.gov](mailto:Yana.Loginova@energysafety.ca.gov)  
[Babak.Kaviani@energysafety.ca.gov](mailto:Babak.Kaviani@energysafety.ca.gov)  
[Samuel.Isaiah@energysafety.ca.gov](mailto:Samuel.Isaiah@energysafety.ca.gov)  
[Ivan.Garcia@energysafety.ca.gov](mailto:Ivan.Garcia@energysafety.ca.gov)  
[Patrick.Doherty@energysafety.ca.gov](mailto:Patrick.Doherty@energysafety.ca.gov)