



Bear Valley Electric Service, Inc.
P.O. Box 9028
San Dimas, CA 91773-9028
A Subsidiary of American States Water Company

November 16, 2023

Shannon O'Rourke
Deputy Director
Electrical Infrastructure Directorate
Office of Energy Infrastructure Safety
715 P Street, 20th Floor
Sacramento, CA 95814

RE: Office of Energy Infrastructure Safety Non-Substantive Errata Request for Bear Valley Electric Service Company, Inc.'s 2023-2025 Wildfire Mitigation Plan

Dear Deputy Director O'Rourke,

In accordance with the Office of Energy Infrastructure Safety's ("Energy Safety") 2023-2025 Wildfire Mitigation Plan Process and Evaluation Guidelines,¹ specifically Section 4.3, Bear Valley Electric Service, Inc. ("BVES") hereby submits an updated version of its 2023-2025 Wildfire Mitigation Plan ("WMP").

This updated version reflects the following:

- BVES's errata submitted to OEIS on May 18, 2023
- BVES's Revision Notice and Erratum submitted to OEIS on August 22, 2023
- Additional non-substantive corrections (provided below) requested by OEIS on:
 - June 7, 2023 (Submission date)
 - October 6, 2023

Sincerely,

/s/ Paul Marconi
Paul Marconi President, Treasurer and Secretary
Bear Valley Electric Service, Inc.
P.O. Box 9028
San Dimas, CA 91773-9028
Email: Paul.Marconi@bvesinc.com
(909) 202-9539

¹ 2023-2025 Wildfire Mitigation Plan Process and Evaluation Guidelines, December 6, 2022

Non-Substantive Changes:

| Issue | Action Taken | Section & Page Number |
|---|---|-------------------------|
| Table 6-5 on page 84 incorrectly listed the ranking of the BVES circuits | BVES updated the table to correct the risk ranking based on overall risk score | Section 6, pg. 76 |
| Hyperlink/references for Tables and Figures throughout the document were deleted or broken in the conversion to PDF | BVES, where necessary, recreated the references that had been lost and verified they worked properly in the PDF version of the file. | Entire Document |
| General spelling, grammar and formatting | BVES conducted a review of its WMP and corrected all minor spelling, grammar and formatting errors to improve readability. | Entire Document |
| Update Table 8-6 title from “Vegetation Management Inspection Frequency, Methos, and Criteria” to “Asset Inspection Frequency, Method, and Criteria” in Section 8.1.3. | BVES updated the title of Table 8-6 to “Asset Inspection Frequency, Method, and Criteria” in Section 8.1.3 | Section 8.1.3 pp. 142 |
| Update “An exemplar of the minimum acceptable level of information is provided in Table 8-42” to “An exemplar of the minimum acceptable level of information is provided in Table 8-43” in Section 8.4.2.4, page 287. | BVES updated the Energy Safety Guidance Statement to “An exemplar of the minimum acceptable level of information is provided in Table 8-43” | Section 8.4.2.4 pp. 287 |
| Update the table referenced in the first sentence of Section 8.5.1.3 “Performance Metrics Identified by BVES” from Table 8-66 to Table 8-57. | BVES updated the table reference for Table 8-57 | Section 8.5.1.3 pp. 348 |
| Renummer Table 10-1 “Lessons Learned” ID# column. Number 12 was skipped. | BVES updated the numbering in Table 10-1 to correct for number 12 being skipped | Section 10 pp. 394-397 |