



2024 Liberty Work Complete QC

QC of work complete



260086, Cottonwood, 14, 1

4/5/2024, 6:29:27 PM UTC



CREATED

🕒 4/1/2024, 1:49:49 PM UTC
👤 by Jared Kim

UPDATED

🕒 4/5/2024, 6:29:27 PM UTC
👤 by Eric Oiler

STATUS

🟢 Complete Pass

LOCATION

📍 38.552017, -119.503438



Map data ©2024



CFVM
143 W Main St Suite 8
Merced, CA 94952



QC Assessment Date | April 1, 2024

Tree Information

Tree_ID	W119503657N38551958_2
Work_Status	Complete
Work_Order_Circuit	TPZ1261
Refusal	False
Date_Created	10/24/2023 9:49:17 AM
Modified_Date	March 20, 2024
Section	2
Time Entry Date Created	
Work_Order_Span_ID	TPZ1261+W11950315N3855201-W11950361N3855200
Physical_Address	110437 HIGHWAY 395
Pole_Number	260086
Quantity	1
Time_Entry_Quantity	
Species	Cottonwood
Height	38
DBH	14
Defect_Type	
Location_Comments	
Q1 Work Not Performed	0
Work_Type	TD
Q2 MCD Not Achieved or Not as Prescribed	0
Q3 Will Not Hold	0
Q4 Potential Hazard Remain	0
Cleanup_Method	Chip & Haul
Work_Order_Comments	
Q5 Site Clean	0
Q6 ANSI Not Achieved	0
Q7 Other Trees Affected by Removal	0
Q8 Site Condition Not Stable	0
Comments	Cottonwood was recently pruned, currently has 13 ft clearance under conductors. Customer very sensitive about this tree, insisting we are not going to take more off it. I told them it currently has adequate clearance and wouldn't need pruning again until next cycle. Potentially good TGR candidates for the cottonwoods along this tap to minimize pruning and address his concerns for shade trees at the campground.



Photos

