

July 10, 2024

VIA ELECTRONIC FILING

Docket # 2023 NOV

Patrick Doherty
Program Manager
Compliance Assurance Division
Office of Energy Infrastructure Safety
715 P Street, 20th Floor
Sacramento, CA 95814

RE: PacifiCorp's Response to Notice of Violation – NOV_CAD_PC_SIS_20240509_0914

Dear Patrick Doherty:

PacifiCorp provides the following response to the finding(s) identified in the “Notice of Violation NOV_CAD_PC_SIS_20240509_0914” (Notice of Violation or NOV) issued by the Office of Energy Infrastructure Safety (Energy Safety) on June 10, 2024. On May 9, 2024, Energy Safety conducted an inspection of PacifiCorp's WMP initiatives in the vicinity of the city of Mount Shasta, California. The inspection report is enclosed herewith.


Energy Safety found the following violations:

Violation 1. Energy Safety observed that in implementing 2023 WMP initiative 8.1.2.12 - Expulsion Fuse Replacements, PacifiCorp failed to provide accurate data in reporting that expulsion fuses were replaced on pole ID 06240004.0219703 at coordinates 41.3009857032377, -122.307145186836. Energy Safety considers this data accuracy violation to be in the Minor risk category.

PacifiCorp Response:

In response to the notice of violation, the company conducted a field inspection on June 26, 2024. PacifiCorp provided an inaccurate Structure ID, PacifiCorp crews removed the capacitor bank and fuse, which aligns with the engineered design.

See the screenshot below from the engineered design.



PacifiCorp appreciates the opportunity to provide this response to Energy Safety's NOV_CAD_PC_SIS_20240509_0914. Please refer any questions to Pooja Kishore, Regulatory Affairs Manager at 503-813-7314 or californiadockets@pacificorp.com.

Sincerely,

Allen Berreth
Vice President of Transmission & Distribution Operations
PacifiCorp
825 NE Multnomah Street, Suite 2000
Portland, OR 97232