

Caroline Thomas Jacobs, Director

November 26, 2025

Sumeet Singh Executive Vice President, Operations and Chief Operating Officer Pacific Gas and Electric Company

Notice on Errata for the Pacific Gas and Electric Company 2026-2028 Base **SUBJECT:**

Wildfire Mitigation Plan

Mr. Singh:

Pacific Gas and Electric Company (PG&E) submitted revision 2 of its 2026-2028 Base Wildfire Mitigation Plan (2026-2028 Base WMP) to the Office of Energy Infrastructure Safety's (Energy Safety) 2026-2028 Base WMPs docket (#2026-2028-Base-WMPs) on September 9, 2025.1 Energy Safety identifies non-substantive errors listed in Table 1 of this Notice on Errata for PG&E to correct.

PG&E must revise its 2026-2028 Base WMP R2 to correct the errors identified in Table 1, herein. PG&E must submit its revised 2026-2028 Base WMP to Energy Safety's 2026-2028 Base WMPs docket by December 30, 2025.

If PG&E, during its review, identifies additional non-substantive errors (spelling, grammar, etc.), it may make corrections to its 2026-2028 Base WMP beyond those listed in Table 1. If PG&E makes additional corrections, it must provide a list of each correction in its cover letter that will accompany its response to this Notice on Errata. Classification of errata as substantive or nonsubstantive is solely within the discretion of Energy Safety.² PG&E should consult with Energy Safety if it uncertain whether an errata is nonsubstantive.

Sincerely,

Nicole Dunlap

Program Manager | Electrical Safety Policy Division Office of Energy Infrastructure Safety

¹ PG&E 2026-2028 Base WMP Vol 1 R2, published September 9, 2025.

 $[\]label{lem:url:lem:u$

² Energy Safety Policy Division Process Guidelines, p. 9, published February 24, 2025.

URL: (https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=58025&shareable=true).

Table 1. Errors in the PG&E 2026-2028 Base WMP R2

Section	WMP Page Number	Correction or Clarification
8.2.2 Undergrounding of Electric Lines and/or Equipment	202	Under "Program Description," PG&E refers to "wildfire rebuild areas described in Section 8.2.1." This is inconsistent with PG&E's program names for "Community Rebuild" and "Fire Rebuild." PG&E must correct the "wildfire rebuild" terminology.
10.2.1 Existing Systems, Technologies, and Procedures	439	Table 10-2, the "Fuel moisture sampling and modelling" row incorrectly references 30 sampling locations. The narrative on page 445 and Table 10-1 (page 437) correctly references 25 sampling locations. PG&E must correct the sampling locations in Table 10-2.