



December 23, 2025

Kyle Ferree  
Senior Advisor, Wildfire & Public Safety Strategy & Regulatory Affairs  
Southern California Edison Company  
2244 Walnut Grove Ave.  
Rosemead, CA 91770

**SUBJECT: Notice on Errata for the Southern California Edison Company 2026-2028 Base Wildfire Mitigation Plan**

Mr. Ferree:

Southern California Edison Company (SCE) submitted its 2026-2028 Base WMP Wildfire Mitigation Plan (2026-2028 Base WMP) to the Office of Energy Infrastructure Safety's (Energy Safety) 2026-2028 Base WMPs docket (#2026-2028-Base-WMPs) on October 27, 2025.<sup>1, 2</sup> Energy Safety identified non-substantive errors listed in Table 1 of this Notice on Errata for SCE to correct.

SCE submitted a revised 2026-2028 Base WMP in response to Energy Safety's Revision Notice to the same docket (#2026-2028-Base-WMPs) on September 15, 2025. SCE submitted a second revised 2026-2028 Base WMP and non-substantive errata to the same docket (#2026-2028-Base-WMPs) on October 27, 2025. Following SCE's resubmissions, Energy Safety identified non-substantive errors that remain for SCE to correct.<sup>3</sup>

---

<sup>1</sup> Southern California Edison Company, [SCE 2026-2028 Base WMP R2](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59549&shareable=true), published October 27, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59549&shareable=true>). Hereafter: SCE 2026-2028 Base WMP, R2.


<sup>2</sup> Office of Energy Infrastructure Safety, [2026 - 2028 Electrical Corporation Wildfire Mitigation Plans docket](https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026-2028-Base-WMPs), Accessed April 10, 2025, (URL:(<https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026-2028-Base-WMPs>).

<sup>3</sup> Office of Energy Infrastructure Safety, [2026 - 2028 Electrical Corporation Wildfire Mitigation Plans docket](https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026-2028-Base-WMPs), Accessed April 10, 2025, URL:(<https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2026-2028-Base-WMPs>).

**SCE must revise its 2026-2028 Base WMP R2 to correct the errors identified in Table 1, herein. SCE must submit its revised 2026-2028 Base WMP to Energy Safety's 2026-2028 Base WMPs docket by January 22, 2026.**

If SCE, during its review, identifies additional non-substantive errors (spelling, grammar, etc.), it may make corrections to its 2026-2028 Base WMP beyond those listed in Table 1. If SCE makes additional corrections, it must provide a list of each correction in its cover letter that will accompany its response to this Notice on Errata.

Sincerely,

A handwritten signature in black ink, appearing to read "Dunlap", with a stylized flourish at the end.

Nicole Dunlap  
Program Manager | Electrical Safety Policy Division  
Office of Energy Infrastructure Safety

Encl: Table 1. Errors in the SCE 2026-2028 Base WMP R2

Table 1. Errors in the SCE 2026-2028 Base WMP R2

Section	WMP Page Number	Correction or Clarification
Table of Contents	Starting on page i	SCE must update the table of contents page number references to accurately reflect the correct WMP Sections, subsections, and page numbers throughout the WMP.
Section 13.3 Discontinued Activities	Page 502	<p>In its response to Data Request 18, Question 3, SCE stated that its SH-10 and SA-10 activities are experiencing delays and may have work scoped for 2026 or beyond.<sup>4</sup></p> <p>SCE must revise Section 13.3 of its 2026-2028 Base WMP to remove the SH-10 and SA-10 activities consistent with its response to Data Request 18, Question 3.<sup>5</sup></p>
Section 9.12 Work Orders	Page 375	The summation of all past due work orders in <i>Table 9-7: Number of Past Due Vegetation Management Work Orders Categorized by Age and HFTD Tier</i> (16,735) is not the same as the summation of all past due work orders in <i>Table 9-8: Number of Past Due Vegetation Management Work Orders Categorized by Age and Priority Levels</i> (14,136) in the 2026-2028 Base WMP.

---

<sup>4</sup> Southern California Edison Company, [Response to OEIS-P-WMP 2025-SCE-018 Q.01.a-b - 03.a](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true), published October 3, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true>).

<sup>5</sup> Southern California Edison Company, [Response to OEIS-P-WMP 2025-SCE-018 Q.01.a-b - 03.a](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true), published October 3, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true>).

Section	WMP Page Number	Correction or Clarification
		<p>SCE addressed this discrepancy in its response to Data Request 17, Question 2, where SCE explained that this is because Table 9-7 erroneously includes the category “≥GRCD (grid resiliency clearance distance),” and Table 9-8 does not include this category.<sup>6</sup></p> <p>The summation of all past due work orders within each table, Table 9-7 and Table 9-8, should be identical. SCE must adjust Table 9-7 and/or Table 9-8 so that past due vegetation management work order totals for each table are the same.</p>
Section 9.2.1.5 Scheduling, and Section 9.2.2.5 Scheduling	Pages 339 and 342.	<p>SCE introduced equivocating language in Sections 9.2.1.5 and 9.2.2.5 that appeared to dilute its vegetation management commitments.<sup>7</sup> SCE clarified this statement in its response to Data Request 18, Question 1, by explaining that “[w]hile the timing of inspection work may not always adhere to the original planned schedule, it is ultimately completed.”<sup>8</sup> Furthermore, SCE responded in the same Data Request response, Question 2, that inspection “work is monitored to ensure completion.”<sup>9</sup></p> <p>SCE must update its 2026-2028 Base WMP to include the clarifications made in its response to Data Request 18, Questions 1 and 2.</p>

---

<sup>6</sup> Southern California Edison Company, [OEIS-P-WMP 2025-SCE-017 Q.02 – Answer](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59446&shareable=true), published September 26, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59446&shareable=true>).

<sup>7</sup> SCE 2026-2028 Base WMP, R2, pages 339 and 342.

<sup>8</sup> Southern California Edison Company, [Response to OEIS-P-WMP 2025-SCE-018 Q.01.a-b - 03.a](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true), published October 3, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true>).

<sup>9</sup> Southern California Edison Company, [Response to OEIS-P-WMP 2025-SCE-018 Q.01.a-b - 03.a](https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true), published October 3, 2025, URL:(<https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=59467&shareable=true>).