

CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INVESTIGATION REPORT

DATE: May 5, 2022

CASE No.: 22LA01484

INCIDENT: Lack of operator response to ticket for more than a week

Violations:

Southern California Edison Company

Gov't Code 4216.3 (a) (1) (A): Failure to provide timely response to

excavator

Gov't Code 4216.3 (c) (1) (A): Failure to provide electronic positive

response

Charter Communications

Gov't Code 4216.3 (a) (1) (A): Failure to provide timely response to

excavator

Frontier Communications

Gov't Code 4216.3 (a) (1) (A): Failure to provide timely response to

excavator

Gov't Code 4216.3 (c) (1) (A): Failure to provide timely electronic

positive response

19 CCR 4151 (c): Obstruction of an investigation

Yucaipa Valley Water District

Gov't Code 4216.3 (a) (1) (A): Failure to provide timely response to

excavator

Sprint Communications Company

Gov't Code 4216.3 (c) (1) (A): Failure to provide timely electronic

positive response

Executive Summary:

Frontier, Southern California Edison, and Spectrum responded late to a notification of excavation made by Merlin Johnson Construction, and Yucaipa Valley Water District did not respond at all, in violation of Government Code Section 4216.3 (a)(1)(A). Johnson was conducting water system upgrade work in Noble Creek Regional Park in Beaumont. Sprint/T-Mobile marked the area, but

failed to provide an electronic positive response, in violation of Government Code Section 4216.3 (c)(1)(A).

Futhermore, Frontier and Southern California Edison provided incorrect electronic positive responses, indicating that they had no subsurface installations in the area at substantially the same time as they told the excavator via a phone call that the area would not be marked until the next day, in violation of Government Code Section 4216.3 (c)(1)(A).

Frontier would not locate and mark a fiber line until after the installation of a tracer wire, sixteen days after the legal start date and time. During that period, Frontier provided another incorrect electronic positive response, indicating that the area was marked, when it had not been. Due to a lack of cooperation from Frontier, it is unclear that conduit repair was performed with a valid ticket and unclear whether Frontier acted expeditiously in attempting to mitigate the safety consequences of the unlocated fiber optic cable.

Report Date:	Case Number:	Notification Date:
May 5, 2022	22LA01484	January 18, 2022

Subject of Investigation:

Lack of operator response to ticket for more than a week

Reporting Party Information:

Merlin Johnson

Merlin Johnson Construction, Inc.

P.O. Box 777 Mentone CA 92359

Prior Relevant Board Actions:

Southern California Edison

Date	Case No.	Violations	Actions Taken	
October 31, 2021	19LA1050	4216.3(a)(1)(A)	Advisory Letter	

Date and Time of Incident:

January 10-27, 2022

Location of the Incident:

Noble Creek Park, in Beaumont

Ticket:

```
B220050037-00B | Type: NEW | Created: 1/5/22 | Legal Start: 1/7/22 | Expires: 2/2/22 B220050037-01B | Type: NRSP | Created: 1/10/22 | Legal Start: 1/10/22 | Expires: 2/2/22 B220050037-02B | Type: NRSP | Created: 1/13/22 | Legal Start: 1/13/22 | Expires: 2/2/22 B220050037-03B | Type: NRSP | Created: 1/14/22 | Legal Start: 1/14/22 | Expires: 2/2/22 B220050037-04B | Type: NRSP | Created: 1/17/22 | Legal Start: 1/17/22 | Expires: 2/2/22 B220050037-05B | Type: NRSP | Created: 1/18/22 | Legal Start: 1/18/22 | Expires: 2/2/22 B220050037-06B | Type: NRSP | Created: 1/18/22 | Legal Start: 1/18/22 | Expires: 2/2/22 B220050037-07B | Type: NRSP | Created: 1/19/22 | Legal Start: 1/19/22 | Expires: 2/2/22 B220050037-08B | Type: NRSP | Created: 1/20/22 | Legal Start: 1/20/22 | Expires: 2/2/22 B220050037-09B | Type: NRSP | Created: 1/21/22 | Legal Start: 1/21/22 | Expires: 2/2/22 B220050037-10B | Type: RNEW | Created: 1/31/22 | Legal Start: 1/21/22 | Expires: 2/2/22 B220050037-11B | Type: RNEW | Created: 2/3/22 | Legal Start: 1/21/22 | Expires: 3/3/22
```

Operator:

Frontier Communications Southern California Edison Spectrum (Charter Communications) Sprint/T-Mobile Yucaipa Valley Water District

Excavator:

Merlin Johnson Construction, Inc.

Facility Type Damaged:

None

Scene Description

Various locations in Noble Creek Park

Investigation

On January 18, 2022, Merlin Johnson, President of Merlin Johnson Construction (CSLB License 467306, **Exh. 1**), filed a complaint alleging that Frontier Communications (Frontier) had not marked its facilities despite a start date and time of January 7, 5:01 p.m., and that he had sent "no response" notices each day with no response from Frontier. Johnson was performing a water system upgrade in Noble Creek Regional Park in Beaumont for the Beaumont-Cherry Valley Recreation and Park District.



Figure 1: Map images of Noble Creek Park. The satellite view on the left obtained from Google Earth. The map view on the right, identified in a ticket search of B220050037 on DigAlert's website, shows the excavation area over the park area.

Johnson had notified DigAlert on Wednesday, January 5 of his intent to excavate, requesting a ticket with a legal start date and time of 5:01 p.m. on Friday, January 7 (**Exh. 2**). Johnson identified in the "Location" field of the ticket a "meet and mark" at 9:00 a.m. on January 10, identifying that the work area was various locations within Noble Creek Park. At 8:22 a.m. Friday, January 7, Spectrum, Southern California Edison, and Frontier provided electronic positive response identifying a negotiated marking schedule.

In an interview (**Exh. 3**), Johnson identified several reasons for the meet and mark invitation on the ticket. The work area identified on the ticket was approximately 20 acres, and it would not be attractive to mark up the entire area of the park. He'd delineated with flags and whiskers the specific areas in which he was working, but he thought it might nonetheless be confusing to locators without his guidance. Johnson stated that all operators contacted him by phone or showed up for the Monday morning meeting, with the exception of operators who used UtiliQuest.

Sprint Locate and Marks, but Does Not Provide Electronic Positive Response

Sprint did not provide an electronic positive response (**Exh. 2**), though Johnson indicated in an email that they had marked (**Exh. 4**). DigAlert electronic positive response data indicates that, of the 11,753 tickets Sprint (member code SPRINT1) received in 2021 that required a response, 231 were canceled prior to response, and it did not provide electronic positive response to 11,522 (**Exh. 5**). Sprint had not requested an extension to the January 2021 electronic positive response deadline per Section 4020 of Division 4 of Title 19 of the California Code of Regulations. Attempts to use the phone number listed on the ticket to talk to someone knowledgeable at Sprint were unsuccessful (**Exh. 6**).

Yucaipa Valley Water Does Not Respond

Yucaipa Valley Water District did not respond to the ticket, through electronic positive response or otherwise. Johnson indicated that he'd done work for Yucaipa Valley Water and that they had no facilities in the area (Exh. 3). Mike Rivera, Public Works Manager for Yucaipa Valley Water, indicated that the ticket was out of Yucaipa Valley Water service territory (Exh. 7). Rivera indicated that they did not respond to tickets outside of their service area. Once the legal requirement was explained to him, including the electronic positive response requirement, and that an excavator may not know what Yucaipa Valley Water's territory is, Rivera stated that he'd tell his staff to respond to every ticket and would contact DigAlert to tighten up the area in which he was notified of tickets. DigAlert electronic positive response data indicates that, of the 2,350 tickets Yucaipa Valley Water (member code YVC01) received in 2021 that required a response, it responded to 13 indicating "no conflict," 28 were canceled prior to response, and it did not provide electronic positive response to 2,309 (Exh. 5). Yucaipa Valley Water had not requested an extension to the January 2021 electronic positive response deadline per Section 4020 of Division 4 of Title 19 of the California Code of Regulations.1

Late Responses of Spectrum, Southern California Edison, and Frontier

At 10:13 a.m. on Monday, January 10, after the scheduled "meet and mark," Johnson made a "no response" notification through DigAlert (**Exh. 2**), and shortly thereafter he received a phone call from a UtiliQuest technician, in which Johnson agreed that he would not begin potholing until the morning of Wednesday, January 12 (**Exh. 8**).

UtiliQuest representatives contacted Johnson by email at 12:11 p.m. on Tuesday, January 11 to inform him that their technician had not yet marked the area and would arrive on location as soon as possible (**Exh. 8**). Johnson indicated that UtiliQuest had marked for Southern California Edison by the evening of Tuesday, January 11 (**Exh. 3**). Electronic positive response notifications confirm this, indicating that Southern California Edison Transmission

5

¹ Electronic positive response extensions: https://energysafety.ca.gov/who-we-are/underground-safety-board/requirement-to-provide-electronic-positive-response-epr/

Telecommunications and Southern California Distribution – Desert Region marked the area the morning of January 11. Electronic positive response notifications also indicate that Spectrum - Riverside responded with no conflict the morning of January 11 (Exh. 2). Member name "Spectrum – Riverside" (member code UCHTRW_S1) is a brand of Charter Communications, who is the DigAlert member responsible for the Spectrum lines (Exh. 9).

Frontier's Unlocatable Fiber Line

At 3:46 p.m. on January 11, after Spectrum and Southern California Edison had provided electronic positive responses, Frontier responded "(014) PARTIALLY MARKED - MORE TIME IS NEEDED" (**Exh. 2**). At 5:50 p.m., Johnson emailed UtiliQuest and Frontier personnel suggesting that Frontier "pull out all the stops" to get facilities marked prior to beginning of work (**Exh. 10**).

On January 13, 14, 17, 18, and 19, Johnson made "no response" notifications to DigAlert identifying "**NO RESPONSE** FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED" (Exh. 2).

Johnson called the UtiliQuest number for Frontier provided on the ticket on January 18 and was directed to contact Gabriel Gonzales, also of UtiliQuest (**Exh. 11**). Johnson called Gonzales, with whom Johnson was familiar from work on previous jobs, on January 19. According to Johnson, Gonzales informed him that they were waiting on Frontier, who had a fiber optics line without a tracer wire. UtiliQuest needed Frontier to install the tracer wire in order to mark the facility (**Exh. 3**). Johnson asked Gonzales for a Frontier phone number, but the number Gonzales provided to Johnson was the Frontier customer tech/repair department number (**Exhs. 3 & 12**).

Joseph Anton, Regional Manager of Claims and Compliance at UtiliQuest, indicated that the UtiliQuest technician locating for Frontier on January 11 identified a fiber line without a tracer wire through visual inspection of the line inside the structure (**Exh. 13**). At 4:18 p.m. pm January 11, Dochelle Lewis, for UtiliQuest, escalated made a client assistance request to Frontier regarding ticket B220050037 and requesting that Frontier notify her when the tracer wire had been installed (**Exh. 10**).

Johnson made further "no response" notifications to DigAlert on January 20 and 21. On Thursday, January 27, Jaime Meza of Frontier emailed Johnson to let him know that a crew would be installing tracer wire the following day (**Exh. 14**). Johnson verified that the area was marked on January 27 (**Exh. 15**).

Anton believed that Frontier had contractor SECC add a tracer wire, which was complete on January 27, with the exception of a 30-foot portion of conduit. The 30-foot section had conduit damage, and tracer wire could not be pushed through it (**Exh. 16**). Anton stated that Johnson was made aware of the 30-foot section that had not been marked (**Exh. 13**), which Johnson confirmed (**Exh. 17**).

Anton stated during the February 1 interview that he believed the conduit was to be repaired the next day, or February 2. When asked during the interview about who may have performed the conduit repair work, Anton stated that he didn't know, but that question could be asked of Frontier. Ticket information provided by DigAlert about excavations in the Noble Creek Park area from January 10 through February 28 did not indicate any excavation work in the area associated with the installation of tracer wire or the repair of damage to buried conduit (Exh. 18). Johnson indicated on March 4 that he did not believe any conduit repair had been done (Exh. 17).

When asked how UtiliQuest informed Frontier of the unlocatable line, he stated that it had been done through a form. When asked if he would provide the form, he said that he could not, but that it could be asked of Frontier (**Exh. 16**), and he provided the contact information for Frontier representative Bin Liang (**Exh. 19**). Mr. Liang is also listed as the Frontier contact for vacuum excavation on ticket B220050037 (**Exh. 20**).

Mr. Liang did not respond to emails requesting:

- The report that UtiliQuest provided to notify them of the unlocatable facility
- The names of companies performing installing the tracer wire and repairing the conduit, and whether any required excavation work, along with relevant ticket numbers
- Maps of the fiber line location
- A timeline of events from notification by UtiliQuest of the unlocatable line through installation of the line and conduit repair

(Exh. 21)

Anton indicated that UtiliQuest did what it could do: it located the lines, when it found and unlocatable line it passed that information to Frontier to address, and it kept the excavator informed of the situation (**Exh. 16**).

A timeline of communications between Johnson and Frontier may be seen in **Table 1**.

Day	Date	Time	Event	Exhibit
Wednesday	1/5/2022	6:56 AM	Johnson requests new ticket, indicating meet & mark 9:00 am Monday, Jan 10	2
Friday	1/7/2022	8:22 AM	Spectrum, So Cal Edison, and Frontier provide EPR identifying a negotiated marking schedule	2
Monday	1/10/2022	10:13 AM	Johnson submits a "no response" ticket to DigAlert, identifying cable, electric, and fiber as no-show to meet & mark and provided no marks	2

Monday	1/10/2022	10:26	Spectrum, So Cal Edison, and Frontier	2
,	, ,	AM	provide EPR stating "clear - no conflict"	
Monday	1/10/2022	11 AM approx	UtiliQuest technician contacts Johnson stating that he'll be able to provide marks by the afternoon of 1/11. Johnson agrees.	3, 16
Monday	1/10/2022	3:51 PM	Spectrum, So Cal Edison, and Frontier provide updated EPR stating "scheduled meet with excavator at requested date and time"	2
Tuesday	1/11/2022	10:52 AM	Spectrum provides EPR indicating "clear - no conflict." So Cal Edison provides EPR indicating "locate area marked." Frontier provides EPR indicating "partially marked - more time is needed."	2
Tuesday	1/11/2022	12:11 AM	UtiliQuest personnel contacts Johnson notifying him that their technician has not yet marked and would arrive on location as soon as possible.	8
Monday	1/11/2022	4:18 PM	Dochelle Lewis of UtiliQuest sends email to Frontier requesting an email when tracer wire had been installed	10
Tuesday	1/11/2022	5:50 PM	Johnson emails UtiliQuest and Frontier personnel suggesting that Frontier "pull out all the stops" to get facilities marked prior to beginning of work	10
Thursday	1/13/2022	4:46 PM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show and that excavator has not agreed to more time	2
Friday	1/14/2022	2:43 PM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Monday	1/17/2022	5:34 AM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Tuesday	1/18/2022	7:02 AM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Tuesday	1/18/2022	4:32 PM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Tuesday	1/18/2022	5:00 PM	Johnson submits complaint to Board	
Wednesday	1/19/2022	8:42 AM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Wednesday	1/19/2022	9:13 AM	Johnson emails UtiliQuest and Frontier personnel that he has not received	10

			response "as to if or when" facilities would be located	
Wednesday	1/19/2022		Johnson contacts Gabriel Gonzales of UtiliQuest, who indicates that they are still waiting on Frontier	24
Thursday	1/20/2022	6:23 AM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Friday	1/21/2022	8:55 AM	Johnson submits a "no response" ticket to DigAlert, identifying fiber as no-show	2
Thursday	1/27/2022	3:12 PM	Jaime Meza of Frontier emails Johnson to let him know that a crew will be installing a tracer wire the following day	14
Friday	1/28/2022		Anton receives an email from Frontier's contractor indicating that tracer wire work was done	16
Monday	1/31/2022	8:18 AM	Johnson submits a renewal ticket	2
Thursday	2/3/2022	4:44 PM	Johnson requests remarks from electric, cable, telephone, and fiber	2

Table 1: Timeline of communications between Johnson and Frontier.

<u>Incorrect Electronic Positive Responses</u>

On January 21, Johnson indicated that he'd received an electronic positive response from Frontier indicating the area had been marked even though he saw the area and the portion that still needed to be marked was not marked. The electronic positive response was transmitted to him by DigAlert via automated email as soon as the response was made (Exh. 22). DigAlert sends automated emails to excavators listing the electronic positive responses after the legal start date and time and subsequently, when any operator submits an electronic positive response after the legal start date and time (Exh. 23).

Johnson stated that he contacted Gabriel Gonzales at UtiliQuest, a representative of Frontier, and Gonzales agreed that the area that needed marked was still not marked (**Exh. 24**). When asked about the response, Anton stated that the response may have been in error, and that the appropriate response should have been that the area was partially marked, and that more time was needed (**Exh. 16**).

The electronic positive response by Frontier on January 21 was not the only incorrect electronic positive response issued for ticket B220050037. Spectrum, Southern California Edison, and Frontier all responded to version 01B of ticket B220050037 with "(001) CLEAR - NO CONFLICT" at about 10:42 a.m. on January 10. At about 3:52 p.m., each changed their responses to "(053)

SCHEDULED MEET WITH EXCAVATOR AT REQUESTED DATE AND TIME" (**Exh. 2**) following discussion between Johnson and a UtiliQuest representative, in which Johnson agreed that he would not begin potholing until the morning of Wednesday, January 12 (**Exh. 8**).

The initial electronic positive response was demonstrated to be incorrect for Frontier, as Frontier would respond "(014) PARTIALLY MARKED - MORE TIME IS NEEDED" at 3:43 p.m. on January 11, as discussed above. The electronic positive response was also incorrect for the two Southern California Edison divisions (SCE DIST - DESERT REG and SCE Trans Telecom), who at 10:52 p.m. on January 11 indicated "(010) LOCATE AREA MARKED." Anton did not respond to an email requesting the reason why incorrect electronic responses were made on January 10 (Exh. 25).

Findings

I. The legal start date for the new ticket (B220050037-00B) was Monday, January 10

While the legal start date and time indicated on the ticket was 5:01 p.m. on Friday, January 7, Johnson Construction identified a "meet and mark" in the location field of the ticket of Monday, January 10, at 9:00 a.m. This constituted an agreement on the part of Johnson Construction that facilities would not need to be marked until that time. Spectrum, Southern California Edison, and Frontier electronic positive responses on January 7 identifying a negotiated marking schedule reflect the January 10 start date.

II. Spectrum, Southern California Edison, Frontier, and Yucaipa Valley Water are in violation of Government Code Section 4216.3 (a)(1)(A)

At 10:13 a.m. January 10, after the 9:00 a.m. "meet and mark" identified on the ticket, Johnson Construction sent made a "no response" notification with DigAlert for cable, electric, and fiber. Only afterward did Spectrum, Southern California Edison, and Frontier contacted Johnson Construction. That Johnson Construction later told the Spectrum, Southern California Edison, and Frontier January 10 that he would not begin potholing until 7:00 a.m. on Wednesday, January 12 does not impact their obligations under Government Code 4216.3 (a)(1)(A) to respond to the excavator prior to the legal start date and time.

Furthermore, Frontier did not complete marking until January 27.

Yucaipa Valley Water did not respond to ticket B220050037-00B because the work area was out of Yucaipa Valley Water's territory. Yucaipa Valley Water may change its notification area. Yucaipa Valley Water must respond to notification it receives pursuant to Government Code 4216.3 (a)(1)(A).

III. Sprint/T-Mobile is in violation of Government Code Section 4216.3(c)(1)(A)

Sprint responded to B220050037-00B but did not provide electronic positive response. One-call center data from 2021 indicates that, while Sprint provided electronic positive responses in USA North 811 territory in 2021, Sprint did not provide electronic positive response in DigAlert territory in all of 2021, though it had not requested an extension to the requirement. All operators are required to provide electronic positive response pursuant to Government Code Section 4216.3 (c)(1)(A).

IV. Frontier's failure to cooperate with the investigation impairs the Board's ability to determine if conduit repair was performed in accordance with Government Code Section 4216 et seq. or to determine whether the timeline for locate and mark completion was reasonable or excessive.

Information from UtiliQuest indicated that Frontier was performing conduit repair—which would be expected to require excavation—but DigAlert did not identify tickets in the area that would indicate such work. The excavator stated that he did not believe that Frontier had performed the repair work. As Frontier chose not to identify the contractors performing the work, provide tickets for the work, or acknowledge that work was being performed at all, it could not be determined whether conduit repair occurred to make that section of fiber optic cable electromagnetically locatable was being conducted according to the requirements of Government Code Section 4216 *et seq.*

Frontier did not indicate to the excavator that the locate area was marked until January 27, twenty-one days after the ticket was issued on January 5 and 16 days after the legal start date of January 10. Both the excavator and Frontier's UtiliQuest representative stated that Frontier needed to install tracer wire in an "unlocatable" conduit containing fiber optic cable, but Frontier chose not to provide a timeline that could have indicated whether Frontier acted expeditiously in attempting to mitigate the safety consequences of the violation.

V. Frontier and Southern California Edison provided incorrect electronic positive responses on January 10, and Frontier again provided an

incorrect response on January 20, in violation of Government Code Section 4216.3 (c)(1)(A).

Frontier and Southern California Edison initially told the excavator, on the legal start date of January 10, through electronic positive response, that they did not have subsurface installations in the work area. This is despite, as substantially the same time, a locator representative of Frontier and Southern California Edison telling the excavator that he would be able to provide marks by the next day.

On January 20, Frontier provided an electronic positive response indicating that the area was marked, when it had not yet been, providing the excavator an opportunity to strike the line. The excavator received this response via a DigAlert email and only found out that it was incorrect after going to the site and calling a representative of Frontier to confirm that the area was not yet marked.

These incorrect electronic positive response notifications are in violation of Government Code Section 4216.3 (c)(1)(A).

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
Signature	Signature
Tony Marino	Jason Corsey

Witness List

Name: Mike Rivera

Organization: Yucaipa Valley Water District Address: P.O. Box 730 Yucaipa, CA 92399

Knowledge of: Non-response of Yucaipa Valley Water to ticket B220050037

Name: Merlin Johnson

Organization: Merlin Johnson Construction, Inc.

Address: P.O. Box 777 Mentone, CA 92359

Knowledge of: Excavation

Name: Joseph Anton Organization: UtiliQuest

Address:

Knowledge of: UtiliQuest response on behalf of Frontier to ticket B220050037

Exhibit List

Exhibit #	Description	Date Received	Received From
1	CSLB License 467306 for	1/19/22	CSLB License
	Merlin Johnson Construction		Check
	Inc		
2	Electronic Positive Response	1/24/22	Amber Dahl
	for Ticket B220050037, as of		
	1/24 9:48am		
3	Report Of Interview For	1/19/22	Merlin Johnson
	Merlin Johnson, 1/19		
4	Email from Merlin Johnson	1/20/22	Merlin Johnson
	regarding Sprint response to		
	ticket		
5	CY 2021 EPR Responses for	4/26/22	DigAlert USA
	Sprint and Yucaipa Valley		
	Water	, ,	
6	Sprint Contact Log	2/15/22	Tony Marino
7	Report of Interview for Mike	2/3/22	Mike Rivera
	Rivera, 2/3		
8	Email correspondence	1/19/22	Merlin Johnson
	between M Johnson and		
	UtiliQuest 1/11/22	-1.1	A D: 1
9	Invoice for Spectrum member	5/4/22	Ann Diamond
	code, addressed to Charter		
10	Communications	1/10/05	Moulin Inhance
10	Email correspondence	1/19/22	Merlin Johnson
	between M Johnson and		
44	UtiliQuest 1/19/22	1/10/05	Moulin Inhance
11	Email response of M. Johnson	1/19/22	Merlin Johnson
	1/19/22 with ticket, email		
12	chain, and narrative	1/10/22	Marlin Johnson
12	Ticket B220050037-00B	1/19/22	Merlin Johnson
	provided to M Johnson on 1/5/22 with handwritten notes		
12	Email response from J. Anton	2/2/22	Joseph Anton
13	regarding locatability	2/2/22	Joseph Anton
	questions		
14	Email message from Jaime	2/1/22	Merlin Johnson
14	Mesa to Merlin Johnson on		Wici iiii juliiisuli
	1/27/2022		
	1/4//4044	l]

_		
Report of Interview of Merlin	2/1/22	Merlin Johnson
Johnson, 2/1		
Report of Interview of Joseph	2/1/22	Joseph Anton
Anton, 2/1		
Report of Interview for Merlin	3/4/22	Merlin Johnson
Johnson, 3/4		
Response from DigAlert	2/28/22	DigAlert USA
regarding Noble Creek Park		
tickets, 2/28		
Email from J. Anton providing	2/1/22	Joseph Anton
Frontier contact		
Ticket B220050037-07B	1/19/22	DigAlert USA
Follow up to request to B.	2/10/22	Tony Marino
Liang for information		
regarding excavation ticket		
B220050037		
EPR email from DigAlert to	2/1/22	Merlin Johnson
Johnson 1/21 12:37pm		
Response of A. Diamond	3/3/22	Ann Diamond
regarding DigAlert EPR		
notification procedures, 3/3		
Report of Interview of Merlin	1/21/22	Merlin Johnson
Johnson 1/21		
Request of J. Anton regarding	2/6/22	Tony Marino
incorrect EPR responses on		
1/10		
	Johnson, 2/1 Report of Interview of Joseph Anton, 2/1 Report of Interview for Merlin Johnson, 3/4 Response from DigAlert regarding Noble Creek Park tickets, 2/28 Email from J. Anton providing Frontier contact Ticket B220050037-07B Follow up to request to B. Liang for information regarding excavation ticket B220050037 EPR email from DigAlert to Johnson 1/21 12:37pm Response of A. Diamond regarding DigAlert EPR notification procedures, 3/3 Report of Interview of Merlin Johnson 1/21 Request of J. Anton regarding incorrect EPR responses on	Report of Interview of Joseph Anton, 2/1 Report of Interview for Merlin Johnson, 3/4 Response from DigAlert regarding Noble Creek Park tickets, 2/28 Email from J. Anton providing Frontier contact Ticket B220050037-07B Follow up to request to B. Liang for information regarding excavation ticket B220050037 EPR email from DigAlert to Johnson 1/21 12:37pm Response of A. Diamond regarding DigAlert EPR notification procedures, 3/3 Report of Interview of Merlin Johnson 1/21 Request of J. Anton regarding incorrect EPR responses on

Exhibit 1

Contractor's License Detail for License # 467306



- CSLB complaint disclosure is restricted by law (<u>B&P 7124.6</u>) If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click <u>here</u> for a definition of disclosable actions.
- Only construction related civil judgments reported to CSLB are disclosed (<u>B&P 7071.17</u>).
- Arbitrations are not listed unless the contractor fails to comply with the terms.
- Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Business Information

MERLIN JOHNSON CONSTRUCTION INC P O BOX 777 MENTONE, CA 92359 Business Phone Number:(909) 794-7702

> Entity Corporation Issue Date 12/24/1984 Expire Date 12/31/2022

License Status

This license is current and active.

All information below should be reviewed.

Classifications

A - GENERAL ENGINEERING

Bonding Information

Contractor's Bond

This license filed a Contractor's Bond with <u>AMERICAN CONTRACTORS INDEMNITY</u> COMPANY.

Bond Number: 62159

Bond Amount: \$15,000

Effective Date: 01/01/2016

Contractor's Bond History

Bond of Qualifying Individual

The qualifying individual MERLIN KENNETH JOHNSON certified that he/she owns 10 percent or more of the voting stock/membership interest of this company; therefore, the Bond of Qualifying Individual is not required.

Effective Date: 12/24/1984

Workers' Compensation

This license has workers compensation insurance with the <u>STATE COMPENSATION</u> <u>INSURANCE FUND</u>

Policy Number:9058830 Effective Date: 06/01/2013 Expire Date: 06/01/2022

Workers' Compensation History

Other

 Personnel listed on this license (current or disassociated) are listed on other licenses.

Exhibit 2

MBRCOD 00001A USAS 01/24/22 09:48:02 B220050037-00B NEW NORM POLY LREQ

Ticket: B220050037 Rev: 00B Created: 01/05/22 06:56 User: MERLIN Chan: WEB

Work Start: 01/07/22 17:01 Legal Start: 01/07/22 17:01 Expires: 02/02/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876 : 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=786u3x0v0syvyq2-h

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-00B

Member	Name	Rev	Responded	Ву	Response
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	00B	01/07/22 05:01:06 PM	Late Notice	(999) Member did not respond by the required time
BEAU01	CITY OF BEAUMONT		01/06/22 03:27:09 PM		(010) LOCATE AREA MARKED
MCISOCAL	MCI (VERIZON BUSINESS)	00B	01/05/22 07:03:42 AM	FLPS	(001) CLEAR - NO CONFLICT
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00B	01/10/22 08:23:11 AM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT

Member	Name	Rev	Responded	Ву	Response
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00B	01/07/22 05:01:06 PM	Late Notice	(999) Member did not respond by the required time
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	00B	01/06/22 06:47:32 AM	PRSDG01 JSPEREZ1	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER
SPRINT1	SPRINT	00B	01/07/22 05:01:06 PM	Late Notice	(999) Member did not respond by the required time
UCHTRW_S1	SPECTRUM - RIVERSIDE	00B	01/07/22 08:22:15 AM	UQ Responder	(050) NEGOTIATED MARKING SCHEDULE
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	00B	01/07/22 08:22:15 AM	UQ Responder	(050) NEGOTIATED MARKING SCHEDULE
USCETT84SE	SCE TRANS TELECOM	00B	01/07/22 08:22:15 AM	UQ Responder	(050) NEGOTIATED MARKING SCHEDULE
UTFTRCA01	UTILIQUEST FOR FRONTIER		01/07/22 08:22:19 AM	UQ Responder	(050) NEGOTIATED MARKING SCHEDULE
YVC01	YUCAIPA VALLEY WTR	00B	01/07/22 05:01:06 PM	Late Notice	(999) Member did not respond by the required time

MBRCOD 00001A USAS 01/24/22 09:48:03 B220050037-01B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 01B Created: 01/10/22 10:13 User: MERLIN Chan: WEB

Work Start: 01/10/22 10:09 Legal Start: 01/10/22 10:13 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

USCETT84SE UTFTRCA01

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=689r7p4vyu6ryr5-i

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.
HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

Members:

USCEDE

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

YVC01

Ticket Responses for: B220050037-01B

Member Name Rev Responded By Response Comment

Member	Name	Rev Respond	ed By	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	01/10/22 01B 10:19:43 AM		(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/10/22, 10:19 AM
MCISOCAL	MCI (VERIZON BUSINESS)	01/10/22 01B 10:18:44 AM		(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	01/10/22 01B 10:26:19 AM	PRNIJALI	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	01/13/22 01B 07:42:00 AM	PRNIJALI	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	01/11/22 01B 10:52:32 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	01/10/22 01B 03:51:36 PM		(053) SCHEDULED MEET WITH EXCAVATOR AT REQUESTED DATE AND TIME	
UCHTRW_S1	SPECTRUM - RIVERSIDE	01/10/22 01B 11:42:42 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01/11/22 01B 10:52:33 AM	UQ Responder	(010) LOCATE AREA MARKED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01/10/22 01B 03:51:37 PM		(053) SCHEDULED MEET WITH EXCAVATOR AT REQUESTED DATE AND TIME	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01/10/22 01B 11:42:42 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM	01/11/22 01B 10:52:33 AM	UQ Responder	(010) LOCATE AREA MARKED	
USCETT84SE	SCE TRANS TELECOM	01/10/22 01B 03:51:37 PM	11()	(053) SCHEDULED MEET WITH EXCAVATOR AT REQUESTED DATE AND TIME	
USCETT84SE	SCE TRANS TELECOM	01/10/22 01B 11:42:42 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01/11/22 01B 03:46:52 PM	, uų	(014) PARTIALLY MARKED - MORE TIME IS NEEDED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01/11/22 01B 10:52:34 AM	UQ Responder	(010) LOCATE AREA MARKED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01/10/22 01B 03:51:42 PM		(053) SCHEDULED MEET WITH EXCAVATOR AT REQUESTED DATE AND TIME	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01/10/22 01B 11:42:46 AM	UQ Responder	(001) CLEAR - NO CONFLICT	

MBRCOD 00001A USAS 01/24/22 09:48:03 B220050037-02B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 02B Created: 01/13/22 16:46 User: MERLIN Chan: WEB

Work Start: 01/13/22 16:45 Legal Start: 01/13/22 16:46 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=584w1z5uzxx5o0u-p

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.
HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B220050037-02B

Member	Name	Rev	Responded	By	Response
MCISOCAL	MCI (VERIZON BUSINESS)	02B P	01/13/22 04:53:40 M	FLPS	(001) CLEAR - NO CONFLICT
SCG1BT	BEALIMON I	Δ	01/14/22 06:46:58 M	I F I F NIN I N	(001) CLEAR - NO CONFLICT
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	02B A	 01/14/22 09:26:40 M	PRSDG01 JSPEREZ1	(001) CLEAR - NO CONFLICT

MBRCOD 00001A USAS 01/24/22 09:48:04 B220050037-03B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 03B Created: 01/14/22 14:43 User: MERLIN Chan: WEB

Work Start: 01/14/22 14:42 Legal Start: 01/14/22 14:43 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City: MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=486u3t0zuyw8hAo-z

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED. ***HAD NO CONTACT FROM UTILITY*** PER MERLIN JOHNSON--[MERLIN 01/10/2022

10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING

PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-03B

Member Name Rev Responded By Response

MCISOCAL MCI (VERIZON BUSINESS) 03B 01/14/22 02:48:41 PM FLPS (001) CLEAR - NO CONFLICT

MBRCOD 00001A USAS 01/24/22 09:48:04 B220050037-04B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 04B Created: 01/17/22 05:34 User: MERLIN Chan: WEB

Work Start: 01/17/22 05:34 Legal Start: 01/17/22 05:34 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City: MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=38u5yyx0t1t2n9p-y

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.

HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS

PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-04B

Member	Name	Rev	Responded	Ву	Response
MCISOCAL	MCI (VERIZON BUSINESS)	04B 01 AM	1/17/22 05:38:41 1	FLPS	(001) CLEAR - NO CONFLICT
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	04B 01 AM	1/18/22 06:59:51 N	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT

MBRCOD 00001A USAS 01/24/22 09:48:04 B220050037-05B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 05B Created: 01/18/22 07:02 User: MERLIN Chan: WEB

Work Start: 01/18/22 07:02 Legal Start: 01/18/22 07:02 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=28v4v8nChBjEbIg-6

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED. ***HAD NO CONTACT FROM UTILITY*** PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW S1

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B220050037-05B

Member	Name	Rev Responde	d By	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	05B 01/18/22 09:20:37 A	M pcvmd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/18/22, 9:20 AM
MCISOCAL	MCI (VERIZON BUSINESS)	05B 01/18/22 07:08:47 A	M FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	05B 01/18/22 07:52:27 A	PRSDG01 M TEJENNIN	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	05B 01/18/22 09:33:41 A	PRSDG01 M JSPEREZ1	(001) CLEAR - NO CONFLICT	

MBRCOD 00001A USAS 01/24/22 09:48:05 B220050037-06B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 06B Created: 01/18/22 16:32 User: MERLIN Chan: WEB

Work Start: 01/18/22 16:32 Legal Start: 01/18/22 16:32 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=18s7w1yx1vzyr6o-v

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.
HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN JOHNSON--[MERLIN 01/18/2022 04:32:26 PM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-06B

Member	Name	Rev	Responded	Ву	Response	Comment	
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	06В (01/18/22 04:47:21 PM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/18/22, 4:47 PM	
MCISOCAL	MCI (VERIZON BUSINESS)	06В (01/18/22 04:38:42 PM	FLPS	(001) CLEAR - NO CONFLICT		
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	06В (01/19/22 06:47:35 AM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT		

MBRCOD 00001A USAS 01/24/22 09:48:05 B220050037-07B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 07B Created: 01/19/22 08:42 User: MERLIN Chan: WEB

Work Start: 01/19/22 08:42 Legal Start: 01/19/22 08:42 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=08t6t2t5o3r5kBn-0

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.
HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN JOHNSON--[MERLIN 01/18/2022 04:32:26 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/19/2022 08:42:35 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B220050037-07B

Member	Name	Rev Res	ponded By	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	07B 01/19, 10:54	/22 :03 AM bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/19/22, 10:54 AM
MCISOCAL	MCI (VERIZON BUSINESS)	07B 01/19 08:48	/22 :44 AM FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	07B 01/19 10:12	/22 PRSDG01 :19 AM TEJENNIN	(001) CLEAR - NO CONFLICT)

MBRCOD 00001A USAS 01/24/22 09:48:05 B220050037-08B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 08B Created: 01/20/22 06:23 User: MERLIN Chan: WEB

Work Start: 01/20/22 06:23 Legal Start: 01/20/22 06:23 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City : MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=F8PbOYNcHbJeAmB-c

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.
HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN

JOHNSON--[MERLIN 01/18/2022 04:32:26 PM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/19/2022 08:42:35 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CCREW ONSITE
WORKING PER MERLIN JOHNSON--[MERLIN 01/20/2022 06:23:04 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-08B

11cket kesponses 101: b220050057-00b										
Member	Name	Rev	Responded	Ву	Response	Comment				
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	08B	01/20/22 08:41:03 AM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/20/22, 8:41 AM				
MCISOCAL	MCI (VERIZON BUSINESS)	08B	01/20/22 06:26:16 AM	FLPS	(001) CLEAR - NO CONFLICT					
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	08B	01/20/22 06:47:05 AM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT					
UTFTRCA01	UTILIQUEST FOR FRONTIER	08B	01/20/22 12:37:07 PM	UQ Responder	(010) LOCATE AREA MARKED					

MBRCOD 00001A USAS 01/24/22 09:48:06 B220050037-09B NRSP RUSH POLY LREQ

Ticket: B220050037 Rev: 09B Created: 01/21/22 08:55 User: MERLIN Chan: WEB

Work Start: 01/21/22 08:55 Legal Start: 01/21/22 08:55 Expires: 02/02/22 23:59

Response required: N Priority: 0

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City: MENTONE State: CA Zip: 92359
Created By: MERLIN JOHNSON Language: ENGLISH
Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=E8MeLfKbMWKZKZP-O

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED. ***HAD NO CONTACT FROM UTILITY*** PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN JOHNSON--[MERLIN 01/18/2022 04:32:26 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE

WORKING PER MERLIN JOHNSON--[MERLIN 01/19/2022 08:42:35 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CCREW ONSITE
WORKING PER MERLIN JOHNSON--[MERLIN 01/20/2022 06:23:04 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE
WORKING PER MERLIN JOHNSON--[MERLIN 01/21/2022 08:55:14 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B220050037-09B

Member	Name	Rev	Responded	By	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	09B	01/24/22 08:40:03 AM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/24/22, 8:40 AM
MCISOCAL	MCI (VERIZON BUSINESS)	09B	01/21/22 09:01:14 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	09B	01/21/22 10:40:32 AM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	09B	01/24/22 07:19:29 AM	PRSDG01 RLIESTER	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	09B	01/21/22 03:01:48 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	09B	01/21/22 03:01:48 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM		01/21/22 03:01:48 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	09B	01/21/22 03:01:52 PM	UQ Responder	(001) CLEAR - NO CONFLICT	



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 1/19/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 1/19/2022 4:15 PM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Merlin Johnson, P.O. Box 777 Mentone, CA 92359

Tel: 9093226061

NARRATIVE:

I spoke with Merlin Johnson, President of Merlin Johnson Construction, Inc., regarding the project he was performing and the timeline of responses from operators to ticket B220050037 and its revisions. I told Mr. Johnson that I would be asking him questions about the electronic positive responses to the ticket and its revisions. I asked him if he was familiar with electronic positive response and if he reviews the responses, and he stated that he is familiar with it and does review the responses.

I asked about the project that he was performing, and he said that he was performing a water system upgrade for Beaumont-Cherry Valley Recreation and Park District in the Noble Creek Regional Park.

I asked about the "meet and mark" directions in the location description on the ticket. Johnson stated that, while the ticket was due at 5:01pm on Friday, January 7, they weren't going to begin working Friday night, and so he requested a meet for Monday morning January 10 at 9am to discuss marking. He stated that the work area was approximately 20 acres, and that it wouldn't be attractive to mark up the entire park the entire area identified in the ticket. He'd carefully delineated with flags and whiskers the specific areas in which he was working, but thought it might be confusing to locators without his guidance. Johnson stated that everyone had contacted him by phone or showed up for the Monday morning meeting with the exception of the operators using UtiliQuest.

He had received a phone call from the UtiliQuest technician requesting more time to mark. He stated that so long as the work was done the evening of January 11, it was fine with him, as he was not to begin potholing until the morning of January 12 (Wednesday). He indicated that UtiliQuest had marked for Southern California Edison on Tuesday night (1/11) but not for Frontier. I asked Johnson if the "Negotiated Marking Schedule" listed on the EPR for Spectrum, the two Edison units, and Frontier was accurate, and he indicated that the potholing discussion constituted in his mind a negotiated marking schedule.

Upon Frontier not marking prior to January 12, Johnson began submitting no response tickets. He tried contacting Frontier using the phone number on the ticket, but that went to UtiliQuest. He contacted Gabriel Gonzales at UtiliQuest, who he is familiar with from work on other jobs on January 19, and Mr. Gonzales stated that they were waiting on Frontier. According to Gonzales, Frontier had a fiber line without

tracer wire and needed to address the situation so that UtiliQuest could mark. Johnson asked Gonzales for a Frontier phone number, but the number Gonzales provided to Johnson was the Frontier customer service line. I asked if the electronic positive response Frontier provided to revision -01B of the ticket—"Partially Marked—More Time is Needed"—was accurate insofar as whether Frontier had partially marked. Johnson said yes, that was true—UtiliQuest marked for Frontier in some places, but did not mark the most important area—the fiber line.

I noted that Yucaipa Valley Water did not provide an electronic positive response to the -00B ("NEW") version of the ticket. I asked if they had ever responded. Johnson said that they had not, but that they didn't have any facilities in the area. He stated that he'd worked for them before and was familiar with the location of their system.

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
Tony Marino	Jason Corsey

From: Merlin Johnson

To: Marino, Tony@EnergySafety
Cc: "Jake Johnson"; Merlin Johnson

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

Date: Thursday, January 20, 2022 6:07:25 AM

Tony,

Sprint **DID** respond both by phone and marked their facilities. The Sprint facilities were not within the limits of our construction area, but they marked them anyway. The Tech. from print responded to the first two or three "No Response" Tickets that I sent in. I then explained what was going on and told him that he did not need to respond to the "No Response" Tickets anymore.

Let me know if you have additional questions.

THANKS

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777 Mentone, California 92359 909-794-7702 Office 909-322-6061 Cell mj.mjc@verizon.net

From: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Sent: Wednesday, January 19, 2022 6:02 PM **To:** Merlin Johnson <mj.mjc@verizon.net> **Cc:** 'Jake Johnson' <jake.mjc@verizon.net>

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

Merlin,

Thanks for talking with me today. In reviewing the electronic positive responses again for the different revisions of the ticket, I noticed that Sprint did not respond to the new ticket (B220050037-00B) or any of the subsequent revisions. Did Sprint ever respond to you? If so, by what means did they respond (phone, email, etc) and how did they respond (locating and marking, no conflict, etc)?

Thanks,

Tony

From: Merlin Johnson <mj.mjc@verizon.net>
Sent: Wednesday, January 19, 2022 3:53 PM

To: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Cc: 'Jake Johnson' <<u>jake.mjc@verizon.net</u>>; Merlin Johnson <<u>mj.mjc@verizon.net</u>>

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

Tony,

Just got back in office and can do interview anytime

Merlin Johnson

Merlin Johnson Construction, Inc.

P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizonnet

From: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Sent: Wednesday, January 19, 2022 1:28 PM **To:** Merlin Johnson < mj.mjc@verizon.net > **Cc:** Jake Johnson < jake.mjc@verizon.net >

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

To follow up, I'll be using the attached document of electronic positive responses to ask questions.

Thanks, Tony

From: Marino, Tony@EnergySafety

Sent: Wednesday, January 19, 2022 1:22 PM **To:** Merlin Johnson <<u>mj.mjc@verizon.net</u>> **Cc:** Jake Johnson <<u>jake.mjc@verizon.net</u>>

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

Mr. Johnson,

I am reviewing the documentation you sent today. Would you have time 3pm or later for an interview? There are some questions regarding Frontier/UtiliQuest electronic positive responses I'd like to ask about, in addition to me asking general questions about the project.

Thanks, Tony

From: Marino, Tony@EnergySafety

Sent: Wednesday, January 19, 2022 12:14 PM

To: Merlin Johnson <mj.mjc@verizon.net> **Cc:** Jake Johnson <<u>jake.mjc@verizon.net</u>>

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

Thank you Mr. Johnson. Could you send the email string from 1-11-22 in a way that doesn't come from a scanned image? We're having trouble making it ADA accessible, which we'll need if it is necessary in the final report. If you can convert it to a pdf within outlook, that would be great. If not, a .msg file should be fine as well.

Thanks, Tony

From: Merlin Johnson <mj.mjc@verizon.net>
Sent: Wednesday, January 19, 2022 11:10 AM

To: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Cc: Jake Johnson < <u>jake.mjc@verizon.net</u>>; Merlin Johnson < <u>mj.mjc@verizon.net</u>> **Subject:** RE: Complaint C220180003; Case 22LA01484 -- Request for information

Mr. Marino,

Thank you for returning my call this morning. Attached you will find the following:

- 1. Copy of the original USA Ticket for the project.
- 2. Email string from 01-11-22.
- 3. Email string from 01-19-22.
- 4. Narrative of conversations.

NARRATIVE

In the original USA Ticket number B220050037, I requested a field meet to go over the project limits with all utilities. Utiliquest is the only Utility representative that did not show up or call.

On January 10, 2022 I sent in the first "No Response" Ticket to USA. Later that day a Tech. from Utiliquest called and stated that he would have everything marked by the end of the day on January 12th. (See Email chain of 01-11-22)

I have sent in a No Response Ticket almost every day since.

On January 18, 2022, I call the phone number provided on the Ticket and spoke with the operator for Utiliquest. He advised that I call the field supervisor for that area, Gabriel Gonzales, which I did. Mr. Gonzales stated that Utiliquest was waiting on Frontier and that there was nothing that he could do to expedite.

Please let me know if you need any additional information.

THANK YOU FOR YOUR HELP

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizonnet

From: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Sent: Wednesday, January 19, 2022 10:01 AM

To: mj.mjc@verizon.net

Subject: Complaint C220180003; Case 22LA01484 -- Request for information

Mr. Johnson,

We have opened a case into your complaint from yesterday, and I am assigned to perform the investigation. Thank you for speaking with me this morning. Could you provide some information to assist us in pursuing this investigation? Particularly, could you provide

- The ticket number for the excavation
- Any written correspondence you had with Frontier or their contract locator UtiliQuest, including their responses
- A brief description of any verbal conversations you had with Frontier or UtiliQuest representatives

After reviewing these documents, I'll likely reach out to you for a request to interview.

Thanks, Tony

Tony Marino

Executive Officer | Underground Infrastructure Safety Directorate Office of Energy Infrastructure Safety

1516 9th Street Sacramento, CA 95814 916-767-3370 EnergySafety.ca.gov

From: <u>Amber Dahl</u>

To: <u>Marino, Tony@EnergySafety</u>

Subject: RE: EPR information request, Investigation 22LA01484

Date:Tuesday, April 26, 2022 11:55:04 AMAttachments:YVC01 and SPRINT1 EPR Data.xlsx

Please see attached. Let me know if there is anything else.

Thank you,



Amber Dahl, Safety Director

Underground Service Alert of Southern California (DigAlert) PO Box 77070 Corona, CA 92877

O: (951) 808-8115 F: (951) 808-8101

E: amber@digalert.org W: www.digalert.org

This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.

From: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Sent: Tuesday, April 26, 2022 9:53 AM **To:** Amber Dahl <amber@digalert.org>

Subject: EPR information request, Investigation 22LA01484

Amber, could you provide electronic positive response information for Board Investigation 22LA01484? Specifically, I'm looking for the numbers of tickets requiring EPR by the following companies in 2021, and the numbers of tickets associated with each code, including code 999 (no response).

I am looking for this information for the following operators:

Sprint (SPRINT1)

Yucaipa Valley Water (YVC01)

Let me know if you have any questions.

Thanks,

Tony

Executive Officer | Underground Infrastructure Directorate

Office of Energy Infrastructure Safety 1516 9th Street, Sacramento, CA 95814 (916) 767-3370 tony.marino@energysafety.ca.gov

Code	TKTS	1	2	3	4	10	11	12	13	14	15	20	21	22	23	30
YVC01	2260	13	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SPRINT1	11134	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

31	32	33	34	35	40	41	42	43	50	51	52	53	80	990	999 To	otal
0	0	0	0	0	0	0	28	0	0	0	0	0	0	0	2309	2350
0	0	0	0	0	0	0	231	0	0	0	0	0	0	0	11522	11753

Sprint contact

Date	Time	Number	Result		
2/3/22	9:28am	800-521-0579	Contacted the emergency/vacuum/no response number		
			for Sprint on ticket B220050037. I explained to the		
			person who picked up the reason for my call, and she		
			referred me to Nathan Brookman (816-309-4004),		
			though said he might refer me to "Jason."		
2/3/22	9:34am	816-309-4004	Left VM for Brookman explaining who I was and my		
			request for info regarding response to ticket		
			B220050037. Left my phone number.		
2/10/22	10:12am	816-309-4004	Left follow-up VM with my phone number and email		
			address.		
2/15/22	9:02am	800-521-0579	Contacted again the emergency/vacuum/no response		
			number for Sprint on ticket B220050037. Rang for		
			approximately 60 seconds w/o going to voicemail, and		
			then hung up.		



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 2/3/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 2/3/2022 10:50 AM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Mike Rivera, P.O. Box 730 Yucaipa, CA 92399

Tel: 909-721-2462

NARRATIVE:

I spoke with Mike Rivera, Public Works Manager for Yucaipa Valley Water District, regarding Yucaipa Valley Water's lack of response to Ticket B220050037. Rivera stated that, since the URL that allowed electronic response became available on the tickets they receive, he has been telling his guys to respond using the ticket. He said that the ticket he received was out of their grid. I asked if they responded to tickets that were out of his service territory, and he said that they didn't. I informed him of the requirement that they respond to every ticket they receive, and I explained that, while they might have known that the excavation was outside their area, an excavator may not know. Rivera stated that he would tell all of his guys to respond to all tickets they receive. I also explained that, as of January 2021, they need to respond electronically, in addition to any other response they provide, due to a new requirement in law.

I asked him if he was aware that he could contact DigAlert to tighten up the area in which they receive tickets to only their service territory, and he said yes, he was aware, and based on our conversation planned to do so. I asked him if he had contact information for DigAlert, and he said yes, that he had contact information for Ann.

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
tony Marino	Jason Corsey

Merlin Johnson

From:

Merlin Johnson <mj.mjc@verizon.net>

Sent:

Tuesday, January 11, 2022 2:24 PM

To:

'Cazares, Jasmin'

Cc:

Merlin Johnson (mj.mjc@verizon.net)

Subject:

RE: USA Ticket #B220050037

Good Afternoon Jasmin,

In a phone call with your tech yesterday I had agreed that you would be able to mark this morning and thereby let us look at the marks and start potholing tomorrow January 12th. Our crew will be potholing starting at 0700 January 12, 2022. **All** facilities must be marked prior to that date and time.

THANK YOU

Merlin Johnson
Merlin Johnson Construction, Inc.
P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: Cazares, Jasmin < jasmin.cazares@utiliquest.com>

Sent: Tuesday, January 11, 2022 12:11 PM To: Merlin Johnson <mj.mjc@verizon.net>

Subject: USA Ticket #B220050037

Merlin.

I am emailing in regards to USA Ticket #B220050037. Our tech has not marked yet and will arrive at the location as soon as possible. Do not start excavating until you have received a positive response on site.

Thank You,

Jasmin Cazares
UtiliQuest

Dispatch

Cell (562) 916-6010

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

Merlin Johnson

From:

Merlin Johnson <mj.mjc@verizon.net>

Sent:

Tuesday, January 11, 2022 5:50 PM

To:

'Lewis, Dochelle'; 'Gustavo Gamboa'; 'Sergio Salcedo'; 'Meza, Jaime'; 'Samp, Wayne';

'Rider II, Troy'; 'King, Richard'; 'Ortiz, Gabriel'; 'Gabriel Gonzalez'

Cc:

Jake Johnson (jake.mjc@verizon.net); Merlin Johnson (mj.mjc@verizon.net)

Subject:

RE: Client Assistance Request Form for Ticket B220050037

Utiliquest

Dochelle Lewis,

Ticket Number B220050037 was called in at 0658 hrs on 01/05/22.

The "Legal Start": was 01/07/22 at 1701 hrs.

To assist in locating the existing facilities I scheduled a "Meet and Mark" for January 10, 2022 at 0900 (all utilities with the exception of those marked by Utiliquest responded).

At 1013 hrs 01/10/22 I sent in a "NO RESPONSE" Ticket to USA. Approximately one hour after that I received a phone call from a Tech with Utiliquest saying that he needed help to mark the existing facilities, but that he would have them marked by Tuesday afternoon, the 11th. I agreed as long as all marking was complete on Tuesday.

I to can also quote 4216, (although my quote would be correct), but I also know the following:

Utiliquest is not the owner or operator of any Frontier facilities.

All utilities received timely notice of our work per 4216.

Utiliquest chose to ignore that notice and now asks us to wait on them. This now makes it the OPERATORS problem.

The LEGAL START date and time is over four days ago.

I would suggest that the real OPERATOR pull out all of the stops and get their facilities marked prior to when we will be legally starting our work.

You may want to also take a look at 4216.7 (c), (d).

THANK YOU FOR YOUR PROMPT ATTENTION TO THIS

Merlin Johnson
Merlin Johnson Construction, Inc.
P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: Lewis, Dochelle <dochelle.lewis@utiliquest.com>

Sent: Tuesday, January 11, 2022 4:18 PM

To: Gustavo Gamboa <gustavo.gamboa@utiliquestops.com>; Sergio Salcedo <sergio.salcedo@utiliquestops.com>; Meza, Jaime <jaime.meza@ftr.com>; Samp, Wayne <wayne.k.samp@ftr.com>; Rider II, Troy <troy.e.rider@ftr.com>; King, Richard <richard.king1@ftr.com>; Ortiz, Gabriel <gabriel.b.ortiz@ftr.com>; MJ.MJC@verizon.net; Gabriel Gonzalez <gabriel.gonzalez@utiliquest.com>

Subject: Client Assistance Request Form for Ticket B220050037

MERLIN JOHNSON CONSTRUCTION, INC. MERLIN JOHNSON

This email is regarding ticket B220050037 in the City of Beaumont

At this time the markings for Frontier are incomplete, there are undetectable facilities that we are escalating to our customer.

You are not clear to proceed with any excavation at this time.

Please be patient

California Government Code 4216.7.

(a) If a subsurface installation is damaged by an excavator as a result of failing to comply with Section 4216.2 or 4216.4, or subdivision (b) of Section 42163, or as a result of failing to comply with the perator's (UtiliQuest) requests to protect the subsurface installation as specified by the operator before the start of excavation, the excavator shall be liable to the operator of the subsurface installation for resulting damages, costs, and expenses to the extent the damages, costs, and expenses were caused by the excavator's failure to comply.

Frontier Jaime Meza Wayne Samp Gabriel Ortiz Richard King Troy Rider

Gentlemen.

Attached is a client assistance request in the City of Beaumont

If you have any questions or concerns, or if you would like a Field Meet, please feel free to send me an email.

Please send an email when the Tracer Wire has been installed.

Thank you,

Dochelle Lewis

Administrative Assistant
<u>UtiliQuest</u>
Colton Office

951-295-0573 - cell 951-682-0777 - office dochelle.lewis@utiliquest.com

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

From: **Ann Diamond**

Marino, Tony@EnergySafety To:

Subject: RE: Request for corporate entity: Investigation 22LA01484

Date: Wednesday, May 4, 2022 11:10:43 AM

Attachments: uchtrw s1.pdf

Tony

Attached is an invoice that UCHTRW_S1 is billed

Thanks.



Ann Diamond, President PO BOX 77070 Corona, CA 92877

P: 951-808-8113 F: 951-808-8101



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.

From: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Sent: Wednesday, May 4, 2022 11:07 AM To: Ann Diamond <ann@digalert.org>

Subject: Request for corporate entity: Investigation 22LA01484

Ann,

Could you provide an invoice for member code/name UCHTRW S1/SPECTRUM - RIVERSIDE that identifies the corporate entity that pays the invoice? For your reference, this is related to Investigation 22LA01484.

Thank you, Tony

Tony Marino

Executive Officer | Underground Infrastructure Directorate

Office of Energy Infrastructure Safety

1516 9th Street. Sacramento, CA 95814 (916) 767-3370 tony.marino@energysafety.ca.gov



Underground Service Alert of Southern California PO Box 77070 Corona, CA 92877-0102

5/1/2022 Invoice # 420220696

Charter Communications 10450 Pacific Center Court San Diego, CA 92121 Business Planning SOCALSOUTH

PO #4200567319

Quantity	Description	Rate	Amount
2,905	UCHTRW_S1 New Ticket Charges	1.65	4,793.25
5,402	UCHTRW_S2 New Ticket Charges	1.65	8,913.30
-4	UCHTRW_S2-ca New Ticket Credits	1.65	-6.60
1,726	UCHTRW_S3 New Ticket Charges	1.65	2,847.90
1,440	UCHTRW_S4 New Ticket Charges	1.65	2,376.00
-1	UCHTRW_S4-ca New Ticket Credits	1.65	-1.65
1	Monthly Database Maintenance Fee for 1 to 5 member codes	10.00	10.00

Total Due \$18,932.20

Detach remittance and return with your check made payable to Underground Service Alert of Southern California

REMITTANCE

The rate for new tickets will increase to \$1.75 beginning July 1, 2022

Member Code: SOCALSOUTH

Invoice # 420220696

Due Date: 6/15/2022 Amount Due: \$18,932.20

Amount Enclosed:

Underground Service Alert/SC PO Box 77070 Corona, CA 92877-0102

Merlin Johnson

From:

Merlin Johnson <mj.mjc@verizon.net>

Sent:

Wednesday, January 19, 2022 9:13 AM

To:

'Dochelle"; 'Gustavo Gamboa'; 'Sergio Salcedo'; 'Jaime"; 'Angela Navarro'; 'Wayne";

'Troy"; 'Richard"; 'Gabriel"; 'Gabriel Gonzalez'

Cc:

Jake Johnson; Merlin Johnson

Subject:

FW: Client Assistance Request Form for Ticket B220050037

As of this date and time I have NO response from Utiliquest or Frontier as to if or when the underground facilities will be located per 4216.

We have a crew onsite working.

ANY AND ALL DAMAGES WHICH MAY OCCUR DUE TO THE FAILURE OF FRONTIER TO MARK THEIR FACILITIES PER 4216, WILL BE THE RESPONSILILITY OF FRONTIER.

Merlin Johnson
Merlin Johnson Construction, Inc.
P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: Merlin Johnson <mj.mjc@verizon.net> Sent: Tuesday, January 11, 2022 5:50 PM

To: 'Lewis, Dochelle' <dochelle.lewis@utiliquest.com>; 'Gustavo Gamboa' <gustavo.gamboa@utiliquestops.com>; 'Sergio Salcedo' <sergio.salcedo@utiliquestops.com>; 'Meza, Jaime' <jaime.meza@ftr.com>; 'Samp, Wayne' <wayne.k.samp@ftr.com>; 'Rider II, Troy' <troy.e.rider@ftr.com>; 'King, Richard' <richard.king1@ftr.com>; 'Ortiz, Gabriel' <gabriel.b.ortiz@ftr.com>; 'Gabriel Gonzalez' <gabriel.gonzalez@utiliquest.com>
Cc: Jake Johnson (jake.mjc@verizon.net) <jake.mjc@verizon.net>; Merlin Johnson (mj.mjc@verizon.net)
<mj.mjc@verizon.net>

Subject: RE: Client Assistance Request Form for Ticket B220050037

Utiliquest

Dochelle Lewis,

Ticket Number B220050037 was called in at 0658 hrs on 01/05/22.

The "Legal Start": was 01/07/22 at 1701 hrs.

To assist in locating the existing facilities I scheduled a "Meet and Mark" for January 10, 2022 at 0900 (all utilities with the exception of those marked by Utiliquest responded).

At 1013 hrs 01/10/22 I sent in a "NO RESPONSE" Ticket to USA. Approximately one hour after that I received a phone call from a Tech with Utiliquest saying that he needed help to mark the existing facilities, but that he would have them marked by Tuesday afternoon, the 11th. I agreed as long as all marking was complete on Tuesday.

I to can also quote 4216, (although my quote would be correct), but I also know the following:

Utiliquest is not the owner or operator of any Frontier facilities.

All utilities received timely notice of our work per 4216.

Utiliquest chose to ignore that notice and now asks us to wait on them. This now makes it the OPERATORS problem.

The LEGAL START date and time is over four days ago.

I would suggest that the real OPERATOR pull out all of the stops and get their facilities marked prior to when we will be legally starting our work.

You may want to also take a look at 4216.7 (c), (d).

THANK YOU FOR YOUR PROMPT ATTENTION TO THIS

Merlin Johnson
Merlin Johnson Construction, Inc.
P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: Lewis, Dochelle <dochelle.lewis@utiliquest.com>

Sent: Tuesday, January 11, 2022 4:18 PM

To: Gustavo Gamboa <gustavo.gamboa@utiliquestops.com>; Sergio Salcedo <sergio.salcedo@utiliquestops.com>; Meza, Jaime <jaime.meza@ftr.com>; Samp, Wayne <wayne.k.samp@ftr.com>; Rider II, Troy <troy.e.rider@ftr.com>; King, Richard <ri>richard.king1@ftr.com>; Ortiz, Gabriel <gabriel.b.ortiz@ftr.com>; MJ.MJC@verizon.net; Gabriel Gonzalez <gabriel.gonzalez@utiliquest.com>

Subject: Client Assistance Request Form for Ticket B220050037

MERLIN JOHNSON CONSTRUCTION, INC. MERLIN JOHNSON

This email is regarding ticket B220050037 in the City of Beaumont

At this time the markings for Frontier are incomplete, there are undetectable facilities that we are escalating to our customer.

You are not clear to proceed with any excavation at this time.

Please be patient

California Government Code 4216.7.

(a) If a subsurface installation is damaged by an excavator as a result of failing to comply with Section 4216.2 or 4216.4, or subdivision (b) of Section 42163, or as a result of failing to comply with the perator's (UtiliQuest) requests to protect the subsurface installation as specified by the operator before the start of excavation, the excavator shall be liable to the operator of the subsurface installation for resulting damages, costs, and expenses to the extent the damages, costs, and expenses were caused by the excavator's failure to comply.

Frontier Jaime Meza Wayne Samp Gabriel Ortiz Richard King Troy Rider

Gentlemen.

Attached is a client assistance request in the City of Beaumont

If you have any questions or concerns, or if you would like a Field Meet, please feel free to send me an email.

Please send an email when the Tracer Wire has been installed.

Thank you,

Dochelle Lewis

Administrative Assistant
<u>UtiliQuest</u>
Colton Office

951-295-0573 - cell 951-682-0777 - office dochelle.lewis@utiliquest.com

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

From: Merlin Johnson

To: <u>Marino, Tony@EnergySafety</u>
Cc: <u>Jake Johnson; Merlin Johnson</u>

Subject: RE: Complaint C220180003; Case 22LA01484 -- Request for information

 Date:
 Wednesday, January 19, 2022 11:09:56 AM

 Attachments:
 USA Ticket No. B220050037, dated 01-05-22.pdf

Email Chain from 01-11-22.pdf Email Chain from 01-19-22.pdf

Mr. Marino,

Thank you for returning my call this morning. Attached you will find the following:

- 1. Copy of the original USA Ticket for the project.
- 2. Email string from 01-11-22.
- 3. Email string from 01-19-22.
- 4. Narrative of conversations.

NARRATIVE

In the original USA Ticket number B220050037, I requested a field meet to go over the project limits with all utilities. Utiliquest is the only Utility representative that did not show up or call.

On January 10, 2022 I sent in the first "No Response" Ticket to USA. Later that day a Tech. from Utiliquest called and stated that he would have everything marked by the end of the day on January 12th. (See Email chain of 01-11-22)

I have sent in a No Response Ticket almost every day since.

On January 18, 2022, I call the phone number provided on the Ticket and spoke with the operator for Utiliquest. He advised that I call the field supervisor for that area, Gabriel Gonzales, which I did. Mr. Gonzales stated that Utiliquest was waiting on Frontier and that there was nothing that he could do to expedite.

Please let me know if you need any additional information.

THANK YOU FOR YOUR HELP

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777 Mentone, California 92359 909-794-7702 Office 909-322-6061 Cell mj.mjc@verizon.net

From: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Sent: Wednesday, January 19, 2022 10:01 AM

To: mj.mjc@verizon.net

Subject: Complaint C220180003; Case 22LA01484 -- Request for information

Mr. Johnson,

We have opened a case into your complaint from yesterday, and I am assigned to perform the investigation. Thank you for speaking with me this morning. Could you provide some information to assist us in pursuing this investigation? Particularly, could you provide

- The ticket number for the excavation
- Any written correspondence you had with Frontier or their contract locator UtiliQuest, including their responses
- A brief description of any verbal conversations you had with Frontier or UtiliQuest representatives

After reviewing these documents, I'll likely reach out to you for a request to interview.

Thanks, Tony

Tony Marino
Executive Officer | Underground Infrastructure Safety Directorate
Office of Energy Infrastructure Safety
1516 9th Street
Sacramento, CA 95814
916-767-3370
EnergySafety.ca.gov

Merlin Johnson

From:

noreply@digalert.org

Sent:

Wednesday, January 5, 2022 6:58 AM

To:

MJ.MJC@VERIZON.NET

Subject:

DigAlert Confirmation for Ticket B220050037-00B

EMLCFM 00444B USAS 01/05/22 06:58:09 B220050037-00B NEW NORM POLY LREO

Thank you for contacting Underground Service Alert of Southern California. This is an automatically generated confirmation of your DigAlert.

For your safety please excavate carefully around the marked utility lines.

For more information regarding DigAlert's web portals, mobile apps and text messaging, please visit www.digalert.org or text Services to DIGALT (344258).

This email comes from an automated program that is NOT MONITORED. DO NOT REPLY TO THIS EMAIL.

This is not a certified copy of the ticket.

Ticket: B220050037 Rev: 00B Created: 01/05/22 06:56 User: MERLIN Chan: WEB

Work Start: 01/07/22 17:01 Legal Start: 01/07/22 17:01 Expires: 02/02/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City: MENTONE
Created By: MERLIN JOHNSON
Office Phone: 909-794-7702

State: CA Zip: 92359 Language: ENGLISH SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 Site SMS/Cell: 909-322-6061

Site Email: mj.mjc@verizon.net

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST1: ELM AVE

: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900

: WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT.

Permit: NOT AVAILABLE Job/Work order: 2236W 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.950798/-116.990010 33.950747/-116.985876

: 33.946643/-116.990062 33.946591/-116.985928

Excavator Provided:

Map link:

Momhare.

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=786u3x0v0syvyq2-h

- 1	Members:		
	BCV01 BEAUMONT-CHERRY VLY WTR	KNUTE DAHLSTROM	951-757-6870
]	BEAU01 C/OF BEAUMONT-TRAF, SWR, D	ROBERT VESTAL	951-769-8520x358
]	MCISOCAL MCI (VERIZON BUSINESS) FIBER	R	
		FIBER SECURITY DEPT	800-624-9675
	SCG1BT SOCALGAS DISTRIBUTION BEAUMONT	Γ	
		MARGARITO DOMINGUEZ	800-423-1391
	SCG29T SOCALGAS TRANSMISSION BEAUMONT	Γ	
		CINDY PINON-PACHECO	951-845-0705
	SPRINT1 SPRINT - FIBER	SPRINT	800-521-0579
	UCHTRW_S1 SPECTRUM RIV - CATV	SPECTRUM DAMAGE ONLY	844-780-6054
	USCEDE UTILIQUEST FOR SCE- DESERT REC	3	
		SC EDISON DIST	800-611-1911
	USCETT84SE UTIL 4 SCE TRNS TELEC-FIBE	R OPT	
		TCC	800-655-8844
	UTFTRCA01 UTILIQUEST/FRONTIER - TEL/F		
		~	323-795-2654
	YVC01 YUCAIPA VALLEY WTR - WTR		909-797-5117
	(c) Copyright 2017 Underground S		California.
	All righ	hts reserved.	

Called UTI Main office at & Stoke w/
Obrator, he gave me Gabriel Gonzeles (Field Super-)
Phone It 909-772-2235 & Fontier Tech. Dept.

Phone # 800-921-8104

From: Anton, Joseph

To: <u>Marino, Tony@EnergySafety</u>

Subject: Re: Request for information regarding ticket B220050037; Underground Safety Board Case 22LA014084

Date: Wednesday, February 2, 2022 3:17:27 PM

Hi Tony,

I was able to confirm that the cable was mapped, and the tech found the cable inside the structure without a tracer wire during the course of his locate.

The excavator was on site when we went back to mark the cable and was aware of the 30' section that had conduit in need of fixing before a tracer could be placed. That 30' section was away from his area of concern for the excavation. Our area supervisor also reached out today to make sure he knows.

Thank you

Joe Anton

UtiliQuest / Locating Inc Regional Manager, Claims & Compliance joseph.anton@utiliquest.com

Cell: 858-230-9876

On Tue, Feb 1, 2022 at 6:57 PM Marino, Tony@EnergySafety <\text{Tony.Marino@energysafety.ca.gov} wrote:

CAUTION: External

Joe,

Thanks for answering my questions this afternoon. As we discussed, I am sending two follow-up questions related to how specifically the field technician learned that there was an unlocatable Frontier fiber line in the area of proposed excavation of ticket B220050037.

- 1. Can you confirm that the fiber line was indicated on the map provided to the technician?
- 2. Please provide specifics about how the technician identified that the fiber line was unlocatable (*e.g.* it was on a map but couldn't be found, it could be seen in a handhole or above ground box but had no tracer wire or signal associated with it, etc.)

If you need to ask the technician for the answer to these questions, could you provide the technician's name along with your answer?

[&]quot;An ounce of PREVENTION is worth a pound of cure." -- Benjamin Franklin

Also, I want to reiterate my suggestion that you make sure that the excavator/ticket holder is aware of the 30-ft section of fiber where the tracer wire could not be installed last week and therefore has not yet been marked.
Thank you,
Tony
From: Anton, Joseph < <u>joseph.anton@utiliquest.com</u> > Sent: Monday, January 24, 2022 12:33 PM To: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u> > Subject: Re: Request for information regarding ticket B220050037; Underground Safety Board Case 22LA014084
Tony,
I'm still trying to track info down on this one.
Thank you
Joe Anton
UtiliQuest / Locating Inc Regional Manager, Claims & Compliance
joseph.anton@utiliquest.com
Cell: 858-230-9876
"An ounce of PREVENTION is worth a pound of cure."Benjamin Franklin
On Wed, Jan 19, 2022 at 6:24 PM Marino, Tony@EnergySafety <\tag{Tony.Marino@energysafety.ca.gov} wrote: CAUTION: External

Mr. Anton,

I am investigating a complaint of "no response" against Frontier for ticket B220050037 (and revisions). For your reference, our case number is 22LA01484. My understanding from the complainant (who had made the notification to DigAlert) is that a portion of Frontier's subsurface installations in the excavation area are fiber without tracer wire, and that the issue has been raised by UtiliQuest to Frontier to address.

I have questions for you, one of your employees more familiar with the ticket, or Frontier to answer.

- The electronic positive response of revision -00B of ticket B220050037 states that Frontier (UTFTRCA01), Spectrum Riverside (UCHTRW_S1), SCE Distribution Desert Region (USCEDE), and SCE Transmission Telecom (USCETT84SE) each negotiated a marking schedule for the ticket. The responder for each is listed as "UQ Responder." Can you describe how the negotiation took place, and what UtiliQuest staff negotiated with the excavator? Can you describe the parameters of the marking schedule that were agreed upon?
- The electronic positive response of revision -01B of ticket B220050037 states that Frontier responded with "Partially Marked More Time is Needed." Was this need discussed with the excavator? When? Can you describe to me why more time was needed?
- The complainant indicated that a UtiliQuest representative—Gabriel Gonzales—had told him that the issue was the lack of tracer wire for a fiber line, and that the issue had been raised to Frontier. Is it true that the line hasn't been marked as of today due to an absence of tracer wire? How did UtiliQuest employees discover the issue? Has UtiliQuest contacted Frontier about the issue? When was the contact with Frontier made? To whom at Frontier was this information provided?
- Can you provide an appropriate person at Frontier for me to contact during the course of this investigation?

If you would like to provide answers in writing, that is fine. If you feel a verbal interview more appropriate to conveying the facts in your possession, I am happy to set one up. If it will take longer than a day to provide the answers to these questions, please let me know with an expected timeline for your response.

Thank	vou.

Tony

Tony Marino

Executive Officer | Underground Infrastructure Safety Directorate

Office of Energy Infrastructure Safety

1516 9th Street

Sacramento, CA 95814

916-767-3370

EnergySafety.ca.gov

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

From: Merlin Johnson

To: <u>Marino, Tony@EnergySafety</u>

Cc: Merlin Johnson

Subject: FW: Client Assistance Request Form for Ticket B220050037

Date: Tuesday, February 1, 2022 3:11:52 PM

Tony,

Below is the email from Jaime Mesa stating that the "Tracer Wire" will be placed on the 28th of January.

Merlin Johnson

Merlin Johnson Construction, Inc.

P.O. Box 777 Mentone, California 92359 909-794-7702 Office 909-322-6061 Cell mj.mjc@verizon.net

From: Meza, Jaime <jaime.meza@ftr.com> **Sent:** Thursday, January 27, 2022 3:12 PM **To:** Merlin Johnson <mj.mjc@verizon.net>

Subject: RE: Client Assistance Request Form for Ticket B220050037

Merlin,

I have our crew going out tomorrow morning to place tracer wire so UTILIQUEST can mark location. My apologies I was out sick so I couldn't check on this.

From: Merlin Johnson <mj.mjc@verizon.net>
Sent: Wednesday, January 19, 2022 9:13 AM

To: 'Dochelle'' < dochelle.lewis@utiliquest.com >; 'Gustavo Gamboa'

<gustavo.gamboa@utiliquestops.com>; 'Sergio Salcedo' <sergio.salcedo@utiliquestops.com>; Meza,

Jaime < <u>jaime.meza@ftr.com</u>>; 'Angela Navarro' < <u>angela@wvwd.org</u>>; Samp, Wayne < <u>wayne.k.samp@ftr.com</u>>; Rider II, Troy < <u>troy.e.rider@ftr.com</u>>; King, Richard

<<u>richard.king1@ftr.com</u>>; Ortiz, Gabriel <<u>gabriel.b.ortiz@ftr.com</u>>; 'Gabriel Gonzalez'

<gabriel.gonzalez@utiliquest.com>

Cc: Jake Johnson < <u>jake.mjc@verizon.net</u>>; Merlin Johnson < <u>mj.mjc@verizon.net</u>>

Subject: FW: Client Assistance Request Form for Ticket B220050037

WARNING: External email. Please verify sender before opening attachments or clicking on links.

As of this date and time I have NO response from Utiliquest or Frontier as to if or when the underground facilities will be located per 4216.

We have a crew onsite working.

ANY AND ALL DAMAGES WHICH MAY OCCUR DUE TO THE FAILURE OF FRONTIER TO MARK THEIR FACILITIES PER 4216, WILL BE THE RESPONSILILITY OF FRONTIER.

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: Merlin Johnson <mj.mjc@verizon.net>
Sent: Tuesday, January 11, 2022 5:50 PM

To: 'Lewis, Dochelle' < dochelle.lewis@utiliquest.com >; 'Gustavo Gamboa'

<gustavo.gamboa@utiliquestops.com>; 'Sergio Salcedo' <sergio.salcedo@utiliquestops.com>;

'Meza, Jaime' <<u>jaime.meza@ftr.com</u>>; 'Samp, Wayne' <<u>wayne.k.samp@ftr.com</u>>; 'Rider II, Troy'

<trov.e.rider@ftr.com>; 'King, Richard' <richard.king1@ftr.com>; 'Ortiz, Gabriel'

<gabriel.b.ortiz@ftr.com>; 'Gabriel Gonzalez' <gabriel.gonzalez@utiliquest.com>

Cc: Jake Johnson (<u>jake.mjc@verizon.net</u>) < <u>jake.mjc@verizon.net</u>>; Merlin Johnson

(mi.mic@verizon.net) <mi.mic@verizon.net>

Subject: RE: Client Assistance Request Form for Ticket B220050037

Utiliquest
Dochelle Lewis,

Ticket Number B220050037 was called in at 0658 hrs on 01/05/22.

The "Legal Start": was 01/07/22 at 1701 hrs.

To assist in locating the existing facilities I scheduled a "Meet and Mark" for January 10, 2022 at 0900 (all utilities with the exception of those marked by Utiliquest responded).

At 1013 hrs 01/10/22 I sent in a "NO RESPONSE" Ticket to USA. Approximately one hour after that I received a phone call from a Tech with Utiliquest saying that he needed help to mark the existing facilities, but that he would have them marked by Tuesday afternoon, the 11th. I agreed as long as all marking was complete on Tuesday.

I to can also quote 4216, (although my quote would be correct), but I also know the following:

Utiliquest is not the owner or operator of any Frontier facilities.

All utilities received timely notice of our work per 4216.

Utiliquest chose to ignore that notice and now asks us to wait on them. This now makes it the OPERATORS problem.

The LEGAL START date and time is over four days ago.

I would suggest that the real OPERATOR pull out all of the stops and get their facilities marked prior to when we will be legally starting our work.

You may want to also take a look at 4216.7 (c), (d).

THANK YOU FOR YOUR PROMPT ATTENTION TO THIS

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mi.mic@verizon.net

From: Lewis, Dochelle < <u>dochelle.lewis@utiliquest.com</u>>

Sent: Tuesday, January 11, 2022 4:18 PM

To: Gustavo Gamboa <<u>gustavo.gamboa@utiliquestops.com</u>>; Sergio Salcedo

<sergio.salcedo@utiliquestops.com>; Meza, Jaime <jaime.meza@ftr.com>; Samp, Wayne

<wayne.k.samp@ftr.com>; Rider II, Troy <troy.e.rider@ftr.com>; King, Richard

<ri>chard.king1@ftr.com>; Ortiz, Gabriel <gabriel.b.ortiz@ftr.com>; MJ.MJC@verizon.net; Gabriel</ri>

Gonzalez < gabriel.gonzalez@utiliquest.com >

Subject: Client Assistance Request Form for Ticket B220050037

MERLIN JOHNSON CONSTRUCTION, INC. MERLIN JOHNSON

This email is regarding ticket B220050037 in the City of Beaumont

At this time the markings for Frontier are incomplete, there are undetectable facilities that we are escalating to our customer.

You are not clear to proceed with any excavation at this time.

Please be patient

California Government Code 4216.7.

(a) If a subsurface installation is damaged by an excavator as a result of failing to comply with Section 4216.2 or 4216.4, or subdivision (b) of Section 42163, or as a result of failing to comply with the perator's (UtiliQuest) requests to protect the subsurface installation as specified by the operator before the start of excavation, the excavator shall be liable to the operator of the subsurface installation for resulting damages, costs, and expenses to the extent the damages, costs, and expenses were caused by the excavator's failure to comply.

Frontier
Jaime Meza
Wayne Samp
Gabriel Ortiz
Richard King
Troy Rider

Gentlemen,

Attached is a client assistance request in the City of Beaumont

If you have any questions or concerns, or if you would like a Field Meet, please feel free to send me an email.

Please send an email when the Tracer Wire has been installed.

Thank you,

Dochelle Lewis

Administrative Assistant <u>UtiliQuest</u> Colton Office

951-295-0573 - cell 951-682-0777 - office dochelle.lewis@utiliquest.com

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies

of the communication and any attachments.

This communication is confidential. Frontier only sends and receives email on the basis of the terms set out at http://www.frontier.com/email_disclaimer.



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 2/1/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 2/1/2022 2:59 PM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Merlin Johnson, P.O. Box 777 Mentone, CA 92359

Tel: 9093226061

NARRATIVE:

I called Mr. Johnson to follow up on our previous conversation on 1/21 and find out if the facilities had yet been marked. Johnson indicated that it had been marked. He indicated that Jaime Mesa of Frontier had sent him an email late the previous week that the tracer wire would be installed on the fiber line the next day so that UtiliQuest could mark it. I asked Johnson if he could send me the email, and he said that he would. I asked Johnson if he'd been able to verify that the marks were made, and he indicated that yes, he had seen the new marks on Thursday. I asked him if he had had any issues in the rest of his project, and he said that he'd done a lot of the work in the area that had already been marked and had no problems, and that he hadn't yet begun work in the area of the newly-marked fiber, but would likely do that tomorrow.

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
tony Marino	Jason Corsey



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 2/1/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 2/1/2022 3:42 PM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Joseph Anton Tel: 8582309876

NARRATIVE:

I called Joseph Anton, Regional Manager of Claims and Compliance at UtiliQuest, to follow up on his voicemail left Friday 1/28, in which he was calling to follow up on my 1/19 email that included questions for him regarding Ticket B220050027. I told him that I would be referencing the ticket's electronic positive response data in my questions, and he informed me that he was looking at data input into the UtiliQuest system to answer my questions.

Mr. Anton stated that his system indicates that a UtiliQuest technician spoke with the ticket holder on the 10^{th} , and indicated that they would come out to mark the line the next day. The technician, in the course of locating, identified the unlocatable fiber line. This information was then passed up to Frontier. Anton indicated that UtiliQuest did what it could do: it located the lines, when it found an unlocatable line it passed that information to Frontier to address, and it kept the excavator informed of the situation. Anton also indicated that he had contact information for a Frontier representative, which I had asked for in my email, and he said he would send it to me by email (and did send it while we were speaking).

I asked Mr. Anton about the "meet and mark" language that the excavator had placed in the "location" field of the ticket. I noted that the comment field was not enabled in new tickets and asked him if it was common for an excavator to use the location field for that purpose. He stated that it happened, but that it wasn't common, and that excavators usually found ways to provide information on the ticket that they wanted to convey. He indicated that sometimes an excavator would immediately re-send a ticket in order to open up the comment field so that they could provide information in it.

I asked Mr. Anton how the technician understood that the line was unlocatable. He stated that the technician identified the unlocatable line during the course of the locate. I asked for more specific information, and Anton said that the locator was able to see it. I asked if this was in the process of opening a hand hole or an above-ground box, and he said yes, that was how the technician would do that, but that he didn't have the specifics identified in the system. I asked if Frontier provided maps to UtiliQuest for technicians to use in locating Frontier facilities. Anton said that yes, they did. I told Anton that I would send a follow-up email requesting specific information about how the technician identified that the fiber line was unlocatable and confirmation that the fiber line was indicated in the maps Frontier provided to UtiliQuest.

I asked Mr. Anton how the lack of a tracer wire was communicated to Frontier. He stated that it was sent to Frontier in a form. I asked if he could provide the form, and he said that he couldn't, but that I could ask Frontier for it.

I asked Mr. Anton if the unlocateable fiber facility was ever marked. He said yes. He stated that he received an email on 1/28 from Frontier's contractor who installed the tracer wire that the work was done, and Anton believed that the work had been performed on 1/27. Anton stated that UtiliQuest marked the facility, except for 30 ft in which there was a broken conduit and the contractor couldn't get the tracer wire through. He stated that he believed that the conduit would be repaired on the 2nd. I asked if Frontier was doing the repair work, or if a contractor was. Anton stated that he believed that Frontier used a contractor for that work. I asked if he knew who the contractor was. He stated that that was a question better answered by Frontier. I asked if he knew who the contractor was that installed the tracer wire, and Anton stated that he believed it was SECC, but that Frontier would be able to confirm.

I asked Mr. Anton if the excavator has been notified of the 30 feet of fiber that has not yet been marked. Anton said he didn't know but thought maybe the excavator hadn't been notified. I suggested to Anton that he make sure that the excavator was notified. Anton agreed.

I stated to Mr. Anton that my last series of questions would revolve around an electronic positive response provided by UtiliQuest on behalf of Frontier on 1/20 to ticket version 08B. I asked if he could explain how the electronic positive response at 12:37pm on 1/20 was listed as "locate area marked" if UtiliQuest didn't mark the area until after the tracer wire was installed on 1/27 or 1/28. Anton stated that the response may have been an error, as the excavation area was only partially marked. I asked if, given the facts we'd discussed, the code of "partially marked – more time is needed" may have been the more appropriate response, and he agreed that yes, a response of partially marked would have been more appropriate. Anton stated that, despite what the code may have said, the UtilitQuest supervisor had been in regular communication with the excavator and the excavator was aware that it hadn't all been marked. I asked if his information showed any communication with the excavator related to that electronic positive response. He said that it didn't. I asked if all communications with the excavator are logged, or if field personnel had informal communications that are not logged. Anton indicated that there are so many communications, and no, not all communications were logged.

Finally, I asked Mr. Anton if he is generally the best person to contact if I or another investigator had questions on an investigation that involved UtiliQuest. Anton stated that yes, he generally had the most information and was the best person to talk to.

Investigator Name	Supervisor Name			
Tony Marino	Jason Corsey			
tony Marino	Jason Corsey.			



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 3/4/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 3/4/2022 2:05 PM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Merlin Johnson, P.O. Box 777 Mentone, CA 92359

Tel: 9093226061

NARRATIVE:

I contacted Merlin Johnson via phone and asked him a few questions. I asked if he had had any issues with the project since we'd last spoken, and he indicated that he had finished the project with no issues. I asked if he was aware of the issue where Frontier didn't mark approximately 30 feet of fiber because of a broken conduit, and he said that he was aware, that he had spoken to UtiliQuest representatives, but that he wasn't working in that area and so didn't need it marked. He said that they left the section without tracer wire and stated that he hoped they would have fixed it by the time the next person needs to excavate in the area. I asked if he thought he would have been aware if they came out to repair the conduit, and he said yes, he was around the area frequently enough to have been aware.

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
tony Marino	Jason Corsey

From: Amber Dahl

To: Marino, Tony@EnergySafety

Subject: Re: Request for EPR for ticket B220050037

Date: Monday, February 28, 2022 2:07:05 PM

Attachments: <u>b213060313.pdf</u>

b213060309.pdf a213510083.pdf a213510078.pdf a220270041.pdf a220270042.pdf a220270047.pdf

v\:* {behavior:url(#default#VML);} o\:* {behavior:url(#default#VML);} w\:* {behavior:url(#default#VML);} .shape {behavior:url(#default#VML);}

Tony

Filling in for Amber - Attached are tickets that are in/near Noble Creek Park. I found nothing by SEC (working or work being done for)

Hope that helps.

Ann

---- Original Message ----

From: "Marino, Tony@EnergySafety" <Tony.Marino@energysafety.ca.gov>

Sent: 2/28/2022 8:30:24 AM

To: "Amber Dahl" <amber@digalert.org>

Subject: RE: Request for EPR for ticket B220050037

Amber, can you run a report to identify any tickets that spatially overlap B220050037? I am looking to see if there were any other tickets in the same area (Noble Creek Park) from January 10 through today. One of the companies may have been requested by SECC. I don't know if that is an easy or a difficult search to do.

Thanks,

Tony

From: Amber Dahl <amber@digalert.org>
Sent: Monday, January 24, 2022 9:52 AM

To: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Subject: Re: Request for EPR for ticket B220050037

Tony

Amber's out today - attached are all the versions of B220050037 with EPR included.

Ann

---- Original Message ----

From: "Marino, Tony@EnergySafety" < Tony.Marino@energysafety.ca.gov>

Sent: 1/24/2022 8:31:16 AM

To: "Amber Dahl" <amber@digalert.org>

Subject: RE: Request for EPR for ticket B220050037

Amber, do you mind running the same report again? I understand there may have been a change in EPR response from one of the operators Thurs/Fri that is relevant to the investigation.

Thanks,

Tony

From: Marino, Tony@EnergySafety

Sent: Wednesday, January 19, 2022 1:05 PM

To: Amber Dahl amber@digalert.org>

Subject: RE: Request for EPR for ticket B220050037

Great. Thank you.

From: Amber Dahl <amber@digalert.org>

Sent: Wednesday, January 19, 2022 12:58 PM

To: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Subject: RE: Request for EPR for ticket B220050037

See attached.

Thank you,

Amber Dahl, Safety Director

Underground Service Alert of Southern California (DigAlert)

PO Box 77070

Corona, CA 92877

O: (951) 808-8115 F: (951) 808-8101

E: amber@digalert.org W: www.digalert.org

This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.

From: Marino, Tony@EnergySafety < Tony.Marino@energysafety.ca.gov >

Sent: Wednesday, January 19, 2022 12:47 PM

To: amber@digalert.org

Subject: Request for EPR for ticket B220050037

Amber, could you assist in providing the EPR for all versions of ticket B220050037. I can grab it off your website, but it ends up being very difficult to make that version ADA compliant, unlike your internal system EPR reports. For your records, this is for investigation 22LA01484.

Thanks,

Tony

Tony Marino

Executive Officer | Underground Infrastructure Safety Directorate

Office of Energy Infrastructure Safety

1516 9th Street

Sacramento, CA 95814

916-767-3370

EnergySafety.ca.gov

MBRCOD 00001A USAS 02/28/22 13:56:01 B213060313-00B NEW NORM POLY LREQ

Ticket: B213060313 Rev: 00B Created: 11/02/21 10:22 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 11/15/21 17:01 Legal Start: 11/15/21 17:01 Expires: 11/30/21 23:59

Response required: Y Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

: X/ST2: APPROX 1750 FT WEST OF ELM AVE

:

: BOTH SIDES OF OAK VALLEY PKWY FROM ELM AVE TO APPROX 1750 FT WEST OF

: ELM AVE;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947340/-116.990714 33.947411/-116.983941 : 33.946515/-116.990706 33.946587/-116.983932

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=27w3v3s8lAiBeAo-z

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B213060313-00B

Member	Name	Rev Resp	onded By	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	11/1 00B 03:1 PM	•	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 11/16/21, 3:13 PM
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	11/1 00B 05:0 PM	1416	(999) Member did not respond by the required time	

Member	Name	Rev	Responded	Ву	Response	Comment
BEAU01	CITY OF BEAUMONT	00B	11/02/21 02:36:46 PM	ROBERT VESTAL	(001) CLEAR - NO CONFLICT	
MCISOCAL	MCI (VERIZON BUSINESS)	00B	11/02/21 10:24:37 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00B	11/08/21 09:16:51 AM	PRSDG01 KJVIEFHA	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	00B	11/03/21 01:10:39 PM	PRSDG01 JSPEREZ1	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER	
SPRINT1	SPRINT	00B	11/15/21 05:01:03 PM	Late Notice	(999) Member did not respond by the required time	
UCHTRW_S1	SPECTRUM - RIVERSIDE	00B	11/08/21 03:26:07 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	00B	11/08/21 03:26:08 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM	00B	11/08/21 03:26:08 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	00B	11/08/21 03:26:14 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
YVC01	YUCAIPA VALLEY WTR	00B	11/15/21 05:01:03 PM	Late Notice	(999) Member did not respond by the required time	

MBRCOD 00001A USAS 02/28/22 13:56:02 B213060313-01B RNEW NORM POLY LREQ

Ticket: B213060313 Rev: 01B Created: 11/30/21 07:19 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 11/30/21 07:19 Legal Start: 11/30/21 07:19 Expires: 12/28/21 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

: X/ST2: APPROX 1750 FT WEST OF ELM AVE

:

: BOTH SIDES OF OAK VALLEY PKWY FROM ELM AVE TO APPROX 1750 FT WEST OF

: ELM AVE;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947340/-116.990714 33.947411/-116.983941 : 33.946515/-116.990706 33.946587/-116.983932

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=37v9pAlJeDfEbEg-1

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021 07:19 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B213060313-01B

Rev Responded Comment Member Name Βv Response Existing markings 01B 11/30/21 BEAUMONT-CHERRY VALLEY (003) EXISTING adequate BCV01 bcvwd1 WATER DISTRICT 03:05:42 PM MARKINGS ADEQUATE By bcvwd1 on 11/30/21, 3:05 PM

Member	Name	Rev	Responded	Ву	Response	Comment
MCISOCAL	MCI (VERIZON BUSINESS)	01B	11/30/21 07:26:28 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	01B	12/02/21 10:05:01 AM	PRSDG01 JSPEREZ1	(003) EXISTING MARKINGS ADEQUATE	
UCHTRW_S1		01B	07:32:43 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01B	11/30/21 07:32:44 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	01B	11/30/21 07:32:44 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01B	11/30/21 07:33:31 AM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:56:02 B213060313-02B RNEW NORM POLY LREQ

Ticket: B213060313 Rev: 02B Created: 12/28/21 11:59 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 12/28/21 11:59 Legal Start: 12/28/21 11:59 Expires: 01/25/22 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

: X/ST2: APPROX 1750 FT WEST OF ELM AVE

:

: BOTH SIDES OF OAK VALLEY PKWY FROM ELM AVE TO APPROX 1750 FT WEST OF

: ELM AVE;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947340/-116.990714 33.947411/-116.983941 : 33.946515/-116.990706 33.946587/-116.983932

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=07u5t5qAjCgDcEk-2

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021

07:19 AM1

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 12/28/2021 11:59 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B213060313-02B

Member Name Rev Responded By Response Comment

Member	Name	Rev	Responded	Ву	Response	Commen	t
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	02B	12/29/21 01:51:16 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 12/29/21, PM	
MCISOCAL	MCI (VERIZON BUSINESS)	02B	12/28/21 12:03:42 PM	FLPS	(001) CLEAR - NO CONFLICT		
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	02B	01/13/22 07:35:22 AM	PRSDG01 JSPEREZ1	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER		
UCHTRW_S1	SPECTRUM - RIVERSIDE	02B	12/28/21 12:17:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED		
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	02B	12/28/21 12:17:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED		
USCETT84SE	SCE TRANS TELECOM	02B	12/28/21 12:17:11 PM	UQ Responder	(004) NO MARKINGS REQUESTED		
UTFTRCA01	UTILIQUEST FOR FRONTIER	02B	12/28/21 12:17:24 PM	UQ Responder	(004) NO MARKINGS REQUESTED		

MBRCOD 00001A USAS 02/28/22 13:40:47 B213060313-03B RNEW NORM POLY LREQ

Ticket: B213060313 Rev: 03B Created: 01/25/22 11:34 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 01/25/22 11:34 Legal Start: 01/25/22 11:34 Expires: 02/22/22 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

: X/ST2: APPROX 1750 FT WEST OF ELM AVE

:

: BOTH SIDES OF OAK VALLEY PKWY FROM ELM AVE TO APPROX 1750 FT WEST OF

: ELM AVE;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947340/-116.990714 33.947411/-116.983941 : 33.946515/-116.990706 33.946587/-116.983932

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=17tBnCjLcFdGZIc-6

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021

07:19 AM]

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 12/28/2021

11:59 AM]

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 01/25/2022 11:34 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B213060313-03B

Member Name Rev Responded By Response Comment

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	03B	01/26/22 02:28:35 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 on 1/26/22, 2:28 PM
MCISOCAL	MCI (VERIZON BUSINESS)	03B	01/25/22 11:41:52 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	03B	02/16/22 01:31:47 PM	PRSDG01 RLIESTER	(003) EXISTING MARKINGS ADEQUATE	
UCHTRW_S1			01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	- DESEKT KEG		01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	03B	01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	03B	01/25/22 11:43:05 AM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:55:19 B213060309-00B NEW NORM POLY LREQ

Ticket: B213060309 Rev: 00B Created: 11/02/21 10:21 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 11/15/21 17:01 Legal Start: 11/15/21 17:01 Expires: 11/30/21 23:59

Response required: Y Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879 Created By: CALEB CHIN Language: ENGLISH Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: OAK VIEW DR

: X/ST2: APPROX 1750 FT EAST OF OAK VIEW DR

: BOTH SIDES OF OAK VALLEY PKWY FROM OAK VIEW DR TO APPROX 1750 FT EAST

: OF OAK VIEW DR;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947455/-116.996231 33.947412/-116.989453

: 33.946630/-116.996236 33.946587/-116.989458

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=25y0y5qAjCfKVJf-8

Members:

BCV01

UCHTRW_S1 BCV01 BEAU01 **MCISOCAL** SCG1BT SCG29T SPRINT1

USCEDE USCETT84SE UTFTRCA01 YVC01

DISTRICT

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

PΜ

Ticket Responses for: B213060309-00B Member Rev Responded Response Name Ву **BEAUMONT-CHERRY** 11/16/21 BCV01 VALLEY WATER 00B 03:13:05 bcvwd1 (001) CLEAR - NO CONFLICT

By bcvwd1 on 11/16/21, 3:13

PΜ

BEAUMONT-CHERRY 11/15/21 (999) Member did not Late VALLEY WATER 00B 05:01:03 respond by the required Notice **DISTRICT** PMtime

Comment

Clear - No

conflict

Member	Name	Rev	Responded	Ву	Response	Comment
BEAU01	CITY OF BEAUMONT	00B	11/02/21 02:33:58 PM	ROBERT VESTAL	(001) CLEAR - NO CONFLICT	
MCISOCAL	MCI (VERIZON BUSINESS)	00B	11/02/21 10:24:37 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00B	11/08/21 09:15:49 AM	PRSDG01 KJVIEFHA	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	00B	11/03/21 01:20:08 PM	PRSDG01 JSPEREZ1	(001) CLEAR - NO CONFLICT	
SPRINT1	SPRINT	00B	11/15/21 8 05:01:03 PM	Late Notice	(999) Member did not respond by the required time	
UCHTRW_S1	SPECTRUM - RIVERSIDE	00B	11/05/21 02:36:12 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	00B	11/05/21 02:36:12 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM	00B	11/05/21 02:36:12 PM	UQ Responder	(001) CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	00B	11/05/21 02:36:14 PM	UQ Responder	(010) LOCATE AREA MARKED	
YVC01	YUCAIPA VALLEY WTR	00B	11/15/21 05:01:03 PM	Late Notice	(999) Member did not respond by the required time	

MBRCOD 00001A USAS 02/28/22 13:55:19 B213060309-01B RNEW NORM POLY LREQ

Ticket: B213060309 Rev: 01B Created: 11/30/21 07:19 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 11/30/21 07:19 Legal Start: 11/30/21 07:19 Expires: 12/28/21 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: OAK VIEW DR

: X/ST2: APPROX 1750 FT EAST OF OAK VIEW DR

:

: BOTH SIDES OF OAK VALLEY PKWY FROM OAK VIEW DR TO APPROX 1750 FT EAST

: OF OAK VIEW DR;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947455/-116.996231 33.947412/-116.989453 : 33.946630/-116.996236 33.946587/-116.989458

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=35x7r8nHgBkBi1x-q

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021 07:19 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B213060309-01B

Member Rev Responded Comment Name Βv Response Existing markings 01B 11/30/21 BEAUMONT-CHERRY VALLEY (003) EXISTING adequate BCV01 bcvwd1 WATER DISTRICT 03:06:00 PM MARKINGS ADEQUATE By bcvwd1 on 11/30/21, 3:06 PM

Member	Name	Rev	Responded	Ву	Response	Comment
MCISOCAL	MCI (VERIZON BUSINESS)	01B	11/30/21 07:26:28 AM	FLPS	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	01B	11/30/21 07:32:44 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01B	11/30/21 07:32:44 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	01B	11/30/21 07:32:44 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	01B	11/30/21 07:33:31 AM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:55:19 B213060309-02B RNEW NORM POLY LREQ

Ticket: B213060309 Rev: 02B Created: 12/28/21 11:59 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 12/28/21 11:59 Legal Start: 12/28/21 11:59 Expires: 01/25/22 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: OAK VIEW DR

: X/ST2: APPROX 1750 FT EAST OF OAK VIEW DR

:

: BOTH SIDES OF OAK VALLEY PKWY FROM OAK VIEW DR TO APPROX 1750 FT EAST

: OF OAK VIEW DR;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947455/-116.996231 33.947412/-116.989453 : 33.946630/-116.996236 33.946587/-116.989458

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=05w3v3s8lAhIXJf-8

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021

07:19 AM1

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 12/28/2021 11:59 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: B213060309-02B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	02В ¹	12/29/21 01:50:54 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 on 12/29/21, ₀₁ 0;50 PM

Member	Name	Rev	Responded	Ву	Response	Comment
MCISOCAL	MCI (VERIZON BUSINESS)	02B	12/28/21 12:03:42 PM	FLPS	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	02B	12/28/21 12:17:13 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	02B	12/28/21 12:17:14 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	02B	12/28/21 12:17:14 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	02B	12/28/21 12:17:26 PM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:43:41 B213060309-03B RNEW NORM POLY LREQ

Ticket: B213060309 Rev: 03B Created: 01/25/22 11:34 User: CDOMINGUEZ1127 Chan: WEB

Work Start: 01/25/22 11:34 Legal Start: 01/25/22 11:34 Expires: 02/22/22 23:59

Response required: N Priority: 2

Excavator Information

Company: ALL AMERICAN ASPHALT Co Addr: 1776 ALL AMERICAN WAY

City : CORONA State: CA Zip: 92879
Created By: CALEB CHIN Language: ENGLISH
Office Phone: 951-736-3806 SMS/Cell: 424-385-1311

Office Email: DIG.TICKETS@ALLAMERICANASPHALT.COM

Site Contact: MAZEN ELMANI

Site Phone: 951-551-8226 Site SMS/Cell: 951-551-8226

Site Email: melmani@allamericanasphalt.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: OAK VIEW DR

: X/ST2: APPROX 1750 FT EAST OF OAK VIEW DR

:

: BOTH SIDES OF OAK VALLEY PKWY FROM OAK VIEW DR TO APPROX 1750 FT EAST

: OF OAK VIEW DR;

Delineated Method: WHITEPAINT

Work Type: GRIND & OVERLAY, 2 IN; DIGOUTS, 2FT

Work For : CITY OF BEAUMONT

Permit: Job/Work order: JOB#33949 1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947455/-116.996231 33.947412/-116.989453 : 33.946630/-116.996236 33.946587/-116.989458

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=15v9pAlJeDiDg7r-w

Comments:

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 11/30/2021

07:19 AM]

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 12/28/2021

11:59 AM]

RENEW TICKET WORK CONTINUING PER CALEB CHIN--[CDOMINGUEZ1127 01/25/2022 11:34 AM]

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: B213060309-03B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	03B	01/26/22 02:28:57 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 on 1/26/22, 2:28 PM
MCISOCAL	MCI (VERIZON BUSINESS)	03B	01/25/22 11:41:52 AM	FLPS	(001) CLEAR - NO CONFLICT	
UCHTRW_S1	SPECTRUM - RIVERSIDE	03B	01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	03B	01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	03B	01/25/22 11:42:48 AM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	03B	01/25/22 11:43:05 AM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:53:51 A213510083-00A NEW NORM POLY LREQ

Ticket: A213510083 Rev: 00A Created: 12/17/21 07:35 User: ADS Chan: 100

Work Start: 12/28/21 06:00 Legal Start: 12/28/21 06:00 Expires: 01/14/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City : RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: GABRIEL RUBIO

Site Phone: 951-312-2909 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK
: X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 1/2 MILE N/E OF OAK VALLEY PKWY N/E : FOR APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**

: **AREA WILL BE DELINEATED AFTER CALL AS RCSC*

Delineated Method: NONE Work Type: RESHAPE CHANNEL

Work For: RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.959881/-116.981969 33.959192/-116.981198 : 33.953415/-116.987754 33.952725/-116.986983

Excavator Provided: 33.953444/-116.987117,33.959239/-116.981836

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=0DgKeLfGdFk8h6r-w

Members:

BCV01 BEAU01 SCG1BT UCHTRW S1 USCEDE YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510083-00A								
Member	Name	Rev	Responded B	У	Response	Comment		
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	00A	12/20/21 08:45:38 AM bcvwc	d1 (010)	LOCATE AREA MARKED	Locate area marked By bcvwd1 on 12/20/21, 8:45 AM		
BEAU01	CITY OF BEAUMONT	00A	12/17/21 ROBER 02:37:24 PM VESTA	RT AL (001)	CLEAR - NO CONFLICT			
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00A	12/21/21 PRSDO 09:22:28 AM TEJEN	G01 NNIN (001)	CLEAR - NO CONFLICT			

Member	Name		Responded	•	Response	Comment
UCHTRW_S1	SPECTRUM - RIVERSIDE	00A	12/21/21 03:25:48 F	UQ PM Responder	(001) CLEAR - NO CONFLICT	
USCEDE					(001) CLEAR - NO CONFLICT	
YVC01	YUCAIPA VALLEY WTR		12/28/21 06:00:00 A		(999) Member did not respond by the required time	

MBRCOD 00001A USAS 02/28/22 13:53:52 A213510083-01B RNEW NORM POLY LREQ

Ticket: A213510083 Rev: 01B Created: 12/30/21 13:13 User: DIRECT Chan: WEB

Work Start: 12/30/21 13:13 Legal Start: 12/30/21 13:13 Expires: 01/27/22 23:59

Response required: N Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City: RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: GABRIEL RUBIO

Site Phone: 951-312-2909 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK : X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 1/2 MILE N/E OF OAK VALLEY PKWY N/E : FOR APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**

: **AREA WILL BE DELINEATED AFTER CALL AS RCSC*

Delineated Method: NONE Work Type: RESHAPE CHANNEL

Work For: RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.959881/-116.981969 33.959192/-116.981198 : 33.953415/-116.987754 33.952725/-116.986983

Excavator Provided: 33.953444/-116.987117,33.959239/-116.981836

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=05v4u4wzuy5o5kE-Z

Comments:

RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 12/30/2021 01:13 PM]

Members:

BCV01 BEAU01 SCG1BT UCHTRW_S1 USCEDE YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510083-01B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	01B 0	1/03/22 1:24:00 PM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/3/22, 1:24 PM
UCHTRW_S1	L SPECTRUM - RIVERSIDE	01B ¹	2/30/21 1:21:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED	

Member	Name	Rev	Responded	Ву	Response	Comment
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	01B ¹	12/30/21 01:21:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:47:47 A213510083-02B RNEW NORM POLY LREQ

Ticket: A213510083 Rev: 02B Created: 01/19/22 13:34 User: DIRECT Chan: WEB

Work Start: 01/19/22 13:34 Legal Start: 01/19/22 13:34 Expires: 02/16/22 23:59

Response required: N Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City : RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: GABRIEL RUBIO

Site Phone: 951-312-2909 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK
: X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 1/2 MILE N/E OF OAK VALLEY PKWY N/E : FOR APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**

: **AREA WILL BE DELINEATED AFTER CALL AS RCSC*

Delineated Method: NONE Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.959881/-116.981969 33.959192/-116.981198 : 33.953415/-116.987754 33.952725/-116.986983

Excavator Provided: 33.953444/-116.987117,33.959239/-116.981836

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=3535t6q5s33qzv1-m

Comments:

RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 12/30/2021 01:13 PM]
RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 01/19/2022 01:34 PM]

Members:

BCV01 BEAU01 SCG1BT UCHTRW_S1 USCEDE YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510083-02B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	02B	01/19/22 01:38:04 PM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/19/22, 1:38 PM
UCHTRW_S1	L SPECTRUM - RIVERSIDE	02B	01/19/22 01:41:49 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	02B	01/19/22 01:41:49 PM	UQ Responder	(004) NO MARKINGS REQUESTED	0117

MBRCOD 00001A USAS 02/28/22 13:54:36 A213510078-00A NEW NORM POLY LREQ

Ticket: A213510078 Rev: 00A Created: 12/17/21 07:31 User: ADS Chan: 100

Work Start: 12/28/21 06:00 Legal Start: 12/28/21 06:00 Expires: 01/14/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City: RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: GABRIEL RUBIO

Site Phone: 951-312-2909 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK : X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 60FT N/E OF OAK VALLEY PKWY N/E FOR

: APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**

: **AREA WILL BE DELINEATED AFTER CALL AS RCSC*

Delineated Method: NONE Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.954069/-116.987254 33.953533/-116.986483 : 33.947031/-116.992148 33.946495/-116.991377

Excavator Provided: 33.947125/-116.991511,33.953444/-116.987117

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=485v1y0vyu2wtv0-n

Members:

BCV01 BEAU01 SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE

USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510078-00A

Member	Name	Rev	Responded	Ву	Response
SPRINT1	SPRINT	00A A	2/28/21 06:00:00 M	Late Notice	(999) Member did not respond by the required time
YVC01	YUCAIPA VALLEY WTR	00A AI	2/28/21 06:00:00 M	Late Notice	(999) Member did not respond by the required time

MBRCOD 00001A USAS 02/28/22 13:54:36 A213510078-01A AMND EMER POLY LREQ

Ticket: A213510078 Rev: 01A Created: 12/17/21 13:50 User: BRJ Chan: 100

Work Start: 12/18/21 06:00 Legal Start: 12/28/21 06:00 Expires: 01/14/22 23:59

Response required: N Priority: 9

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City : RIVERSIDE State: CA Zip: 92501 Created By: GABRIEL RUBIO Language: ENGLISH Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: JOSH GUTKNECHT

Site Phone: 951-743-6718 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK : X/ST1: OAK VALLEY PKWY

: BOTH SIDES OF NOBLE CRK FRM APPROX 60FT N/E OF OAK VALLEY PKWY N/E FOR

: APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR** : **AREA WILL BE DELINEATED AFTER CALL AS RCSC* **ALT SITE CONTACT

: CHRIS MACIAS AT 909-557-8689**

Delineated Method: NONE Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.954069/-116.987254 33.953533/-116.986482 : 33.947031/-116.992148 33.946495/-116.991376

Excavator Provided: 33.947125/-116.991511,33.953444/-116.987117

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=589v1yyt2q2wtw8-b

Comments:

AMENDMENT CHANGING WORK DATE/TIME FRM 12/28 6AM & SITE CONTACT FRM GABRIEL RUBIO AT 951-312-2909 7 ADDING ALT SITE CONTACT ALT SITE CONTACT CHRIS MACIAS AT 909-557-8689 PER GABRIEL RUBIO--[BRJ 12/17/2021 01:44:19 PM]

Members:

BCV01 BEAU01 SCG1BT SCG29T SPRINT1 UCHTRW S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: A213510078-01A Member Name Rev Responded By Response

MBRCOD 00001A USAS 02/28/22 13:54:37 A213510078-02A AMND EMER POLY LREQ

Ticket: A213510078 Rev: 02A Created: 12/17/21 13:54 User: BRJ Chan: 100

Work Start: 12/18/21 06:00 Legal Start: 12/28/21 06:00 Expires: 01/14/22 23:59

Response required: N Priority: 9

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City : RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: JOSH GUTKNECHT

Site Phone: 951-743-6718 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK : X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 60FT N/E OF OAK VALLEY PKWY N/E FOR

: APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**
: **AREA WILL BE DELINEATED AFTER CALL AS RCSC* **ALT SITE CONTACT

: CHRIS MACIAS AT 909-557-8689**

Delineated Method: WHITEPAINT Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.954069/-116.987254 33.953533/-116.986482 : 33.947031/-116.992148 33.946495/-116.991376

. 55.347051/-110.332140 55.340435/-110.33

Excavator Provided: 33.947125/-116.991511,33.953444/-116.987117

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=687t3w2t6mCm1p7-g

Comments:

AMENDMENT CHANGING WORK DATE/TIME FRM 12/28 6AM & SITE CONTACT FRM GABRIEL RUBIO AT 951-312-2909 7 ADDING ALT SITE CONTACT ALT SITE CONTACT CHRIS MACIAS AT 909-557-8689 PER GABRIEL RUBIO--[BRJ 12/17/2021 01:44:19 PM]

AMENDMENT CHANGING PRE-MARKED FRM NONE PER GABRIEL RUBIO--[BRJ 12/17/2021 01:54:09 PM]

01:54:09 PM

Members:

BCV01 BEAU01 SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE

USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510078-02A

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	02A	12/20/21 08:44:51 AM	bcvwd1	(010) LOCATE AREA MARKED	Locate area marked By bcvwd1 on 12/20/21, 8:44 AM
BEAU01	CITY OF BEAUMONT	02A	12/17/21 02:36:22 PM	ROBERT VESTAL	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	02A	12/21/21 09:26:06 AM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	02A	12/18/21 10:12:41 AM	PRSDG01 JSPEREZ1	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER	
UCHTRW_S1	SPECTRUM - RIVERSIDE	02A	12/21/21 08:32:47 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	02A	12/21/21 08:32:47 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM	02A	12/21/21 08:32:47 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	02A	12/21/21 08:33:01 AM	UQ Responder	(001) CLEAR - NO CONFLICT	

MBRCOD 00001A USAS 02/28/22 13:54:37 A213510078-03B RNEW NORM POLY LREQ

Ticket: A213510078 Rev: 03B Created: 12/30/21 13:13 User: DIRECT Chan: WEB

Work Start: 12/30/21 13:13 Legal Start: 12/30/21 13:13 Expires: 01/27/22 23:59

Response required: N Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City: RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: JOSH GUTKNECHT

Site Phone: 951-743-6718 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK : X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 60FT N/E OF OAK VALLEY PKWY N/E FOR

: APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**
: **AREA WILL BE DELINEATED AFTER CALL AS RCSC* **ALT SITE CONTACT

: CHRIS MACIAS AT 909-557-8689**

Delineated Method: WHITEPAINT Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.954069/-116.987254 33.953533/-116.986482 : 33.947031/-116.992148 33.946495/-116.991376

Excavator Provided: 33.947125/-116.991511,33.953444/-116.987117

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=60QaObPWNVTVKXR-M

Comments:

AMENDMENT CHANGING WORK DATE/TIME FRM 12/28 6AM & SITE CONTACT FRM GABRIEL RUBIO AT 951-312-2909 7 ADDING ALT SITE CONTACT ALT SITE CONTACT CHRIS MACIAS AT 909-557-8689 PER GABRIEL RUBIO--[BRJ 12/17/2021 01:44:19 PM]

AMENDMENT CHANGING PRE-MARKED FRM NONE PER GABRIEL RUBIO--[BRJ 12/17/2021 01:54:09 PM]

RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 12/30/2021 01:13 PM]

Members:

BCV01 BEAU01 SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

Ticket Responses for: A213510078-03B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	03B	01/03/22 01:24:22 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 on 1/3/22, 1:24 PM
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	03B	01/13/22 07:30:11 AM	PRSDG01 JSPEREZ1	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	03B	01/03/22 08:21:23 AM	PRSDG01 JSPEREZ1	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER	
UCHTRW_S1	SPECTRUM - RIVERSIDE	03B	12/30/21 01:21:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	03B	12/30/21 01:21:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM	03B	12/30/21 01:21:10 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	03B	12/30/21 01:21:13 PM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:46:55 A213510078-04B RNEW NORM POLY LREQ

Ticket: A213510078 Rev: 04B Created: 01/19/22 13:34 User: DIRECT Chan: WEB

Work Start: 01/19/22 13:34 Legal Start: 01/19/22 13:34 Expires: 02/16/22 23:59

Response required: N Priority: 2

Excavator Information

Company: RIVERSIDE COUNTY FLOOD CONTROL

Co Addr: 1995 MARKET ST

City: RIVERSIDE State: CA Zip: 92501
Created By: GABRIEL RUBIO Language: ENGLISH
Office Phone: 951-312-2909 SMS/Cell: 951-312-2909

Office Email: GRUBIO@RIVCO.ORG

Site Contact: JOSH GUTKNECHT

Site Phone: 951-743-6718 Site SMS/Cell:

Site Email:

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: NOBLE CRK
: X/ST1: OAK VALLEY PKWY

:

: BOTH SIDES OF NOBLE CRK FRM APPROX 60FT N/E OF OAK VALLEY PKWY N/E FOR

: APPROX 1/2 MILE **NOBLE CRK LOC APPROX 1255FT E/OF OAK VIEW DR**
: **AREA WILL BE DELINEATED AFTER CALL AS RCSC* **ALT SITE CONTACT

: CHRIS MACIAS AT 909-557-8689**

Delineated Method: WHITEPAINT Work Type: RESHAPE CHANNEL

Work For : RIVERSIDE COUNTY FLOOD CONTROL

Permit: Job/Work order:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.954069/-116.987254 33.953533/-116.986482 : 33.947031/-116.992148 33.946495/-116.991376

Excavator Provided: 33.947125/-116.991511,33.953444/-116.987117

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=10Dr7s4nAiCm3t5-i

Comments:

AMENDMENT CHANGING WORK DATE/TIME FRM 12/28 6AM & SITE CONTACT FRM GABRIEL RUBIO AT 951-312-2909 7 ADDING ALT SITE CONTACT ALT SITE CONTACT CHRIS MACIAS AT 909-557-8689 PER GABRIEL RUBIO--[BRJ 12/17/2021 01:44:19 PM]

AMENDMENT CHANGING PRE-MARKED FRM NONE PER GABRIEL RUBIO--[BRJ 12/17/2021 01:54:09 PM]

RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 12/30/2021 01:13 PM]
RENEW TICKET WORK CONTINUING PER GABRIEL RUBIO--[DIRECT 01/19/2022 01:34 PM]

Members:

BCV01 BEAU01 SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A213510078-04B

Member	Name	Rev	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	04B	01/19/22 01:38:19 PM	bcvwd1	(003) EXISTING MARKINGS ADEQUATE	Existing markings adequate By bcvwd1 on 1/19/22, 1:38 PM
UCHTRW_S1	SPECTRUM - RIVERSIDE	04B	01/19/22 01:41:49 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	04B	01/19/22 01:41:49 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
USCETT84SE	SCE TRANS TELECOM		01/19/22 01:41:49 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	04B	01/19/22 01:41:53 PM	UQ Responder	(004) NO MARKINGS REQUESTED	

MBRCOD 00001A USAS 02/28/22 13:39:03 A220270041-00A NEW NORM POLY LREQ

Ticket: A220270041 Rev: 00A Created: 01/27/22 06:56 User: SME Chan: WEB

Work Start: 01/31/22 17:01 Legal Start: 01/31/22 17:01 Expires: 02/24/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: WESTERN CONSTRUCTION Co Addr: 11850 FOSTER RD

City: NORWALK State: CA Zip: 90650 Created By: JAIR ARANGO Language: ENGLISH Office Phone: 714-299-4014 SMS/Cell: 714-299-4014

Office Email: JARANGO@ASPLUNDH.COM

Site Contact: LARRY RUSSELL

Site Phone: 929-763-6112 Site SMS/Cell:

Site Email: digalert@western-csi.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

:

: S/SIDE OF OAK VALLEY PKWY AT APPROX 375FT, 545FT & 1555FT W/OF ELM AVE

:

: ** 30 FT RADIUS **

: POLE NUMBER: 4361079E, 4067392E, 4612329E,

Delineated Method: WHITEPAINT Work Type: POLE REPLACEMENT

Work For : SCE

Permit: Job/Work order: TD1673944 1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947242/-116.990088 33.947276/-116.985203 : 33.946423/-116.990082 33.946457/-116.985197

Excavator Provided: 33.94683825/-116.98959072,33.94685702/-116.98623263,33.94685800/-116.98569499

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=FBDnAm9sBhDe9fI-V

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE USCETT84SE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

		Ticket Respons	es for:	A220270041-00A	
Member	Name	Rev Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	01/31/22 00A 10:42:34 AM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/31/22, 10:42 AM
BEAU01	CITY OF BEAUMONT	01/27/22 00A 09:36:57 AM	ROBERT VESTAL	(001) CLEAR - NO CONFLICT	

Member	Name	Rev	Responded	Ву	Response	Comment
MCISOCAL	MCI (VERIZON BUSINESS)	00A	01/27/22 07:11:52 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00A	01/28/22 12:32:59 PM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	00A	01/27/22 07:28:33 AM	PRSDG01 RLIESTER	(001) CLEAR - NO CONFLICT	
SPRINT1	SPRINT	00A	01/31/22 05:01:04 PM	Late Notice	(999) Member did not respond by the required time	
UCHTRW_S1	SPECTRUM - RIVERSIDE	00A	01/28/22 09:41:45 AM	UQ Responder	(010) LOCATE AREA MARKED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	00A	01/28/22 09:41:45 AM	UQ Responder	(001) CLEAR - NO CONFLICT	
USCETT84SE	SCE TRANS TELECOM	00A	01/28/22 09:41:45 AM	UQ Responder	(010) LOCATE AREA MARKED	
UTFTRCA01	UTILIQUEST FOR FRONTIER	00A	01/28/22 09:41:49 AM	UQ Responder	(010) LOCATE AREA MARKED	
YVC01	YUCAIPA VALLEY WTR	00A	01/31/22 05:01:04 PM	Late Notice	(999) Member did not respond by the required time	

MBRCOD 00001A USAS 02/28/22 13:38:29 A220270042-00A NEW NORM POLY LREQ

Ticket: A220270042 Rev: 00A Created: 01/27/22 06:57 User: ADS Chan: WEB

Work Start: 01/31/22 17:01 Legal Start: 01/31/22 17:01 Expires: 02/24/22 23:59

Response required: Y Priority: 2

Excavator Information

Company: WESTERN CONSTRUCTION Co Addr: 11850 FOSTER RD

City: NORWALK State: CA Zip: 90650 Created By: JAIR ARANGO Language: ENGLISH Office Phone: 714-299-4014 SMS/Cell: 714-299-4014

Office Email: JARANGO@ASPLUNDH.COM

Site Contact: LARRY RUSSELL

Site Phone: 929-763-6112 Site SMS/Cell:

Site Email: digalert@western-csi.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: ELM AVE : X/ST1: OAK VALLEY PKWY

:

: E/SIDE OF ELM AVE AT APPROX 40FT S/OF OAK VALLEY PKWY

:

: ** 30 FT RADIUS ** : POLE NUMBER: 4612327E

Delineated Method: WHITEPAINT Work Type: POLE REPLACEMENT

Work For : SCE

Permit: Job/Work order: TD1673944 1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947186/-116.984918 33.947344/-116.983955 : 33.946384/-116.984786 33.946542/-116.983823

Excavator Provided: 33.94686543/-116.98437009

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=3BnHm9s4p6p6j8p-y

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1 USCEDE UTFTRCA01 YVC01

(c) Copyright 2018 Underground Service Alert of Southern California.

All rights reserved.

Ticket Responses for: A220270042-00A Member Rev Responded Comment Response Name By Locate area **BEAUMONT-CHERRY** marked 01/31/22 10:43:15 AM bcvwd1 BCV01 VALLEY WATER (010) LOCATE AREA MARKED By bcvwd1 on DISTRICT 1/31/22, 10:43 AΜ 01/27/22 ROBERT BEAU01 CITY OF BEAUMONT (001) CLEAR - NO CONFLICT 09:40:34 AM VESTAL MCI (VERIZON 01/27/22 MCISOCAL (001) CLEAR - NO CONFLICT **BUSINESS)** 07:11:52 AM

Member	Name	Rev	Responde	d	Ву		Response	Comment
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT	00A	01/27/22 01:24:27	РМ	PRSDG01 TEJENNIN	(001)	CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	00A	01/27/22 07:25:25	ΑМ	PRSDG01 RLIESTER	(001)	CLEAR - NO CONFLICT	
SPRINT1	SPRINT	00A	01/31/22 05:01:05	PM	Late Notice		Member did not nd by the required	
UCHTRW_S1	. SPECTRUM - RIVERSIDE	00A	01/28/22 03:50:44	PM	UQ Responder	(010)	LOCATE AREA MARKED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG	00A	01/28/22 03:50:44	PM	UQ Responder	(001)	CLEAR - NO CONFLICT	
UTFTRCA01	UTILIQUEST FOR FRONTIER	00A	01/28/22 03:50:48	PM	UQ Responder	(010)	LOCATE AREA MARKED	
YVC01	YUCAIPA VALLEY WTR	00A	01/31/22 05:01:05	РМ	Late Notice	` '	Member did not nd by the required	

MBRCOD 00001A USAS 02/28/22 13:37:43 A220270047-00A NEW NORM POLY LREQ

Ticket: A220270047 Rev: 00A Created: 01/27/22 07:06 User: KAW Chan: WEB

Work Start: 01/31/22 17:01 Legal Start: 01/31/22 17:01 Expires: 02/24/22 23:59

Response required: Y Priority: 2

Excavator Information Company: WESTERN CONSTRUCTION Co Addr: 11850 FOSTER RD

City : NORWALK State: CA Zip: 90650 Created By: JAIR ARANGO Language: ENGLISH Office Phone: 714-299-4014 SMS/Cell: 714-299-4014

Office Email: JARANGO@ASPLUNDH.COM

Site Contact: LARRY RUSSELL

Site Phone: 929-763-6112 Site SMS/Cell:

Site Email: digalert@western-csi.com

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: OAK VALLEY PKWY

: X/ST1: ELM AVE

S/SIDE OF OAK VALLEY : N/SIDE OF OAK VALLEY PKWY AT E/SIDE OF ELM AVE; : PKWY A APPROX 195FT, 390FT & 575FT E/OF ELM AVE ** 30 FT RADIUS ** : POLE NUMBER: 1764312E, 1764309E, 1764308E, 1764307E

Delineated Method: WHITEPAINT Work Type: POLE REPLACEMENT (4)

Work For : SCE

Permit: Job/Work order: TD1673944 1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.947610/-116.984775 33.947197/-116.981995 : 33.946614/-116.984923 33.946201/-116.982143

Excavator Provided: 33.94712821/-116.98434935,33.94686593/-116.98380111,33.9468650/-116.98316612,33.94686706/-116.98254207

Map link:

https://newtin.digalert.org/newtinweb/map tkt.nap?TRG=7A07w7u1wwzyrAn-7

Members:

BCV01 BEAU01 MCISOCAL SCG1BT SCG29T SPRINT1 UCHTRW_S1

USCEDE UTFTRCA01 YVC01

> (c) Copyright 2018 Underground Service Alert of Southern California. All rights reserved.

> > Ticket Resnances for: A220270047-004

	No	_		-	tor: A220270047-00A	
Member	Name	кеv	Responded	Ву	Response	Comment
BCV01	BEAUMONT-CHERRY VALLEY WATER DISTRICT	00A 0	01/31/22 10:43:44 AM	bcvwd1	(001) CLEAR - NO CONFLICT	Clear - No conflict By bcvwd1 on 1/31/22, 10:43 AM
BEAU01	CITY OF BEAUMONT		01/27/22 09:37:29 AM	ROBERT VESTAL	(001) CLEAR - NO CONFLICT	
MCISOCAL	MCI (VERIZON BUSINESS)		01/27/22 07:11:52 AM	FLPS	(001) CLEAR - NO CONFLICT	
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT		01/28/22 L2:27:45 PM	PRSDG01 TEJENNIN	(001) CLEAR - NO CONFLICT	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT		02/02/22 L2:57:27 PM	PRSDG01 RLIESTER	(031) REQUIRES STAND BY AT TIME OF EXCAVATION - CONTACT FACILITY OWNER	
SCG29T	SOCALGAS TRANSMISSION BEAUMONT	ииΔ	01/27/22 07:58:18 AM	PRSDG01 RLIESTER	(010) LOCATE AREA MARKED	
SPRINT1	SPRINT	ииΔ	01/31/22 05:01:05 PM	Late Notice	(999) Member did not respond by the required time	
UCHTRW_S1	SPECTRUM - RIVERSIDE		01/31/22 07:51:37 AM	UQ Responder	(010) LOCATE AREA MARKED	
USCEDE	UTILIQUEST FOR SCE DIST - DESERT REG		01/31/22 07:51:37 AM	UQ Responder	(001) CLEAR - NO CONFLICT	

Member	Name	Rev	Responded	Ву	Response	Comment
UTFTRCA01	UTILIQUEST FOR FRONTIER	00A	01/31/22 07:51:38 AM	UQ Responder	(010) LOCATE AREA MARKED	
YVC01	YUCAIPA VALLEY WTR	00A	01/31/22 05:01:05 PM	Late Notice	(999) Member did not respond by the required time	

From: Anton, Joseph

To: <u>Marino, Tony@EnergySafety</u>

Subject: Frontier Contact

Date: Tuesday, February 1, 2022 3:52:35 PM

Bin Liang

SPCLST-Construction

32477 Haun Rd, Menifee, CA 92584

C: 951-723-0736

E: bin.liang@ftr.com

Thank you

Joe Anton

UtiliQuest / Locating Inc Regional Manager, Claims & Compliance joseph.anton@utiliquest.com

Cell: 858-230-9876

"An ounce of PREVENTION is worth a pound of cure." -- Benjamin Franklin

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

This document is not a certified record of Underground Service Alert

MBRCOD 00000 USAS 01/19/22 08:42 B220050037-07B RUSH NRSP POLY

Ticket: B220050037 Rev: 07B Created: 01/19/22 08:42 User: MERLIN Chan: WEB Work Start: 01/19/22 08:42 Legal Start: 01/19/22 08:42 Expires: 02/02/22 23:59 Response Required: N Priority: RUSH

Excavator Information

Company: MERLIN JOHNSON CONSTRUCTION, INC.

Co Addr: P.O. BOX 777

City: MENTONE State: CA Zip: 92359

Created By: MERLIN JOHNSON Language: ENGLISH Office Phone: 909-794-7702 SMS/Cell: 909-322-6061

Office Email: MJ.MJC@VERIZON.NET

Site Contact: MERLIN JOHNSON

Site Phone: 909-322-6061 SMS/Cell: 909-322-6061

Site Email: MJ.MJC@VERIZON.NET

Excavation Area

State: CA County: RIVERSIDE Place: BEAUMONT

Zip: 92223

Location: Address/Street: 650 OAK VALLEY PKWY

: X/ST 1 : ELM AVE

: X/ST 2 :

: *** MEET AND MARK***

MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

DATE: JANUARY 10, 2022.

TIME: 0900

WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK

Delineated Method: WHITEPAINT

Work Type: WATER MAIN AND SERVICE INSTALLATION

Work For : BCVPARKS DEPT. Permit: NOT AVAILABLE

1 Year: N Boring: N Street/Sidewalk: Y Vacuum: N Explosives: N

Lat/Long

Center Generated (NAD83): 33.946643/-116.990062 33.950798/-116.990010 : 33.950747/-116.985876 33.946591/-116.985928

Excavator Provided:

Comments:

NO RESPONSE FROM CATV, ELEC, FIBR - CALLER CONFIRMS SITE IS DELINEATED - ABOVE NO-SHOW AT MEET AND MARK, I WAS ONSITE UNTIL 0930, NO FACILITIES MARKED.

HAD NO CONTACT FROM UTILITY PER MERLIN JOHNSON--[MERLIN 01/10/2022 10:09:54 AM]
NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - MORE TIME HAS NOT
BEEN AGREED TO BY MERLIN JOHNSON CONSTRUCTION, INC. PER MERLIN JOHNSON--[MERLIN 01/13/2022 04:45:49 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/14/2022 02:42:40 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/17/2022 05:34:04 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/18/2022 07:02:02 AM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED PER MERLIN JOHNSON-[MERLIN 01/18/2022 04:32:26 PM]

NO RESPONSE FROM FIBR - CALLER CONFIRMS SITE IS DELINEATED - CREW ONSITE WORKING PER MERLIN JOHNSON--[MERLIN 01/19/2022 08:42:35 AM]

Members:

© Copyright 2018 Underground Service Alert of Southern California All rights reserved

BCV01 BEAUMONT-CHERRY VALLEY WATER DISTRICT

EMER - KNUTE DAHLSTROM 951-757-6870 KNUTE@BCVWD.ORG

VACU - KNUTE DAHLSTROM 951-845-9581 KNUTE@BCVWD.ORG

NRSP - KNUTE DAHLSTROM 951-845-9581 KNUTE@BCVWD.ORG

BEAU01 CITY OF BEAUMONT

EMER - ROBERT VESTAL 951-769-8520 RVESTAL@BEAUMONTCA.GOV

VACU - MARTIN GUTIERREZ 951-769-8520 MGUTIERREZ@BEAUMONTCA.GOV

NRSP - MARTIN GUTIERREZ 951-769-8520 MGUTIERREZ@BEAUMONTCA.GOV

MCISOCAL MCI

EMER - FIBER SECURITY DEPT 800-624-9675

VACU - MCI OPERATOR 800-289-3427

NRSP - MANAGER FIBER SECURITY 800-289-3427

SCG1BT SC GAS

EMER - MARGARITO DOMINGUEZ 800-423-1391

VACU - ALLOWED BUT CAN BE REFUSED

NRSP - LEE CHRISTENSEN 909-335-3946 LMCHRISTENSEN@SOCALGAS.COM

SCG29T SC GAS

EMER - CINDY PINON-PACHECO 951-845-0705

VACU - ALLOWED BUT CAN BE REFUSED

NRSP - TERRY BOARDMAN 951-845-0712

SPRINT1 SPRINT

EMER - SPRINT 800-521-0579

VACU - JASON JENIA 800-521-0579

NRSP - SPRINT 800-521-0579

UCHTRW_S1 SPECTRUM REGIONAL OPERATIONS CENTER

EMER - SPECTRUM DAMAGE ONLY 844-780-6054

VACU - DAVID ANDERSON 951-406-1606 DAVID.ANDERSON1@CHARTER.COM

NRSP - DAVID ANDERSON 951-406-1606 DAVID.ANDERSON@CHARTER.COM

USCEDE SC EDISON DIST - DESERT REGION

EMER - SC EDISON DIST 800-611-1911

VACU - GILBERT ACEVES 909-548-7249 GILBERT.ACEVES@SCE.COM

NRSP - UTILIQUEST MAIN OFFICE 805-658-7801

USCETT84SE SCE TRANS TELECOM

EMER - TCC 800-655-8844 TCCINBOX@SCE.COM

VACU - JACK NEILL 909-873-3263 JACK.NEILL@SCE.COM

NRSP - UTILIQUEST 323-724-0081

UTFTRCA01 UTILIQUEST FOR FRONTIER

EMER - UTILIQUEST DISPATCH 323-795-2654

VACU - BIN LIANG 951-723-0736 BIN.LIANG@FTR.COM

NRSP - UTILIQUEST 323-795-2654

YVC01 YUCAIPA VALLEY CO WTR

EMER - FRONT OFFICE 909-797-5117

VACU - FRONT OFFICE 909-797-5117

NRSP - MIKE RIVERA 909-721-2462

From: <u>Marino, Tony@EnergySafety</u>

To: <u>bin.liang@ftr.com</u>

Subject: RE: Request for information regarding excavation ticket B220050037; Underground Safety Board Case

22LA014084

Date: Thursday, February 10, 2022 8:54:00 AM

Mr. Liang,

I'm following up on my request from last week. If you feel a verbal interview would be more appropriate to conveying the facts in your possession, I am happy to set one up. If it will take longer than the end of the week to provide answers to these questions, please let me know with an expected timeline for your response.

Thank you, Tony

From: Marino, Tony@EnergySafety

Sent: Thursday, February 3, 2022 11:29 AM

To: bin.liang@ftr.com

Subject: Request for information regarding excavation ticket B220050037; Underground Safety

Board Case 22LA014084

Mr. Liang,

I'm investigating a no/late response complaint for ticket B220050037, in which the ticket holder alleged that Frontier did not provide markings by the legal start date and time. For your reference, this is for case 22LA01484. I spoke with Joe Anton of UtiliQuest earlier this week, and he provided your information as the best person to talk to at Frontier.

These questions are for you or another Frontier employee familiar with the circumstances surrounding the ticket.

First, could you let me know if my understanding of the situation is correct? My understanding is that UtiliQuest, in the course of locate and mark activities for Frontier, discovered a Frontier fiber line that was unlocatable due to lack of a tracer wire. UtiliQuest notified Frontier, and Frontier had a contractor install a tracer wire. That contractor installed tracer wire for most of the length of fiber, but was not able to install tracer wire for an approximately 30-foot length of fiber, due to a break in the conduit. Frontier had another contractor repair the line—which may have happened yesterday—to allow tracer wire to be installed in that 30-foot section. Let me know if all of this is accurate, or if there are any facts that I don't have or am misunderstanding.

Second, here are my specific questions:

- Could you provide the report that UtiliQuest provided to you that informed you of the unlocatable facility? Mr. Anton indicated that he could not provide it and so I should ask someone at Frontier.
- Could you provide the names of the companies that installed the tracer wire and repaired the conduit? Did either or both jobs require excavation? If so, could you provide me the ticket

numbers?

- Were maps identifying the location of the fiber line provided to the companies installing tracer wire and repairing the conduit? If so, could you provide whatever maps were provided to those companies?
- Could you provide a timeline of the following relevant dates:
 - When Frontier was notified by UtiliQuest that it had an unlocatable fiber line
 - When Frontier contacted the company assigned with installing the tracer wire
 - When the tracer wire was installed, except for where it could not be installed due to a damaged conduit
 - When Frontier was notified that a damage in conduit prevented the company installing the tracer wire from completing the job
 - When the damage conduit was repaired
 - When the tracer wire installation was completed

If you would like to provide answers in writing, that is fine. If you feel a verbal interview would be more appropriate to conveying the facts in your possession, I am happy to set one up. If it will take longer than the end of the week to provide answers to these questions, please let me know with an expected timeline for your response.

Thank you, Tony

Tony Marino
Executive Officer | Underground Infrastructure Directorate
Office of Energy Infrastructure Safety
1516 9th Street
Sacramento, CA 95814
916-767-3370
EnergySafety.ca.gov

From: Merlin Johnson

To: <u>Marino, Tony@EnergySafety</u>

Cc: Merlin Johnson

Subject: FW: DigAlert Positive Response for Ticket B220050037-08B

Date: Tuesday, February 1, 2022 3:18:13 PM

Importance: High

Tony,

Below is the Positive Response dated (01-20-22 at 1237) stating "Locate Area Marked". This impossible because Jaime Mesa's email of 01-27-22 states that the "Tracer Wire" will not be installed until 01-28-22.

Let me know if you need anything else.

THANKS

Merlin Johnson Merlin Johnson Construction, Inc.

P.O. Box 777
Mentone, California 92359
909-794-7702 Office
909-322-6061 Cell
mj.mjc@verizon.net

From: noreply@digalert.org <noreply@digalert.org>

Sent: Thursday, January 20, 2022 12:37 PM

To: MJ.MJC@VERIZON.NET

Subject: DigAlert Positive Response for Ticket B220050037-08B

Importance: High

EMLCFM 01778B USAS 01/20/22 12:37:10 B220050037-08B NRSP RUSH POLY LREQ

Thank you for contacting Underground Service Alert of Southern California.

This is an automated electronic positive response confirmation for the ticket number below.

For your safety please excavate carefully around the marked utility lines.

For more information regarding DigAlert's web portals, mobile apps and text messaging, please visit $\underline{www.digalert.org}$ or text Services to DIGALT (344258).

This email comes from an automated program that is NOT MONITORED. DO NOT REPLY TO THIS EMAIL.

Ticket: B220050037 Rev: 08B Taken: 01/20/22 06:23 AM

State: CA County: RIVERSIDE Place: BEAUMONT

Address: 650 OAK VALLEY PKWY

Location: *** MEET AND MARK***

: MEET AND MARK LOCATION: IN DRIVEWAY 300' NORTH OF OAK VALLEY PKWY.

: DATE: JANUARY 10, 2022.

: TIME: 0900 : WORK AREA IS VARIOUS LOCATIONS WITHIN NOBLE CREEK PARK WorkType: WATER MAIN AND SERVICE INSTALLATION

Utility BCV01	Description BEAUMONT-CHERRY VLY WTR CLEAR - NO CONFLICT Comments: Clear - No conflict	Response 01/20/22	08:41	AM	001
BEAU01	By bcvwd1 on 1/20/22, 8:41 AM C/OF BEAUMONT-TRAF, SWR, D LOCATE AREA MARKED	01/06/22	03:27	PM	010
MCISOCAL		01/20/22	06:26	AM	001
SCG1BT	SOCALGAS DISTRIBUTION BEAUMONT CLEAR - NO CONFLICT	01/20/22	06:47	AM	001
SCG29T	SOCALGAS TRANSMISSION BEAUMONT CLEAR - NO CONFLICT	01/18/22	09:33	AM	001
SPRINT1	SPRINT - FIBER Member did not respond by the	01/07/22		PM	999
UCHTRW_S1	SPECTRUM RIV - CATV CLEAR - NO CONFLICT			AM	001
USCEDE	UTILIQUEST FOR SCE- DESERT REG	01/11/22	10:52	AM	010
USCETT84SE	UTIL 4 SCE TRNS TELEC-FIBR OPT	01/11/22	10:52	AM	010
UTFTRCA01	LOCATE AREA MARKED UTILIQUEST/FRONTIER - TEL/FIB	01/20/22	12:37	PM	010
YVC01	LOCATE AREA MARKED YUCAIPA VALLEY WTR - WTR Member did not respond by the :			PM	999

From: Ann Diamond

To: <u>Marino, Tony@EnergySafety</u>

Subject: RE: DigAlert electronic positive response procedure: Investigation 22LA01484

Date: Thursday, March 3, 2022 9:31:46 AM

Tony

If there are any EPRs done after the legal excavation start date and time those are sent immediately to the excavator email and/or sms (again if they have asked that the information be sent to them). All ticket/EPR sending processes are automated

We decided not to send as they came in before the excavation start date and time as we felt the excavator might start ignoring the notices if they kept getting "updates" on the EPRs – an excavator can look on line at any time to see the latest even before the legal excavation start date and time

Hope that helps.

Thanks,



Ann Diamond, President
PO BOX 77070 Corona, CA 92877
P: 951-808-8113 F: 951-808-8101
E: ann@digalert.org W: www.digalert.org



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.

From: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Sent: Thursday, March 3, 2022 9:09 AM **To:** Ann Diamond <ann@digalert.org>

Subject: DigAlert electronic positive response procedure: Investigation 22LA01484

Ann,

I have a question for you regarding DigAlert electronic positive response procedures, in connection with Board Investigation 22LA01484.

On your website, I see that DigAlert sends electronic positive response information to the excavator at the legal start date and time: "DigAlert will email the excavator at the start date and time listed on the ticket a complete status of responses, if the excavator has supplied an email address on the ticket." https://docs.digalert.org/display/WebSrv/Electronic+Positive+Response

Does DigAlert update an excavator via email when DigAlert receives an electronic positive

response AFTER the legal start date and time (assuming the excavator has provided their email)? Is this an automated process?

Thank you, Tony

Tony Marino
Executive Officer | Underground Infrastructure Directorate
Office of Energy Infrastructure Safety
1516 9th Street
Sacramento, CA 95814
916-767-3370
EnergySafety.ca.gov



CALIFORNIA UNDERGROUND FACILITIES SAFE EXCAVATION BOARD INVESTIGATION DIVISION INTERVIEW REPORT

REPORT DATE: 2/1/2022

CASE NO: 22LA01484

DATE/TIME OF INTERVIEW: 1/21/2022 9:19 AM

LOCATION OF INTERVIEW: Phone

NAME/ADDRESS OF INTERVIEWEE:

Merlin Johnson, P.O. Box 777 Mentone, CA 92359

Tel: 9093226061

NARRATIVE:

I contacted Mr. Johnson to inform him that if Yucaipa Valley Water has not responded to his ticket, he could not begin work. I informed him that statute requires response from all members who receive the excavation notification, and an excavator can't begin working until the excavator receives those responses, so he might wish to be proactive in confirming with Yucaipa Valley Water that they had no facilities in the proposed work area.

Mr. Johnson indicated that he'd just received an electronic positive response the day before indicating that the locate area was marked, when he had seen that the portion of the area that still needed to be marked was not yet marked. He stated that he contacted Gabriel Gonzales at UtiliQuest and Gonzales agreed that the area that needed marked was still not marked. Johnson indicated that Gonzales had indicated to him that Gonzales was in contact with someone named Jaime Mesa of Frontier on the issue. I indicated to Mr. Johnson that I'd likely contact him the following week to follow up to see if the line was marked.

Investigator Name	Supervisor Name
Tony Marino	Jason Corsey
Tony Marino	Jason Corsey

From: Marino, Tony@EnergySafety

To: Anton, Joseph

Subject: RE: Request for information regarding ticket B220050037; Underground Safety Board Case 22LA014084

Date: Sunday, February 6, 2022 8:56:00 AM

Thank you Joe.

I have another follow-up question on ticket B220050037-01B. Can you explain the responses from UtiliQuest on behalf of Spectrum, the two Southern California Edison divisions, and Frontier at around 11:42 am on January 10 that each indicate "Clear – No Conflict"? For each of them, there were follow-up responses (one at 3:51pm that afternoon for a scheduled meet and another midmorning the next day). All but Spectrum had a follow-up message that indicated that there were lines in the area to be marked. Can you help me understand why there was an initial indication on January 10 of "Clear – No Conflict"?

Thanks, Tony

From: Anton, Joseph < joseph.anton@utiliquest.com>

Sent: Wednesday, February 2, 2022 3:17 PM

To: Marino, Tony@EnergySafety <Tony.Marino@energysafety.ca.gov>

Subject: Re: Request for information regarding ticket B220050037; Underground Safety Board Case

22LA014084

Hi Tony,

I was able to confirm that the cable was mapped, and the tech found the cable inside the structure without a tracer wire during the course of his locate.

The excavator was on site when we went back to mark the cable and was aware of the 30' section that had conduit in need of fixing before a tracer could be placed. That 30' section was away from his area of concern for the excavation. Our area supervisor also reached out today to make sure he knows.

Thank you

Joe Anton

UtiliQuest / Locating Inc Regional Manager, Claims & Compliance joseph.anton@utiliquest.com

Cell: 858-230-9876

[&]quot;An ounce of PREVENTION is worth a pound of cure." -- Benjamin Franklin

On Tue, Feb 1, 2022 at 6:57 PM Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>> wrote:

CAUTION: External

Joe,

Thanks for answering my questions this afternoon. As we discussed, I am sending two follow-up questions related to how specifically the field technician learned that there was an unlocatable Frontier fiber line in the area of proposed excavation of ticket B220050037.

- 1. Can you confirm that the fiber line was indicated on the map provided to the technician?
- 2. Please provide specifics about how the technician identified that the fiber line was unlocatable (e.g. it was on a map but couldn't be found, it could be seen in a handhole or above ground box but had no tracer wire or signal associated with it, etc.)

If you need to ask the technician for the answer to these questions, could you provide the technician's name along with your answer?

Also, I want to reiterate my suggestion that you make sure that the excavator/ticket holder is aware of the 30-ft section of fiber where the tracer wire could not be installed last week and therefore has not yet been marked.

Thank you, Tony

From: Anton, Joseph < <u>ioseph.anton@utiliguest.com</u>>

Sent: Monday, January 24, 2022 12:33 PM

To: Marino, Tony@EnergySafety < <u>Tony.Marino@energysafety.ca.gov</u>>

Subject: Re: Request for information regarding ticket B220050037; Underground Safety Board

Case 22LA014084

Tony,

I'm still trying to track info down on this one.

Thank you

Joe Anton

UtiliQuest / Locating Inc Regional Manager, Claims & Compliance joseph.anton@utiliquest.com

Cell: 858-230-9876

On Wed, Jan 19, 2022 at 6:24 PM Marino, Tony@EnergySafety <\table Tony.Marino@energysafety.ca.gov> wrote:

CAUTION: External

Mr. Anton,

I am investigating a complaint of "no response" against Frontier for ticket B220050037 (and revisions). For your reference, our case number is 22LA01484. My understanding from the complainant (who had made the notification to DigAlert) is that a portion of Frontier's subsurface installations in the excavation area are fiber without tracer wire, and that the issue has been raised by UtiliQuest to Frontier to address.

I have questions for you, one of your employees more familiar with the ticket, or Frontier to answer.

- The electronic positive response of revision -00B of ticket B220050037 states that Frontier (UTFTRCA01), Spectrum Riverside (UCHTRW_S1), SCE Distribution Desert Region (USCEDE), and SCE Transmission Telecom (USCETT84SE) each negotiated a marking schedule for the ticket. The responder for each is listed as "UQ Responder." Can you describe how the negotiation took place, and what UtiliQuest staff negotiated with the excavator? Can you describe the parameters of the marking schedule that were agreed upon?
- The electronic positive response of revision -01B of ticket B220050037 states that Frontier responded with "Partially Marked More Time is Needed." Was this need discussed with the excavator? When? Can you describe to me why more time was needed?
- The complainant indicated that a UtiliQuest representative—Gabriel Gonzales—had told him that the issue was the lack of tracer wire for a fiber line, and that the issue had been raised to Frontier. Is it true that the line hasn't been marked as of today due to an absence of tracer wire? How did UtiliQuest employees discover the issue? Has UtiliQuest contacted Frontier about the issue? When was the contact with Frontier made? To whom at Frontier was this information provided?
- Can you provide an appropriate person at Frontier for me to contact during the course of this investigation?

If you would like to provide answers in writing, that is fine. If you feel a verbal interview more appropriate to conveying the facts in your possession, I am happy to set one up. If it will take longer than a day to provide the answers to these questions, please let me know with an expected timeline for your response.

Thank you, Tony Tony Marino
Executive Officer | Underground Infrastructure Safety Directorate
Office of Energy Infrastructure Safety
1516 9th Street
Sacramento, CA 95814
916-767-3370
EnergySafety.ca.gov

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.

This email message, and any documents which may accompany it, contain information which is intended for use only by the intended recipient(s), and may contain information that is privileged and/or confidential. If you are not the intended recipient of this message you are hereby notified that any review, disclosure, dissemination, distribution, copy or other use of this message or its attachments is strictly prohibited. If you have received this message in error, please notify the sender by reply email, delete the email from your computer and destroy all copies of the communication and any attachments.