

	2022
Number of outages that occurred while fast trip settings were enabled.	6
Number of customers affected by such outages.	6989
Duration of outages that occurred while fast trip settings were enabled.	8 hours 55 minutes
Customer interruption minutes associated with such outages.	526,525.10
Number of devices with fast trip setting capabilities.	57
Number of days fast trip settings were enabled.	24
Number of times fast trip settings were enabled.	9
Duration of enablement.	347 hours