

Daniel Kushner Sr. Director Electric Compliance 300 Lakeside Drive Oakland, CA 94612

E-mail: Daniel.Kushner@pge.com

August 25, 2025

Patrick Doherty
Program Manager | Compliance Assurance Division
Office of Energy Infrastructure Safety
715 P Street, 20th Floor
Sacramento, CA 95814

RE: Energy Safety NOV ID: NOV_CAD_PGE_KSF_20250408_1027 Notice of Violation: Government Code § 15475.1 and the California Code of Regulations, Title 14, Division 17 § 29302(b)(2)

Dear Mr. Doherty:

This letter is in response to the above referenced Notice of Violation (NOV) dated July 24, 2025, regarding the Office of Energy Infrastructure Safety (Energy Safety) inspection of Pacific Gas and Electric Company's (PG&E) 2024 Wildfire Mitigation Plan (WMP) initiatives.

Energy Safety based its compliance assessment on the following statute and code sections:

California Government Code Section 15475.1, states:

- (a) The office may determine that a regulated entity is not in compliance with any matter under the authority of the office. If necessary, the office may undertake an investigation into whether the regulated entity is noncompliant with its duties and responsibilities or has otherwise committed violations of any laws, regulations, or guidelines within the authority of the office.
- (b) The office's primary objective is to ensure that regulated entities are reducing wildfire risk and complying with energy infrastructure safety measures as required by law.

California Code of Regulations, Title 14, Section 29302(b)(2), "Investigations, Notices of Defect and Violation, and Referral to the Commission" states in part:

"The Director may designate a compliance officer to consider the findings of any investigation. The compliance officer may issue any of the following:

(2) Notice of violation, identifying noncompliance with an approved Wildfire Mitigation Plan or any law, regulation, or guideline within the authority of the Office."

Energy Safety's April 8, 2025, inspection identified the following violation:

Violation 1. Energy Safety observed that in implementing 2024 WMP initiative 8.1.2.10.5 - Non-Exempt Expulsion Fuses, on pole ID 240580, Grid Hardening ID 31661057 at 14912-14918 Montalvo Rd, Saratoga, CA, 95070, USA, 37.250267919652664, -122.02786853287508, the inspector observed that exempt fuses were not attached to the cutouts.

Response

PG&E respectfully disagrees with the Energy Safety finding in this Notice of Violation (NOV) from April 8, 2025.

PG&E replaced the non-exempt fuses with solid blade disconnects per EC Tag 126535166, Grid Hardening ID 31661057, at pole SAP ID 100553714. GIS records are shown in Image 1 as device 29225 SB.

The reason for the solid blades at this location with an empty cutout is that the fuse is essentially not needed as there has not been any outage history for up to five years as well as difficulty coordinating the protection scheme. The spare/alternate cutouts will remain available in the event there is a loading or configuration change to the circuit, but they are not necessary for the present design. Additionally, there already exists an upstream source-side fuse providing protection for this zone at pole SAP Equipment ID 100551366.

Doing so is in alignment with PG&E's standards. As described in PG&E's 2023-2025 WMP for target GH-10: "Occasionally, when replacing existing non-exempt fuses with exempt fuses, the exempt fuse will disrupt the protection scheme for that circuit. In these cases, PG&E will be deploying Solid Blade switches to support operational flexibility and protect coordination." ¹



¹ PG&E 2023-2025 WMP R7 (Feb. 13, 2025) at 465.

Public

Please do not hesitate to contact our shared inbox at <u>WSComplianceMailbox@pge.com</u> if you have any questions regarding this matter.

Sincerely,

Daniel Kushner, PhD Sr. Director, Electric Regulatory Compliance

cc: Samuel Isaiah, Senior Utilities Engineer Specialist, Energy Safety

Yana Loginova, Program Manager, Energy Safety Shannon Greene, Program Manager, Energy Safety

Ivan Garcia, Field Inspector, Energy Safety