



July 2, 2026

Brandon Tolentino
Vice President, Wildfire and Business Resiliency
Southern California Edison Company
2244 Walnut Grove Ave
Rosemead, CA 91770

NOTICE OF DATA INACCURACY

Mr. Tolentino:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Southern California Edison Company (SCE) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues SCE a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy may lead to a Notice of Non-Performance (NON) if the inaccuracy causes SCE to miss a WMP target or prevents Energy Safety from ensuring that SCE performed the targets and statements made in SCE's 2025 WMP.

On May 14, 2026, Energy Safety conducted an inspection of Southern California Edison Company's WMP initiatives in the vicinity of the city of Orange, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Pole ID 1374128E, Grid Hardening ID TD2247808-1374128E at coordinates 33.8126543087376, -117.769999708812, the inspector observed that Inaccurate data provided on covered conductor installation.

The data inaccuracy identified in this notice could make it appear as though SCE reached the target set in WMP initiative 8.1.2.1.1 – Covered Conductor when it has not. If SCE does not address this data inaccuracy and includes the inaccurate data in its reporting regarding WMP initiative 8.1.2.1.1 – Covered Conductor, SCE may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on SCE's WMP Performance.

Within 30 days from the issuance date of this NODI, SCE should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

/s/ Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.Doherty@energysafety.ca.gov

Cc:

Peter Van Mieghem, SCE
Peter.Vanmieghem@sce.com

Elizabeth Leano, SCE
Elizabeth.Leano@sce.com

Cynthia Childs, SCE
Cynthia.Childs@sce.com

Raghu Rayalu, SCE
Raghu.Rayalu@sce.com

Erick G Sanchez, SCE
Erick.G.Sanchez@sce.com

Sally Jeun, SCE
Sally.Jeun@sce.com

Yana Loginova, Energy Safety
Yana.Loginova@energysafety.ca.gov

Samuel Isaiah, Energy Safety
Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety
Shannon.Greene@energysafety.ca.gov
AssetPerformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/Lists/DocketLog.aspx?docketnumber=2025%20NODI>



State of California – A Natural Resources Agency

OFFICE OF ENERGY INFRASTRUCTURE SAFETY

715 P Street, 15th Floor | Sacramento, CA 95814

916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor

Forest Kaser, Director

INSPECTION REPORT

Electrical Corporation:	Southern California Edison Company
Report Number:	PAD_SCE_YLO_20260514_1159
Date of Inspection:	May 14, 2026
City and/or County of Inspection:	Orange, Orange County
Inspector:	Yana Loginova
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 4 (Q4)
Inspection Selection:	Energy Safety viewed the contents of the Q4 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.1.1 – Covered Conductor
Inspection Purpose:	Assess the accuracy of Southern California Edison Company's QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	1374128E	TD2247808-1374128E	33.8126543087376, -117.769999708812	Tier 3	8.1.2.1.1 – Covered Conductor	Inaccurate data provided on covered conductor installation

Observations

On Pole ID 1374128E, Grid Hardening ID TD2247808-1374128E at 7713-7733 E Lolita St, Orange, CA, 92869, 33.8126543087376, -117.769999708812, the inspector observed that no covered conductor was installed. The inspector's observation is documented in Data Inaccuracy 1 photographs GImg1, GImg2 and IA1Img1, which are attached to this report as Exhibit A.

Energy Safety concludes that there are inaccurate data because of these facts:

1. Southern California Edison Company's Covered Conductor (8.1.2.1.1) work was identified as complete at this location.
2. In 2024, SCE informed Energy Safety that stub pole work does not count toward Covered Conductor WMP totals and would either identify or exclude these points in future QDRs. This data point did not contain an identifier and was not excluded.
3. Covered conductor was not installed.

This observation indicates that the data regarding covered conductor installation was not accurate. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance. Energy Safety maintains that work that does not count towards WMP totals should not be submitted as part of completed work in the QDR and looks forward to SCE identifying or excluding these points as described in 2024.

Exhibits

Exhibit A: Photo Log

Structure ID: 1374128E

Data Inaccuracy 1

	
G1mg1: Overall Structure	G1mg2: Structure ID
	
IA1Img1: No covered conductor installed	