



Prescription

**036-OFFC - Major Dismantle R3 24-35.99 in**  
[\(/OneVM/s/detail/a325c000001QREUAA4\)](/OneVM/s/detail/a325c000001QREUAA4)

Create Prescription Constraint

Update Span WOLI Association

Status  
Constrained

Constrained ✓

Reported on Work Order  
[00518721](#)  
[\(/OneVM/s/workor...](/OneVM/s/workor...)

[Details \(?tabset-40187=1\)](#)

[Images \(?tabset-40187=7940c\)](#)

[History \(?tabset-40187=2\)](#)

Project  
[2026 CHALLENGE 1102 Q2 Routine \(/OneVM/s/vm-project/a2zPF000004zY4JYAU/2026-challenge-1102-q2-routine\)](#)

Region  
North Valley

Reported on Work Order ⓘ  
[00518721](#)

Division  
North Valley

VM Prescription Name  
RX-07527304

Delivery Type  
Distribution

Constrained  
✓

EVM Relevant

Tree Crew Added ⓘ

Underbuild  
No

Resource Type  
VMI

Joint Pole Span  
Yes

IsRevised

Inspector Added ⓘ

Tree Risk Assessment Form #

Project Type  
Routine

Tree Risk Assessment Performed

Span WOLI Association

**C  
o  
n  
s  
t  
r  
a  
i  
n  
t  
s**

(1) [\(/OneVM/s/vm-prescription/related/a2vPF00000DvCz\)](/OneVM/s/vm-prescription/related/a2vPF00000DvCz)

Case Nu...	Status	Constrain...	Constrain...
<a href="#">010154...</a>	In Progress	Clearance...	Primary <input type="button" value="▼"/>

[View All](#)

[\(/OneVM/s/vm-prescription/related/a2vPF00000DvCzSYAV/Prescription\\_r\)](/OneVM/s/vm-prescription/related/a2vPF00000DvCzSYAV/Prescription_r)

**W  
o  
r  
k  
I  
t**

(1) [\(/OneVM/s/vm-prescription/related/a2vPF00000DvCz\)](/OneVM/s/vm-prescription/related/a2vPF00000DvCz)

File Count  
2

Span Asset Association  
100356912\_100418909

### ✓ Veg Point

Veg. Point  
[VP-10805492 \(/OneVM/s/vm-veg-point/a31PF000005lksXYAQ/vp10805492\)](#)

Latitude  
39.479324000000000

00000011  
Work Category  
[\(/OneVM/s/workorderlineitem/1WLPF000007QBOx4AO/detail\)](#)  
Standard

Auto ID

Longitude  
-121.251739000000000

### ✓ Veg Point Details at Time of Inspection

Common Name  
Pine, Ponderosa

Scientific Name  
[Pinus ponderosa \(/OneVM/s/detail/a305c000005Y3zMAAS\)](#)

Dead/Dying  
✓

DBH ⓘ  
34

Height  
139

Tree Ownership ⓘ  
Private

Tree Connect  


MWS Doc Number

Major Woody Stem (MWS)  


Exempt Type

Redwood Exemption

Parcel

Directions  
BETWEEN NEW YORK FLAT ROAD AND CHALLENGE CUT-OFF;  
IN SHARON VALLEY DEVELOPMENT

Street  
9478 LA PORTE RD

City  
BROWNSVILLE

County  
[Yuba \(/OneVM/s/detail/a03o0000008175PAAQ\)](#)

State  
CA


Location  
39.479324, -121.251739

Inspection Frequency  
Annual

Next Inspection Date  
5/8/2027

Veg Point Comments  
0.3SP E/O PL#10 N/O LNS

City Jurisdiction  


Work O...	Work Ord...	Status	Work Cat...
<a href="#">000000...</a>	<a href="#">0052394...</a>	Not Comp...	Standard 
<a href="#">View All</a>			
<a href="#">(/OneVM/s/vm-prescription/related/a2vPF00000DvCzSYAV/WorkItems_r)</a>			

11202881090  
Master Parcel ID  
(OneVM/s/account/0015c00001vihVeAAI/11202881090)  
1120288109\_050-240-048-000

## Prescription

Work Code ⓘ

036-OFFC - Major Dismantle R3 24-35.99 in  
(/OneVM/s/detail/a325c00001QREUAA4)

Reason for Removal ⓘ

Fall In Risk

Reason for Fall In ⓘ

Potential Trunk Failure

Is Complete Removal Prescribed ⓘ

True

Delisting Comments ⓘ

Priority

Routine

Priority Reason ⓘ

P1 Escalation Date

P2 Escalation Date

Is Priority Prescription?

No

Observed Radial Dist. to Asset ft

15

Observe Radial Dist to Com Neut ft ⓘ

Trim to Vertical Clearance ft

Trim to Horizontal Clearance ft

Trim to Radial Clearance ft

Com Neut Trim to Radial Clear ft ⓘ

Brush Quantity ⓘ

WM Prescription ?



Reason for Grow In ⓘ

Observed Defects ⓘ

01-Dead tree and or Tree parts

Removal Comments ⓘ

Reason for Delisting ⓘ

Priority Root Cause

Is L2 Inspection Completed ?



Device Coordinates ⓘ

39.4792857561, -121.2517599468

DateTime of Device Coordinates ⓘ

5/8/2026 9:51 AM

Device Distance (Feet) ⓘ

15.147422

Distance Justification ⓘ

Request Central WM Support ⓘ



VM Program ⓘ

Describe Other VM Program ⓘ

Is Wood Within Scope? ⓘ

---

Veg Survey

---

Debris (<4" diameter; included under TW)

Haul Offsite

---

Prescription Comments

CUT TO GROUND; NICE CLEANUP

---

Reason for Work Code Change

---

PG&E Representative

---

Tag Type

---

Tag Number

---

### ▼ Scheduling Information

Roadside Accessible



---

Traffic Mitigation



---

Signage Required



---

Road Closure



---

Flagger Required



---

Line Clearance Required



Lift Truck Required



---

Lift Truck Height Ft

---

Crane Required



---

Crane Height Ft

---

Work Duration

1.00

---

Scheduling Comments

---

### ▼ Release Information

Earliest Start Date

Due Date

---

### ▼ Status Information

Status

Constrained

---

Vendor Co.

PG&E VMI

Approval Hold Expiration ⓘ

5/13/2026

Manual Approval ⓘ



Approved Date

5/11/2026 11:25 AM

Approved By



Rejected Date

Rejected By

Rejection Reason

Rejection Comments

▼ System Information

Created By



5/8/2026 10:01 AM


Class Size

Class 3

Field Creation Date

5/8/2026 9:51 AM

Last Modified By



5/12/2026 3:48 PM

Prescription Immed Create VegWork



Record Type Name

VM\_Prescription

[Do Not Sell My Personal Information](#)  
[Privacy](#)

Copyright © 2026 Pacific Gas and Electric Company. All rights reserved.