



June 11, 2026

**BY ENERGY SAFETY E-FILING**

Elizabeth McAlpine

Supervisory Environmental Scientist | Environmental Science

Division Office of Energy Infrastructure Safety

[Elizabeth.McApline@energysafety.ca.gov](mailto:Elizabeth.McApline@energysafety.ca.gov)

Docket: 2025 NON

**Subject:** Bear Valley Electric Service, Inc. Response to Notice of Performance-  
NON\_ESD\_BVES\_RGA\_20260505\_1253

Dear Ms. McAlpine:

Bear Valley Electric Service, Inc. (BVES) is providing a response to the Notice of Performance- NON\_ESD\_BVES\_RGA\_20260505\_1253. The enclosed response describes corrective actions taken to by BVES to remedy the findings identified in the above notice.

If you have any questions, or require additional information, please contact Jared Hennen at 909-255-2948 or [Jared.Hennen@bvesinc.com](mailto:Jared.Hennen@bvesinc.com).

Sincerely,

//s//

Jared Hennen

Wildfire Mitigation and Reliability

Engineer Bear Valley Electric Service, Inc.

## BVES RESPONSE

**Notice of Non-Performance:** NON\_ESD\_BVES\_RGA\_20260505\_1253

**Finding:** On May 5, 2026, Energy Safety conducted an inspection of BVES's WMP initiatives in the vicinity of Big Bear City, California in High Fire Threat District (HFTD) Tier 2 and State Responsibility Area (SRA). The inspection report is enclosed herewith. Energy Safety found the following deficiency:

Deficiency 1. Energy Safety observed that BVES failed to implement its 2025 WMP initiative 8.2.3.4 Fall-in Mitigation, by not removing a dead, rotten or diseased tree near coordinates 34.26713531028709, -116.84599287356302. Energy Safety considers this non-performance to be in the Moderate risk category. BVES must complete a corrective action for this non-performance by six months from the date of this notice.

**Response:** BVES received NON\_ESD\_BVES\_RGA\_20260505\_1253 on May 12, 2026 regarding a dead tree located at 945 Sierra Ave, Big Bear City. BVES dispatched a vegetation management crew to remove the tree. The work was completed the same day, and all wood and debris were removed from the site. Please see the photographs below for before and after images of the tree, labeled "2".



P.O. Box 1547, 42020 Garstin Drive, Big Bear Lake, California, 92315  
Tel: (909) 866-4678 \* Fax (909) 866-5056



P.O. Box 1547, 42020 Garstin Drive, Big Bear Lake, California, 92315  
Tel: (909) 866-4678 \* Fax (909) 866-5056



After work was completed.