



**CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION**

INVESTIGATION REPORT

Date: April 24, 2026

Case No.: N242910076

Violations:

David Oh DBA Insight Landscaping
Government Code § 4216.2(b):

Excavating without first notifying the regional notification center of intent to excavate.

Executive Summary:

On October 15, 2024, Insight Landscaping used a shovel to dig up tree roots and damaged a half-inch plastic natural gas pipeline without first contacting the regional notification center. Insight Landscaping called emergency services 911 to report the gas leak after the damage occurred. No one was injured and no equipment, other than the half-inch plastic natural gas pipeline, was damaged.

Reporting Party Information:

Southern California Gas Company
555 West 5th Street, Suite 1700
Los Angeles, California 90013

Date of Incident:

October 15, 2024

Location of the Incident:

2055 Cambridge Avenue
Cardiff, California 92007

Operator:

Southern California Gas Company
555 West 5th Street, Suite 1700
Los Angeles, California 90013

Excavator:

David Oh DBA Insight Landscaping
4783 Marblehead Drive
Oceanside, California 92057

Facility Type Damaged:

1/2" Plastic natural gas pipeline

Investigation:**Notification of the Incident**

On October 17, 2024, Southern California Gas Company submitted a notification of an incident to the California Underground Safety Board (Board). The notification stated, "Contractors hit gas line during excavation." (Exh. 1.)

The case was assigned to Investigator Ousama Alkahwaji (Investigator).

Excavation and Damage

Government Code section 4216(g) defines "excavation" to be the use of tools or equipment to move or displace earth, rock, or other material in the ground.

On October 15, 2024, Insight Landscaping used a shovel to dig tree roots at 2055 Cambridge Avenue, Cardiff, California 92007, and damaged a half-inch plastic natural gas pipeline, causing a gas leak. (Exh. 2.) Encinitas Fire Department responded to the 911 call and arrived at the incident location at 9:42 a.m. (Exh. 7)



Photo 1: Provided by San Diego Gas and Electric, depicts the excavation area at 2055 Cambridge Avenue, Cardiff, California 92007.



Photo 2: Provided by San Diego Gas and Electric, depicts the damaged 0.5-inch plastic natural gas pipeline.

Identity of the Excavator

Government Code section 4216(h) defines an excavator to be “any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with their own employees or equipment performs any excavation.”

David Oh DBA Insight Landscaping was licensed, as of November 8, 2024, by the California Contractors State License Board, license number 674721 with C27 - Landscaping, C-61, D06 - Concrete Related Services, A - General Engineering, and B - General Building classifications. (Exh. 3.)

12Insight Landscaping Did Not Contact the Regional Notification Center Before Excavating

Government Code section 4216.2(b) states that an excavator planning to excavate shall notify the appropriate Regional Notification Center of the excavator’s intent to excavate at least two working days, and not more than 14 calendar days, before beginning that excavation.

Insight Landscaping did not notify the Regional Notification Center prior to excavation at 2055 Cambridge Avenue, Cardiff, California 92007. David Oh (Oh), Owner of Insight Landscaping stated Insight Landscaping “never thought of hitting gas pipe while working around the tree.” (Exh. 2.)

On November 7, 2024, the investigator emailed Amber Dahl, Safety Awareness Director at Underground Service Alert of Southern California, requesting ticket information for 2055 Cambridge Avenue, Cardiff, California 92007, from September 3, 2024, to October 15, 2024. (Exh. 4.)

On November 7, 2025, Dahl provided tickets numbered A242890769-00A and A242890769-01A for 2055 Cambridge Avenue, Cardiff, California 92007, from September 3, 2024, through October 15, 2024. (Exh. 5.)

Insight Landscaping notified the regional notification center of planting a tree. The regional notification center created ticket number A242890769-00A on October 15, 2024, at 10:33 a.m., and a damage ticket number A242890769-01A was created on October 15, 2024, at 10:36 a.m. for a damaged plastic gas line. Both tickers were created after the damage occurred. (Exh. 5.)

Insight Landscaping Called 911 Emergency Services Upon Gas Release

Government Code section 4216.4(c)(1) requires an excavator to call 911 emergency services upon discovering or causing damage to a gas or hazardous liquid pipeline subsurface installation in which the damage results in the escape of any flammable, toxic, or corrosive gas or liquid.

Oh stated Insight Landscaping called 911 after the damage occurred. (Exh. 2.)

On February 16, 2025, the investigator submitted a public record request to the City Clerk's Department of City of Encinitas, requesting a copy of all police and fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA 92007, on October 15, 2024. (Exh. 6.)

On February 21, 2025, Deputy City Clerk, Pete Weichers, City of Encinitas, provided a copy of the emergency response report stating Encinitas Fire Department arrived at the incident location at 9:42 a.m. on October 15, 2024. (Exh. 7.)

Findings:

1. Insight Landscaping excavated without first contacting the regional notification center before beginning to dig tree roots on October 15, 2024, at 2055 Cambridge Avenue, Cardiff, California 92007.

Investigator	Supervisor
Ousama Alkahwaji	Anona Bonner
Signature	Signature
/s/ Ousama Alkahwaji	/s/ Anona Bonner

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 10/17/2024, at 1:05 p.m.	Mark Engel, Damage Prevention Manager, Southern California Gas Company
2.	Board's Investigation Questionnaire received from Insight Landscaping	Received on 1/7/2025	David Oh, Owner, Insight Landscaping
3.	Contractors License Detail for License No. 674721 obtained from the Contractors State License Board's website	Downloaded on 11/8/2024	California Contractors State License Board's website at https://www.cslb.ca.gov/onlineservices/checklicense/checklicense.aspx
4.	Investigator's email to Underground Service Alert of Southern California requesting ticket information on the underlying job to this incident	Emailed on 11/7/2024	
5.	Email from Underground Service Alert of Southern California providing ticket number A242890769	Received on 11/07/2024	Amber Dahl, Safety Director, Underground Service Alert of Southern California

6.	Public Records requested from City Clerk's Department of City of Encinitas	Submitted on 02/16/2025	
7.	Email from Deputy City Clerk, Pete Weichers, City of Encinitas, confirms finding records	Received on 02/21/2025	Deputy City Clerk, Pete Weichers, City of Encinitas

Exhibit 1

No-Ticket Damage Reporting Form

Submitted: October 17, 2024 1:05 PM

Reporter Information

Provide the names, titles, phone numbers, and email addresses of all individuals who are involved in reporting this damage or contributing to the answers to these questions

Full Name

Mark Engel

Title

Damage Prevention Manager

Phone Number

442-232-7720

E-mail address

mengel@sdge.com

Company

Provide the name, address, phone number, email address, and, if applicable, the Regional Notification Center (member code for your company).

Company Name

San Diego Gas and Electric

Address

517 Enterprise St, Escondido , 92029

Phone Number

442-232-7720

Email Address

mengel@sdge.com

Regional Notification Center member code

Other Contacts

Is the photographer same as the primary reporter named above?

Yes

Incident Information

What was the date and approximate time of the incident?

October 15, 2024 10:30 AM

What is the address where your facility was damaged on 10/15/2024?

Damage Street Address

2055 Cambridge Ave

Damage County

San Diego

Damage City

Cardiff By the Sea

Damage Cross Street 1

Birmingham Dr

Damage Cross Street 2

Liverpool Dr

Other Damage location description

Does San Diego Gas and Electric own, operate or maintain the facility damaged on 10/15/2024?

Yes

What type of excavation did you observe on 10/15/2024 at that address?

Landscaping

Describe the excavation activity you identified.

Contractors hit gas line during excavation

What excavation companies did you observe on 10/15/2024?

Company Name

Insight Landscaping

Company Address

4783 marblehead Dr, Oceanside , 92057

Phone Number

619-929-6310

Email Address

purvee1211@yahoo.com

Did this company damage the facility?

Yes

Provide the name, title, phone number, and email address for at least one contact for each excavation company working at or near incident address on date of incident. If you have more than one contact, please provide all of them. Email addresses are required for submission of this form.

Personnel Name

David Oh

Title

Foreman

Phone Number

619-929-6310

Email Address

purvee1211@yahoo.com

Notification Details

Was San Diego Gas and Electric notified of the proposed excavation by the Regional Notification Center before 10/15/2024?

No

What date and time did you learn of the damage to the facility?

October 15, 2024 10:30 AM

How did San Diego Gas and Electric learn of the damage to the facility?

Dispatched

Facility Damaged

What kind of facility was damaged on 10/15/2024?

Natural Gas

Natural Gas

What type of material was the damaged facility?

Plastic

Facility diameter (inches)?

0.5

Incident Details

What kinds of excavation equipment did you observe at the location of the damaged facility?

Shovel

Do you know what equipment damaged the facility?

Yes

What equipment damaged the facility?

Shovel

What information are you relying on regarding damage to the facility?

Interview with excavator

Did San Diego Gas and Electric contact the Regional Notification Center before repairing the damaged facility?

No

Provide any other relevant information about the damage on 10/15/2024.

Contractors hit a gas line during excavation.

Damages

Were there any injuries to any personnel or bystanders due to the damage to your facility on 10/15/2024?

No

Was any property damaged other than the damaged facility?

No

Was there a fire caused by this damage on 10/15/2024?

No

Was there an evacuation of any nearby homes or businesses caused by this damage on 10/15/2024?

No

Provide an estimate of the number of your customers whose service was interrupted by this damage on 10/15/2024.

1

Conclusions

What date and time were repairs completed to the damaged facility?

October 15, 2024 11:30 AM

Please explain why you think the facility was damaged on 10/15/2024?
Contractors hit the gas line and gas was released

Is there any other information which you feel is important to share about this incident?

Not counting your answers to these questions, did San Diego Gas and Electric create an investigatory or incident report pertaining to the damage on 10/15/2024?

Yes

Please attach investigatory or incident report here.

Have your answers to these questions and or the documents you are sending today been reviewed, changed or amended by anyone?

No

Files

Please attach all Facility Repair Orders.

Please attach all Photos.



Date and time photographed

Photographer Name

`\${Reporter\_Name}` `\${Reporter\_Name2}`



Date and time photographed

Photographer Name

\${Reporter_Name} \${Reporter_Name2}

Additional Records

Reference Number

N242910076

Exhibit 2

No-Ticket Damage Reporting Form

Submitted Time: January 7, 2025 8:02 PM

Provide your name, title, phone number, and email address

Name

David

Title

Owner

Phone Number

858-922-6333

Email Address

davidohdnd@yahoo.com

Please provide the identifying information for Insight Landscaping in general.

California Contractor's State License Board (CSLB) license

674721

Physical Address

4783 Marblehead Bay Dr. Oceanside CA 92057

Mailing Address

4783 Marblehead Bay Dr. Oceanside CA 92057

Phone Number

858-922-6333

Email Address

davidohdnd@yahoo.com

Did Insight Landscaping damage the NaturalGas facility while excavating at 2055 Cambridge Ave, Cardiff By the Sea on the 10/15/2024? (Select One)

Yes

Were there any other companies at or near 2055 Cambridge Ave, Cardiff By the Sea on 10/15/2024? (Select One)

No

Did someone in Insight Landscaping, or anyone else, contact the Regional Notification Center on 10/15/2024?

No

Did San Diego Gas and Electric respond after the Regional Notification Center created the 811 ticket?

Is Insight Landscaping aware that it needed to contact the Regional Notification Center prior to excavating?

No

Did the Regional Notification Center create an 811-ticket for 2055 Cambridge Ave, Cardiff By the Sea that Insight Landscaping worked?

No

If no one at Insight Landscaping, or anyone else, contacted the Regional Notification Center before excavating, why not?

Other

Explain why Insight Landscaping did not obtain an 811 ticket?
never thought of hitting gas pipe while working around the tree.

Has Insight Landscaping ever obtained an 811 ticket, either by calling 811 or using the Regional Notification Center's website?

Yes

The damage notification indicated that a facility was damaged at 2055 Cambridge Ave, Cardiff By the Sea on 10/15/2024. Is that correct?

Yes

Was Insight Landscaping the prime contractor on the project at 2055 Cambridge Ave, Cardiff By the Sea on 10/15/2024?

Yes

What was mentioned or what direction did the prime contractor provide to you?

Provide the names, phone numbers, and if applicable, their email address for all your personnel who were at 2055 Cambridge Ave, Cardiff By the Sea when the facility was damaged.

Name

Roman Ramos

Title

helper

Phone Number

858-343-0021

Email Address

davidohdnd@yahoo.com

Add an additional individual?

No

Which one of the individuals you identified was the foreman on the project when the facility was damaged?

no foreman

Facility Damage

Was a facility damaged on 10/15/2024?

Yes

Describe the damaged facility.

copper pipe(1/2 inch) was hit accidentally by shovel that caused gas leak

Identify the type of material damaged.

copper pipe (1/2) inch

Explain how the facility was damaged?

the gas pipe was cut by shovel while digging tree roots.

What equipment did Insight Landscaping use on 10/15/2024? (Select All That Are Applicable)

Shovel

What type of equipment damaged the facility?

Shovel

Who was operating the equipment that damaged the facility on 10/15/2024?

No equipment used.

Does Insight Landscaping own that equipment?

Yes

Emergency Response

How did Insight Landscaping learn that the San Diego Gas and Electric facility was damaged on 10/15/2024?

gas leaked after the pipe got hit

Did anyone with Insight Landscaping call 911 on 10/15/2024 after the damage had occurred?

Yes

Was there an emergency response to the incident from the fire department, a law enforcement department, or an ambulance on 10/15/2024?

Yes

Were there any injuries to any personnel or bystanders on 10/15/2024?

No

Were there any fatalities on 10/15/2024 or afterwards, due to the damage at 2055 Cambridge Ave, Cardiff By the Sea?

No

Was there property damage on 10/15/2024, excluding the facility damage?

No

Was there a fire on 10/15/2024 as a result of the damage to the facility?

No

Was there an evacuation of any homes or businesses on 10/15/2024 as a result of the damage to the facility?

No

Are you aware of anyone else that called 911?

No

Did anyone at Insight Landscaping contact the Regional Notification Center after the damage on 10/15/2024?

No

Did anyone at Insight Landscaping contact San Diego Gas and Electric after the damage?

No

What steps, if any, have Insight Landscaping taken to prevent a similar damage in the future?
call 811 before digging.

Is there any other information you want to share about this damage?

no

Exhibit 3



▼ Contractor's License Detail for License # 674721

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law () If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed ().
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Data current as of 11/8/2024 9:24:10 AM

Business Information

DAVID OH
DBA INSIGHT LANDSCAPING

4783 MARBLEHEAD BAY DR
OCEANSIDE, CA 92057
Business Phone Number:(858) 922-6333

Entity Sole Ownership
Issue Date 07/23/1993
Expire Date 07/31/2025

License Status

This license is current and active.

All information below should be reviewed.

Classifications

- ▶ C27 - LANDSCAPING
- ▶ C-61 / D06 - CONCRETE RELATED SERVICES
- ▶ A - GENERAL ENGINEERING
- ▶ B - GENERAL BUILDING

Bonding Information

Contractor's Bond

This license filed a Contractor's Bond with [BUSINESS ALLIANCE INSURANCE COMPANY](#).

Bond Number: G90107501604

Bond Amount: \$25,000

Effective Date: 01/01/2023

[Contractor's Bond History](#)

Workers' Compensation

This license has workers compensation insurance with the [ENDURANCE ASSURANCE CORPORATION](#)

Policy Number:EAW000020090

Effective Date: 08/06/2024

Expire Date: 08/06/2025

[Workers' Compensation History](#)

- ▶ Personnel listed on this license (current or disassociated) are listed on other licenses.

[Back to Top](#)

[Privacy Policy](#)

[Accessibility Certification](#)

[Conditions of Use](#)

[Accessibility](#)

Exhibit 4

Alkhwaji, Ousama@EnergySafety.ca.gov

From: Alkhwaji, Ousama@EnergySafety.ca.gov
Sent: Thursday, November 7, 2024 10:19 AM
To: Amber Dahl
Cc: Alcantar, Daysi@EnergySafety
Subject: 811 Ticket Request for N242910076

Hi Amber,

Please provide a copy of all tickets, revisions, and electronic positive responses at about 2055 Cambridge Ave, Cardiff-by-the-Sea, CA 92007 for September 03, 2024, to October 15, 2024.

If there is not a ticket at this address for this date, confirm that finding.

Thanks,

Ousama Alkhwaji

Investigator
Underground Infrastructure Directorate
Phone: (279) 245-1157

www.energysafety.ca.gov



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Stay connected and informed by signing up for the [Underground Safety Board's subscriber list](#).

Exhibit 5

Alkhwaji, Ousama@EnergySafety.ca.gov

From: Amber Dahl <amber@digalert.org>
Sent: Thursday, November 7, 2024 12:18 PM
To: Alkhwaji, Ousama@EnergySafety.ca.gov
Cc: Alcantar, Daysi@EnergySafety
Subject: File N242910076
Attachments: N242910076.pdf

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you,



Amber Dahl, Safety Director
Underground Service Alert of Southern California
PO BOX 77070 Corona, CA 92877
P: 951-808-8115 F: 951-808-8101
E: amber@digalert.org W: www.digalert.org



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.



Underground Service Alert

of Southern California™

November 7, 2024

Ousama Alkahwaji
Underground Safety Board

File Number: N242910076

Dear Ousama,

After searching our records from 9/3/24 through 10/15/24, we found the following DigAlert ticket(s) A242890769 for the location at or near 2055 Cambridge Ave in Cardiff-by-the-Sea. I hope this information will be helpful.

If we can be of further assistance, please call us at 951-808-8100.

Sincerely,

Amber Dahl
Safety Awareness Director

MBRCOD 00001B USAS 11/07/24 11:40:59 A242890769-00A NEW RUSH POLY LREQ

Ticket: A242890769 Rev: 00A Created: 10/15/24 10:33 User: RIC Chan: 100

Work Start: 10/15/24 10:16 Legal Start: 10/17/24 17:01 Expires: 11/12/24 23:59

Response required: Y Priority: 0

Excavator Information

Company: INSIGHT LANDSCAPING Type: CONT
Co Addr: 4783 MARBLEHEAD BAY DR
City : OCEANSIDE State: CA Zip: 92057
Created By: H/O PARIKH, PURVEE Language: ENGLISH
Office Phone: 619-929-6310 SMS/Cell: 619-929-6310
Office Email: PURVEE1211@YAHOO.COM

Site Contact: DAVID OH

Site Phone: 858-922-6333

Site SMS/Cell: 858-922-6333

Site Email:

Excavation Area

State: CA County: SAN DIEGO Place: CARDIFF-BY-THE-SEA

Zip: 92007

Address : 2055 Street: CAMBRIDGE AVE

Cross 1 : LIVERPOOL DR

Cross 2 :

Location: **FRONT OF ADDRESS** **WORK HAS ALREADY STARTED** **ALSO SPOKE WITH
: DAVID OH** **AREA WILL BE DELINEATED BY 10/15/24 BY 11:30AM**

Searchable Tags:

Job size: sq-feet: 38175 sq-miles: 0.001369

Delineated Method: NONE

Work Type: PLANT (1) TREE

Work For : H/O PARIKH, PURVEE

Permit: Job/Work order:

Project ID:

Project Name:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N Pavement Only: N

Lat/Long

Center Generated (NAD83): 33.023775/-117.279221 33.024136/-117.278512

: 33.023327/-117.278993 33.023688/-117.278284

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=77CoDpIhGfMZKUT-K

Members:

ATTDSOUTH COX04 ENC01 SDG01 SDW01 UBIQUITY

(c) Copyright 2022 Underground Service Alert of Southern California.
All rights reserved.

**Ticket Responses for: A242890769-
00A**

Member Name Rev Responded By Response

MBRCOD 00001B USAS 11/07/24 11:41:01 A242890769-01A DMGE EMER POLY LREQ

Ticket: A242890769 Rev: 01A Created: 10/15/24 10:36 User: RIC Chan: 100

Work Start: 10/15/24 10:34 Legal Start: 10/17/24 17:01 Expires: 11/12/24 23:59
Response required: N Priority: 9

Excavator Information

Company: INSIGHT LANDSCAPING Type: CONT
Co Addr: 4783 MARBLEHEAD BAY DR
City : OCEANSIDE State: CA Zip: 92057
Created By: H/O PARIKH, PURVEE Language: ENGLISH
Office Phone: 619-929-6310 SMS/Cell: 619-929-6310
Office Email: PURVEE1211@YAHOO.COM

Site Contact: DAVID OH
Site Phone: 858-922-6333 Site SMS/Cell: 858-922-6333
Site Email:

Excavation Area

State: CA County: SAN DIEGO Place: CARDIFF-BY-THE-SEA
Zip: 92007
Address : 2055 Street: CAMBRIDGE AVE
Cross 1 : LIVERPOOL DR
Cross 2 :
Location: **FRONT OF ADDRESS** **WORK HAS ALREADY STARTED** **ALSO SPOKE WITH
: DAVID OH** **AREA WILL BE DELINEATED BY 10/15/24 BY 11:30AM**
Searchable Tags:
Job size: sq-feet: 38175 sq-miles: 0.001369

Delineated Method: NONE

Work Type: PLANT (1) TREE

Work For : H/O PARIKH, PURVEE

Permit: Job/Work order:

Project ID:

Project Name:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N Pavement Only: N

Lat/Long

Center Generated (NAD83): 33.023774/-117.279221 33.024136/-117.278511
: 33.023327/-117.278993 33.023689/-117.278283

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=679rAoFo3w7sxs3-k

Comments:

****DAMAGE****A DAMAGED LINE FOR GAS - DAMAGED PLASTIC GAS LINE. LEAKING GAS IN FRONT OF ADDRESS. PER PURVEE PARIKH--[RIC 10/15/2024 10:34:57 AM]

Members:

ATTDSOUTH COX04 ENC01 SDG01 SDW01 UBIQUITY

(c) Copyright 2022 Underground Service Alert of Southern California.
All rights reserved.


Ticket Responses for: A242890769-01A

Member	Name	Rev	Responded	By	Response	Comment
ATTDSOUTH	AT&T - DISTRIBUTION	01A	10/15/24 10:58:12 AM	UQ Responder (001)	CLEAR - NO CONFLICT	
COX04	COX COMMUNICATIONS - NO SD	01A	10/15/24 11:00:30 AM	Urbint- UtiliQues	(001) CLEAR - NO CONFLICT	
ENC01	CITY OF ENCINITAS	01A	10/16/24 02:25:30 PM	Charlie	(001) CLEAR - NO CONFLICT	No conflict for SL.
SDG01	SDG&E GAS DISTRIBUTION AND ELECTRIC	01A	10/15/24 11:23:03 AM	PRSDG01 JBUTLER1	(010) LOCATE AREA MARKED	
SDW01	SAN DIEGUITO WTR DIST	01A	10/15/24 11:49:49 AM	Ryan Stone	(002) CLEAR - NO CONFLICT BUT PRIVATELY OWNED UTILITY ON PROPERTY - CONTACT PRIVATE UTILITY OWNER FOR LOCATE	
UBIQUITY	UBIQUITY	01A	10/15/24 11:33:49 AM	DENNIS BAUMAN	(001) CLEAR - NO CONFLICT	

Exhibit 6

From: Encinitas Public Records Center <encinitasca@mycusthelp.net>
Sent: Sunday, February 16, 2025 04:09 PM
To: Alkahlwaji, Ousama@EnergySafety.ca.gov
Subject: Public Records Request :: W006529-021625

CAUTION: This email originated from outside of the organization. Do not click links



Dear Ousama

This is confirmation that your Records Request has been received and is being processed.

Your request was received by the City Clerk's Department on 2/16/2025. Record Requested: Dear Custodian of Records, This letter is a request for a copy of all police/fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA 92007, on 10/15/2024. If no records exist, please confirm that finding. We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19. If any fees are accrued per our request, please advise and we will address accordingly. Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned.

The City Clerk's Department will be contacting you with a prepared response.

If you have any questions, please contact the City Clerk's Department via return email or by phone at 760-633-2601.

Track the issue status and respond at:

https://encinitasca.mycusthelp.com/WEBAPP/_rs/RequestEdit.aspx?rid=6529

Public Records Menu

- [Home](#)
- [FAQs](#)
- [Submit a Request](#)
- [My Request Center](#)

FAQs

[See All FAQs](#)

[Recorded Documents](#)

[Property Tax Information](#)

[Fictitious Business Name](#)

[Marriage Licenses](#)

[Death Certificates](#)

[View File\(s\)](#)

[View Message\(s\)](#)

Request Type:

Public Records Request

Description:

A public record is any record relating to the conduct of the City's business, and which is prepared or retained by the City. The record may be in a variety of forms such as writing, a recording, a picture, electronic data, etc.

Contact E-Mail:

Ousama.Alkawahji@energysafety.ca.gov

Reference No:

W006529-021625

Status:

Closed

UPLOAD DATE



DOWNLOAD ALL

Files:

02/21/2025 W006529-021625.pdf

02/21/2025 W006529-021625_CadReport.pdf

Correspondents should be aware that all communications to and from this address are subject to public disclosure and may be reviewed by third parties.

Request Information:

From:

10/15/2024

Date Range of Records:

To:

10/15/2024

Receive Records:

Electronic via Records Center

Type of Record(s) Requested:

Fire Incident Reports

Describe the Record(s) Requested:

Dear Custodian of Records, This letter is a request for a copy of all police/fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA 92007, on 10/15/2024. If no records exist, please confirm that finding. We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19. If any fees are accrued per our request, please advise and we will address accordingly. Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned.

Please note not all public documents are available in electronic format. If the document(s) requested are not available electronically, we will make them available for inspection or by paper copy in accordance with the Public Records Law.

Cancel

Messages 3

 Print Messages (PDF)

✓ On 2/21/2025 9:41:00 AM, Encinitas Public Records Center wrote:

Subject: Public Records Request :: W006529-021625

Body:

02/21/2025

Ousama Alkahwaji
715 P Street, 20th Floor
Sacramento CA 95814

RE: PUBLIC RECORDS REQUEST of 2/16/2025,
Reference # W006529-021625

Dear Ousama,

The City received a public information request from you on 2/16/2025.

Your request mentioned "Dear Custodian of Records,

This letter is a request for a copy of all police/fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA

We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19.

If any fees are accrued per our request, please advise and we will address accordingly. Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned."

The City has reviewed its files and has located responsive records to your request.

Hello, the city contracts with the Sheriff's department for law enforcement. Any records would need to be requested from the San Diego County Sheriff's Department
<https://www.sdsheriff.gov/i-want-to/request>

for 911 audio recordings please contact North County Dispatch Joint Powers Authority
<https://ncdjpa.org/contact-ncdjpa/online-request-form/>

Sincerely,

Pete Weichers
Deputy City Clerk

✓ On 2/16/2025 4:08:19 PM, Encinitas Public Records Center wrote:

 [View Image](#)

Dear Ousama

This is confirmation that your Records Request has been received and is being processed.

Your request was received by the City Clerk's Department on 2/16/2025. Record Requested:
Dear Custodian of Records,

This letter is a request for a copy of all police/fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA 92007, on 10/15/2024. If no records exist, please confirm that finding.

We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19.

If any fees are accrued per our request, please advise and we will address accordingly. Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned

The City Clerk's Department will be contacting you with a prepared response.

If you have any questions, please contact the City Clerk's Department via return email or by phone at 760-633-2601.

Track the issue status and respond at:

https://encinitasca.mycusthelp.com/WEBAPP/_rs/RequestEdit.aspx?rid=6529

▼ ☒ On 2/16/2025 4:08:19 PM, Ousama Alkahwaji wrote:

Request Created on Public Portal

Exhibit 7

Alkahlwaji, Ousama@EnergySafety.ca.gov

From: Encinitas Public Records Center <encinitasca@mycusthelp.net>
Sent: Friday, February 21, 2025 09:41 AM
To: Alkahlwaji, Ousama@EnergySafety.ca.gov
Subject: Public Records Request :: W006529-021625

CAUTION: This email originated from outside of the organization. Do not click links

Attachments:

[W006529-021625.pdf](#)

[W006529-021625_CadReport.pdf](#)

--- Please respond above this line ---



02/21/2025

Ousama Alkahlwaji
715 P Street, 20th Floor
Sacramento CA 95814

RE: PUBLIC RECORDS REQUEST of 2/16/2025,
Reference # W006529-021625

Dear Ousama,

The City received a public information request from you on 2/16/2025.

Your request mentioned "Dear Custodian of Records,

This letter is a request for a copy of all police/fire dispatch call logs, 911 audio recordings and any incident reports from responding emergency personnel surrounding the landscaping, due to a gas leak, located at 2055 Cambridge Avenue, Cardiff-by-the-Sea, CA 92007, on 10/15/2024. If no records exist, please confirm that finding.

We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19.

If any fees are accrued per our request, please advise and we will address accordingly. Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned.”

The City has reviewed its files and has located responsive records to your request.

Hello, the city contracts with the Sheriff's department for law enforcement. Any records would need to be requested from the San Diego County Sheriff's Department <https://www.sdsheriff.gov/i-want-to/request>

for 911 audio recordings please contact North County Dispatch Joint Powers Authority <https://ncdjpa.org/contact-ncdjpa/online-request-form/>

Sincerely,

Pete Weichers
Deputy City Clerk

Encinitas (ENC)

FDID: 37065

State: CA

Date: 10/15/2024 Station: 02

Incident #: 2024-099532

Exposure: 0

Agency Address:

BASIC MODULE (NFIRS-1)

Location Type: 1 - Street address

Census Tract:

Address: 2055 Cambridge AVE - Avenue

City, State & Zip ENCINITAS, CA - California 92007

Incident Type: 412-412 - Gas leak (natural gas or LPG)

Aid Given/Received: N - None

Dates and Times

Alarm: 10/15/2024 09:38

Arrival: 10/15/2024 09:42

Controlled:

Last Unit Cleared: 10/15/2024 10:19

Shifts And Alarms

Shift: C

Alarms: 0

District: ENC

Special Studies

Special Study ID Value

Actions Taken: 64 - Shut down system (64); 65 - Secure property (65); 86 - Investigate (86)

Resources**Apparatus****Personnel**

Suppression: 5

EMS: 1

Other: 1

Suppression: 15

EMS: 2

Other: 1

Casualties

Fire Service Deaths: 0

Fire Service Injuries: 0

Civilian Deaths: 0

Civilian Injuries: 0

Detector alerted:

Mixed Use Property: NN - Not mixed use

HazMat Release: N - None

Property Use: 419 - 419 - 1 or 2 family dwelling

Narrative

Primary Jurisdiction: ENCINITAS FD; CAD Incident Number: 2024-099532; CAD Problem/Nature: NAT GAS LN BRK - OUTSIDE; Call Disposition: .AOR ONLY

At 0938 hours on Tuesday October 15, 2024, 7 vehicles were assigned to this incident. 16 personnel responded. The incident occurred at 2055 Cambridge Av, ENCINITAS. The local station is 02.

Alarm number 4099532 has been assigned to this incident.

E232 arrived on scene at the listed address to residential multi-family home to find a natural gas leak located in the front yard in a ditch that had been dug previously by a construction crew (per homeowner). The leak had been duck tapped by crew PTA which slowed the leak.

E232 established Cambridge IC and requested 1 additional unit to assist with gas monitoring. SDGE was enroute PTA and arrived shortly after our arrival. They assisted with gas monitoring and it was determined that there was no need to shelter the surrounding neighbors due to the minimal leak.

B233 arrived on scene. E231 assisted with gas monitoring and was cancelled shortly after. All other units were cancelled and E232 remained on scene until the leak was controlled by SDGE. E232 went AOS without further. {END}

Remarks

E232 arrived on scene at the listed address to residential multi-family home to find a natural gas leak located in the front yard in a ditch that had been dug previously by a construction crew (per homeowner). The leak had been duck tapped by crew PTA which slowed the leak.

E232 established Cambridge IC and requested 1 additional unit to assist with gas monitoring. SDGE was enroute PTA and arrived shortly after our arrival. They assisted with gas monitoring and it was determined that there was no need to shelter the surrounding neighbors due to the minimal leak.

B233 arrived on scene. E231 assisted with gas monitoring and was cancelled shortly after. All other units were cancelled and E232 remained on scene until the leak was controlled by SDGE. E232 went AOS without further. {END}

APPARATUS OR RESOURCES / PERSONNEL MODULES (NFIRS-9/10)

ID: B233 Type: 92 - Chief officer car

Use: 0 - 0 - Other

Number of People: 1

Dispatch Time: 10/15/2024 09:38

Arrival Time: 10/15/2024 09:44

Clear Time: 10/15/2024 10:00

Remarks:

Personnel ID: ENC009515

Rank / Grade: BC

Encinitas (ENC)

FDID: 37065

State: CA

Date: 10/15/2024 Station: 02

Incident #: 2024-099532

Exposure: 0

Agency Address:

ID: E231 Type: 11 - Engine

Use: 1 - 1 - Suppression

Number of People: 3

Dispatch Time: 10/15/2024 09:38

Arrival Time: 10/15/2024 09:45

Clear Time: 10/15/2024 09:59

Remarks:

Personnel ID: 8061

Rank / Grade: Captain

Personnel ID: 9977

Rank / Grade: Engineer

Personnel ID: ENC101269

Rank / Grade: FF/PM

ID: E232 Type: 11 - Engine

Use: 1 - 1 - Suppression

Number of People: 3

Dispatch Time: 10/15/2024 09:38

Arrival Time: 10/15/2024 09:43

Clear Time: 10/15/2024 10:19

Remarks:

Personnel ID: 199

Rank / Grade: Captain

Personnel ID: 4329

Rank / Grade: Captain

Personnel ID: ENC101302

Rank / Grade: FF - Firefighter

ID: E233 Type: 11 - Engine

Use: 1 - 1 - Suppression

Number of People: 3

Actions taken: Cancelled en route (93)

Dispatch Time: 10/15/2024 09:38

Arrival Time:

Clear Time: 10/15/2024 09:46

Remarks:

Personnel ID: 100796

Rank / Grade: Captain

Personnel ID: 8703

Rank / Grade: Engineer

Personnel ID: ENC101389

Rank / Grade: FF/PM

ID: E235 Type: 11 - Engine

Use: 1 - 1 - Suppression

Number of People: 3

Dispatch Time: 10/15/2024 09:38

Arrival Time: 10/15/2024 09:46

Clear Time: 10/15/2024 10:19

Remarks:

Personnel ID: 100719

Rank / Grade: FF/PM

Personnel ID: ENC0H8349

Rank / Grade: Captain

Personnel ID: ENC100635

Rank / Grade: Engineer

Encinitas (ENC)

FDID: 37065 State: CA Date: 10/15/2024 Station: 02 Incident #: 2024-099532 Exposure: 0
Agency Address:

ID: M232 Type: 76 - 76 - ALS unit

Use: 2 - 2 - EMS Number of People: 2
Dispatch Time: 10/15/2024 09:38 Arrival Time: 10/15/2024 09:42 Clear Time: 10/15/2024 09:59
Remarks:

Personnel ID: CSA000680

Personnel ID: CSA06922

ID: T237 Type: 12 - Truck or aerial

Use: 1 - 1 - Suppression Number of People: 3
Dispatch Time: 10/15/2024 09:38 Arrival Time: 10/15/2024 09:46 Clear Time: 10/15/2024 09:47
Remarks:

Personnel ID: 3425

Rank / Grade: Captain

Personnel ID: 6454

Rank / Grade: Engineer

Personnel ID: SOL00773

Rank / Grade: FF - Firefighter

SIGNATURES / AUTHORIZATIONS

Date/Time: 10/16/2024 06:52 Signed By: Christopher Sayer

Rank: Captain Assignment:

Reason: Member making report

CAD Report
2024-099532

Unit Call Sign:	B233	Response #:	10152024-0011872	Provider:	Service Level:
Assigned:	10/15/2024 09:38	Staged:		En route:	10/15/2024 09:39
Arrived scene:	10/15/2024 09:44	Back @ Home:		Call Disposition:	
Cancel Type:		Cancel Reason:			
Personnel:	WILLIAMS, ROBERT L(ENC009515)				

Comments		
Date	By	Comment
10/15/2024 09:38	RJK	[1] SDGE ER WITH 20 MIN ETA
10/15/2024 09:43	JKB	[2] E232- OS MED SIZE 2 STORY RES DUPLEX NSI EST CAMBRIDGE IC ALL UNITS STAGE 1 BLOCK OUT
10/15/2024 09:47	JKB	[3] IC- UPDATED ADDRESS 2053 CAMBRIDGE, CAN HANDLE W ONE ADDL ENG AND CHIEF
10/15/2024 09:56	JKB	[4] IC- SDGE OS CXL IC E232 POC