



**CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION**

INVESTIGATION REPORT

Date: April 2, 2026

Case No.: N250141025

Violations:

Sunshine Communications, Inc.

Government Code § 4216.2(b): Excavating without first notifying the regional notification center of intent to excavate.

Executive Summary:

On January 13, 2025, Sunshine Communications, Inc. dug without first contacting the regional notification center and damaged a ½" plastic natural gas facility with a shovel while repairing a conduit. No one was injured and no equipment, other than the ½" plastic natural gas facility, was damaged.

Reporting Party Information:

San Diego Gas and Electric
1919 South State College Drive
Anaheim, California 92806

Date of Incident:

January 13, 2025

Location of the Incident:

653 Via La Cuesta
Chula Vista, California 91913

Operator:

San Diego Gas and Electric
Regional Notification Member Code SDG01
735 33rd Street
San Diego, California 92100

Excavator:

Sunshine Communications, Inc.
350 Cypress Lane, Suite D

El Cajon, California 92020

Facility Type Damaged:

½" Plastic natural gas facility

Investigation:

Notification of the Incident

On January 14, 2025, at 10:53 a.m., San Diego Gas and Electric (SDG&E) submitted a notification of an incident to the California Underground Safety Board. The notification stated, "Workers hit gas line with hand tool while excavating to repair conduit." (Exh. 1.)

The case was assigned to Investigator Angel Barton (Investigator).

Excavation and Identity of the Excavator

Government Code section 4216(g) defines "excavation" to be the use of tools or equipment to move or displace earth, rock, or other material in the ground.

Government Code section 4216(h) defines an excavator to be "any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with their own employees or equipment, performs any excavation."

Sunshine Communications, Inc. was digging with a shovel and damaged a ½" plastic natural gas facility at 653 Via La Cuesta, Chula Vista, California 91913. (Exh. 2.)

Sunshine Communications, Inc. is licensed by the Contractors State License Board, license number 770746 with C-7 – Low Voltage Systems and A – General Engineering classifications. (Exh. 3.)

Sunshine Communications, Inc. Did Not Contact the regional notification center Before Digging

Government Code section 4216.2(b) states that an excavator planning to excavate shall notify the appropriate regional notification center of the excavator's intent to excavate at least two working days, and not more than 14 calendar days, before beginning that excavation.

Sunshine Communications, Inc. did not notify the regional notification center prior to digging with a shovel. Scot Ludwig, Supervisor for Sunshine Communications, Inc., stated that it did not contact the regional notification center because Sunshine Communications, Inc. was "following the existing conduits and under normal circumstances other utilities are buried deeper or further away" from the conduits. (Exh. 2.)

On February 26, 2025, investigator emailed Safety Director at DigAlert, Amber Dahl, requesting ticket information for 653 Via La Cuesta, Chula Vista, California 91913, between December 13, 2024, to January 25, 2025. (Exh. 4.)

Safety Director at DigAlert, Amber Dahl, responded on February 26, 2025, with ticket information for ticket number B250150356 at 653 Via La Cuesta, Chula Vista, California 91913. (Exh. 5.)

Sunshine Communications, Inc. contacted the regional notification after the damage occurred. The regional notification center created ticket number B250150356 for Sunshine Communications, Inc. on January 15, 2025. . (Exh. 5.)

Sunshine Communications, Inc. Called 911 Emergency Services Upon Gas Release

Government Code section 4216.4(c)(1) states an excavator shall call 911 emergency services upon discovering or causing damage to a gas or hazardous liquid pipeline subsurface installation in which the damage results in the escape of any flammable, toxic, or corrosive gas or liquid.

On January 13, 2025, while digging with a shovel, Sunshine Communications, Inc. called 911 after damaging a ½" plastic natural gas facility and hearing hissing sounds. (Exh. 2.) The City of Chula Vista Fire Department responded to the 911 call for the gas leak with multiple engines. (Exh. 6).

Findings:

1. Sunshine Communications, Inc. excavated without first notifying the regional notification center on January 13, 2025, at 653 Via La Cuesta, Chula Vista, California 91913, because Sunshine Communications, Inc. stated it “following the existing conduits and under normal circumstances other utilities are buried deeper or further away” from the conduits.
2. Sunshine Communications, Inc. called 911 after damaging a ½" plastic natural gas facility.
3. After the damage occurred, ticket number B250150356 for Sunshine Communications, Inc. was created on January 15, 2025.

Investigator	Supervisor
Angel Barton	Anona Bonner
Signature	Signature
/s/ Angel Barton	/s/ Anona Bonner

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 1/14/2025, at 10:53 a.m.	Gas Construction Manager, San Diego Gas and Electric, Mark Engel
2.	Board's investigation questionnaire response by Sunshine Communications, Inc.	Received on 3/11/2025	Supervisor at Sunshine Communications, Inc., Scott Ludwig
3.	Contractor's License Detail for License No. 770746 obtained from the Contractors State License Board's website	Downloaded on 2/28/2025	Contractors State License Board's website at https://www.cslb.ca.gov/onlineservices/checklicensell/checklicense.aspx
4.	Investigator's email to DigAlert requesting ticket information on the underlying job to this incident	Emailed on 2/26/2025	
5.	Email from DigAlert providing ticket information for the underlying job to this incident	Received on 2/26/2025	Safety Director at DigAlert, Amber Dahl
6.	Email from Chula Vista Fire Department responding to the public records request	Received on 4/3/2025	Chula Vista Fire Department

Exhibit 1

No-Ticket Damage Reporting Form

Submitted: January 14, 2025 10:53 AM

Reporter Information

Provide the names, titles, phone numbers, and email addresses of all individuals who are involved in reporting this damage or contributing to the answers to these questions

Full Name

Mark Engel

Title

Gas Construction Manager

Phone Number

442-232-7720

E-mail address

mengel@sdge.com

Company

Provide the name, address, phone number, email address, and, if applicable, the Regional Notification Center (member code for your company).

Company Name

San Diego Gas and Electric

Address

517 Enterprise St, Escondido , 92029

Phone Number

442-232-7720

Email Address

mengel@sdge.com

Regional Notification Center member code

Other Contacts

Is the photographer same as the primary reporter named above?

Incident Information

What was the date and approximate time of the incident?

January 13, 2025 12:10 PM

What is the address where your facility was damaged on 1/13/2025?

Damage Street Address

653 Via La Cuesta

Damage County

San Diego

Damage City
Chula Vista

Damage Cross Street 1
Via Hacienda

Damage Cross Street 2

Other Damage location description

Does San Diego Gas and Electric own, operate or maintain the facility damaged on 1/13/2025?

Yes

What type of excavation did you observe on 1/13/2025 at that address?

Communications

Describe the excavation activity you identified.

Gas line damaged with hand tool

What excavation companies did you observe on 1/13/2025?

Company Name

Sunshine Communications Inc

Company Address

350 Cypress Ln, El Cajon , 92021

Phone Number

619-218-4841

Email Address

PETER.ZAMORA@SUNSHINECOM.COM

Did this company damage the facility?

Yes

Provide the name, title, phone number, and email address for at least one contact for each excavation company working at or near incident address on date of incident. If you have more than one contact, please provide all of them. Email addresses are required for submission of this form.

Personnel Name

Scott Ludwig

Title

Foreman

Phone Number

619-218-4841

Email Address

PETER.ZAMORA@SUNSHINECOM.COM

Notification Details

Was San Diego Gas and Electric notified of the proposed excavation by the Regional Notification Center before 1/13/2025?

No

What date and time did you learn of the damage to the facility?

January 13, 2025 12:10 PM

How did San Diego Gas and Electric learn of the damage to the facility?

Dispatch

Facility Damaged

What kind of facility was damaged on 1/13/2025?

Natural Gas

Natural Gas

What type of material was the damaged facility?

Plastic

Facility diameter (inches)?

0.5

Incident Details

What kinds of excavation equipment did you observe at the location of the damaged facility?

Other hand tools

Do you know what equipment damaged the facility?

Yes

What equipment damaged the facility?

Other hand tools

What information are you relying on regarding damage to the facility?

Interview with excavator

Did San Diego Gas and Electric contact the Regional Notification Center before repairing the damaged facility?

No

Provide any other relevant information about the damage on 1/13/2025.

Workers hit gas line with hand tool while excavating to repair conduit.

Damages

Were there any injuries to any personnel or bystanders due to the damage to your facility on 1/13/2025?

No

Was any property damaged other than the damaged facility?

No

Was there a fire caused by this damage on 1/13/2025?

No

Was there an evacuation of any nearby homes or businesses caused by this damage on 1/13/2025?

No

Provide an estimate of the number of your customers whose service was interrupted by this damage on 1/13/2025.

2

Conclusions

What date and time were repairs completed to the damaged facility?

January 13, 2025 4:36 PM

Please explain why you think the facility was damaged on 1/13/2025?
Workers hit gas line with hand tool while excavating to repair conduit.

Is there any other information which you feel is important to share about this incident?

Not counting your answers to these questions, did San Diego Gas and Electric create an investigatory or incident report pertaining to the damage on 1/13/2025?
No

Have your answers to these questions and or the documents you are sending today been reviewed, changed or amended by anyone?
No

Files

Please attach all Facility Repair Orders.

Please attach all Photos.



Date and time photographed

January 13, 2025 8:10 PM

Photographer Name

`\${Reporter\_Name}` `\${Reporter\_Name2}`

Additional Records

Reference Number

N250141025

Exhibit 2

No-Ticket Damage Reporting Form

Submitted Time: March 11, 2025 8:34 PM

Provide your name, title, phone number, and email address

Name

Scott

Title

Supervisor

Phone Number

619-218-4841

Email Address

scott.ludwig@sunshinecom.com

Please provide the identifying information for Sunshine Communications Inc in general.

California Contractor's State License Board (CSLB) license

770746

Physical Address

350 Cypress Lane Suite D, El Cajon, Ca 92020

Mailing Address

350 Cypress Lane Suite D, El Cajon, Ca 92020

Phone Number

619-448-7600

Email Address

scott.ludwig@sunshinecom.com

Did Sunshine Communications Inc damage the NaturalGas facility while excavating at 653 Via La Cuesta, Chula Vista on the 1/13/2025? (Select One)

Yes

Were there any other companies at or near 653 Via La Cuesta, Chula Vista on 1/13/2025? (Select One)

No

Did someone in Sunshine Communications Inc, or anyone else, contact the Regional Notification Center on 1/13/2025?

No

Did San Diego Gas and Electric respond after the Regional Notification Center created the 811 ticket?

Is Sunshine Communications Inc aware that it needed to contact the Regional Notification Center prior to excavating?

Yes

Did the Regional Notification Center create an 811-ticket for 653 Via La Cuesta, Chula Vista that Sunshine Communications Inc worked?

Yes

If no one at Sunshine Communications Inc, or anyone else, contacted the Regional Notification Center before excavating, why not?

Other

Explain why Sunshine Communications Inc did not obtain an 811 ticket?

We were following the existing conduits and under normal circumstances other utilities are buried deeper or further away from Cox conduits.

Has Sunshine Communications Inc ever obtained an 811 ticket, either by calling 811 or using the Regional Notification Center's website?

Yes

The damage notification indicated that a facility was damaged at 653 Via La Cuesta, Chula Vista on 1/13/2025. Is that correct?

Yes

Was Sunshine Communications Inc the prime contractor on the project at 653 Via La Cuesta, Chula Vista on 1/13/2025?

Yes

What was mentioned or what direction did the prime contractor provide to you?

Provide the names, phone numbers, and if applicable, their email address for all your personnel who were at 653 Via La Cuesta, Chula Vista when the facility was damaged.

Name

Jesus Rodriguez

Title

Lead

Phone Number

619-734-8844

Email Address

jesus.rodriguez@sunshinotech.net

Add an additional individual?

Yes

Name

Leo Meza

Title

Lead

Phone Number

619-757-4781

Email Address

leonel.mezaespitia@sunshinotech.net

Add an additional individual?

No

Which one of the individuals you identified was the foreman on the project when the facility was damaged?

Neither both are leads

Facility Damage

Was a facility damaged on 1/13/2025?

Yes

Describe the damaged facility.

Gas

Identify the type of material damaged.

Pex

Explain how the facility was damaged?

It was wrapped inside of a tree root

What equipment did Sunshine Communications Inc use on 1/13/2025? (Select All That Are Applicable)

Shovel

What type of equipment damaged the facility?

Shovel

Who was operating the equipment that damaged the facility on 1/13/2025?

Leo

Does Sunshine Communications Inc own that equipment?

Yes

Emergency Response

How did Sunshine Communications Inc learn that the San Diego Gas and Electric facility was damaged on 1/13/2025?

heard hissing

Did anyone with Sunshine Communications Inc call 911 on 1/13/2025 after the damage had occurred?

Yes

Was there an emergency response to the incident from the fire department, a law enforcement department, or an ambulance on 1/13/2025?

Yes

Were there any injuries to any personnel or bystanders on 1/13/2025?

No

Were there any fatalities on 1/13/2025 or afterwards, due to the damage at 653 Via La Cuesta, Chula Vista?

No

Was there property damage on 1/13/2025, excluding the facility damage?

No

Was there a fire on 1/13/2025 as a result of the damage to the facility?

No

Was there an evacuation of any homes or businesses on 1/13/2025 as a result of the damage to the facility?

No

Are you aware of anyone else that called 911?

No

Did anyone at Sunshine Communications Inc contact the Regional Notification Center after the damage on 1/13/2025?

Yes

What is the damage 811-ticket number?

Its no longer listed in my portal

Did anyone at Sunshine Communications Inc contact San Diego Gas and Electric after the damage?

No

What steps, if any, have Sunshine Communications Inc taken to prevent a similar damage in the future?

No longer digging without 811 mark outs

Is there any other information you want to share about this damage?

Even with mark outs we would have not been able to know that the gas line was inside the tree root

Exhibit 3



CONTRACTORS STATE LICENSE BOARD

▼ Contractor's License Detail for License # 770746

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law ([B&P 7124.6](#)) If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click [here](#) for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed ([B&P 7071.17](#)).
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Data current as of 2/28/2025 8:57:41 AM

Business Information

SUNSHINE COMMUNICATIONS INC
350 CYPRESS LN STE D
EL CAJON, CA 92020
Business Phone Number:(619) 498-1700

Entity Corporation
Issue Date 10/28/1999
Expire Date **10/31/2025**

License Status

This license is current and active.

All information below should be reviewed.

Classifications

- ▶ [C-7 - LOW VOLTAGE SYSTEMS](#)
- ▶ [A - GENERAL ENGINEERING](#)

Bonding Information

Contractor's Bond

This license filed a Contractor's Bond with [AMERICAN CONTRACTORS INDEMNITY COMPANY](#).

Bond Number: 9021048

Bond Amount: \$25,000

Effective Date: 01/01/2023

[Contractor's Bond History](#)

Bond of Qualifying Individual

- ▶ The qualifying individual ROBERT ANTHONY STRAUB certified that he/she owns 10 percent or more of the voting stock/membership interest of this company; therefore, the Bond of Qualifying Individual is not required.
Effective Date: 04/02/2009
- ▶ This license filed Bond of Qualifying Individual number **100377649** for BRIAN JAMES DAGENAIS in the amount of **\$25,000** with [AMERICAN CONTRACTORS INDEMNITY COMPANY](#).
Effective Date: 01/01/2023
[BQI's Bond History](#)

Workers' Compensation

This license has workers compensation insurance with the [SERVICE AMERICAN INDEMNITY COMPANY](#)
Policy Number:SAMTWC1011601
Effective Date: 06/30/2024
Expire Date: 06/30/2025
[Workers' Compensation History](#)

Other

- ▶ Personnel listed on this license (current or disassociated) are listed on other licenses.

[Back to Top](#)

[Privacy Policy](#)

[Accessibility Certification](#)

[Conditions of Use](#)

[Accessibility](#)

Exhibit 4

Barton, Angel@EnergySafety

From: Barton, Angel@EnergySafety
Sent: Wednesday, February 26, 2025 1:19 PM
To: amber@digalert.org
Cc: Alcantar, Daysi@EnergySafety
Subject: 811 ticket request N250141025

Good afternoon Amber,

Please provide a copy of all tickets and revisions at about 653 Via La Cuesta in Chula Vista California for December 13, 2024, to January 25, 2025.

If there is not a ticket at this location for any of these dates, please confirm that finding.

Cordially,

Angel Barton
Investigator
Underground Infrastructure Directorate
Phone: (916) 216-0251
www.energysafety.ca.gov



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Stay connected and informed by signing up for the [Underground Safety Board's subscriber list](#).

Exhibit 5

Barton, Angel@EnergySafety

From: Amber Dahl <amber@digalert.org>
Sent: Wednesday, February 26, 2025 1:49 PM
To: Barton, Angel@EnergySafety
Cc: Alcantar, Daysi@EnergySafety
Subject: File N250141025
Attachments: N250141025.pdf

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you,



Amber Dahl, Safety Director
Underground Service Alert of Southern California
PO BOX 77070 Corona, CA 92877
P: 951-808-8115 F: 951-808-8101
E: amber@digalert.org W: www.digalert.org



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.



Underground Service Alert

of Southern California™

February 26, 2025

Angel Barton
Underground Safety Board

File Number: N250141025

Dear Angel,

After searching our records from 12/13/24 through 1/25/25, we found the following DigAlert ticket(s) B250150356 for the location at or near 653 Via La Cuesta in Chula Vista. I hope this information will be helpful.

If we can be of further assistance, please call us at 951-808-8100.

Sincerely,

Amber Dahl
Safety Awareness Director

Ticket: B250150356-00B

MBRCOD 00001B USAS 02/26/25 13:27:21 B250150356-00B NEW NORM POLY LREQ

Ticket: B250150356 Rev: 00B Created: 01/15/25 10:22 User: SLUDWIG Chan: WEB

Work Start: 01/17/25 17:01 Legal Start: 01/17/25 17:01 Expires: 02/12/25 23:59
Response required: Y Priority: 2

Excavator Information

Company: SUNSHINE COMMUNICATIONS INC Type: CONT
 Co Addr: 350 CYPRESS LN STE D
 City : EL CAJON State: CA Zip: 92020
 Created By: SCOTT LUDWIG Language: ENGLISH
 Office Phone: 619-218-4841 SMS/Cell: 619-218-4841
 Office Email: SCOTT.LUDWIG@SUNSHINECOM.COM

Site Contact: SCOTT LUDWIG

Site Phone: 619-218-4841 Site SMS/Cell: 619-218-4841
 Site Email: scott.ludwig@sunshinecom.com

Excavation Area

State: CA County: SAN DIEGO Place: CHULA VISTA
 Zip: 91913
 Address : 660 Street: VIA LA CUESTA
 Cross 1 : VIA HACIENDA
 Cross 2 :
 Location:
 Searchable Tags:
 Job size: sq-feet: 61600 sq-miles: 0.002210

Delineated Method: WHITEPAINT

Work Type: POT HOLE TO REPAIR CONDUIT

Work For : COX COMMUNICATIONS

Permit: Job/Work order: 16880568

Project ID:

Project Name:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N Pavement Only: N

Lat/Long

Center Generated (NAD83): 32.649989/-117.000944 32.650242/-117.000086
 : 32.649335/-117.000751 32.649588/-116.999892

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=D0fLhFhIbKcKVJf-7

Members:

ATDSOUTH CHU01 COX01 OTAYWTR SDG01 SDG02

(c) Copyright 2022 Underground Service Alert of Southern California.
 All rights reserved.

Ticket Responses for: B250150356-00B

Member	Name	Rev	Responded	By	Response
ATDSOUTH	AT&T - DISTRIBUTION	00B	01/15/25 11:32:59 AM	PRATTDIST	(001) CLEAR - NO CONFLICT
CHU01	CITY OF CHULA VISTA-PUBLIC WORKS OPER	00B	01/15/25 01:06:33 PM	Daniel	(010) LOCATE AREA MARKED
COX01	COX COMMUNICATIONS - SO SD	00B	01/16/25 11:42:35 AM	Urbint- UtiliQues	(010) LOCATE AREA MARKED

Member	Name	Rev	Responded	By	Response
OTAYWTR	OTAY WATER DIST	00B	01/16/25 09:33:00 AM	AACOSTA	(001) CLEAR - NO CONFLICT
SDG01	SDG&E GAS DISTRIBUTION AND ELECTRIC	00B	01/17/25 10:47:20 AM	DBALLES	(010) LOCATE AREA MARKED
SDG02	SDG&E (GAS TRANSMISSION)	00B	01/15/25 10:37:05 AM	GSANCHE5	(001) CLEAR - NO CONFLICT

Exhibit 6

Barton, Angel@EnergySafety

From: CHULAVISTACA Support <chulavistaca@govqa.us>
Sent: Thursday, April 3, 2025 6:27 PM
To: Barton, Angel@EnergySafety
Subject: [Records Center] City Records Request :: R005279-031325

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

--- Please respond above this line ---



RE: PUBLIC RECORDS REQUEST of March 13, 2025., Reference # R005279-031325.

Dear Angel Barton,

The City of Chula Vista is in receipt of your March 13, 2025 request for the following public records pursuant to the California Public Records Act ("CPRA") (Cal. Gov. Code section 7920.000 et seq.):

"Dear Custodian of Records,

This is a request for an electronic copy of all fire dispatch call logs, 911 audio recordings, and any incident reports from responding emergency personnel surrounding the potential gas leak of an underground natural gas service facility at 653 Via La Cuesta, Chula Vista on January 13, 2025. If no records exist, confirm that finding.

We are currently investigating the incident per California Government Code TITLE 1 – GENERAL - DIVISION 5 - PUBLIC WORK AND PUBLIC PURCHASES - CHAPTER 3.1 - Protection of Underground Infrastructure - ARTICLE 2 - Regional Notification Center System Section 4216.19.

Any information received will be beneficial to our investigation. If you have any questions, feel free to contact the undersigned.

Sincerely,

**Angel Barton
Investigator, Underground Infrastructure Directorate
Office of Energy Infrastructure Safety
Angel.Barton@energysafety.ca.gov"**

The City has identified records responsive to your request. The records that have been identified and are responsive are being sent to you electronically via My Request Center. **Please log in to your Request Center to access the records.**

Any additional information such as Body Worn Camera footage, Audio, and/or unredacted Call for Service log do not fall under public information and will require a Subpoena.

I have been informed by staff that they believe that they have fully responded to your request; however, if you need additional information I will assist you in your efforts pursuant to Government Code section 7922.600.

Should you have any questions or need assistance with accessing your records, please feel free to respond to this email directly.

Sincerely,
City Clerk Records Staff

Link to Request Center: https://chulavistaca.govqa.us/WEBAPP/_rs/supporthome.aspx





NFIRS-1 Basic

A

37030	CA	01	13	2025		CV25001168	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Location Type

Census tract:

- ☒ Street Address
☐ Intersection
☐ In Front Of
☐ Rear Of
☐ Adjacent To
☐ Directions
☐ US National Grid

653		Via La Cuesta		
Number	Prefix	Street or Highway	Street Type	Suffix

	CHULA VISTA	CA	91913
Apt./Suite/Room	City	State	Zip Code

Cross Street

C

Incident Type

412-Gas leak (natural gas or LPG)

E1 Dates and Times

Alarm 01 13 2025 11:52

Arrival 01 13 2025 11:58

Controlled

Last Unit Cleared 01 13 2025 13:49

E2 Shifts and Alarms

C		CHV54-WL-01
---	--	-------------

Shift or Alarms District
Platoon

D

Aid Given Or Received

- ☐ 1 Mutual Aid Received
☐ 2 Auto. Aid Received
☐ 3 Mutual Aid Given
☐ 4 Auto. Aid Given
☐ 5 Other Aid Given
☒ None

Their FDID Their State

Their Incident Number

E3 Special Studies

ID# Value

F Actions Taken

86-Investigate

Primary Action Taken

G1 Resources

- ☒ Apparatus or Personnel Module is used.

	Apparatus	Personnel
Suppression	10	32
EMS	1	2
Other	0	0

- ☐ Resource counts include aid received resources.

G2

Estimated Dollar Losses and Values

Losses: Required for all fires if None
known. Optional for all non-fires.

Property: \$ ☒

Contents: \$ ☒

Pre-Incident Values: Optional None

Property: \$ ☒

Contents: \$ ☒

Completed Modules ☐ 2 - Fire ☐ 3 - Structure Fire ☐ 4 - Civilian Fire Cas. ☐ 5 - Fire Service Cas. ☐ 6 - EMS ☐ 7 - HazMat ☐ 8 - Wildland Fire ☐ 9 - Apparatus ☐ 10 - Personnel ☐ 11 - Arson	H1 Casualties ☒ None <table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 30%;"></td> <td style="width: 35%; text-align: center;">Deaths</td> <td style="width: 35%; text-align: center;">Injuries</td> </tr> <tr> <td>Fire Service</td> <td style="text-align: center;"> 0 </td> <td style="text-align: center;"> 0 </td> </tr> <tr> <td>Civilian</td> <td style="text-align: center;"> 0 </td> <td style="text-align: center;"> 0 </td> </tr> </table>		Deaths	Injuries	Fire Service	0	0	Civilian	0	0	H3 Hazardous Materials Release ☐ 1 - Natural Gas ☐ 2 - Propane Gas ☐ 3 - Gasoline ☐ 4 - Kerosene ☐ 5 - Diesel Fuel / Fuel Oil ☐ 6 - Household Solvents ☐ 7 - Motor Oil ☐ 8 - Paint ☐ 0 - Other ☒ None	I Mixed Use Property ☐ Not Mixed ☐ 10 - Assembly Use ☐ 20 - Education Use ☐ 33 - Medical Use ☐ 40 - Residential Use ☐ 51 - Row Of Stores ☐ 53 - Enclosed Mall ☐ 58 - Business and Residential ☐ 59 - Office Use ☐ 60 - Industrial Use ☐ 63 - Military Use ☐ 65 - Farm Use ☐ 00 - Other Mixed Use
	Deaths	Injuries										
Fire Service	0	0										
Civilian	0	0										
H2 Detector Required For Confined Fires ☐ 1 - Detector Alerted Occupants ☐ 2 - Detector Did Not Alert Them ☐ 3 - Unknown												

J Property Use ☐ None Structures ☐ 131 Church, Place of Worship ☐ 161 Restaurant or Cafeteria ☐ 162 Bar/Tavern or Nightclub ☐ 213 Elementary School, Kindergarten ☐ 215 High School, Junior High ☐ 241 College, Adult Education ☐ 311 Nursing Home ☐ 331 Hospital	☐ 341 Clinic, Clinic-Type Infirmary ☐ 342 Doctor/Dentist Office ☐ 361 Prison or Jail, Not Juvenile ☒ 419 1- or 2-Family Dwelling ☐ 429 MultiFamily Dwelling ☐ 439 Rooming/Boarding House ☐ 449 Commerical Hotel or Motel ☐ 459 Residential, Board and Care ☐ 464 Dormitory/Barracks ☐ 519 Food and Beverage Sales	☐ 539 Household Goods, Sales, Repairs ☐ 571 Gas or Service Station ☐ 579 Motor Vehicle/Boat Sales/Repairs ☐ 599 Business Office ☐ 615 Electric-Generating Plant ☐ 629 Laboratory/Science Laboratory ☐ 700 Manufacturing Plant ☐ 819 Livestock/Poultry Storage (Barn) ☐ 882 Non-Residential Parking Garage ☐ 891 Warehouse
---	---	--

Outside ☐ 124 Playground or Park ☐ 655 Crops or Orchard ☐ 669 Forest (Timberland) ☐ 807 Outdoor Storage Area ☐ 919 Dump or Sanitary Landfill ☐ 931 Open Land or Field ☐ 936 Vacant Lot	☐ 938 Graded/Cared for Plot of Land ☐ 946 Lake, River, Stream ☐ 951 Railroad Right-of-Way ☐ 960 Other Street ☐ 961 Highway/Divided Highway ☐ 962 Residential Street/Driveway ☐ 981 Construction Site ☐ 984 Industrial Plant Yard	Property Use: Description Look up and enter a Property Use code and description only if you have NOT checked a Property Use box.
---	---	--

K2				
Owner				
Local Option	Person/Entity Type	Business Name (if applicable)	Phone Number	
Mr., Ms., Mrs.	First Name	MI	Last Name	Suffix
Number	Prefix	Street or Highway	Street Type	Suffix
Post Office Box	Apt./Suite/Room		City	
State		Zip Code		

L	Remarks:

M Authorization

CV404	Garcia, James	Capt/Pm		01/13/2025
Officer In Charge ID	Signature	Position or Rank	Assignment	Date
CV404	Garcia, James	Capt/Pm		01/13/2025
Member Making Report ID	Signature	Position or Rank	Assignment	Date

NFIRS-9 Apparatus or Resources

A

37030	CA	01	13	2025		CV25001168	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B Apparatus/Resource		Dates/Times		Sent	Number of People	Apparatus Use	Actions Taken
ID: CVB51	Dispatch: 01/13/2025 11:52	☒ Sent	1	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 92-Chief officer car	Arrival: 01/13/2025 12:02						
	Clear: 01/13/2025 12:08						
ID: CVB52	Dispatch: 01/13/2025 11:52	☒ Sent	1	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 92-Chief officer car	Arrival: 01/13/2025 11:58						
	Clear: 01/13/2025 12:50						
ID: CVE51	Dispatch: 01/13/2025 11:56	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 11-Engine	Arrival: 01/13/2025 12:04						
	Clear: 01/13/2025 12:07						
ID: CVE54	Dispatch: 01/13/2025 11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 11-Engine	Arrival: 01/13/2025 11:58						
	Clear: 01/13/2025 13:49						
ID: CVE56	Dispatch: 01/13/2025 11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 11-Engine	Arrival: 01/13/2025 12:00						
	Clear: 01/13/2025 12:07						
ID: CVE57	Dispatch: 01/13/2025 11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 11-Engine	Arrival: 01/13/2025 11:59						
	Clear: 01/13/2025 12:40						
ID: CVE58	Dispatch: 01/13/2025 11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	93-Cancelled en route		
Type: 11-Engine	Arrival: ☐ ☐						
	Clear: 01/13/2025 11:57						
ID: CVM52	Dispatch: 01/13/2025 11:52	☒ Sent	2	☒ Suppression ☐ EMS ☐ Other	93-Cancelled en route		
Type: 76-ALS unit	Arrival: ☐ ☐						
	Clear: 01/13/2025 12:07						
ID: CVSQ63	Dispatch: 01/13/2025 11:52	☒ Sent	2	☒ Suppression ☐ EMS ☐ Other	93-Cancelled en route		
Type: 70-Medical & rescue unit, other	Arrival: ☐ ☐						
	Clear: 01/13/2025 12:06						
ID: CVT51	Dispatch: 01/13/2025 11:54	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 12-Truck or aerial	Arrival: 01/13/2025 12:04						
	Clear: 01/13/2025 12:07						
ID: CVT57	Dispatch: 01/13/2025 11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐		
Type: 12-Truck or aerial	Arrival: 01/13/2025 12:01						
	Clear: 01/13/2025 12:13						

NFIRS-10 Personnel

A							
37030	CA	01	13	2025		CV25001168	0
FDID	State	Month	Day	Year	Station	Number	Exposure

B		Apparatus/Resource		Dates/Times	Sent	Number of People	Apparatus Use	Actions Taken
ID:	CVB51	Dispatch:	01/13/2025	11:52	☒ Sent	1	☒ Suppression ☐ EMS ☐ Other	☐
Type:	92-Chief officer car	Arrival:	01/13/2025	12:02				
		Clear:	01/13/2025	12:08				
Personnel ID	Name	Rank	Role	Attend	Actions Taken			
CV394	Brocchini, Richard	BC		☐	☐			

ID:	CVB52	Dispatch:	01/13/2025	11:52	☒ Sent	1	☒ Suppression ☐ EMS ☐ Other	☐
Type:	92-Chief officer car	Arrival:	01/13/2025	11:58				
		Clear:	01/13/2025	12:50				
Personnel ID	Name	Rank	Role	Attend	Actions Taken			
CV393	Albright, David	BC		☐	☐			

ID:	CVE51	Dispatch:	01/13/2025	11:56	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐
Type:	11-Engine	Arrival:	01/13/2025	12:04				
		Clear:	01/13/2025	12:07				
Personnel ID	Name	Rank	Role	Attend	Actions Taken			
CV464	Fondacaro, Andrew	Eng/PM		☐	☐			
CV477	Martinez, Modesto	Capt/PM		☐	☐			
CV517	Squibb, Garrett	FF		☐	☐			
CV524	Vazquez, Ruben	FF/PM		☐	☐			

ID:	CVE54	Dispatch:	01/13/2025	11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐
Type:	11-Engine	Arrival:	01/13/2025	11:58				
		Clear:	01/13/2025	13:49				
Personnel ID	Name	Rank	Role	Attend	Actions Taken			
CV404	Garcia, James	Capt/Pm		☐	☐			
CV528	Garcia, Nicholas	FF/PM		☐	☐			
CV601	Fisher, Isaac	FF		☐	☐			
CV679	Dodge, Christopher	FF		☐	☐			

ID:	CVE56	Dispatch:	01/13/2025	11:52	☒ Sent	4	☒ Suppression ☐ EMS ☐ Other	☐
Type:	11-Engine	Arrival:	01/13/2025	12:00				
		Clear:	01/13/2025	12:07				
Personnel ID	Name	Rank	Role	Attend	Actions Taken			
CV462	Bertelsen, Kenneth	Capt/Pm		☐	☐			
CV505	Humes, Phoenix	Eng/PM		☐	☐			

CV529	Martinson, Clifton	FF/PM	☐	☐
CV704	Flanagan, Asher	FF	☐	☐

ID: CVE57	Dispatch: 01/13/2025 11:52	☐ Sent 4	☒ Suppression ☐
Type: 11-Engine	Arrival: 01/13/2025 11:59		☐ EMS
	Clear: 01/13/2025 12:40		☐ Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV478	Fuentes, Ricardo	Capt/Pm		☐	☐
CV487	Cardona, Vincent	Eng/PM		☐	☐
CV6755	De La Rosa, David	FF/EMT		☐	☐
CV700	Weinstein, Kyle	FF/PM		☐	☐

ID: CVE58	Dispatch: 01/13/2025 11:52	☐ Sent 4	☒ Suppression 93-Cancelled en route
Type: 11-Engine	Arrival:		☐ EMS
	Clear: 01/13/2025 11:57		☐ Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV259	Mclintock, John	Captain		☐	☐
CV438	Alt, Bradley	FF/PM		☐	☐
CV527	Mendoza, Jaime	FF		☐	☐
CV6497	Macias, Mark	FF/EMT		☐	☐

ID: CVM52	Dispatch: 01/13/2025 11:52	☐ Sent 2	☐ Suppression 93-Cancelled en route
Type: 76-ALS unit	Arrival:		☒ EMS
	Clear: 01/13/2025 12:07		☐ Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV710	Carlson, Jillian A	Transport EMT		☐	☐
CV7585	Scarpace, Garrett	Transport Paramedic		☐	☐

ID: CVSQ63	Dispatch: 01/13/2025 11:52	☐ Sent 2	☒ Suppression 93-Cancelled en route
Type: 70-Medical & rescue unit, other	Arrival:		☐ EMS
	Clear: 01/13/2025 12:06		☐ Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV436	Zeilinger, Craig	FF/PM		☐	☐
CV7799	Fernandez, Jonathan	Transport EMT		☐	☐

ID: CVT51	Dispatch: 01/13/2025 11:54	☐ Sent 4	☒ Suppression ☐
Type: 12-Truck or aerial	Arrival: 01/13/2025 12:04		☐ EMS
	Clear: 01/13/2025 12:07		☐ Other

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV395	Baca, Kurt	Captain		☐	☐
CV430	Gorman, Timothy	Engineer		☐	☐
CV519	Schaeffer, Joshua	FF/PM		☐	☐

CV7254	Wilson, Richard	FF/EMT	☐	☐
--------	-----------------	--------	--------------------------	--------------------------

ID:	CVT57	Dispatch:	01/13/2025	11:52	☐ Sent	4	☒ Suppression	☐
Type:	12-Truck or aerial	Arrival:	01/13/2025	12:01			☐ EMS	
		Clear:	01/13/2025	12:13			☐ Other	

Personnel ID	Name	Rank	Role	Attend	Actions Taken
CV400	Flores, Trevor	Captain		☐	☐
CV495	Colorina, Jason	Eng/PM		☐	☐
CV7448	Cordova, Noah	FF/EMT		☐	☐
CV7568	Tirnetta, Christopher	FF/PM		☐	☐

NFIRS-1S Supplemental

A

37030	CA	01	13	2025		CV25001168	0
FDID	State	Month	Day	Year	Station	Number	Exposure

Apparatus Narrative for CVB51:

.

Apparatus Narrative for CVB52:

.

Apparatus Narrative for CVE51:

E51 AOS and staged. IC cancelled units at scene shortly thereafter. MM

Apparatus Narrative for CVE54:

Engine 54 established initial IC. Investigated and found a hissing natural gas line in hole in front of residence, Workers were digging and perforated line. SDG&E crew able to stop leak. E54 went available. MG #404

Apparatus Narrative for CVE56:

E56 arrived at scene, staged and was released by IC. KDB

Apparatus Narrative for CVE57:

E57 arrived and provided a road block on the north side of the incident. E57 was released by the IC.

Apparatus Narrative for CVE58:

Cancelled

Apparatus Narrative for CVM52:

.

Apparatus Narrative for CVT51:

Arrived to staging, then released. KB

Apparatus Narrative for CVT57:

.