



CALIFORNIA UNDERGROUND SAFETY BOARD INVESTIGATION DIVISION

INVESTIGATION REPORT

Date: June 30, 2026

Case No.: N2425057

Violations:

Aqua Pool & Spa Construction Inc.

Government Code § 4216.2(b): Excavating without first notifying the regional notification center of intent to excavate.

Government Code § 4216.4(c)(1): Excavator failure to contact 911 emergency services upon causing damage to subsurface installation resulting in the escape of flammable, toxic, or corrosive gas or liquid.

Executive Summary:

On August 20, 2024, Aqua Pool & Construction Inc. (Aqua Pool) was using a pick and damaged a ½-inch plastic gas service while trenching to install a gas line for a pool without first contacting the regional notification center. Upon the escape of gas from the subsurface installation, Aqua Pool did not contact 911 emergency services to report it. No one was injured, and no equipment, other than the ½ inch plastic gas service, was damaged.

Reporting Party Information:

Southern California Gas Company
555 West 5th Street, Suite 1700
Los Angeles, California 90013

Date of Incident:

August 20, 2024

Location of the Incident:

1661 East Mendocino Street
Altadena, California 91001

Operator:

Southern California Gas Company
555 West 5th Street, Suite 1700
Los Angeles, California 90013

Excavator:

Aqua Pool & Spa Construction Inc
7361 Ethel Avenue #4
North Hollywood, California 91605

Facility Type Damaged:

½ inch plastic gas service

Notification of the Incident

On September 6, 2024, Southern California Gas Company submitted a notification of an incident to the California Underground Safety Board. The notification stated, “3rd party was trenching to install gas line for pool and damaged a 1/2" plastic gas service with no USA.” and “Aqua Pool & Spa was trenching with a mini excavator to install a gas line for a pool and struck 1/2" plastic gas service.” (Exh. 1.)

The Southern California Gas Company reported that a mini-excavator was used when the damage occurred (Exh. 1.) However, Doran Toledano, Reporting Managing Officer, Chief Executive Officer, and President with Aqua Pool, (Exh. 3.) stated that the pick damaged the natural gas pipeline while trenching to install a gas line. (Exh. 2.)

Excavation and Damage

Government Code section 4216(g) defines “excavation” to be the use of tools or equipment to move or displace earth, rock, or other material in the ground.

Aqua Pool was using a pick and damaged an 1/2" plastic gas service while trenching to install a gas line for a pool at 1661 East Mendocino Street, Altadena, California 91001, on August 20, 2024, when the natural gas pipeline was damaged. (Exhs. 2.) Doran Toledano, Reporting Managing Officer, Chief Executive Officer, and President with Aqua Pool, (Exh. 3.) stated that the pick damaged the natural gas pipeline while trenching to install a gas line. (Exh. 2.)

Identity of Excavator

Government Code section 4216(h) defines an excavator to be “any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with their own employees or equipment performs any excavation.”

Aqua Pool & Spa Construction Inc. is licensed by the California Contractors State License Board, as of November 18, 2024, holding license number 1046115, with a C53– Swimming Pool and a B-General Building classifications. (Exh. 3.)

Aqua Pool Did Not Contact the Regional Notification Center Before Excavating

Government Code section 4216.2(b) states that an excavator planning to excavate shall notify the appropriate regional notification center of the excavator's intent to excavate at least two working days, and not more than 14 calendar days, before beginning that excavation.

On August 20, 2024, Aqua Pool did not notify the regional notification center before trenching with a shovel and a pick to install a gas line. Doran Toledano, Reporting Managing Officer, Chief Executive Officer, and President of Aqua Pool, (Exh. 3.) stated he was aware of the need to contact the regional notification center prior to excavating but didn't as "we were not excavating near the gas line, it was a 18" deep trench for lines." (Exh. 2.)

On December 30, 2024, the investigator emailed Amber Dahl, DigAlert's Safety Awareness Director, requesting ticket information for 1661 East Mendocino Street, Altadena, California 91001, for August 20, 2024. (Exh. 4.)

Director Dahl responded by email that same day, indicating no tickets were located for 1661 East Mendocino Street, Altadena, California 91001 for February 20, 2024, through August 20, 2024. (Exh. 5.)

Aqua Pool Did Not Contact 911 Emergency Services Upon a Gas Release

Government Code section 4216.4(c)(1) states an excavator shall call 911 emergency services upon discovering or causing damage to a gas or hazardous liquid pipeline subsurface installation in which the damage results in the escape of any flammable, toxic, or corrosive gas or liquid.

Doran Toledano, Reporting Managing Officer, Chief Executive Officer, and President with Aqua Pool, answered "No" to the Board's Investigation Questionnaire on whether Aqua Pool had called 911 after the damage occurred on August 20, 2024. (Exh. 2.)

Findings:

1. Aqua Pool did not notify the regional notification center before beginning excavation on August 20, 2024, at 1661 East Mendocino Street, Altadena, California 91001, as they felt they were not excavating near the gas line, only doing an 18” deep trench for a gas line.
2. Aqua Pool failed to contact 911 emergency services to report the escaping gas from the subsurface installation after it was damaged while trenching to install a gas line.

Investigator	Supervisor
Adrian Anaya	Anona Bonner
Signature	Signature
/s/ Adrian Anaya	/s/ Anona Bonner

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 09/06/2024	Andrew Rodriguez, Damage Prevention Analyst, Southern California Gas Company
2.	Board's Investigation Questionnaire and Investigator's email to Reporting Managing Officer, Chief Executive Officer, and President, Doran Toledano, Aqua Pool Board's Investigation Questionnaire completed by Reporting Managing Officer, Chief Executive Officer, and President, Doran Toledano	Emailed on 11/18/2024 Received on 11/26/2024	Doran Toledano, Reporting Managing Officer, Chief Executive Officer, and President, Aqua Pool
3.	Contractor's License Detail for License No. 1046115 obtained from the Contractors State License Board website	Downloaded on 11/18/2024	California Contractors State License Board website at https://www.cslb.ca.gov/onlineservices/checklicensell/checklicense.aspx
4.	Investigator's email to DigAlert requesting ticket information on the underlying job to this incident	Emailed on 12/30/2024	
5.	Email from DigAlert indicating no tickets were found for the underlying job to this incident	Received on 12/30/2024	Amber Dahl, Safety Awareness Director, DigAlert

Exhibit 1

No-Ticket Damage Reporting Form

Submitted: September 6, 2024 10:17 AM

Reporter Information

Provide the names, titles, phone numbers, and email addresses of all individuals who are involved in reporting this damage or contributing to the answers to these questions

Full Name

Andrew Rodriguez

Title

Damage Prevention Analyst

Phone Number

805-441-4803

E-mail address

arodrig9@socalgas.com

Company

Provide the name, address, phone number, email address, and, if applicable, the Regional Notification Center (member code for your company).

Company Name

SoCal Gas

Address

555 W 5th St , Los Angeles , 90013

Phone Number

805-441-4803

Email Address

arodrig9@socalgas.com

Regional Notification Center member code

Other Contacts

Is the photographer same as the primary reporter named above?

Yes

Incident Information

What was the date and approximate time of the incident?

August 20, 2024 11:40 AM

What is the address where your facility was damaged on 8/20/2024?

Damage Street Address

1661 E Mendocino St

Damage County

Los Angeles

Damage City

Altadena

Damage Cross Street 1

Porter Ave

Damage Cross Street 2

Tanoble Dr

Other Damage location description

private property

Does SoCal Gas own, operate or maintain the facility damaged on 8/20/2024?

Yes

What type of excavation did you observe on 8/20/2024 at that address?

Other

Describe the excavation activity you identified.

3rd party was trenching to install gas line for pool and damaged a 1/2" plastic gas service with no USA.

What excavation companies did you observe on 8/20/2024?

Company Name

Aqua Pool & Spa Construction

Company Address

7361 Ethel Ave #4, North Hollywood , 91605

Phone Number

818-633-5900

Email Address

goaquaconstruction@gmail.com

Did this company damage the facility?

Yes

Provide the name, title, phone number, and email address for at least one contact for each excavation company working at or near incident address on date of incident. If you have more than one contact, please provide all of them. Email addresses are required for submission of this form.

Personnel Name

Tatum Kendrick

Title

Foreman

Phone Number

818-633-5900

Email Address

goaquaconstruction@gmail.com

Notification Details

Was SoCal Gas notified of the proposed excavation by the Regional Notification Center before 8/20/2024?

No

What date and time did you learn of the damage to the facility?

August 20, 2024 11:40 AM

How did SoCal Gas learn of the damage to the facility?

Internal email notification

Facility Damaged

What kind of facility was damaged on 8/20/2024?

Natural Gas

Natural Gas

What type of material was the damaged facility?

Plastic

Facility diameter (inches)?

0.5

Incident Details

What kinds of excavation equipment did you observe at the location of the damaged facility?

Backhoe/trackhoe/excavator

Do you know what equipment damaged the facility?

Yes

What equipment damaged the facility?

Backhoe/trackhoe/excavator

What information are you relying on regarding damage to the facility?

Eyewitness statement, Photographs, Interview with excavator

Did SoCal Gas contact the Regional Notification Center before repairing the damaged facility?

No

Provide any other relevant information about the damage on 8/20/2024.

Aqua Pool & Spa was trenching with a mini excavator to install a gas line for a pool and struck 1/2" plastic gas service.

Damages

Were there any injuries to any personnel or bystanders due to the damage to your facility on 8/20/2024?

No

Was any property damaged other than the damaged facility?

No

Was there a fire caused by this damage on 8/20/2024?

No

Was there an evacuation of any nearby homes or businesses caused by this damage on 8/20/2024?

No

Provide an estimate of the number of your customers whose service was interrupted by this damage on 8/20/2024.

1

Conclusions

What date and time were repairs completed to the damaged facility?

August 20, 2024 1:34 PM

Please explain why you think the facility was damaged on 8/20/2024?

1/2" plastic gas service was damaged with gas escape.

Is there any other information which you feel is important to share about this incident?

Not counting your answers to these questions, did SoCal Gas create an investigatory or incident report pertaining to the damage on 8/20/2024?

Yes

Please attach investigatory or incident report here.

1661 E Mendocino Damage report.docx, 0.03MB

Have your answers to these questions and or the documents you are sending today been reviewed, changed or amended by anyone?

No

Files

Please attach all Facility Repair Orders.

Please attach all Photos.



Date and time photographed

August 21, 2024 1:43 PM

Photographer Name

Andrew Rodriguez



Date and time photographed

August 21, 2024 1:43 PM

Photographer Name

Andrew Rodriguez



Date and time photographed

August 21, 2024 1:50 PM

Photographer Name

Andrew Rodriguez

Additional Records

Business cards, photo of company vehicles onsite, etc.

Em_4_.jpg, 0.08MB

Reference Number

N2425057

Incident Time: (24hr) 11:40 am

Incident Date: 8/20/2024

Incident Location:

City/County: Altadena/ Los Angeles

Address/Location: 1661 E Mendocino St

Incident Cause: No USA damage

Gas Equipment Affected: Gas Service

Material: Plastic Pipe size: 1/2"

Dig In Information:

USA notification required: **Yes / No**

USA notified: **Yes / No** USA #

Facilities properly marked: **Yes / No**

Name of Excavator: Aqua Pool & Spa Construction Inc

Excavator Contact Person: Tatum Kendrick

Phone: 818-633-5900

On Scene:	Date	Time
Company Personnel on Scene	<u>8/20/2024</u>	<u>12:03 pm</u>
Gas Flow Stopped	<u>8/20/2024</u>	<u>1:34 pm</u>

Customer Outages (Quantity) 1

Summary of incident Aqua Pool & Spa was trenching with a mini excavator to install a gas line for a pool and struck 1/2" plastic gas servic

[Home](#) | [Online Services](#) | License Details

Contractor's License Detail for License # 1046115

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law (B&P 7124.6) If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click [here](#) for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed (B&P 7071.17).
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Business Information

AQUA POOL & SPA CONSTRUCTION INC
 7361 ETHEL AVE #4
 NORTH HOLLYWOOD, CA 91605
 Business Phone Number: (818) 633-5900

Entity Corporation
Issue Date 10/24/2018
Expire Date 10/31/2024

License Status

This license is current and active.

All information below should be reviewed.

Classifications

- ▶ [CS3 - SWIMMING POOL](#)
- ▶ [B - GENERAL BUILDING](#)

Online Services Quick Hits

- ▶ [Check a License or HIS Registration](#)
- ▶ [Find My Licensed Contractor](#)
- ▶ [Frequently Asked Questions](#)
- ▶ [Forms and Applications](#)
- ▶ [Guides and Publications](#)
- ▶ [CSLB Laws and Regulations](#)
- ▶ [List of All CSLB Fees](#)
- ▶ [License Classifications](#)
- ▶ [Contractor Newsletter](#)
- ▶ [Application Status](#)
- ▶ [Application Status \(Secured\)](#)
- ▶ [Application Status by Personnel Name](#)
- ▶ [Application Status by Business Name](#)
- ▶ [CSLB Email Login](#)

Online Services









Exhibit 2

Anaya, Adrian@EnergySafety

From: Anaya, Adrian@EnergySafety
Sent: Monday, November 18, 2024 1:36 PM
To: goaquaconstruction@gmail.com
Subject: Underground Safety Board – No-811 Investigation Case N2425057

Importance: High

Dear Aqua Pool and Spa Construction Incorporated,

Response Due Date: November 26, 2024

The Underground Safety Board (Board) has been notified about damage to a facility, potentially involving Aqua Pool and Spa Construction Incorporated. You have the option to respond to the following questions below using this interactive form or through a scheduled telephone interview.

[Respond to the survey by clicking here.](#)

All questions must be answered to submit this form. Alternatively, you can contact the investigator within the next two business days to schedule a phone interview to answer these questions.

Should you encounter any difficulties with the questions or prefer a telephone interview, contact the investigator within the next two business days to schedule a time to discuss. I have been assigned with following up on notification reporting that Aqua Pool damaged the facility on 8/20/2024 by excavating without first contacting the Regional Notification Center. The damage occurred at or near 1661 E Mendocino St, Altadena.

The purpose of this report is to gather all the pertinent facts. The questions below, tailored for Aqua Pool, may serve to replace a formal interview. Respond to each question. The Board investigates excavation incidents to identify potential safety violations, and employ this data to enhance accident prevention, safeguard worker welfare, and protect people and property.

Furthermore, this information will aid in determining if any enforcement measures are warranted. In such a scenario, Aqua Pool will initially receive a Notice of Possible Violation (NOPV) following this investigation. NOPVs will be reviewed during public meetings of the Board to determine whether any violations of Government Code section 4216 et seq. have occurred. Should Aqua Pool receive an NOPV, you will be notified of your response options and of the date of your hearing.

To answer these questions, you will need to gather information where applicable regarding excavation activities on the site, company and personnel contact information, the 811 ticket number and response information from the utility companies, emergency response actions, and prime contractor contact information.

Send with your answers to the questions, all the documents listed below that you possess, in their original format, which are associated with this damage by the date indicated in the email. "Documents" include photographs, 811 ticket(s), written communications, incident reports, emails, texts, videos, or other related items.

Any documents the Board receives after the response due date may not make it into the case file, resulting in them not being a part of the determination of your possible violation.

Thank you,

[Adrian Anaya](#)

Investigator

Office of Energy Infrastructure Safety

Mobile: (279) 245-1133

EnergySafety.ca.gov



No-Ticket Damage Reporting Form

Submitted Time: November 26, 2024 7:54 PM

Provide your name, title, phone number, and email address

Name

Doran

Title

Contractor

Phone Number

818-633-5900

Email Address

goaquaconstruction@gmail.com

Please provide the identifying information for Aqua Pool in general.

California Contractor's State License Board (CSLB) license

1046115

Physical Address

7361 Ethel Ave #4 North Hollywood, CA 91605

Mailing Address

7361 Ethel Ave #4 North Hollywood, CA 91605

Phone Number

818-633-5900

Email Address

goaquaconstruction@gmail.com

Did Aqua Pool damage the NaturalGas facility while excavating at 1661 E Mendocino St, Altadena on the 8/20/2024? (Select One)

Yes

Were there any other companies at or near 1661 E Mendocino St, Altadena on 8/20/2024? (Select One)

No

Did someone in Aqua Pool, or anyone else, contact the Regional Notification Center on 8/20/2024?

No

Did SoCalGas respond after the Regional Notification Center created the 811 ticket?

Is Aqua Pool aware that it needed to contact the Regional Notification Center prior to excavating?

Yes

Did the Regional Notification Center create an 811-ticket for 1661 E Mendocino St, Altadena that Aqua Pool worked?

No

If no one at Aqua Pool, or anyone else, contacted the Regional Notification Center before excavating, why not?

Other

Explain why Aqua Pool did not obtain an 811 ticket?

We were not excavating near the gas line, it was a 18" deep trench for lines

Has Aqua Pool ever obtained an 811 ticket, either by calling 811 or using the Regional Notification Center's website?

Yes

The damage notification indicated that a facility was damaged at 1661 E Mendocino St, Altadena on 8/20/2024. Is that correct?

Yes

Was Aqua Pool the prime contractor on the project at 1661 E Mendocino St, Altadena on 8/20/2024?

Yes

What was mentioned or what direction did the prime contractor provide to you?

Provide the names, phone numbers, and if applicable, their email address for all your personnel who were at 1661 E Mendocino St, Altadena when the facility was damaged.

Name

Doran Toledano

Title

Contractor

Phone Number

818-633-5900

Email Address

goaquaconstruction@gmail.com

Add an additional individual?

Which one of the individuals you identified was the foreman on the project when the facility was damaged?

Doran Toledano

Facility Damage

Was a facility damaged on 8/20/2024?

No

Describe the damaged facility.

When trenching near the crawl space which the meter is under, the riser for the meter line was accidentally struck

Identify the type of material damaged.

Gas meter riser

Explain how the facility was damaged?

We were trenching to bring a line under the house and we accidentally struck the meter riser when bringing the line under.

What equipment did Aqua Pool use on 8/20/2024? (Select All That Are Applicable)

Shovel, Pick

What type of equipment damaged the facility?

Pick

Who was operating the equipment that damaged the facility on 8/20/2024?

Doran Toledano

Does Aqua Pool own that equipment?

Yes

Emergency Response

How did Aqua Pool learn that the SoCalGas facility was damaged on 8/20/2024?

Doran Toledano and the property owner who was on site.

Did anyone with Aqua Pool call 911 on 8/20/2024 after the damage had occurred?

No

Was there an emergency response to the incident from the fire department, a law enforcement department, or an ambulance on 8/20/2024?

No

Were there any injuries to any personnel or bystanders on 8/20/2024?

No

Were there any fatalities on 8/20/2024 or afterwards, due to the damage at 1661 E Mendocino St, Altadena?

No

Was there property damage on 8/20/2024, excluding the facility damage?

No

Was there a fire on 8/20/2024 as a result of the damage to the facility?

No

Was there an evacuation of any homes or businesses on 8/20/2024 as a result of the damage to the facility?

No

Are you aware of anyone else that called 911?

No

Did anyone at Aqua Pool contact the Regional Notification Center after the damage on 8/20/2024?

No

Did anyone at Aqua Pool contact SoCalGas after the damage?

Yes

Who at Aqua Pool contacted the SoCalGas?

General Leak Number

What is the name of the person at the SoCalGas contacted by the individual you identified above?

N/A

What steps, if any, have Aqua Pool taken to prevent a similar damage in the future?

Yes calling 811 tickets for new projects regardless if its a small trench

Is there any other information you want to share about this damage?

Exhibit 3

▼ Contractor's License Detail for License # 1046115

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law ([B&P 7124.6](#)) If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click [here](#) for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed ([B&P 7071.17](#)).
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Data current as of 11/18/2024 11:41:06 AM

Business Information

AQUA POOL & SPA CONSTRUCTION INC
7361 ETHEL AVE #4
NORTH HOLLYWOOD, CA 91605
Business Phone Number:(818) 633-5900

Entity Corporation
Issue Date 10/24/2018
Expire Date **10/31/2026**

License Status

This license is current and active.

All information below should be reviewed.

Classifications

- ▶ [C53 - SWIMMING POOL](#)
- ▶ [B - GENERAL BUILDING](#)

Bonding Information

Contractor's Bond

This license filed a Contractor's Bond with [MERCHANTS BONDING COMPANY \(MUTUAL\)](#).

Bond Number: 101205677

Bond Amount: \$25,000

Effective Date: 10/18/2024

[Contractor's Bond History](#)

Bond of Qualifying Individual

- ▶ The qualifying individual JORDAN JUDEAH NAJUM certified that he/she owns 10 percent or more of the voting stock/membership interest of this company; therefore, the Bond of Qualifying Individual is not required.
Effective Date: 10/24/2018
- ▶ The qualifying individual DORAN TOLEDANO certified that he/she owns 10 percent or more of the voting stock/membership interest of this company; therefore, the Bond of Qualifying Individual is not required.
Effective Date: 04/20/2023

This license has workers compensation insurance with the [SECURITY NATIONAL INSURANCE COMPANY](#)
Policy Number:SWC1469851
Effective Date: 01/15/2024
Expire Date: 01/15/2025
[Workers' Compensation History](#)

Workers' compensation classification code(s):
9097 - Swimming Pool Cleaning/Serviceing

For a description of the workers' compensation classification code(s) listed for this licensee, contact the licensee's insurance carrier.
Contact information for the licensee's insurer is available by clicking the insurer link above. Classification codes are also available on the
Workers' Compensation Insurance Rating Bureau's classification search page.

The board does not verify or investigate the accuracy of classification codes displayed.

Other

- ▶ Personnel listed on this license (current or disassociated) are listed on other licenses.

Contractor's License Detail (Personnel List)

Contractor License # 1046115
Contractor Name AQUA POOL & SPA CONSTRUCTION INC

Click on the person's name to see a more detailed page of information on that person

Licenses Currently Associated With

Name	JORDAN JUDEAH NAJUM
Title	RMO / CEO / PRES
Association Date	10/24/2018
Classification	C53
Name	DORAN TOLEDANO
Title	RMO / CEO / PRES
Association Date	10/24/2018
Classification	B

Licenses No Longer Associated With

Copyright © 2024 State of California

Exhibit 4

Anaya, Adrian@EnergySafety

From: Anaya, Adrian@EnergySafety
Sent: Monday, December 30, 2024 1:36 PM
To: Amber Dahl
Subject: N2425057 - Ticket Locate Request

Hello,

Could you please provide a copy of all tickets and electronic positive responses at about 1661 East Mendocino Street, Altadena, CA 91001 for August 20, 2024?

If there is not a ticket at this address for this date, confirm that finding.

Thank you,

[Adrian Anaya](#)

Investigator

Office of Energy Infrastructure Safety

Mobile: (279) 245-1133

EnergySafety.ca.gov



Exhibit 5

Anaya, Adrian@EnergySafety

From: Amber Dahl <amber@digalert.org>
Sent: Monday, December 30, 2024 4:28 PM
To: Anaya, Adrian@EnergySafety
Subject: Re: N2425057 - Ticket Locate Request
Attachments: N2425057.pdf

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Here is the information you requested

From: Adrian@EnergySafety <Adrian.Anaya@energysafety.ca.gov>
To: Amber <amber@digalert.org>
Date: Monday, 30 December 2024 1:36 PM PST
Subject: N2425057 - Ticket Locate Request

Hello,

Could you please provide a copy of all tickets and electronic positive responses at about 1661 East Mendocino Street, Altadena, CA 91001 for August 20, 2024?

If there is not a ticket at this address for this date, confirm that finding.

Thank you,

[Adrian Anaya](#)
Investigator
Office of Energy Infrastructure Safety
Mobile: (279) 245-1133
EnergySafety.ca.gov





Underground Service Alert of Southern California

December 30, 2024

Adrian Anaya
Underground Safety Board

File Number: N2425057

Dear Adrian:

After searching our records from 2/20/2024 through 8/20/2024, we were unable to find any DigAlert tickets for the location at or near 1661 E. Mendocino St in Altadena. I hope this information will be helpful.

If we can be of further assistance, please call us at 951-808-8100.

Sincerely,

for Amber Dahl
Safety Awareness Director