



CALIFORNIA UNDERGROUND SAFETY BOARD INVESTIGATION DIVISION

INVESTIGATION REPORT

Date: August 27, 2026

Case No.: N242633

Violations:

L A T Construction Inc.

Government Code § 4216.2(b): Excavating without first notifying the regional notification center of intent to excavate.

Government Code § 4216.4(c)(1): Excavator failure to call 911 emergency services upon causing damage to subsurface installation resulting in the escape of flammable, toxic, or corrosive gas or liquid.

Executive Summary:

On August 26, 2024, L A T Construction Inc. was digging with a shovel without first contacting the regional notification center and damaged a 1/2-inch plastic natural gas line. Upon the escape of gas from the subsurface installation, L A T Construction Inc. did not call 911 emergency services to report it. No one was injured and no equipment, other than the 1/2-inch plastic natural gas line, was damaged.

Reporting Party Information:

Southern California Gas Company
555 West. 5th Street, Suite 1700
Los Angeles, California 90013

Date of Incident:

August 26, 2024

Location of the Incident:

951 Brossard Drive
Thousand Oaks, California 91360

Operator:

Southern California Gas Company
555 West. 5th Street, Suite 1700
Los Angeles, California 90013

Excavator:

L A T Construction Inc.
13275 Branford Street
Arleta, California 91331

Subsurface Installation Type Damaged:

1/2-inch plastic natural gas line

Notification of the Incident

On September 25, 2024, Southern California Gas Company submitted a notification of an incident to the Underground Safety Board. The notification stated, "0.5-inch plastic gas line was damaged and gas escaping, no 811 ticket". (Exh. 1.)

Excavation and Damage

Government Code section Government Code 4216(g) defines "excavation" to be the use of tools or equipment to move or displace earth, rock, or other material in the ground.

On August 26, 2024, L A T Construction Inc. (LAT) was digging a trench with a shovel (Exh. 2) to install an electric line and damaged a 1/2-inch plastic natural gas line at 951 Bossard Drive. (Exh. 1.)

Identity of the Excavator

Government Code section 4216(h) defines an excavator to be "any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with their own employees or equipment, performs any excavation."

L A T Construction Inc. was a licensed contractor, as of December 11, 2024, registered with the Contractor's State License Board, license number 1038128 with B-General Building and C61/D63- Construction Clean-Up Classifications (Exh. 3.)

L A T Construction Inc. Did Not Contact the Regional Notification Center Before Excavating

Government Code section 4216.2(b) states that an excavator planning to excavate shall notify the appropriate regional notification center of the excavator's intent to excavate at least two working days, and not more than 14 calendar days, before beginning that excavation.

L A T Construction Inc. (L A T) did not notify the regional notification center prior to digging with a shovel at 951 Brossard Drive Thousand Oaks, California 91360. Luis Trujillo (Trujillo), with L A T, stated they contacted the regional notification center on August 26, 2024. However, Trujillo did not provide the ticket number. (Exh. 2.) During an interview with the investigator, Trujillo stated that a previous contractor had marked the site on a prior occasion, and he did

not know that he had to call his own ticket. Trujillo stated they started digging which led to the damage. Trujillo also stated that he had his crew take a class offered by SoCalGas and would welcome any further opportunities to learn. (Exh. 4.)

On November 13, 2024, investigator emailed Amber Dahl, Safety Awareness Director at DigAlert, requesting ticket information for 951 Brossard Drive, on August 26, 2024. (Exh. 5.)

Safety Awareness Director, Amber Dahl, responded via email on November 14, 2024, confirming that a ticket did not exist for 951 Brossard Drive on August 26, 2024. (Exh. 6.)

L A T Construction Inc. Did Not Call 911 Emergency Services Upon Gas Release

Government Code section 4216.4(c)(1) states an excavator shall call 911 emergency services upon discovering or causing damage to a gas or hazardous liquid pipeline subsurface installation in which the damage results in the escape of any flammable, toxic, or corrosive gas or liquid.

On August 26, 2024, L A T Construction Inc. was digging a trench with a shovel and damaged a 1/2-inch plastic natural gas line resulting in a gas escape but did not call 911 afterward. (Exh. 2.)

Findings:

1. L A T Construction Inc. did not contact the regional notification center before beginning the excavation on August 26, 2024, at 951 Brossard Drive Thousand Oaks, California 91360.
2. On August 26, 2024, L A T Construction Inc. did not call 911 emergency services to report the escaping gas from the subsurface installation after it was damaged by a shovel while digging.

Investigator	Supervisor
Ammar Bhatti	Anona Bonner
Signature	Signature
/s/ Ammar Bhatti	/s/ Anona Bonner

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 9/25/2025 at 12:06 p.m.	Alejandro Alvarez, Damage Prevention Analyst, Southern California Gas Company
2.	Board's Investigation Questionnaire and Investigator's email to L A T Construction Inc.	Emailed on 11/13/2024	Luis Trujillo, General Contractor, L A T Construction Inc.
3.	Contractor's License Detail for L A T Construction Inc., License No. 1038128 obtained from the Contractors State License Board website	Downloaded on 12/11/2024	Contractors State License Board website at https://www.cslb.ca.gov/onlineservices/checklicensell/checklicense.aspx
4.	Record of Phone Interview with Luis Trujillo at L A T Construction	Conducted on 8/20/2026	
5.	Investigator's email to DigAlert ticket information on the underlying job to this incident	Emailed on 11/14/2024	
6.	Email from DigAlert stating there was no valid ticket for the underlying job to this incident	Received on 11/13/2024	Amber Dahl, Safety Awareness Director, DigAlert

Exhibit 1

No-Ticket Damage Reporting Form

Submitted: September 25, 2024 12:06 PM

Reporter Information

Provide the names, titles, phone numbers, and email addresses of all individuals who are involved in reporting this damage or contributing to the answers to these questions

Full Name

Alejandro Alvarez

Title

Damage Prevention Analyst

Phone Number

714-309-6289

E-mail address

aalvare5@socalgas.com

Company

Provide the name, address, phone number, email address, and, if applicable, the Regional Notification Center (member code for your company).

Company Name

SoCalGas

Address

555 W. 5th. St., Los Angeles , 90013

Phone Number

714-309-6289

Email Address

SCGDamagePrevention@socalgas.com

Regional Notification Center member code

Other Contacts

Is the photographer same as the primary reporter named above?

Yes

Incident Information

What was the date and approximate time of the incident?

August 26, 2024 11:57 AM

What is the address where your facility was damaged on 8/26/2024?

Damage Street Address

951 Brossard Dr.

Damage County

Ventura

Damage City

Simi Valley

Damage Cross Street 1

Houston Dr.

Damage Cross Street 2

Other Damage location description

Does SoCalGas own, operate or maintain the facility damaged on 8/26/2024?

Yes

What type of excavation did you observe on 8/26/2024 at that address?

Electric

Describe the excavation activity you identified.

LAT construction hired by home owner to install Electric line.

What excavation companies did you observe on 8/26/2024?

Company Name

LAT CONSTRUCTION INC

Company Address

13275 Branford St, Arleta , 91331

Phone Number

818-815-1977

Email Address

SCGDamagePrevention@socalgas.com

Did this company damage the facility?

Yes

Provide the name, title, phone number, and email address for at least one contact for each excavation company working at or near incident address on date of incident. If you have more than one contact, please provide all of them. Email addresses are required for submission of this form.

Personnel Name

LUIS TRUJILLO

Title

Employee

Phone Number

818-815-1977

Email Address

SCGDamagePrevention@socalgas.com

Notification Details

Was SoCalGas notified of the proposed excavation by the Regional Notification Center before 8/26/2024?

No

What date and time did you learn of the damage to the facility?

August 26, 2024 11:59 AM

How did SoCalGas learn of the damage to the facility?

Intercompany email notification

Facility Damaged

What kind of facility was damaged on 8/26/2024?

Natural Gas

Natural Gas

What type of material was the damaged facility?

Plastic

Facility diameter (inches)?

0.5

Incident Details

What kinds of excavation equipment did you observe at the location of the damaged facility?

Shovel

Do you know what equipment damaged the facility?

Yes

What equipment damaged the facility?

Shovel

What information are you relying on regarding damage to the facility?

Interview with excavator

Did SoCalGas contact the Regional Notification Center before repairing the damaged facility?

No

Provide any other relevant information about the damage on 8/26/2024.

LAT Construction was excavating with hand tools to install electric conduit for homeowner.

Homeowner called in Dig Alert but LAT construction did not.

Damages

Were there any injuries to any personnel or bystanders due to the damage to your facility on 8/26/2024?

No

Was any property damaged other than the damaged facility?

No

Was there a fire caused by this damage on 8/26/2024?

No

Was there an evacuation of any nearby homes or businesses caused by this damage on 8/26/2024?

No

Provide an estimate of the number of your customers whose service was interrupted by this damage on 8/26/2024.

1

Conclusions

What date and time were repairs completed to the damaged facility?

August 26, 2024 11:57 AM

Please explain why you think the facility was damaged on 8/26/2024?

0.5-inch plastic gas line was damaged and gas escaping

Is there any other information which you feel is important to share about this incident?

Not counting your answers to these questions, did SoCalGas create an investigatory or incident report pertaining to the damage on 8/26/2024?

Yes

Please attach investigatory or incident report here.

USB Damage Report Form Template AA Copy.docx, 0.02MB


Have your answers to these questions and or the documents you are sending today been reviewed, changed or amended by anyone?

No

Files

Please attach all Facility Repair Orders.

Please attach all Photos.



Date and time photographed
September 25, 2024 12:02 PM

Photographer Name

Alejandro Alvarez

Additional Records

Business cards, photo of company vehicles onsite, etc.

LAT Construction Inc CSLB.png, 0.19MB

Reference Number

N242633



951 Brossard Dr, Thousand Oaks, CA 91360

Directions

Nearby

Save to calendar

Nearby

Coffee Shops

Gas Stations

Restaurants

Grocery Stores

Malls

Nearby Transit

Search nearby

United States · CA · Ventura Co. · Thousand Oaks

34.184782, -118.861938



951 Brossard Dr, Thousand Oaks, CA 91360

Feedback

50 ft

20 m

951 Brossard Dr Thousand Oaks California 91360 USA
No USA Damage

Incident Time: (24hr) 11:57 AM

Incident Date: 08/26/24

Incident Location:

City/County: Thousand Oaks/ Ventura

Address/Location: 951 Brossard Dr Thousand Oaks California
91360 USA

Incident Cause: Hand tools punctured 0.5-inch gas service

Gas Equipment Affected:

Material: Plastic Pipe size: 0.5" CTS

Dig In Information:

USA notification required: **Yes / No**

USA notified: **Yes / No** USA # _____

Facilities properly marked: N/A

Name of Excavator: L A T CONSTRUCTION INC

Excavator Contact Person: LUIS TRUJILLO

Phone: (818)815-1977

On Scene:	Date	Time
-----------	------	------

Company Personnel on Scene <u>LCT Nick Cardilino</u>	<u>08/26/24</u>	<u>12:30 PM</u>
--	-----------------	-----------------

Gas Flow Stopped _____	<u>08/26/24</u>	<u>12:50 PM</u>
------------------------	-----------------	-----------------

Customer Outages (Quantity) 1

Summary of incident: Licensed 3rd party contractor damaged 0.5-inch plastic gas service while digging with shovel for install of electrical conduit. No USA called in for excavation by 3rd party contractor. No photos taken by crew that responded to damage or SCG Supervision.



Consumers



Licensees



Applicants



Online Services



Media



Resources

[Home](#) |
 [Online Services](#) |
 [License Details](#)

Contractor's License Detail for License # 1038128

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law ([B&P 7124.6](#)) If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click [here](#) for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed ([B&P 7071.17](#)).
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Business Information

L A T CONSTRUCTION INC
 13275 BRANFORD STREET
 ARLETA, CA 91321
 Business Phone Number:(818) 815-1977

Entity Corporation
Issue Date 04/16/2018
Expire Date **04/30/2026**

License Status

This license is current and active

Online Services Quick Hits

- ▶ [Check a License or HIS Registration](#)
- ▶ [Find My Licensed Contractor](#)
- ▶ [Frequently Asked Questions](#)
- ▶ [Forms and Applications](#)
- ▶ [Guides and Publications](#)
- ▶ [CSLB Laws and Regulations](#)
- ▶ [List of All CSLB Fees](#)
- ▶ [License Classifications](#)
- ▶ [Contractor Newsletter](#)
- ▶ [Application Status](#)
- ▶ [Application Status \(Secured\)](#)
- ▶ [Application Status by Personnel Name](#)
- ▶ [Application Status by Business Name](#)
- ▶ [CSLB Email Login](#)

Online Services



Exhibit 2

Bhatti, Ammar@EnergySafety

From: Bhatti, Ammar@EnergySafety
Sent: Wednesday, November 13, 2024 11:17 AM
To: latconstructioninc8@gmail.com
Subject: Underground Safety Board – No-811 Investigation Case N242633

Dear LAT Construction Inc,

Response Due Date: November 21, 2024

The Underground Safety Board (Board) has been notified about damage to a facility, potentially involving LAT Construction Inc. You have the option to respond to the following questions below using this interactive form or through a scheduled telephone interview.

Respond to the survey by clicking here: [No-811 Excavator Intake Questions](#)

All questions must be answered to submit this form. Alternatively, you can contact the investigator within the next two business days to schedule a phone interview to answer these questions.

Should you encounter any difficulties with the questions or prefer a telephone interview, contact the investigator within the next two business days to schedule a time to discuss. I have been assigned with following up on notification reporting that LAT Construction Inc, damaged the facility on 8/26/2024 by excavating without first contacting the Regional Notification Center. The damage occurred at or near 951 Brossard Dr. , Simi Valley.

The purpose of this report is to gather all the pertinent facts. The questions below, tailored for LAT Construction Inc, may serve to replace a formal interview. Respond to each question. The Board investigates excavation incidents to identify potential safety violations, and employ this data to enhance accident prevention, safeguard worker welfare, and protect people and property.

Furthermore, this information will aid in determining if any enforcement measures are warranted. In such a scenario, LAT Construction Inc will initially receive a Notice of Possible Violation (NOPV) following this investigation. NOPVs will be reviewed during public meetings of the Board to determine whether any violations of Government Code section 4216 et seq. have occurred. Should LAT Construction Inc receive an NOPV, you will be notified of your response options and of the date of your hearing.

To answer these questions you will need to gather information where applicable regarding excavation activities on the site, company and personnel contact information, the 811 ticket number and response information from the utility companies, emergency response actions, and prime contractor contact information.

Send with your answers to the questions, all the documents listed below that you possess, in their original format, which are associated with this damage by date indicated in email. "Documents" includes photographs, 811 ticket(s), written communications, incident reports, emails, texts, videos, or other related items.

Any documents the Board receives after response due date may not make it into the case file, resulting in them not being a part of the determination of your possible violation.

Ammar Bhatti

Investigator

Underground Infrastructure Directorate

Phone: 279-245-1087

www.energysafety.ca.gov



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Stay connected and informed by signing up for the [Underground Safety Board's subscriber list](#).

No-Ticket Damage Reporting Form

Submitted Time: November 13, 2024 11:45 AM

Provide your name, title, phone number, and email address

Name

Luis

Title

General contractor

Phone Number

818-815-1977

Email Address

Latconstructioninc8@gmail.com

Please provide the identifying information for LAT CONSTRUCTION INC in general.

California Contractor's State License Board (CSLB) license

1038128

Physical Address

13275 branford st Arleta Ca 91331

Mailing Address

13275 branford st Arleta CA 91331

Phone Number

818-815-1977

Email Address

Latconstructioninc8@gmail.com

Did LAT CONSTRUCTION INC damage the NaturalGas facility while excavating at 951 Brossard Dr. , Simi Valley on the 8/26/2024? (Select One)

Yes

Were there any other companies at or near 951 Brossard Dr. , Simi Valley on 8/26/2024? (Select One)

No

Did someone in LAT CONSTRUCTION INC, or anyone else, contact the Regional Notification Center on 8/26/2024?

Yes

Provide the number or numbers of the 811 ticket(s) created by the Regional Notification Center.

What is the 811-ticket created date(s) for each 811 ticket(s)?

Did LAT CONSTRUCTION INC, or anyone else, delineate the area where the damage occurred?

No

Did SoCalGas respond after the Regional Notification Center created the 811 ticket?

The damage notification indicated that a facility was damaged at 951 Brossard Dr. , Simi Valley on 8/26/2024. Is that correct?

Yes

Was LAT CONSTRUCTION INC the prime contractor on the project at 951 Brossard Dr. , Simi Valley on 8/26/2024?

Yes

What was mentioned or what direction did the prime contractor provide to you?

Provide the names, phone numbers, and if applicable, their email address for all your personnel who were at 951 Brossard Dr. , Simi Valley when the facility was damaged.

Name

Luis trujillo

Title

General contractor

Phone Number

818-815-1977

Email Address

Latconstructioninc8@gmail.com

Add an additional individual?

No

Which one of the individuals you identified was the foreman on the project when the facility was damaged?

Luis trujillo

Facility Damage

Was a facility damaged on 8/26/2024?

Yes

Describe the damaged facility.

Gas pipe gamage

Identify the type of material damaged.

Yellow ips

Explain how the facility was damaged?

Dig in a trench

What equipment did LAT CONSTRUCTION INC use on 8/26/2024? (Select All That Are Applicable)

Shovel

What type of equipment damaged the facility?

Shovel

Who was operating the equipment that damaged the facility on 8/26/2024?

Luis Trujillo

Does LAT CONSTRUCTION INC own that equipment?

Yes

Emergency Response

How did LAT CONSTRUCTION INC learn that the SoCalGas facility was damaged on 8/26/2024?

Did anyone with LAT CONSTRUCTION INC call 911 on 8/26/2024 after the damage had occurred?

No

Was there an emergency response to the incident from the fire department, a law enforcement department, or an ambulance on 8/26/2024?

No

Were there any injuries to any personnel or bystanders on 8/26/2024?

No

Were there any fatalities on 8/26/2024 or afterwards, due to the damage at 951 Brossard Dr. , Simi Valley?

No

Was there property damage on 8/26/2024, excluding the facility damage?

No

Was there a fire on 8/26/2024 as a result of the damage to the facility?

No

Was there an evacuation of any homes or businesses on 8/26/2024 as a result of the damage to the facility?

No

Are you aware of anyone else that called 911?

No

Did anyone at LAT CONSTRUCTION INC contact the Regional Notification Center after the damage on 8/26/2024?

Yes

What is the damage 811-ticket number?

Did anyone at LAT CONSTRUCTION INC contact SoCalGas after the damage?

Yes

Who at LAT CONSTRUCTION INC contacted the SoCalGas?

Luis Trujillo

What is the name of the person at the SoCalGas contacted by the individual you identified above?

What steps, if any, have LAT CONSTRUCTION INC taken to prevent a similar damage in the future?

We take a class with social gas representative

Is there any other information you want to share about this damage?

Exhibit 3



Contractor's License Detail for License # 1038128

DISCLAIMER: A license status check provides information taken from the CSLB license database. Before relying on this information, you should be aware of the following limitations.

- ▶ CSLB complaint disclosure is restricted by law ([B&P 7124.6](#)). If this entity is subject to public complaint disclosure click on link that will appear below for more information. Click [here](#) for a definition of disclosable actions.
- ▶ Only construction related civil judgments reported to CSLB are disclosed ([B&P 7071.17](#)).
- ▶ Arbitrations are not listed unless the contractor fails to comply with the terms.
- ▶ Due to workload, there may be relevant information that has not yet been entered into the board's license database.

Data current as of 5/1/2026 11:49:07 AM

Business Information

L A T CONSTRUCTION INC
13275 BRANFORD STREET
ARLETA, CA 91321
Business Phone Number:(818) 815-1977

Entity Corporation
Issue Date 04/16/2018
Expire Date 04/30/2028

License Status

This license is current and active.

All information below should be reviewed.

Classifications

- ▶ [B - GENERAL BUILDING](#)
- ▶ [C-61 / D63 - CONSTRUCTION CLEAN-UP](#)

Bonding Information

Contractor's Bond

This license filed a Contractor's Bond with [AMERICAN CONTRACTORS INDEMNITY COMPANY](#).

Bond Number: 100799424

Bond Amount: \$25,000

Effective Date: 09/11/2023

[Contractor's Bond History](#)

Bond of Qualifying Individual

The qualifying individual LUIS ALBERTO TRUJILLO CLIMACO certified that he/she owns 10 percent or more of the voting stock/membership interest of this company; therefore, the Bond of Qualifying Individual is not required.

Effective Date: 04/09/2024

[BQI's Bond History](#)

Workers' Compensation

This license has workers compensation insurance with the [STATE COMPENSATION INSURANCE FUND](#)

Policy Number: 9289361

Effective Date: 12/16/2020

Expire Date: 12/16/2026

[Workers' Compensation History](#)

Workers' compensation classification code(s):

8810 - Clerical Office Employees

For a description of the workers' compensation classification code(s) listed for this licensee, contact the licensee's insurance carrier. Contact information for the licensee's insurer is available by clicking the insurer link above. Classification codes are also available on the Workers' Compensation Insurance Rating Bureau's classification search page.

The board does not verify or investigate the accuracy of classification codes displayed.

Other

► Personnel listed on this license (current or disassociated) are listed on other licenses.

[Back to Top](#)

[Conditions of Use](#)

[Privacy Policy](#)

[Accessibility](#)

[Accessibility Certification](#)

Copyright © 2026 State of California

Exhibit 4



**CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION
INTERVIEW REPORT**

REPORT DATE: August 20, 2026

CASE NO: N242633

DATE AND TIME OF INTERVIEW: August 20, 2026, at 10:28 AM

LOCATION OF INTERVIEW: Phone

INVESTIGATOR: Ammar Bhatti

NAME, TITLE, AND COMPANY OF INTERVIEWEE: Luis Trujillo, General Contractor at LAT Construction Inc.

NOTES: Investigator called Trujillo and introduced himself. Investigator asked about Trujillo's responses on the excavator survey previously submitted by Trujillo. Investigator asked if Trujillo had a ticket number since he answered on the survey that LAT had reached out to call center prior to beginning excavation.

Trujillo explained that a previous contractor had marked the site on a prior occasion and Trujillo had not known then that he had to call his own ticket. He started digging which led to the damage.

Trujillo explained that he had taken his crew for a class offered by SoCalGas and would welcome any further opportunities to learn.

Exhibit 5

Bhatti, Ammar@EnergySafety

From: Bhatti, Ammar@EnergySafety
Sent: Wednesday, November 13, 2024 10:35 AM
To: Amber Dahl
Subject: Underground Safety Board – No-811 Investigation Case N242633

Hi Amber,

Please provide a copy of all tickets and electronic positive responses at about 951 Brossard Dr. Simi Valley for August 1, 2024 through September 15, 2024.

If there is not a ticket at this address for this date, confirm that finding.

Thank you,

Ammar Bhatti

Investigator
Underground Infrastructure Directorate
Phone: 279-245-1087

www.energysafety.ca.gov



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Stay connected and informed by signing up for the [Underground Safety Board's subscriber list](#).

Exhibit 6

Bhatti, Ammar@EnergySafety

From: Amber Dahl <amber@digalert.org>
Sent: Thursday, November 14, 2024 12:01 PM
To: Bhatti, Ammar@EnergySafety
Subject: File N242633
Attachments: N242633.pdf

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you,



Amber Dahl, Safety Director
Underground Service Alert of Southern California
PO BOX 77070 Corona, CA 92877
P: 951-808-8115 F: 951-808-8101
E: amber@digalert.org W: www.digalert.org



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.



Underground Service Alert

of Southern California™

November 14, 2024

Ammar Bhatti
Underground Safety Board

File Number: N242633

Dear Ammar,

After searching our records from 8/1/24 through 9/15/24, we were unable to find any DigAlert tickets for the location at or near 951 Brossard Dr in **Thousand Oaks**. I hope this information will be helpful.

If we can be of further assistance, please call us at 951-808-8100.

Sincerely,

Amber Dahl
Safety Awareness Director