



February 3, 2026

Crystal Bertolini
Team Lead, Wildfire Mitigation Program Compliance
San Diego Gas & Electric Company
8316 Century Park Court, CP32F
San Diego, CA 92123

NOTICE OF DATA INACCURACY

Ms. Bertolini:

Pursuant to Government Code section 15472, et seq, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by San Diego Gas & Electric Company (SDG&E) in accordance with its 2025 Wildfire Mitigation Plan (WMP) and determined the existence of a data inaccuracy. Energy Safety therefore issues SDG&E a Notice of Data Inaccuracy (NODI). Failure to remedy this data inaccuracy prior to the submission of SDG&E's 2025 Annual Implementation Report may lead to a Notice of Non-Performance (NON) if the inaccuracy causes SDG&E to miss a WMP target or prevents Energy Safety from ensuring that SDG&E performed the targets and statements made in SDG&E's 2025 WMP.

On November 5, 2025, Energy Safety conducted an inspection of San Diego Gas & Electric Company's WMP initiatives in the vicinity of the city of Jamul, California. The inspection report is enclosed herewith. Energy Safety found the following data inaccuracies:

Data Inaccuracy 1. On Pole ID P330064, Grid Hardening ID 530000377023-P330064 at coordinates 32.730586, -116.836448, the inspector observed that SDG&E failed to provide accurate data.

The data inaccuracy identified in this notice could make it appear as though SDG&E reached the target set in its WMP initiative related to avian protection, when it has not. If SDG&E does not address this data inaccuracy and includes the inaccurate data in SDG&E's reporting regarding its WMP initiative related to avian protection, SDG&E may be found to fail to achieve the target for that WMP initiative. This failure may be raised in a future NON or in Energy Safety's 2025 Annual Performance Report on SDG&E's WMP Performance.

Within 30 days from the issuance date of this NODI, SDG&E should provide a response advising Energy Safety of corrective actions taken or planned to remedy the identified data inaccuracy or inaccuracies.

This response shall be filed in the Energy Safety e-Filing system under the 2025 NODI Docket,¹ and the associated file name(s) must begin with the NODI identification number.

Sincerely,

Patrick Doherty

Patrick Doherty
Program Manager | Performance Assessment Division
Office of Energy Infrastructure Safety
Patrick.doherty@energysafety.ca.gov

Cc:

WildfireMitigationCompliance@SDGE.com

Jonathan Woldemariam, SDG&E

JWoldemariam@SDGE.com

Kari Kloberdanz, SDG&E

KKloberdanz@SDGE.com

Shewit Woldegiorgis, SDG&E

SWoldegiorgis@SDGE.com

Laura Fulton, SDG&E

LFulton@SDGE.com

Kimberly Siebenthal, SDG&E

KSiebenthal@SDGE.com

Mary Innamorato, SDG&E

MInnamorato@SDGE.com

Yana Loginova, Energy Safety

Yana.Loginova@energysafety.ca.gov

Samuel Isaiah, Energy Safety

Samuel.Isaiah@energysafety.ca.gov

Shannon Greene, Energy Safety

Shannon.Greene@energysafety.ca.gov

Assetperformance@energysafety.ca.gov

¹ <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2025%20NODI>



State of California – A Natural Resources Agency
OFFICE OF ENERGY INFRASTRUCTURE SAFETY
715 P Street, 20th Floor | Sacramento, CA 95814
916.902.6000 | www.energysafety.ca.gov

Gavin Newsom, Governor
Caroline Thomas Jacobs, Director

INSPECTION REPORT

Electrical Corporation:	San Diego Gas & Electric Company
Report Number:	PAD_SDGE_SIS_20251105_0853
Date of Inspection:	November 05, 2025
City and/or County of Inspection:	Jamul, San Diego County
Inspector:	Samuel Isaiah
WMP Year Inspected:	2025
Quarterly Data Report (QDR) Referenced:	Quarter 1 (Q1)
Inspection Selection:	Energy Safety viewed the contents of the Q1 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.10.1 – Avian Protection (WMP.972)
Inspection Purpose:	Assess the accuracy of San Diego Gas and Electric Company's QDR data, completeness of its work, and performance of WMP requirements.

WMP Inspection Data Inaccuracies

Data Inaccuracy #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Data Inaccuracy Description
Data Inaccuracy 1	P330064	530000377023-P330064	32.730586, -116.836448	Tier 3	8.1.2.10.1 Avian Protection	Inaccurate data provided on avian protection

Observations

Data Inaccuracy 1

Findings:

On Pole ID P330064, Grid Hardening ID 530000377023-P330064 at 15061 Lyons Valley Rd, Jamul, CA, 91935, 32.730586, -116.836448, the inspector observed that no avian protection was installed at this location. The inspector's observation is documented in Data Inaccuracy 1 photographs, which are attached to this report as IA1Img1, IA1Img2, IA1Img3 and IA1Img4.

Energy Safety concludes that there is inaccurate data because of these facts:

1. SDG&E's 2025 Q1 QDR identified that WMP Avian Protection (8.1.2.10.1) work was completed at the inspection location.
2. Avian protection was not installed.

This observation indicates that the data regarding avian protection was not accurate. Failure to rectify this data inaccuracy prior to the submission of any performance assessments, such as annual reports, may result in a notice of non-performance.

Exhibits

Exhibit A: Photo Log

Structure ID: P330064

Data Inaccuracy 1



GImg1: Overall Structure

GImg2: Structure ID



IA1Img1: No Avian Protection Observed



IA1Img2: No Avian Protection Observed



IA1Img3: No Avian Protection Observed



IA1Img4: No Avian Protection Observed