

February 26, 2026

Patrick Doherty, Compliance Program Manager
Performance Assessment Division
Office of Energy Infrastructure Safety
California Natural Resources Agency
715 P Street 20th Floor
Sacramento, CA 95814

BY ENERGY SAFETY E-FILING

SUBJECT: Southern California Edison Company's Response to Notice of Non-Performance (NON_ESD_SCE_RGA_20260126_1347)

Dear Mr. Doherty:

Southern California Edison Company (SCE) appreciates the opportunity to provide this response to the finding identified in the Notice of Non-Performance – **NON_ESD_SCE_RGA_20260126_1347** which SCE received on **February 10, 2026 (Notice)**, based on the Office of Energy Infrastructure Safety's (Energy Safety) field inspections conducted in SCE's service area on **January 26, 2026**. SCE appreciates Energy Safety's efforts to identify, communicate and work together to resolve potential wildfire risks. The enclosed response describes corrective actions taken or planned by SCE to remedy the finding identified in the Notice and to prevent recurrence.

If you have any questions, or require additional information, please contact Liz Leano at 626-302-3662 or Elizabeth.Leano@sce.com.

Sincerely,

//s//

Brandon Tolentino
Vice President of Wildfire and Business Resiliency
Southern California Edison

SCE Response

Finding:

Notice	#	Structures
NON_ESD_SCE_RGA_20260126_1347	1	4081768E

Summary of Findings:

Energy Safety’s Notice states that in implementing its 2025 WMP initiative 8.2.3.4.2, which requires compliance with Public Resource Code 4293, SCE failed to remove a dead, declining, or dying tree near coordinates 34.1941, -118.112034.

Energy Safety states that it “considers this non-performance to be in the **Moderate Risk category**.”¹

Response:

An SCE Senior Specialist (SSP), who is an ISA Certified Arborist, visited the location on 2/11/26 and confirmed the trees were dead and required mitigation. The SSP met with the homeowner who wanted his own arborist to validate the condition of the trees.

The SSP and homeowner’s arborist met at the property on 2/13/26 and obtained agreement to remove the trees.

Both trees were removed on 2/17/26. Before and after photos are shown below.

¹ Notice, p. 1.



Before Photo 2/11/26



After Photo 2/17/26